AUGUST 1987Lustralia \$2.20, New Zealand \$2.95 (inc. GST), Malaysia \$5.00**TGUGUST 1987**£1.30**TGUGUST 1987EDUGUST 1987TGUGUST 1987**<



Servicing with a Logic Probe and Pulser Cable Television Techniques Budget Variable PSU • DX-TV VCR Clinic • TV Fault Finding





TELEVISION

August

Vol. 37, No. 10 Issue 442

On sale July 15th

COPYRIGHT

© IPC Magazines Limited, 1987. Copyright in all drawings, photographs and articles published in *Television* is fully protected and reproduction or imitation in whole or in part is expressly forbidden. All reasonable precautions are taken by *Television* to ensure that the advice and data given to readers are reliable. We cannot however guarantee it and we cannot accept legal responsibility for it. Prices are those current as we go to press.

CORRESPONDENCE

All correspondence regarding advertisements should be addressed to the Advertisement Manager, "Television", King's Reach Tower, Stamford Street, London SE1 9LS. Editorial correspondence should be addressed to "Television", IPC Magazines Ltd., King's Reach Tower, Stamford Street, London SE1 9LS.

SUBSCRIPTIONS

An annual subscription costs £16 in the UK, £19 overseas (by surface mail). Send orders with payment to Quadrant Subscription Services Ltd., Oakfield House, Perrymount Road, Haywards Heath, Sussex, RH16 3DH.

BACK NUMBERS

Some copies of issues published **during the** last six months are available from the Editorial Office at £1-40 inclusive of postage and packing. Address requests to Television, Editorial Office, IPC Magazines Ltd., King's Reach Tower, Stamford Street, London, SE1 9LS.

QUERIES

We regret that we cannot answer technical queries over the telephone nor supply service sheets. We will endeavour to assist readers who have gueries relating to articles published in Television, but we cannot offer advice on modifications to our published designs nor comment on alternative ways of using them. Correspondents should enclose a stamped addressed envelope. Requests for advice on dealing with servicing problems should be directed to our Queries Service. For details see our regular feature "Service Bureau". Send to the address above given (see "correspondence").

this month

669 Leader

- 670 Long-distance Television Roger Bunney Reports on DX conditions and reception and news from abroad. Thoughts on removing amateur radio interference in the 50MHz band.
- 675 The 8mm Video System, Part 5 Eugene Trundle This concluding instalment of the series deals with the multi-PCM mode for audio recording/playback and provides some initial guidance on servicing.
- 677 Budget Variable Power Supply William Harrison A simple, cheap to build bench power supply based on the LM723 chip. Provides a stabilised 2-15V output at up to 2A or so.
- 678 Servicing with a Probe and Pulser David Botto The increasing use of digital control systems in both VCRs and TV sets is presenting service engineers with new and tricky problems. Servicing is greatly eased by the use of a probe and pulser to make in and out of circuit checks on the digital i.c.s used in such systems.

682 Teletopics

News, comment and developments.

- 685 The Computer as an Aid to Servicing, Part 3 Chas E. Miller Further notes on the uses of computers in the service department. This time keeping records on sets and customers.
 - VCR Clinic Reports from Christopher Holland, Alfred Damp, Philip Blundell, Eng. Tech. and Eugene Trundle.
- 688 Tiny Tim's Triple Trouble Les Lawry-Johns Awkward problems seem to come to Tim in threes.
- 689 Letters

686

694

- 691 Next Month in Television
 - TV Fault Finding Reports from Aled Roberts, GW6BMP, D.A. Brown, Mick Dutton, Lawrence Ingram, Eugene Trundle, Roger Burchett, Hugh MacMullen, Michael Dranfield and Steve Leatherbarrow.
- 696 Servicing Mechanical VCRs, Part 5 This time the loading system, the reel assemblies and the back-tension band.
- 698 Vintage TV: Early GEC Sets Chas E. Miller The sets that GEC designed and produced before the merger with Sobell.
- 700 A Look at Capacitors George Wilding The action of capacitors and their use in TV circuitry.
- 702 Cable Television Techniques, Part 1 J. LeJeune How cable TV systems developed from the early days of radio relay to the present.
- 704 Service Bureau

705 Test Case 296

OUR NEXT ISSUE DATED SEPTEMBER WILL BE PUBLISHED ON AUGUST 19

P. 104 AE Tel: 02 Telex:	BEY 54 36 6355	STREE	U r, A0 511/3 in G	CCRING 390936 (For P.)	TON E V.)	, LANCS	C 5 N 9 (no	TRADE OUNTER OPEN MON-SAT Jam-5pm ot Wed pm)	BARCIA	ADD 8 Heavier aids, d 52.501 Chargee used w VAT to Sent by 25K (er	HOW TO 7p per ord parcels e. egausing C P+P (U.K d at cost. 1 henever po total exce total exce	ORDER fer P+P (U.K.). g. cabie, service oils piease allow .). Export orders irst Class Mail is sssible. Add 15% pt where it states r items will be .50 + VAT up to s).	THER BOOK Goods If for a speed reque: ask if Prices cases	E IS VAT ON P-1 S AND MANUALS are despatched any reason we are s quickly as pos y, fair and effic st. Give us a ring what you need is are subject to we may have to	-P. S ARE Z on the di solut of s sible. W ient ser y - we'll s not list change supply i	ERO V.A.T. ay we receive your o tock we will try to in e try our best to g vice. V.A.T. invoic give you service. give you service. Hed – we will try to without notice. In an equivalent.	rder. form live a le on lease help. some
NTEGRATE NA2140 AN240 AN318 AN240 AN318 AN240 AN318 AN240 AN318 AN262 AN318 AN262 AN318 AN262 AN318 AN262 AN318 AN262 AN318 AN320 AN318 AN320 AN318 AN320 AN318 AN320 AN	D CIRCU 3.91 3.84 6.37 4.10 5.15 3.97 8.97 7.8.97 7.8.97 7.8.97 7.8.97 7.8.97 7.8.97 7.8.97 3.97 3.97 3.97 3.07 1.82 4.20 1.80 3.07 1.82 4.20 1.80 3.07 1.82 4.20 1.80 3.07 1.82 4.20 1.80 3.07 1.82 4.20 1.80 3.07 1.82 4.20 1.80 3.07 1.82 4.20 1.80 3.07 1.82 4.20 3.07 1.82 4.20 3.07 1.82 4.20 3.07 1.82 4.20 3.07 1.82 4.20 3.07 1.82 4.20 3.07 1.82 4.20 3.07 1.82 4.20 3.20 5.68 2.80 3.20 4.21 4.04 2.3.22 4.3 3.25 3.25 3.25 5.50 5.93 5.57 5.50 5.90 5.20 7.10 6.00 2.20	ITS SL1430 SL1432 SL76544 SL432 SL76544 SL432 SL76544 SL432 SL76544 SL432 SL76544 SL76547 SN765131N SN76533N SN76533N SN76533N SN76543N SN76560N SN76560N SN76560N SN76560N SN76530A STK433 STK433 STK435 STK437 STK455 STK437 STK451 STR4520 STR4520	1.58 3.36 2.05 1.89 2.07 2.00 2.27 1.18 1.70 2.35 8.00 2.27 1.18 1.70 9.06 6.50 4.77 7.85 8.40 9.56 5.65 9.06 6.50 4.73 7.85 8.40 9.56 14.30 9.56 3.90 9.56 3.40 9.50 4.73 7.85 8.40 9.50 4.73 7.85 8.40 9.50 4.73 7.85 8.40 9.50 4.73 7.85 8.40 9.50 8.40 9.50 8.40 9.50 8.40 9.50 8.40 9.50 8.40 9.50 8.40 9.50 8.40 9.50 8.40 9.50 8.40 9.50 8.40 9.50 8.50 8.50 8.40 9.55 8.40 9.50 8.50 8.50 8.40 9.55 8.40 9.50 8.50 8.50 8.40 9.55 8.40 9.55 8.40 9.50 8.50 8.50 8.40 9.55 8.50 8.40 9.55 8.50 8.40 9.55 8.50 8.50 8.40 8.90 8.90 8.90 8.90 8.90 8.90 8.90 8.9	TGA270S0 TGA200S0 TGA800 TCA800 TCA800 TCA900 TCA910 TCA940 TCA940 TDA102 TDA102 TDA102 TDA1037 TDA105 TDA105 TDA105 TDA105 TDA1037 TDA1044 TDA106A TDA1035 TDA1037 TDA1044 TDA1060A TDA1037 TDA1044 TDA1060A TDA1037 TDA1130 TDA1130 TDA1130 TDA1130 TDA11307 TDA1327 TDA1327 TDA1328 TDA1415 TDA1327 TDA1328 TDA1415 TDA1327 TDA1328 TDA1415 TDA1327 TDA1328 TDA1415 TDA1327 TDA1328 TDA1415 TDA1327 TDA1328 TDA1415 TDA1327 TDA1328 TDA1415 TDA1415 TDA1415 TDA1415 TDA1415 TDA14200 TDA2004 TDA2004 TDA2004 TDA2004 TDA2006 TDA2004 TDA2004 TDA2006 TDA2517 TDA2523 TDA2523 TDA2523 TDA2523 TDA2523 TDA2520 TDA2521 TDA2523 TDA2523 TDA2520 TDA2574 TDA2578A TDA2578 TDA2578 TDA2578 TDA2578 TDA2571 TDA2578 TDA2571 TDA2578 TDA2571 TDA2578 TDA2571 TDA3500 TDA4600 TDA3500 TDA4500 TDA4500 TDA4500 TDA4500 TDA4500 TDA4500 TDA4500 TDA4500 TDA4500 TDA4500 TDA4500 TDA4500 TDA4500 TDA45	2.50 2.50 3.44 2.20 1.95 3.60 3.30 1.95 5.50 3.60 3.30 4.70 2.95 3.60 3.30 4.70 2.95 3.60 3.30 4.70 2.95 3.60 3.30 4.44 4.70 4.37 4.44 4.58 3.50 3.50 1.91 1.95 1.90 1.95	UPC1167C2 UPC1168C UPC1178C UPC1178C UPC1180C UPC1181H UPC1182H UPC1182H UPC1182H UPC1185H UPC1185H UPC1185H UPC1185H UPC1185H UPC1184H UPC1186H UPC1185H UPC1212V UPC1212V UPC1212V UPC1217G UPC1217G UPC1226C UPC1228H UPC1228H UPC1228H UPC1228H UPC1228H UPC1228H UPC1228H UPC1228C UPC1350C UPC1350C UPC1350C UPC1350C UPC1365C UPC1365C UPC1365C UPC1365C UPC1365C UPC1365C UPC1368H UPC1368C UP	2.70 2.70 2.70 2.70 2.70 2.70 2.70 2.53 3.20 2.53 3.20 2.53 3.20 2.53 3.20 2.53 3.15 4.21 1.84 4.29 2.248 3.86 4.99 2.20 1.32 4.99 2.20 4.99 2.20 4.39 2.20 4.39 2.20 4.39 2.20 4.39 2.20 4.39 2.20 4.39 2.20 4.39 2.20 4.39 2.20 4.35 4.21 5.25 4.21 1.20 4.39 2.20	SEMICONDUC AC107 AC107 AC126 AC127 AC128 AC128 AC128 AC128 AC128 AC128 AC128 AC128 AC128 AC128 AC128 AC128 AC128 AC138 AC137 AC176 AC176 AC176 AC176 AC176 AC188 AD143 = 0C28 AD143 = 0C28 BC109 BC114 = 0C17 BC108 = BC19 BC140 BC147 BC148 = BC147 BC148 = BC147 BC148 = BC147 BC148 = BC147 BC148 = BC147 BC148 = BC147 BC148 = BC148 BC147 = BC148 BC147 = BC148 BC147 = BC148 BC147 = BC148 BC148 = BC148 BC147 = BC148 = BC558 BC159 = BC558 = BC558 BC204 = BC204 = BC208 BC207 = BC238 = BC28 BC237 = BC428 = BC38 BC237 = BC428 = BC48 = B	TORS 334 34 34 34 34 34 34 34 34 3	8C558 BC637 BC638 BC639 BC640 BC639 BC640 BC772 BC372S BD115 BD116 BD124P BD131 BD133 BD133 BD133 BD133 BD133 BD133 BD133 BD134 BD133 BD135 BD133 BD140 BD159 BD160 BD160 BD160 BD160 BD160 BD160 BD160 BD179 BD182 BD202 BD202 BD203 BD204 BD202 BD204 BD202 BD203 BD204 BD203 BD204 BD203 BD204 BD203 BD204 BD203 BD204 BD203 BD204 BD203 BD204 BD203 BD204 BD203 BD204 BD203 BD204 BD203 BD204 BD203 BD204 BD203 BD204 BD203 BD204 BD203 BD204 BD205 BD203 BD204 BD205 BD206 BD278 BD235 BD236 BD235 BD236 BD235 BD236 BD236 BD237 BD235 BD236 BD238 BD338 BD238 BD338 BD338 BD338 BD338 BD338 BD338 BD338 BD338 BD338 BD338 BD338 BD599 BD338 BD39	$\begin{array}{c} 9\\ 9\\ 19\\ 39\\ 33\\ 30\\ 32\\ 13\\ 85\\ 45\\ 90\\ 84\\ 50\\ 90\\ 84\\ 50\\ 90\\ 84\\ 50\\ 90\\ 84\\ 50\\ 90\\ 84\\ 50\\ 90\\ 84\\ 50\\ 90\\ 84\\ 50\\ 70\\ 1.20\\ 1.60\\ 57\\ 57\\ 55\\ 57\\ 55\\ 85\\ 87\\ 74\\ 86\\ 63\\ 60\\ 57\\ 57\\ 55\\ 85\\ 87\\ 74\\ 86\\ 63\\ 86\\ 81\\ 1.63\\ 1.53\\ 210\\ 38\\ 85\\ 81\\ 1.63\\ 210\\ 38\\ 85\\ 91\\ 1.63\\ 210\\ 38\\ 85\\ 81\\ 1.63\\ 210\\ 38\\ 85\\ 81\\ 1.63\\ 210\\ 38\\ 85\\ 81\\ 1.63\\ 210\\ 38\\ 86\\ 81\\ 1.63\\ 210\\ 39\\ 36\\ 29\\ 422\\ 39\\ 36\\ 29\\ 422\\ 39\\ 36\\ 29\\ 422\\ 39\\ 36\\ 29\\ 422\\ 39\\ 36\\ 30\\ 422\\ 30\\ 30\\ 30\\ 422\\ 30\\ 30\\ 30\\ 422\\ 30\\ 30\\ 30\\ 422\\ 30\\ 30\\ 30\\ 422\\ 30\\ 30\\ 30\\ 30\\ 30\\ 30\\ 30\\ 30\\ 30\\ 30$	BF273 BF274 BF337 BF338 BF337 BF338 BF337 BF338 BF352 BF362 BF371 BF382 BF422 BF422 BF422 BF423 BF424 BF425 BF457 BF458 BF469 BF460 BF470 BF39 BF739 BF739 BF739 BF739 BF739 BF739 BF739 BF739 BF739 BF742 BF739 BF742 BF742 BF743 BF752 BF752 BF752 BF752 BF751 BF752 BF751 BF752 BF752 BF752 BF755 BSV578 BT100	24 24 24 40 41 41 56 58 72 30 334 45 58 66 335 334 45 58 66 35 54 54 54 54 54 54 54 54 60 85 61 61 54 42 7 30 85 66 36 61 61 54 42 42 30 85 88 66 36 61 61 54 42 42 30 85 88 66 36 61 61 54 42 42 30 85 88 66 30 85 88 66 30 85 88 66 30 85 88 66 30 85 88 66 30 85 88 66 30 85 88 66 30 85 88 66 30 85 88 66 30 85 88 66 30 85 88 66 30 85 88 66 30 85 88 66 30 85 88 66 30 85 88 66 30 85 83 80 66 30 85 83 80 85 83 80 85 83 80 85 83 80 85 83 80 85 83 80 85 83 80 85 83 80 85 83 80 85 83 80 85 83 80 85 83 80 85 83 80 80 80 85 83 80 80 80 80 80 80 80 80 80 80 80 80 80	MR475 MR477 MR477 OT121 R2008 R2008 R20106 R2265 R2322 R2323 R2461 R24558 RCA16039 RCA16040 RCA16040 RCA16040 RCA16040 RCA16041 RCA16334 =ON447 RCA16335 =ON447 RCA16957 TIC45 TIC45 TIC45 TIC45 TIC46 TIC47 TIL32 TIL78 TIP29C TIP30A TIP30A TIP30C TIP31C TIP31C TIP32C TIP338 TIP41C TIP42C TIP338 TIP41C TIP42C TIP31C TIP1955 TIP305 TIP315 TIP41C TIP42C TIP42C TIP355 TIS91 TIP11211 TIP120 TIP1255 TIS91 TIP10555 TIS91 TIP10555 TIS91 TIP305 TIS91 TIP305 TIP305 TIS91 TIP305	4.85 4.85 4.90 1.91 1.90 1.92 1.50 84 67 1.60 90 90 90 90 90 2.88 1.18 50 72 2.00 90 90 90 2.88 1.18 50 72 4.8 51 1.96 65 4.8 4.3 55 54 4.8 4.3 55 54 4.8 4.3 55 54 4.8 54 4.7 50 54 4.8 54 4.7 50 54 4.8 54 4.7 55 4.8 54 4.7 50 54 4.8 54 4.7 55 4.8 54 4.7 55 4.8 54 4.7 55 4.8 55 51 51 51 51 51 51 51 51 51 51 51 51	2SC2551 1 2SC2551 1 2SC2785 2 2SC435 1 2SC435 1 2SC435 1 2SC435 1 2SC436 1 2SC436 1 2SC436 1 2SC436 1 2SC1306 2 2SC1307 3 2SC1436 2 2SC1307 3 2SC1420 2 2SC1307 3 2SC1306 2 2SC1307 3 2SC1420 2 2SC1061 2 2SC2028 2 2SC2078 2 2SC2076 2 2SC146 2 2SD173 2 2SD1437 2 2SD1437 2 2SD1437 2 2SD1437 2 2SD1433 1 CPS10 2 2SD1433	.77 43 .10 .31 .32 .50 .67 .90 .67 .90 .67 .90 .67 .90 .67 .90 .67 .90 .67 .90 .67 .90 .67 .90 .94 .94 .94 .94 .94 .94 .94 .94 .94 .94

P.V. TUBES AL	CALLERS WAYS WELCOME		SECURITY EQUIPM DIST. FOR SHORROCKS PROD B1 Shorrock Acorn	ENT	FOR ALL YOUR SPECIFIC COMPONENTS			
TEL: 0254 36521 TELEX: 6355	62		075 panel B2 Eurobell Comp. B5 "C" Polypron box	32.50 21.00	THORN/FERGUSON SONY	SEND FOR OUR FULL CATALOGUE		
32611 GRIFFIN G 390936 FOR P.V.	VARICAP TUNERS ELC1043-05 ELC104305 Mullard	8.40 12.50	with back plate B6 "C" Polycarb. box	4.55	AMSTRAD FIDELITY	-NEW PRODUCTS-		
VIDEO PINCH ROLLERS	ELC1043-06 ELC2003 Philips G8/G9 Philips G11 (11221)	8.40 19.50 10.50	with back plate B7 Freidland Bell	7.80 12.47	HITACHI/GEC PHILIPS	///////////////////////////////////////		
PANASONIC NV7000 4.35 SANYO VTC9300/VBS7000 4.35 SONY C7/J7/SL17 4.35 JVC TCE3V00/01/06/16/ 4.35	U322 U341 U342	7.30 9.50 8.50	CA15 4 core cable CA16 6 core cable	5.55	DECCA SINCLAIR	THORN NEW LIFE * VIDEO HEADS FOR		
23/24 4.35 JVC HR2200/3320/3330/ 3660/1100/7700 4.35 AKAI VS9700 4.35	PUSH BUTTON ASS.		817S Shorrock P.I.R. 815S Shorrock P.I.R	10.31 22.50	COMMODORE ANTEX	VEH0103 VEH0121 £25 95		
HITACHI V15000 4.35 SHARP VC6300/6500 4.35 SONY TC6 GEN 4.35	Hitachi 4 way Philips G8 (early) Philips G8 (late) Philips G11 Tin Switch unit	12.36 17.82 18.97 26.50	010 Orion I.R. SL8 Infrascan	24.00	ANTIFERENCE EVER READY	VEH0218 exchange		
VIDEO BELT KITS	Philips KT3 Philips KT30 Thorn 9000 6 way	16.67 13.22 20.70	137 Shorrock SAB BA9 1.9A battery	8.76 7.77	LABGEAR NEWLIFE	Full equivalent list on request		
HR3300/HR3320/ HR3330/HR3360 TCE 8903/3V00/3V16/3V22 3.50 VEVIT - RAMAC ONLY - NY/2008 AN/2008 - 2.00	Pye 697 repair kit Pye 725-735 (also Red Mk.1) 1 Pye 725-735 tuning head with PCB 1	10.35 12.60 12. 50	S3 712 Siren QUANTITY PRICES ON REC	5.75 NUEST	AMPROBE SERVISOL	SERVISOL COLDKLENE 110		
VENIT 2 SONY SLC5/7 3.75 VEXIT 4 SONY SLC5/7 3.75 VEXIT 4 SONY SL8000/8500/8600 4.50 VEXIT 5 SONY SL3000UB 4.00 VEXIT 6 PANASONIC NV3D00B 3.00	Decca 4 way Decca 6 way Decca 4/6 way conversion kit 1 Decca 7 way piano key rep, kit 1	7.93 9.17 17.50	GEN. EQUIPMENT/TOO	DLS	ARROW SCOTCH	DEGREASE SOLVENT		
VERIT 7 SANYO 9300P 4.25 VERIT 8 PANASONIC NV20006 3.75 VERIT 9 PANASONIC NV20006 3.75 VERIT 9 PANASONIC NV20006 3.05 VERIT 10 DSHID V8600 3.00	GEC 2110 6 way GEC 6 way slim GEC/ITT/PYE 7 way	10.92 10. 29 16.67	Degaussing Coll Stick Electric Circuit Tester	2.20 19.00 1.50	SKC SPARKOMATIC	F.M. AERIAL (round)		
VEKIT 11 SHARP VC7300 3.50 VEKIT 12 SHARP VC6300/6600 4.00 VEKIT 13 SANYO VTC5000 1.95 VEKIT 14 SANYO VTC5000 2.50	GEC Conversion kit 1 Rank A823 1 Rank T20A 11	16.50 12.36 11.21	Probes (x10) or (x1) Philips Switchable Probes Automatic Wire Strippers	10.90 13.25 6.95	JUST ASK!!	£7.95		
VEKIT 15 JVC HR7650 2.50 VEKIT 17 SHARP 8300 1.76 VEKIT 18 SHARP 9300 1.47 VEKIT 18 SHARP 9300 1.47 VEKIT 14 VT8000 1.12	ITT 6 way with V CR Thorn 8500 GEC 7 B/P c neons	8.90 6.50 10.50	I.C. Inserters Micro Pilers	1.18	We cannot advertise our complete range Please ask if you require something which ie: Stationery, Styli, Axial/Radial Electro	of products: is not listed, tytics, Mixed SURGE		
VEKIT 20 HITACHI VT11/33 2.15 VEKIT 21 HITACHI 9500 1.12 VEKIT 22 SONY SLC6 7.95 VEKIT 25 TOSHIBA V7540 1.90	LINE OUTPUT TRANS.		Trim Tools Metai Ended Side Cutters sm.	30 1.20	Dialectric Caps., Polyester Caps., Carbo Wirewound Resistors, Filament Lamps, LEDs, IC Sockets, Floppy Discs, Comput Thorn New Life Tubes (collection on A	Thermistors, PLUG er Cassettes, 13A		
VEKIT 26 JVC HR7000 96p	Philips 210/300 Mono 1 Philips G8 Philips G9 Philips G9	10.00 8.75 9.50	Long Nose Pliers Sm. Neon Screwdriver Quick Set Adhesive (Superglue)	1.20 40 75	Tubes, Crystals, Cables (concition only), Equipment, Electrical Plugs/Sockets, Cor Sinclair, Amstrad and Acom, Uniset Audi	mponents for Bange. £12 50		
0.Dla I.Dla Width SONY 23.7 17.4 4.9 50p SONY 24.2 18 5.1 50p	Philips K30 1 Philips TX2 1 Philips TX3 1	17.94 13.39 14.41	Dynascan Tube Reju./testers 467 model inc. bases * 470 model inc. bases *	399.00	SEND FOR CATAL	DGUEI		
HITACHI 31.8 25 4.9 50p PANASONIC 37 27 3.9 52p AKAI 26 20 3.9 50p	Philips G11 1 Pye 713/715 1 Pye 725 90° 1	5.58 0.00 0.50	available without bases for 50.00	less	REMOTE HANDSETS PHILIPS	DIY AERIAL		
JVC 23.9 4.8 4 56p NATPAN 31.2 56p	Pye 741 Bang & Olutson (2000,3000) 1 DECCA 80	9.90 4.69 8.58	Tube Bases For Dynascan		IR8331 K13/K30 Non Text IR 15.85 IR8420 KT3/K30 Text IR 16.70 IR8435 G11 8 Way Text IR 20.85	inc. 10 ele WB		
VIDEO HEADS Thorn New Life (Nat Pan)* 25.95	Decca 100 Decca 1700 Decca 1730	8.58 9.00 8.58	No. 1 9.09 No. 14 No. 3 9.50 No. 15 No. 5 9.09 No. 18	16.63 16.44 10.83	US8518 G11 2 Function US 18.75 691, 17181 G11 31 Button US 27.00 218 20578 KT3 K30 K35 KT4 KT40 (Non	40ft coax fittings		
Third New Life Reads (exchange) 22.95 3HSSV 24.93 4HSS (3HSSN) 24.93 PS3B Sonv/Beta 28.12	GEC 2110 1 GEC 2040 1 ITT CVC 1/9 1	6.75 9.50	No. 6 11.08 No. 19 No. 7 9.09 No. 21 No. 8 10.08 No. 23	10.83 14.40 13.86	Text or Text) 25.00	£6.00		
Philips V2000 and V2023 64.00 Philips 1700 64.00 Sanyo 9300/9455/9500 53.00	ITT CVC 25/30/32 ITT CVC 20 ITT CVC 45	8.65 8.60 8.60	No. 9 9.09 No. 24 No. 13 11.11 No. 25	27.07 12.57	INSTRUCTIONS Philips KT3/30 1. without Text 8.95			
Sanyo 5000/3300/3400 53,00 Toshiba 9600 Upper Ass. 12.50 Toshiba 9600 (Rep. type only) PS3BT 37.50 Sonv 8000 UB 49.39	R.B.M. 120 1 R.B.M. BUSHRANGER T16A 1 R.B.M. BUSHRANGER T18A 1 Thom 3000 FHT	3.95 0.00⊵ 0.00 9.95	Avo Meters Factory Recon. Avo Battery	119.00	J.V.C.	20 mhz single trace		
Sony SLC9 49.39 Sony SLC5, 6, 7 49.39 Sharp 8300 58.00	Thom 3000 SCAN Thom 8500 1 Thom 3000/3500 Mains 1	7.95 7.50 0.00	Solder Sucker Antistat min. Solder Sucker Antistat std.	4.50 5.40 6.20	RTP843 Text IR (Also G11) 13.50	Colour Bar Gen		
Sharp 3300/9700 56.00 Sharp 3HSS (S.P.) 40.62 Hitachi HIVI/VT8000E 35.62 Hitachi VT33F/GEC 4004 35.62	Thom 1615 1 Thom 1691 Thom 7X9 2 Thom 7X9 2	2.50 9.68 3.85	Solder 500g D.I.Y. Solder Small Pack	7.00	RTP20 Telepilot 12 13.50 RTP05 Telepilot 8 13.50	£199.00		
Hitachi VT11/GEC 4100 35.62 Sharp 7300 49.39 Hitachi 9300/4001 3HSSH 32.12	Thorn 9000 2	5.53	Solda Mop Stnd. For sold. irons see Antex/Weller U	77 nder	RTP07 Telepilot 300 13.50 RTP 400/01 13.50			
 Thom New Life heads are refurbished heads and we have types to cover most VHS types on an exchange basis 	Thom 1500 3 Stick Thom 1500 5 Stick Thom 2500	5.20 6.99	Choc Bloc 5A Fuse Wire 5A, 15A, 30A	20 05	DECCA US8513 101 Non Text US 20.85	ORION V		
VIDEO TAPE SKC E60 2.50 Scotch E30 3.66	Thorn 8000 Thorn 8500/8800 Thorn 9000	6.95 7.15 8.70	Fluorescent Starter 4-80W) Battery Press Studs min. Battery Press Studs std.	15 11 15	US8011 80/100 3 Func. US 19.50	Red with Built in Light		
E120 2.88 E60 4.00 E180 2.80 E120 3.24 E240 3.76 E180 3.86 L500 2.90 L750 5.22	Decca 1730/1830 Decca 30 Decca 80	5.48 6.76 7.12	Vero Board Double Sided Adhesive Tape Tinged Cooper Wire	2.59 5.75	IR8442 T723 19.50 IR8688 T725 TX9/10 23.00 IR8864 T736 TX9/10/100 Text 23.85	111//		
Philips LVC 1700 17.50 VCC480 7.23	Decca/Tatung 120/130 GEC 2100 GEC 2200 (20AX)	7.50 6.50 7.40 6.50	185 WG 45 Amp 14SWG 100 Amp	1.86	IR8689 T731 TX9 23.85	SUPER		
VHS Drum Motor 25.50 VHS Capstan Motor 25.50 Sanua 500 Real Motor 25.50	GEC 2040/2028 GEC 2110 (pre Jan '77) Philips G8 Short Focus Lead	6.60 7.00 7.12	19SWG 45 Amp 20SWG	1.86 2.75	FD09193 TxL 32 butt 15.90 FD09820 15500 13.81 ED09156 E148			
Sharp Reel Motor 19.50 Take up idler Ass./Clutch Ass. VHS (general purpose) 5.95	Philips G9 Pye/Philips KT3 1: Pye 691/3	6.37 2.50 7.58	Insulated Copper Wire Cable Ties ALT1 per 100 (small)	1.86 9.11 84	ED0911 AVS 13.75 ED09141 CTU 20R/140R 13.75 (IR8876)	min. 25 pieces		
Thom/JVC etc. Sharp 381/383/386/9100 9300/9500 2.97	Pye 713 4 Lead Pye 713 5 Lead Pye 731/25	8.79 8.79 8.75	Cable Ties ALT21 per 100 (large) Power Adapter (12v) Reg. 88 Power Adap.	1.69 5.95 5.50	SONY	£1, BU508A £1,		
Hitachi F.F. Idler VT11E/VT33E 3.91 Video Lamps Nat. Pan. Bulb VHS 1.30	Rank T20/22 ITT CVC5/9 ITT CVC2/25/30 (Mullant)	7.12 7.50 7.12	Reg. 650 Power Adap.	6.50	C5 HM/51 29.04 C6 22.62 C7 RMT200 42.00	80806 £1, 80208A 85p, TIP41C 30p,		
General Purpose VHS 1.41 3V23 with plug VHS 1.95 Video Care 1.95	ITT CVC45 Universal TV 11 Stick	8.65 6.00 90	TURBO RECHARGEABLE Screwdriver Kit Drill Kit	22.71 25.99	HITACHI/GEC	TIP31C 30p , TIP32C 30p , BF259 25p ,		
Care NI Cettore 5.00 Universal Copy Kit 5.50 Head Cleaner 90 Beta Eccentricity Gauge 55.00	TV 13 TV 14 TV 18 TV 20	1.20 1.29 1.10 1.43	Sold. Iron Kit Rep. Tips Rep. Bulbs	16.99 2.20 60	9300/V4001 9.93 Remote Control Tester 29.94	BF338 30 p, BF337 30 p.		

WATER TO A DESCRIPTION OF THE PARTY OF THE P		PLY TOP	G.G	L.COM	P		A CAS	5AJ	NITH	
REPUTATION COL	JNTS	WITH US	HONE	0228) 39693/20358	B	CARLISLE, COMBRIN			2	
INTEGRATED	TYPE	PRICE (£)	TYPE	PRICE (£) TRA	ANSIS	TORS TYPE	PRICE (E) E.H.T. TRAY	'S 77	TV ELECTROLYTIC
CIRCUITS	STK435	5.95	TDA2521/3.	2.95 TYPE		PHICE R2008B		DECCA 100		5 FIDELITY ZX(220/385)
YPE PRICE (£)	STK43	7.50	TDA2523	.3.20 BC147		10 R2540		5 DECCA 120/130	6.95	5 PHILIPS G8(600/300)
V2140	STK45	3	TDA2530	2.00 BC148		10 TIP32C		5 ITT CVC20/30	0.30	BBM T204(220/400)
N303	STK461	8.95	TDA2532	2.10 BC327		11 TIP33		PHILIPS G8		D THORN 9000(400/400)
V318 5.25	STK46	3	TDA2540	1.95 BC337		11 TIP41C		PHILIPS KT3		5
17114E	TA719	3P	TDA2541	2.70 BC338				5 RBM T20/T22A		5
N7115E	TA720	4P 1.90	10A2545	4 95 BC548				15 THURN 8500/8800	8.0	
V7116	TA720	5AP1.45	TDA2540	2.40 BC547		10 2SB618		UNIVERSAL		5 "SPECIAL OFFER
V7145191	TA722	2P	TDA2571A	4.95 BC558		10 2SC1034		0		
A1339A	TBA12	0AS	TDA2576A			30 2SC1114		36		(inc. Mod Board)
1.85 A1366W	TBA12	OT	TDA2577			25 25C1413A		5 LINE O/P T	R.	£3.95
A1366WR	TRA12	NU	TDA2578A			2SC1942		DECCA 80		5 22"-26" £9.95
1377 2.95	TBAS		TD A2581	1 95 BD124M		25C3156		DECCA 100	8.3	0
A1392	TBA56		TDA2502	2.30 BD131				5 ITT CVC20		0
A1397	TBAR	10A	TDA2593	2.30 BD132				50 ITT CVC45		5 THORN TV SPAR
1201	TBA81	IOS	TDA2594	2.95 BD160				PHILIPS G8		5
1230	TBA82		TDA2600			90		PHILIPS G11	14.9	15 TX9
2.75	TBA89		TDA2611A			50		PHILIPS KT3		5 Dual PTC
4445	TBA92	00 1.35 50/2X 2.25	TDA2653A			50 DIODE	S	PHILIPS K30	129	5 I.F. Gain Unit
4460	5 TBA14	40G	TDA2655A	195 BD237		40 RV177	PRI	10 THORN 1615	9.7	Dine O/P Trans
245	TBA2	300	TDA3190	3.70 BD238		70 BY164		45 THORN 1690/1		Service Manual
13002	5 TDA20	1.95 60A 1.95	TDA3541			70 BY179		5 THORN 1790/1		5 Tuner
A1251	5 TDA4	40	TDA3560	4.95 BD677		55 BY223		20		
A3027	5 TDAI	J35T	TDA3561A	4.95 BD701		95 BY299/600		.95		TX10
A5010	5 TOA10	137	TDA3562A	6.50 BE337		2 BY299/800		25 PUSH BUTTO	ONS	Focus Unit
AA5012	TDAI	170S	TDA3650A	2.70 BF338		30 BYX10		DECCA/ITT 4 way		10 Line O/P Trans
S1032P	TDAT	180P	TDA3651A	0		20 SKE5E3/10	1	45 DECCAVITT 6 way		0 On/Off Switch
C560S 24	TDAI	190Z	TDA3652	3.35 BF/5/		70 1N4001-7		.07 ITT CVC57 way	10.4	O Service Manual
\$5705 2.4	5 TDAT	506 4.35	TDA4500					.18 ITT CVC8/9	12.0	NO TUNER
AS580S	5 TDAT	510	TDA4600/2				-	FIT CVC45 (porc)	14!	50
AS590S	5 TDAT	512	TDA4600/2	0		195 VALVE	S	PHILIPS KT3		5 TV00
2.9	5 TDAT	515	TDA4010	3.95 BT116		1.30 DY802		.00 RBM T20A 6 way	11.	95 Line O/P Trans
L4/10P	5 TDAT	770A	TDA8170.	3.35 BU126		1.50 PCF802		.95		On/Off Switch
490 2.5	0 TDA1	870	TDA8180	4.50 BU205		1.40 PCF802		.10		Tuner
1430	5 TDA1	908A	TDA8190		·	1.00 PCL85/805		.00 TUNERS (NI	EW)	Service Manual
L1432	5 TDAI	950A	TDA9503	2.95 BU208D)	1.95 PCL96		.05 FLC 1043/05		50
N76660N	5 TDA2	1.55	TDA9513	3.20 BU326A	A	1.45 PCL200		.60 ELC 1043/06		35 TX100
TK0039	5 TDA2	.004	UPC1031H	170 BU426A	A	1.45 PL504		50 ELC 2003		95 Choke
1K0040	TDA2	.005	UPC1182H	1.70 BUSORA	2	1.75 PL509/519		.95 U321		75 Line O/P Trans
STKD78	5 TDA2	1.30	UPC1185H	2.50 BU508D)	1.95 PY500A		25 U322		50 Service Manual
TK2129	O TDA2	030	UPC1230H	4.35 BU526.		2.20 PY801		05 1343		95 Teletext Board
STK433	5 TDA2	295	UPC13630	420 BUWB	A	3.50 PY88		.00 U411		95 Tuner
J1K4332	D IDAZ		01010030			VOD DUOT DUUDE	-	SANVO SPARES		COMPLITER SPARE
GEC/HITACHI		NAT. PAN.		SONY SPARES		V.C.R. PILOT BOLBS	5 5000	5300		280A CPU
TV SPARES		VIDEU SPAR	1 10	05/07		National NV20001.0	O Caps	tan Motor	2.95	2114 (200ns)
AME MODULES	5.95	NV2000 Idler	1.30	Ace Head Assy	35.50	Sharp 8300	O Gea	Idler	6.95	4116-2
/10232	4.70	NV3000 Idler	1.25	Limiter Assy	3.15	Sharp 9300	5 Load	I. Roller	1.90	4164
A9032		NV7000 Idler		Motor (BHF1100D)		Thom (Plug)	D PINC	Motor	9.95	4532/4
R441		NV370 Idler		Pinch Roller	1.30	Universal	Beel	Pulley	6.95	74LS 157
R451		NV2000 Load. Gear	1.60	Service Manual CS	940					ZTX 213
DACA		NV333 Pinch Roller	4.95	Service Manual C7			-		_	ZTX 313
H909		NV/UUU PINCH HOWET		Video Head	45.00					ZTV 551
R6020 (Kit)	14 05		the second se			THODN CDARFS				
R6020 (Kit)	. 14.95					Inonia Scenco		SHARP SPARES		ZTX 650
R6020 (Kit)		PHILIPS				Thomas Pranco	9300 Ree	SHARP SPARES	18.35	ZTX 650
1929 R6020 (Kit)		PHILIPS VIDEO SPAR	ES	CS		3700/16/22	9300 Ree Ree	SHARP SPARES /9700 Motor	18.35 .3.30	ZTX 650
ASS R6020 (Kit)		PHILIPS VIDEO SPAR	ES	C6 Ace Head Assy	. 42.20	3V00/16/22 Capstan Motor	9300 Ree Ree	SHARP SPARES /9700 Motor	18.35 .3.30	ZTX 650
GEC/HITACHI	9.95	PHILIPS VIDEO SPAR	ES 25.95	C6 Ace Head Assy Reel Motor		3V00/16/22 Capstan Motor	9300 Ree Ree	SHARP SPARES /9700 Motor	18.35 -	FUSES
GEC/HITACHI VIDEO SPARES		PHILIPS VIDEO SPAR	ES 25.95 8.25	C6 Ace Head Assy Reel Motor (C6MKII)	42.20	3V00/16/22 Capstan Motor	9300 Ree Ree 5 5	SHARP SPARES 9700 Motor	18.35 -	FUSES
GEC/HITACHI VIDEO SPARES		PHILIPS VIDEO SPAR VCR 6460/00/05 Audio Head Idler Arm	ES 25.95 8.25 	C6 Ace Head Assy Reel Motor (C6MKII) Rewind Kit Service Manual (C8)		3V00/16/22 49.9 Capstan Motor 49.9 Drum Motor 43.1 Fridtler 1.6 Pinch Roller 7.2 Tata and feld (C) 7.8	9300 Ree Ree 15 15 10 20 20 50 50 50 50 50 50 50 50 50 50 50 50 50	Motor Idler	18.35 -	FUSES 20mm A/S: (Pkts of 10) BDAA 100MA 200MA
GEC/HITACHI VIDEO SPARES	18.95	PHILIPS VIDEO SPAR VCR 6460/00/05 Audio Head Idler Arm	ES 25.95 8.25 14.10 12.95	C6 Ace Head Assy Real Motor (C6MKII) Rewind Kit	.42.20 .17.60 .28.00 4.20 9.40 9.40	3V00/16/22 Capstan Motor 49.9 Drum Metor 43.9 F/F Idler 11 Princh Roller 7.2 Take-up Idler (SM) 5.5	9300 Ree Ree 55 50 50 50 50 50 50 50 50 50 50 50 50	SHARP SPARES 49700 Motor Idler ON/OFF SWITCHES inv. (Bem)	18.35 - .3.30 	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA
AS-20 (Kit) 548 Tuner 556A Tuner GEC/HITACHI VIDEO SPARES 000H/VT8000 0dio Head Distan Mator		PHILIPS VIDEO SPAR VCR 6460/00/05 Audio Head Idler Arm. F. Loading Motor Loading Motor Service Menual	ES 25.95 8.25 14.10 12.95 7.50 5.75	C6 Ace Head Assy Real Motor (C6MKII) Rewind Kt Service Manual (C6MKII) Video Head	.42.20 .17.60 .28.00 .4.20 .9.40 .9.40 	3V00/16/22 Capstan Motor 43.9 Drum Motor 43.9 Fri Idler 1.6 Pinch Roller 7.2 Take-up Idler (LG) 7.5 Take-up Idler (SM) 5.2 Video Head (3HSS) 32.2	9300 Ree Ree 50 50 50 50 50 50 50 Fide 50 Fide 50 Fide	SHARP SPARES 9700 Mator Idler ON/OFF SWITCHES lity ity (Rem) ps G11	18.35 - 3.30 1.70 2.95 1.35	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 500MA, 630MA, 800MA,
BO20 (Kit) BO20 (Kit) GEC/HITACHI VIDEO SPARES 000H/VT8000 dio Head pstan Motor er FF.Raw		PHILIPS VIDEO SPAR VCR 6460/00/05 Audio Head Idler Arm	ES 25.95 8.25 14.10 12.95 7.50 11.95	C6 Ace Head Assy Real Motor (C6MKII) Rewind Kit. Service Manual (C6). Service Manual (C6MKII) Video Head		3V00/16/22 Capstan Motor 43.9 Drum Motor 43.9 F/F Idler 1.6 Pinch Roller 7.2 Take-up Idler (LG) 7.4 Video Head (3HSS) 32.5	9300 Ree Ree 95 95 90 90 90 90 90 Fide 95 Phill Phill	SHARP SPARES /9700 Motor Idler ON/OFF SWITCHES lify (Rem) ps G11 ps G11(Rem)	18.35 - 3.30 1.70 2.95 1.35 1.85	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 500MA, 530MA, 800MA, 1A, 1.25A, 1.6A, 2A,
GEC/HITACHI VIDEO SPARES 000/V/18000 dio Head	. 14.95 	PHILIPS VIDEO SPAR VCR 6460/00/05 Audio Head Idler Arm F. Load Motor Service Menual Take-up Reel Tuner Video Head	ES 25.95 8.25 14.10 12.95 7.50 5.30 13.95 63.95	C6 Ace Head Assy Reel Motor (C6MKII) Rewind Kit Service Manual (C6) Service Manual (C6MKII) Video Head	42.20 17.60 28.00 4.20 9.40 9.40 45.00	3V00/16/22 Capstan Motor 49.9 Drum Motor 43.9 Pric Mare 1.6 Pinch Roller 7.2 Take-up Idler (LG) 7.5 Video Head (3HSS) 32.5	9300 Reel Reel 75 75 70 70 70 70 70 70 70 70 70 70 70 70 70	SHARP SPARES /9700 Motor Idler Idler Idler ify (Rem) ps G11 ps G11(Rem) ps G11(Rem) ps G11(Rem)	18.35 - .3.30 .1.70 .2.95 .1.35 .1.85 2.45	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 500MA, 315MA, 400MA, 500MA, 3315A, 40, 5A, 6, 3A 25A, 315A, 40, 5A, 6, 3A
GEC/HITACHI VIDEO SPARES 000H/VT8000 dio Head upstan Motor Jer F.F./Rew		PHILIPS VIDEO SPAR	ES 25.95 8.25 14.10 12.95 7.50 5.30 13.95 63.95	C6 Ace Head Assy Reel Motor (C6MKII) Rewind Kit Service Manual (C6) Service Manual (C6MKII) Video Head	42.20 17.60 28.00 4.20 9.40 9.40 45.00	3V00/16/22 Capstan Motor 49.9 Drum Motor 49.9 Prich Roller 16 Pinch Roller 7.2 Take-up Idler (LG) 7.2 Video Head (3HSS) 32.5 SV29/30 Constan Mater 30	9300 Ree Ree 95 95 90 90 90 90 90 90 90 90 90 90 90 90 90	SHARP SPARES 9700 Motor Idler ON/OFF SWITCHES Iny Iny ps G11 ps G11 ps G11 ps K13 (Rem) G11 (Rem) ATDAG (XR)	18.35 - 3.30 1.70 2.95 1.35 1.35 2.45 1.90 2.45	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 500MA, 630MA, 800MA, 1A, 125A, 16A, 2A, 25A, 315A, 4A, 5A, 6.3A 20mm Q/B: (Pkts of 10)
AS-20 (Kit) 548 Tuner 556A Tuner SEC/HITACHI VIDEO SPARES 000H/VT8000 dio Head pstan Motor ler F.F/Rew	. 14.95 	PHILIPS VIDEO SPAR VCR 6460/00/05 Audio Head Idler Arm. F. Load Motor. Loading Motor Service Menual Take-up Reel Tuner. Video Head	ES 25.95 8.25 14.10 12.95 7.50 5.30 13.95 63.95	C6 Ace Head Assy Real Motor (C6MKII) Revind Kt. Service Manual (C6). Service Manual (C6MKII) Video Head C9 DC-DC Conv		3V00/16/22 Capstan Motor 49.9 Drum Metor 43.9 F/F Idler 1.6 Pinch Roller 1.2 Take-up Idler (LG) 7.5 Take-up Idler (SM) 5.4 Video Head (3HSS) 32.5 3V29/30 Capstan Motor 36.1	9300 Ree Ree 35 36 30 30 30 50 50 50 50 50 50 50 50 50 50 50 50 50	SHARP SPARES 9700 Mator Idler ON/OFF SWITCHES lity Iny ps G11 ps K13 (Rem) ps K13 (Rem) ps K13 (Rem) M120A (3K3) v VV1612	18.35 - 3.30 1.70 2.95 1.35 1.85 2.45 1.90 2.45 4.95	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 500MA, 630MA, 800MA, 1A, 125A, 15A, 2A, 25A, 315A, 4A, 5A, 6, 3A. 20mm Q/B: (Pkts of 10) 200MA, 500MA, 630MA.
RO20 (Kit) Second Kit) Second Kit GEC/HITACHI VIDEO SPARES 0000H/VT8000 dio Head pstan Motor ler F/F.Rev iot Lamp noh Roller yrider wider wider wider	. 14.95 	PHILIPS VIDEO SPAR VCR 6460/00/05 Audio Head Idler Arm. F. Load Motor	ES 25.95 8.25 14.10 12.95 7.50 5.30 13.95 63.95 38.95	C6 Ace Head Assy Reel Motor (C6MKII) Revind Kt Service Manual (C6) Sarvice Manual (C6MKII) Video Head C9 DC-DC Conv Gear Kit	.42.20 	3V00/16/22 Capstan Motor 43.9 Drum Metor 43.9 F/F Idler 1.6 Pinch Roller 7.2 Take-up Idler (LG) 7.4 Video Head (3HSS) 32.5 3V29/30 Capstan Motor 38.4 Loading Motor 8.4	9300 Reel Reel 95 90 90 90 90 90 90 90 90 90 90 90 90 90	SHARP SPARES 19700 Motor Idler ON/OFF SWITCHES lity iny (Rem) ps G11 ps G11 (Rem) ps K13 (Rem) G11 (Rem) A120A (3K3) y KV1612 y KV2022	18.35 - 3.30 	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 250MA, 530MA, 800MA, 1A, 125A, 15A, 2A, 25A, 315A, 4A, 5A, 6, 3A 20mm 0/B: (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 1.6A, 2A,
ABO20 (Kit) 548 Tuner 556A Tuner GEC/HITACHI VIDEO SPARES 000H/VT8000 dio Head pstan Motor er F./Raw ot Lamp to Roller ay Idler price Manual deo Head		PHILIPS VIDEO SPAR	ES 25.95 8.25 14.10 12.95 7.50 5.30 13.95 63.95 38.95 9.95 11.75	C6 Ace Head Assy	.42.20 .17.60 .28.00 .4.20 .9.40 	3V00/16/22 Capstan Motor Drum Motor 49.9 Drum Motor 16 Pinch Roller 72 Take-up Idler (LG) 74 ke-up Idler (SM) Video Head (3HSS) 32 S 3V29/30 Capstan Motor Beal Motor 48 Pinch Roller Ster Ster Ster Ster	9300 Reel Reel 85 95 90 90 90 90 90 90 90 90 90 90 90 90 90	SHARP SPARES /9700 Motor Idler Idler bity ps G11 ps G11 ps G11(Rem) ps G11(Rem) AT20A (3K3) y KV2022 m (Uni)	18.35 - .3.30 	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 500MA, 630MA, 800MA, 1A, 125A, 15A, 2A, 25A, 315A, 4A, 5A, 6.3A 20mm D/B: (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 16A, 2A, 25A, 3.15A
ASS 20 (Kit) 548 Tuner 556A Tuner 556A Tuner GEC/HITACHI VIDEO SPARES 000H/VT8000 dio Head agita Head F.F./Rew to Clamp nch Roller agy Idler morice Manual deo Head 100H/V4002H		PHILIPS VIDEO SPAR	ES 25.95 8.25 14.10 12.95 5.30	C6 Ace Head Assy		3V00/16/22 Capstan Motor 49.9 Drum Motor 49.9 Drum Motor 16 Pinch Roller 7.2 Take-up Idler (LG) 7.2 Take-up Idler (SM) 5.5 Video Head (3HSS) 32.5 3V28/30 Capstan Motor 38.4 Loading Motor 6.5 Pinch Roller 6.1 Pinch Roller 6.2 Pinck Roller 2.1	9300 Ree Ree 85 80 80 80 80 80 80 80 80 80 80 80 80 80	SHARP SPARES 9700 Motor Idler 0N/OFF SWITCHES Iny iny (Rem) ps G11 ps G11 (Rem) ps K13 (Rem) G11 (Rem) AT20A (3K3) y(V1612 y(V2022) m (Uni) m TX (Rem)	18.35 - 3.30 2.95 1.35 1.85 2.45 2.45 4.95 4.95 1.10 1.95	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 200MA, 315MA, 400MA, 500MA, 315MA, 400MA, 500MA, 630MA, 800MA, 1A, 125A, 15A, 2A, 25A, 3.15A, 4A, 5A, 6.3A 20mm Q/B: (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 1.6A, 2A, 25A, 3.15A.
BO20 (Kit) BO20 (Kit) S56A Tuner GEC/HITACHI VIDEO SPARES O00HVT8000 dio Head pstan Motor er F.F.Rew. ot Lamp noth Roller wylder wylder wylder wylder tob Head moul. doo Head tob Head tob Head tob Kead tob Kead tob Kead tob Kead	. 18.95 	PHILIPS VIDEO SPAR	ES 25.95 8.25 14.10 12.95 7.50 5.30 13.95 63.95 38.95 9.95 11.75 5.55 38.35	C6 Ace Head Assy	.42.20 .17.60 .28.00 .4.20 .9.40 .9.40 .45.00 .22.70 .6.70 .4.95 .9.40 45.95	3V00/16/22 Capstan Motor 249.3 Drum Motor 49.9 Drum Motor 49.9 Princh Roller 1 Pinch Roller 1 Take-up Idler (LG) 7.2 Take-up Idler (SM) 5.5 3V29/30 Capstan Motor Cading Motor Cading Motor 34k-up Idler Yeac Motor 1 Cake-up Idler 1 Yeac Motor 2 Take-up Idler 1 Yeac Motor 1 Yeac Inder (19052)	9300 Reei Reei 85 90 90 90 90 90 90 90 90 90 90 90 90 90	SHARP SPARES 9700 Motor Idler ON/OFF SWITCHES lity ity (Rem) ps G11 (Rem) ps K13 (Rem) G11 (Rem) AT20A (3K3) y KV1612 y KV2022 m (Uni) m TX (Rem)	18.35 - .3.30 .2.95 .1.35 .1.85 .2.45 1.90 2.45 4.95 4.95 1.10 1.95	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 500MA, 630MA, 800MA, 1A, 125A, 16A, 2A, 25A, 315A, 4A, 5A, 6.3A 20mm Q/B: (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 1.6A, 2A, 25A, 3.15A
BO20 (Kit) BO20 (Kit) BO20 (Kit) GEC/HITACHI VIDEO SPARES O00H/VT8000 dio Head pstan Motor er E/ Rew ot Lamp noch Roller wy Idler wy Idler IO0H/V4002H 006/95000 pstan Motor	. 14.95 	PHILIPS VIDEO SPAR	ES 25.95 8.25 14.10 12.95 5.30 13.95 5.395 38.95	C6 Ace Head Assy	.42.20 .17.60 .28.00 .4.20 .9.40 .9.40 .45.00 .45.00 .4.95 .9.40 .4.95 .9.40 45.95	Inform Strendown 3V00/16/22 Capstan Motor 43.9 Drum Metor 43.9 F/F Idler 1.6 Pinch Roller 1.2 Take-up Idler (LG) 7.2 Take-up Idler (SM) 5.4 Video Head (3HSS) 32.5 3V29/30 Capstan Motor 36.1 Loading Motor 36.1 Take-up Clutch 2.2 Take-up Idler 1.4 Video Head (3HSS) 32.1	9300 Ree Ree 35 30 50 50 50 50 50 50 50 50 50 71 80 71 80 71 80 85 80 71 85 80 71 85 80 71 85 80 71 85 80 85 80 85 80 85 80 85 80 85 80 80 80 80 80 80 80 80 80 80 80 80 80	SHARP SPARES 9700 Mator Idler Idler ON/OFF SWITCHES lity iny (Rem) ps G11 ps G11 (Rem) ps K13 (Rem) M11 (Rem) ps G11 my KV1612 y KV2022 m (Lni) m TX (Rem)	18.35 - 3.30 	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 500MA, 530MA, 800MA, 1A, 1.25A, 1.5A, 2A, 2.5A, 3.15A, 4A, 5A, 6.3A 20mm 0/B; (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 1.6A, 2A, 2.5A, 3.15A
ABO20 (Kit) 548 Tuner 556A Tuner GEC/HITACHI VIDEO SPARES 000HV/T8000 Idio Head opstan Motor er FJ-Raw ot Lamp nch Roller ay Idler Prvice Manual deo Head 1100H/V4002H 000F/S000E pastan Motor ler FJ-Rew	. 14.95 	PHILIPS VIDEO SPAR	ES 25.95 8.25 14.10 12.95 5.30 13.95 38.95 9.95 11.75 35.95 43.50	C6 Ace Head Assy		3V00/16/22 Capstan Motor 49.9 Drum Motor 43.9 Princh Roller 7.2 Take-up Idler (LG) 7.3 Take-up Idler (SM) 32.5 Video Head (3HSS) 32.5 3V29/30 Capstan Motor Capstan Motor 36.1 Loading Motor 31.1 Take-up Idler (SM) 32.1	9300 Ree Ree 85 95 90 90 90 90 90 95 90 95 90 90 90 90 90 90 90 90 90 90 90 90 90	SHARP SPARES /9700 Motor Idler Idler onvOFF SWITCHES lity iny (Rem) ps G11 ps G13 (Rem) gs (X1 (Rem) G11 (Rem) y KV1612 y KV2022 m (X (Rem) m TX (Rem) MT20A (3K3) PHILIPS KT3/30	18.35 - .3.30 .255 .1.35 .2.45 .1.90 .2.45 .4.95 .1.10 .1.95	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 500MA, 630MA, 800MA, 1A, 125A, 15A, 2A, 25A, 315A, 4A, 5A, 6.3A 20mm 0/B: (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 16A, 2A, 25A, 315A
BO20 (Kit) BO20 (Content of the second of t		VCR 6460/00/5 Audio Head Idler Arm	ES 25.95 8.25 7.50 5.30 13.95 63.95 38.95 38.95 43.35 43.35 25.50	C6 Ace Head Assy	.42.20 .17.60 .28.00 .9.40 .9.40 .45.00 .22.70 .6.70 .4.95 .9.40 45.95	3V00/16/22 Capstan Motor 49.9 Drum Motor 49.9 Drum Motor 16 Pinch Roller 12 Take-up Idler (LG) 12 Take-up Idler (SM) 32.5 3V28/30 32.5 Gapstan Motor 38.4 Loading Motor 31.1 Take-up Idler 14.1 Video Head (3HSS) 32.5 3V28/30 34.4 Capstan Motor 34.4 Take-up Idler 4.1 Video Head (3HSS) 32.1	9300 Ree Ree 85 95 90 90 90 90 90 90 90 90 91 90 95 90 90 95 90 95 95	SHARP SPARES 9700 Motor Idler ON/OFF SWITCHES liny iny ps G11 ps G11 (Rem) ps G11 (Rem) G11 (Rem) AT20A (3K3) y(V1612 y(V2022) m (Uni) m TX (Rem) PHILIPS KT3/30 Handsat Repair Kits	18.35 	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 500MA, 500MA, 200MA 500MA, 530MA, 800MA, 1A, 125A, 15A, 2A, 25A, 3.15A, 4A, 5A, 6.3A 20mm Q/B: (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 1.6A, 2A, 2.5A, 3.15A.
AS-20 (Kit) 548 Tuner 556A Tuner 556A Tuner GEC/HITACHI VIDEO SPARES 000HVT8000 dio Head pstan Motor lar F.F/Rew ay Idler moto Menual deo Head 100HV4002H 006/9500E apstan Motor lar F.F.Rew ay Idler apstan Motor lar F.F.Rew ay Idler apstan Motor lar F.F.Rew ay Idler moto Roller ubue E.F.Rew	. 14.95 	VCR 6460/00/05 Audio Head Idler Arm. F. Load Motor Loading Motor Service Menual Take-up Reel Tuner. Video Head VCR 6662/00 Capstan Motor Control Motor Erase Head Modulator. Vinding Motor Video Head VCR 6520/00/05 Audio Head	ES 25.95 8.25 14.10 5.30 13.95 63.95 38.95 38.95 35.95 43.35 43.350 26.50 14.10	C6 Ace Head Assy		3V00/16/22 Capstan Motor 49.9 Drum Motor 49.9 Princh Roller 16 Pinch Roller 12 Take-up Idler (LG) 7.2 Take-up Idler (SM) 5.2 Video Head (3HSS) 32.5 3V29/30 38.4 Loading Motor 38.4 Loading Motor 36.4 Take-up Idler 6.4 Pinch Roller 6.4 Pinch Roller 34.4 Loading Motor 31.4 Take-up Idler 1.4 Video Head (3HSS) 32.1 3V35/36 32.1 Capstan Motor 28.4	9300 Ree Ree 85 95 90 90 90 90 90 90 90 90 90 90 90 90 95 90 70 90 95 90 90 90 90 90 90 90 90 90 90 90 90 90	SHARP SPARES 9700 Motor Idler ON/OFF SWITCHES lity lity ps G11 ps G13 ps G14 ps G14 ps G15 ps G17 ps G11 ps G13 gs G13 ps G14 gs G13 ps G14 gs G13 ps G14 gs G13 gs G13 gs G13 gs G13 gs G14 gs G13 gs G14 gs G13 gs G13 gs G14 gs G14 gs G14 gs G13 gs G14	18.35 	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 300MA, 200MA 10, 125A, 15A, 20, 25A, 3,15A, 4A, 5A, 6,3A 200MA, 500MA, 630MA, 200MA, 500MA, 630MA, 800MA, 1A, 1.6A, 2A, 2.5A, 3,15A. VOLTAGE REGS 7805 7805
BO20 (Kit) BO20 (Kit) BO20 (Kit) GEC/HITACHI VIDEO SPARES DO0H/VT8000 dio Head pstan Motor er FF/Rew diar pstan Motor lamp hoch Roller sy Idler sy Idler sy Idler source Manual deo Head DOH/V4002H DO0E/S000E pstan Motor ler FF/Rew ay Idler Longetan Source Roller Source	. 14.95 	VCR 6460/00/05 Audio Head Idler Arm Load Motor Loading Motor Service Menual Take-up Reel Tuner Video Head VCR 6462/00 Capstan Motor Control Motor Crass Head Modulator Video Head VCR 6422/00/05 Audio Head F/Load Motor	ES 25.95 8.25 14.10 12.95 7.50 5.30 13.95 38.95 3	C6 Ace Head Assy		3V00/16/22 Capstan Motor 49.9 Drum Motor 43.9 Prick Neiler 1.6 Pinch Roller 7.2 Take-up Idler (LG) 7.4 Take-up Idler (SM) 3.2 Video Head (3HSS) 32.5 3V29/30 2 Capstan Motor 36.1 Loading Motor 6.6 Reel Motor 31.3 Take-up Idler (Jerther 6.5 Yideo Head (3HSS) 32.9 3V35/36 Capstan Motor 28.1 Capstan Motor 26.2 SV35/36 Capstan Motor 34.9	83000 Ree Ree 55 50 50 50 50 50 50 50 50 50 50 50 50	SHARP SPARES 9700 Motor Motor Idler Idler Idler iny (Rem) ps ps G11 ps ps G11 (Rem) ps ps G13 (Rem) gs m (ZaA (3K3) ykV1612 ykV1612 ykV2022 m (Uni) m TX (Rem) PHILIPS KT3/30 Handset Repair Kits Buttons & Foils Text/Non Text	18.35 - .3.30 2.295 1.35 1.45 2.45 4.95 .1.10 .1.95	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 250MA, 530MA, 800MA, 1A, 125A, 15A, 2A, 25A, 315A, 4A, 5A, 6, 3A 20mm (J/B, (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 16A, 2A, 25A, 315A. VOLTAGE REGS 7805 7808
ABO20 (Kit) 548 Tuner 556A T	14.95 	PHILIPS VIDEO SPAR	ES 25.95 8.25 14.10 12.95 5.30 13.95 38.95 9.95 38.95 43.35 43.50 26.50 14.10 8.25 12.95 14.10 1.295 14.10 1.295 14.10 13.95 14.10 14.25 14.10 14.10 14.25 14.10 14.10 14.25 14.10 14.10 14.25 14.10 14.10 14.25 14.10 14.10 14.25 14.10 14.10 14.25 14.10 14.10 14.25 14.10 14.10 14.25 14.10 14.10 14.25 14.10 14.10 14.25 14.10 14.10 14.10 14.25 14.10 14.10 14.10 14.10 14.25 14.10 14	C6 Ace Head Assy	42.20 17.60 28.00 420 	Inform SFARLS Syd0/16/22 Capstan Motor 49.9 Drum Motor 49.9 Drum Motor 49.9 Pinch Roller 72 Take-up Idler (LG) 72 Take-up Idler (SM) 52 Video Head (3HSS) 32.5 3V29/30 Capstan Motor 38.4 Loading Motor 31.4 Take-up Idler 6.1 Video Head (3HSS) 32.1 Video Head (3HSS) 32.1 System Motor 31.4 Capstan Motor 32.1 System Motor 24.1 Capstan Motor 32.1 System Motor 24.1 Cass Motor 34.4 Cass Motor 24.2 Cass Motor 24.2	93000 Ree Ree 75 75 76 70 70 90 70 90 70 95 90 70 95 90 95 95 95 95 95 90 95 95 95 95 95 95 95 95 95 95 95 95 95	SHARP SPARES 9700 Motor Idler ON/OFF SWITCHES Iny Iny ps G11 ps G11 ps G11 (Rem) ps G11 (Rem) G11 (Rem) ps K13 (Rem) G11 (Rem) m TX2A (3K3) y KV2022 m (Uni) m TX (Rem) Handset Repair Kits Buttons & Foils Text/Non Text	18.35 - .3.30 .2.255 .1.35 .2.45 .2.45 .2.45 .4.35 .1.10 1.05	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 25A, 315A, 4A, 5A, 6.3A 20mm 0/B: (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 1.6A, 2A, 25A, 3.15A VOLTAGE REGS 7805 7805 7805
AS-20 (Kit) 548 Tuner 556A Tuner 556A Tuner 556A Tuner GEC/HITACHI VIDEO SPARES 000HVT8000 dio Head Bystan Motor Ier F.F./Rew Ago Head 100HV4002H 00625500E apstan Motor Ier F.F./Rew ap Idler moh Roller Lilley F.F./Rew F. Converter Converter deo Head Blay	14.95 	VCR 6460/00/5 Audio Head Idler Arm	ES 25.95 8.25 14.10 5.30 13.95 63.95 38.95 38.95 38.95 33.95 43.50 265.50 14.10 8.25 12.95 12.95 12.95 12.95 12.95 12.95 12.95 12.95 12.95 12.95 12.95 12.95 13.95 14.10 15.95 13.95 13.95 14.10 15.95 13.95 14.10 15.95 14.10 14.10 15.95 14.15 15.95 14.15 15.95 14.15 15.95 14.10 15.95 14.10 15.95 14.10 15.95 14.10 15.95	C6 Ace Head Assy		3V00/16/22 Capstan Motor 49.9 Drum Motor 49.9 Drum Motor 16 Pinch Roller 7.2 Take-up Idler (LG) 7.4 Take-up Idler (SM) 32.5 Video Head (3HSS) 32.5 3V28/30 Capstan Motor Capstan Motor 34.4 Take-up Idler (SM) 32.5 3V28/30 34.4 Capstan Motor 34.4 Take-up Idler 6.5 Pinch Roller 5.5 Video Head (3HSS) 32.1 3V26/36 Capstan Motor Capstan Motor 24.1 Video Head (3HSS) 32.1	93000 Reserved Reserv	SHARP SPARES 9700 Motor Idler Idler ON/OFF SWITCHES lity (Rem) ps G11 (Rem) ps G11 (Rem) G11 (Rem) G11 (Rem) M 7204 (3K3) y (VY1612 y (V2022 m (Uni) m TX (Rem) HLIPS KT3/300 Handset Repair Kits Buttons & Foils Text/Non Text £5.55	18.35 - .3.30 	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA. 250MA, 315MA, 400MA, 500MA, 630MA, 800MA, 1A, 125A, 15A, 2A, 2.5A, 3.15A, 4A, 5A, 6.3A. 20mm Q/B: (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 1.6A, 2A, 2.5A, 3.15A. VOLTAGE REGS 7805 7805 7808 7815 7818 7818
ABO20 (Kit) 548 Tuner 556A Tuner 556A Tuner GEC/HITACHI VIDEO SPARES 000H/VT8000 dio Head opstan Motor Hot Lamp noch Roller 2006H/V4002H 000E/S500E Bytal Motor Ier F./Rew ay Idler nch Roller 21/00H/V4002H 000E/S500E Bytal Motor Ier F./Rew ay Idler Converter Converter Converter deo Head Blay	14.95 	PHILIPS VIDEO SPAR	ES 25.95 8.25 14.10 12.95 13.95 38.95	C6 Ace Head Assy		3V00/16/22 Capstan Motor 49.9 Drum Motor 43.9 Drum Motor 43.9 Pinch Roller 1.6 Pinch Roller 1.2 Take-up Idler (LG) 1.7 Take-up Idler (SM) 3.2 Video Head (3HSS) 32.9 3V29/30 36.1 Capstan Motor 38.1 Pinch Roller 6.2 Pinch Roller 6.3 Pinch Roller 6.3 Video Head (3HSS) 32.1 3V35/36 Capstan Motor 28.1 Cass. Housing 34.1 Cass. Motor 36.4 Cass. Housing 34.4 Casten Roller 39	93000 Ree Ree Ree So So So So So Fide So	SHARP SPARES 9700 Mator Idler Idler ON/OFF SWITCHES lity Iny ps G11 ps G11 ps G11 ps G11 ps G13 ps G13 ps G14 ps G13 ps G14 ps G13 ps G13 ps G14 ps G13 ps G13 ps G13 ps G14 ps G13 ps G14 ps G14 ps G14 ps G14 <	18.35 - .3.30 .2.95 .1.35 .1.35 .1.35 .1.35 .1.35 .1.455 	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 250MA, 530MA, 800MA, 1A, 125A, 15A, 2A, 25A, 315A, 4A, 5A, 6, 3A 20mm 0/B, (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 16A, 2A, 25A, 3.15A. VOLTAGE REGS 7805 7805 7805 7812 7815 7818 7812
AS-20 (Kit) 548 Tuner 556A Tuner 556A Tuner 556A Tuner GEC/HITACHI VIDEO SPARES 000H/VT8000 udio Head 100H/V4002H 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V400ZH 000F/V40ZH 000F/V400ZH 000F/V40ZH 00	14.95 	PHILIPS VIDEO SPAR	ES 25.95 8.25 14.10 12.25 7.50 5.30 13.95 38.95 38.95 38.95 38.95 38.95 38.95 38.95 38.95 38.95 25.50 11.75 35.95 25.50 14.10 1.25 25.50 14.10 1.25 1.25 5.30 1.175 5.59 25.50 14.10 1.25 1.25 1.55 1.175 5.59 25.50 1.175 5.59 25.50 1.175 5.59 25.50 1.175 5.59 25.50 1.175 5.59 25.50 1.175 5.59 25.50 1.175 5.59 25.50 1.175 5.59 25.50 1.175 5.59 25.50 1.175 5.59 25.50 1.175 5.59 25.50 1.175 5.59 25.50 1.175 5.59 25.50 1.175 5.50 25.50 1.175 5.59 25.50 1.175 5.50 25.50 1.175 5.50 25.50 1.175 5.59 25.50 1.175 5.50 25.50 1.175 5.50 25.50 1.175 5.50 25.50 1.175 5.50 25.50 1.175 5.50 25.50 1.175 5.50 25.50 1.175 5.50 25.50 1.175 5.50	C6 Ace Head Assy	.42.20 .17.60 .28.00 .9.40 .9.40 .45.00 .4.95 	3V00/16/22 Capstan Motor 49.9 Drum Motor 49.9 Drum Motor 16.8 Pinch Roller 7.2 Take-up Idler (LG) 7.4 Take-up Idler (SM) 32.5 3V29/30 Capstan Motor Capstan Motor 38.4 Loading Motor 34.4 Real Motor 31.4 Take-up Idler (Idler 1.4 Video Head (3HSS) 32.1 Take-up Idler 31.4 Take-up Idler 1.4 Video Head (3HSS) 32.1 3V35/36 Capstan Motor Cass. Motor 28. Guide Roller 34.4 Cass. Motor 6.5 Farase Head 9.5 Guide Roller 1.4 Leaf Switch 1.1 Service Manual 26.5	33000 Res Res Res Res Res Res Res So So So Res Res Res So So Fidil Phili Phili Phili So	SHARP SPARES 9700 Motor Motor Idler Idler Idler iny (Rem) ps ps G11 ps ps G11 Genm) ps G13 Genm) ms G11 (Rem) Genm) mail (Rem) Genm) mail (Rem) Genm) m TzQA (3K3) ykV1612 ykV1612 ykV2022 m (Uni) m m TX (Rem) Genma Straits PHILIPS KT3/30 Handset Repair Kits Buttons & Foils Text/Non Text £5.95 PHILIPS	18.35 - .3.30 .2.95 .1.35 .1.35 .1.35 .1.35 .1.455 4.35 4.35 4.35 1.10 4.35	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 250MA, 530MA, 800MA, 1A, 125A, 15A, 2A, 25A, 315A, 4A, 5A, 6 3A 20mm D/B: (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 16A, 2A, 25A, 315A. VOLTAGE REGS 7805 7805 7805 7805 7812 7815 7818 7818
AS-20 (Kit) 548 Tuner 556A Tuner 556A Tuner 556A Tuner GEC/HITACHI VIDEO SPARES 000H/VT8000 dio Head by the Add out amp ch Roller ay Idler F.F./Rew ay Idler The F.F./Rew ay Idler INTOH/V4002H 00E/5500E apstan Motor ler F.F./Rew ay Idler Converter ch Roller Billy F.F./Rew ay Idler Converter Converter dio Head Billy F.F./Rew Alloy F.Converter dio Head Billy F.F./Rew F.Converter dio Head Billy F.F./Rew F.Converter Conver	14.95 	PHILIPS VICR 6460/00/05 Audio Head Idler Arm F. Load Motor Loading Motor Service Menual Take-up Reel Tuner Video Head VCR 6462/00 Capstan Motor Control Motor Control Motor Video Head Fload Motor Idler Unit Loading Motor Service Manual Take-up Reel Video Head	ES 25.95 8.25 14.10 5.30 13.95 63.95 38.95 38.95 38.95 38.95 33.95 33.95 33.95 33.95 33.95 33.95 33.95 33.95 35.95	C6 Ace Head Assy		3V00/16/22 Capstan Motor 49.9 Drum Motor 49.9 Drum Motor 16.6 Pinch Roller 7.2 Take-up Idler (LG) 7.2 Take-up Idler (SM) 32.5 Video Head (3HSS) 32.5 3V29/30 34.0 Capstan Motor 34.4 Loading Motor 31.4 Take-up Idler 1.4 Video Head (3HSS) 32.1 Video Head (3HSS) 32.1 Video Head (3HSS) 32.1 Video Head (3HSS) 32.1 System Motor 34.1 Cass Housing 34.2 Cass Motor 6 Erase Head 3.4 Guide Roller 1.1 Leaf Switch 1.1 Service Manual 26	33000 Resine Res	SHARP SPARES 9700 Motor Idler ON/OFF SWITCHES liny iny ps G11 (Rem) ps G11 (Rem) G11 (Rem) AT20A (3K3) y(V1612 w(V1612 w(Uni) m TX (Rem) HLIPS KT3/30 Handset Repair Kits Buttons & Foils Text/Non Text £5.95 PHILIPS Universal Remote	18.35 - .3.30 .295 .1.35 .245 .1.90 4.95 1.10 1.95	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 25A, 3.15A, 4A, 5A, 6.3A 25A, 3.15A, 4A, 5A, 6.3A 20mm Q/B: (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 1.6A, 2A, 2.5A, 3.15A VOLTAGE REGS 7805 7805 7805 7812 7818 7818
ABO20 (Kit) S48 Tuner S56A Tuner S56A Tuner S56A Tuner GEC/HITACHI VIDEO SPARES 000H/VT8000 dio Head pstan Motor er F./Rew ay Idler NTOCH/V4002H 000H/VT000 000H04002H 000H0400H04002H 000H04002H04002H 000H04002H04002H 000H04002H04002H04002H04002H04002H04002H04002H04002H04002H04002H04002H04002H04002H04000H04002H04000H04002H04000H04000H0400H04000H04	14.95 	PHILIPS VIDEO SPAR	ES 25.95 8.25 14.10 5.30 13.95 63.95 38.95 38.95 38.95 38.95 43.35 26.50 14.10 8.25 12.95 14.10 8.25 13.95 14.10 14.10 15.95 13.95 14.10 15.95 14.10 15.95 14.10 15.95 14.10 15.95 14.10 15.95 14.10 15.95 14.10 15.95 14.10 15.95 14.10 15.95 14.10 15.95 14.10 14	C6 Ace Head Assy Real Motor (C6MKII) Rewind Kit Service Manual (C6) Service Manual (C6) C9 DC-DC Conv Gear Kit Guide Pin Kit		3V00/16/22 Capstan Motor 49.9 Drum Motor 49.9 Drum Motor 16 Pinch Roller 7.2 Take-up Idler (LG) 7.2 Take-up Idler (SM) 32.5 Video Head (3HSS) 32.5 3V28/30 Capstan Motor Capstan Motor 34.4 Loading Motor 31.4 Take-up Idler 1.4 Video Head (3HSS) 32.1 JV28/30 Capstan Motor Capstan Motor 23.1 Take-up Idler 1.4 Video Head (3HSS) 32.1 3V26/36 Capstan Motor Cass. Housing 34.1 Cass. Housing 34.1 Leaf Switch 1. Service Manual 26.5 Take-up Clutch 2.2 Uter Tuner 36.1	9300 Ree Ree Ree 85 90 90 90 90 90 90 90 90 90 90 90 90 90 90 90 91 92 93 940 95	SHARP SPARES 9700 Motor Idler Idler ON/OFF SWITCHES lity (Rem) ps G11 (Rem) ps G11 (Rem) G11 (Rem) G11 (Rem) M120A (3K3) yKV1612 yKV2022 m (Uni) m TX (Rem) HLIPS KT3/300 Handset Repair Kits Buttons & Foils Text/Non Text £5.55 PHILIPS Universal Remote Control Handset	18.35 - .3.30 .225 .1.35 .1.35 .1.45 .2.45 .1.10 .245 .1.10 .1.95	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 305MA, 800MA, 10, 125A, 15A, 2A, 25A, 3,15A, 4A, 5A, 6, 3A 200MA, 500MA, 630MA, 200MA, 500MA, 630MA, 800MA, 1A, 1.6A, 2A, 2.5A, 3,15A. VOLTAGE REGS 7805 7805 7808 7812 7818 7818 7912
AS-20 (Kit) 548 Tuner 556A Tuner 556A Tuner 556A Tuner GEC/HITACHI VIDEO SPARES 000H/VT8000 dio Head apstan Motor let Er Arraw ay Idler ATT Arraw 100H/V4002H 100H/V711E ulley FF./Rew Bastan Motor Bastan Motor Lich Assy	14.95 	PHILIPS VIDEO SPAR	ES 25.95 8.25 14.10 12.95 13.95 38.50 38.50	C6 Ace Head Assy		3V00/16/22 Capstan Motor 49.9 Drum Motor 43.9 Prick Teller 1.6 Pinch Roller 7.2 Take-up Idler (LG) 7.5 Take-up Idler (LS) 32.5 3V29/30 38.1 Capstan Motor 38.1 Loading Motor 6.6 Pinch Roller 6.1 Pinch Roller 6.2 Pinch Roller 6.2 Video Head (3HSS) 32.9 3V36/36 32.9 Capstan Motor 28.1 Capstan Motor 28.2 Switch Head 34.2 Capstan Motor 28.1 Capstan Motor 28.2 Service Meanual 32.9 Guide Roller 1.1 Service Manual 25.7 Take-up Clutch 2.1 UHF Tuner 36.1	93000 Ree Ree Ree Ree Ree So So So Fide Phil Phil Phil Phil Phil So So So So S	SHARP SPARES 9700 Mator Idler Idler Idler ON/OFF SWITCHES Inv. Inv. Inv. State	18.35 .3.30 .255 .1.35 .1.85 .2.45 .4.95 .4.95 .4.95 .1.10 .1.95	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 250MA, 530MA, 830MA, 1A, 125A, 15A, 2A, 25A, 315A, 4A, 5A, 6, 3A. 20mm 0/B, (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 16A, 2A, 25A, 3, 15A. VOLTAGE REGS 7805 7805 7805 7812 7815 7818 7812 7815 7812 7815 7818
AP3-20 (Kit) AP3-	14.95 	PHILIPS VIDEO SPAR	ES 25.95 8.25 14.10 12.25 7.50 5.30 5.395 38.95 35.00 3	C6 Ace Head Assy		Inform SFARLS Syd0/16/22 Capstan Motor Capstan Motor Motor Fil toler Pinch Roller Take-up Idler (LG) Take-up Idler (LG) Take-up Idler (SM) Take-up Idler (SM) Take-up Idler (SM) Capstan Motor Capstan Motor Capstan Motor Capstan Motor Video Head (3HSS) 32 S Symon Capstan Motor Capstan Motor <td>3300 Ree Ree Ree Ree Ree Ree So So So So Ree Ree So So Fidil Phili Phili Phili So So</td> <td>SHARP SPARES 9700 Motor Idler Idler ON/OFF SWITCHES Iny ps G11 ps G11 ps G11 (Rem) ps G11 (Rem) ps G11 (Rem) ps G11 (Rem) m TX (Rem) M1720A (3K3) yKV2022 m (Uni) m TX (Rem) Handset Repair Kits Buttons & Foils Text/Non Text £5.95 PHILIPS Universal Remote Control Handset Suitable For All Text K135, KT4/40 F134.5</td> <td>18.35 .3.30 .2.95 .1.35 .1.35 .2.45 .4.95 .1.10 .1.95</td> <td>FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 250MA, 530MA, 800MA, 1A, 125A, 15A, 2A, 25A, 315A, 4A, 5A, 6, 3A 20mm U/B: (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 16A, 2A, 25A, 3.15A. VOLTAGE REGS 7805 7805 7805 7805 7805 7812 7815 7815 7815 7815 7815 7815 7815 7815</td>	3300 Ree Ree Ree Ree Ree Ree So So So So Ree Ree So So Fidil Phili Phili Phili So	SHARP SPARES 9700 Motor Idler Idler ON/OFF SWITCHES Iny ps G11 ps G11 ps G11 (Rem) ps G11 (Rem) ps G11 (Rem) ps G11 (Rem) m TX (Rem) M1720A (3K3) yKV2022 m (Uni) m TX (Rem) Handset Repair Kits Buttons & Foils Text/Non Text £5.95 PHILIPS Universal Remote Control Handset Suitable For All Text K135, KT4/40 F134.5	18.35 .3.30 .2.95 .1.35 .1.35 .2.45 .4.95 .1.10 .1.95	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 250MA, 530MA, 800MA, 1A, 125A, 15A, 2A, 25A, 315A, 4A, 5A, 6, 3A 20mm U/B: (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 16A, 2A, 25A, 3.15A. VOLTAGE REGS 7805 7805 7805 7805 7805 7812 7815 7815 7815 7815 7815 7815 7815 7815
AS-29 (Kit) 548 Tuner 556A Tuner 556A Tuner 556A Tuner 556A Tuner GEC/HITACHI VIDEO SPARES 5000HVT8000 dio Head apstan Motor ler F.F/Rew ay Idler apstaler 5000HV4002H 5002/5500E apstan Motor ler F.F/Rew 5000HV4002H 5002/5500E apstan Motor ler F.F/Rew 5000HV4002H 5002/5500E apstan Motor ler F.F/Rew 5000HV4002H 5000HV400ZH 5000HV40ZH 5000HV40	14.95 	PHILIPS VICR 6460/00/05 Audio Head Idler Arm F. Load Motor Loading Motor Service Menual Take-up Reel Tuner Video Head VCR 6462/00 Capstan Motor Control Motor Control Motor Winding Motor Video Head VCR 6462/00 Capstan Motor Video Head Video Head VCR 6462/00 Audio Head Video Head VCR 652000/05 Capstan Motor Service Manual Take-up Reel Video Head	ES 25.95 8.25 14.10 5.30 5.305 38.95 38.95 38.95 38.95 35.95 35.95 35.95 44.10 8.25 13.95 35.95 35.95 44.70 8.50 5.00	C6 Ace Head Assy		Inform SFARLD Syd0/16/22 Capstan Motor 49.9 Drum Motor 16 Pinch Roller 12 Take-up Idler (LG) 12 Take-up Idler (SM) 32.5 Video Head (3HSS) 32.5 SV28/30 34.2 Capstan Motor 38.4 Loading Motor 35.4 Yideo Head (3HSS) 32.1 Take-up Idler 1.1 Take-up Idler 2.1 Take-up Idler 2.1 Take-up Idler 2.1 Take-up Idler 2.1 Yideo Head (3HSS) 32.1 Stake-up Idler 1.4 Video Head (3HSS) 32.1 Stake-up Idler 1.1 Cass Housing 34.2 Cass Motor 2.6 Guide Roller 1.1 Service Manual 2.5 Take-up Idtrth 2.5 Jurget Partice Manual 2.5 Take-up Idtrth 36.1	9300 Ree Ree Ree Ree 80 90 90 90 90 90 90 90 90 90 90 90 95	SHARP SPARES 9700 Motor Idler Idler ON/OFF SWITCHES lity lity ps G11 ps G11 (Rem) ps K13 (Rem) G11 (Rem) ps K13 (Rem) G11 (Rem) m (Z0A (3K3) y KV0512 m (Uni) m TX (Rem) Madsst Repair Kits Buttons & Foils Text/Ebs Universal Remote Control Handset Suitable For All Text Suitable For All Text KT3/30, KT35, KT4/40 £19.95	18.35 .3.30 .1.70 .2.95 .1.85 .1.85 .1.85 .2.45 1.90 .2.45 1.90 	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 25A, 315A, 4A, 5A, 6.3A 25A, 315A, 4A, 5A, 6.3A 20mm Q/B: (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 1A, 1.6A, 2A, 2.5A, 3.15A VOLTAGE REGS 7805 7805 7805 7805 7812 7818 7818 7912 ORDERING Please add 75p for p/p Add 15% VAT to this to
RS20 (Kit) 548 Tuner 556A Tu	14.95 	PHILIPS VIDEO SPAR	ES 25.95 8.25 14.10 7.50 7.50 13.95 38.95 38.95 38.95 38.95 38.95 38.95 38.95 38.95 38.95 5.95 63.95 26.50 5.05 5.05 5.05 63.95 44.10 8.25 5.00 63.95 44.10 8.25 5.00 63.95 44.10 8.25 5.00 63.95 44.10 8.25 5.00 63.95 44.10 8.25 5.00 63.95 6	C6 Ace Head Assy		3V00/16/22 Capstan Motor 49.9 Drum Motor 49.9 Princh Roller 7.2 Take-up Idler (LG) 7.2 Take-up Idler (SM) 32.5 Video Head (3HSS) 32.5 SV28/30 34.1 Capstan Motor 34.1 Loading Motor 34.1 Take-up Idler 6.6 Reel Motor 31.1 Take-up Idler 1.4 Video Head (3HSS) 32.1 3V26/36 2 Capstan Motor 24.2 Take-up Idler 1.4 Video Head (3HSS) 32.1 3V35/36 2 Capstan Motor 26.2 Gaude Roller 1.4 Service Manual 26.2 Take-up Clutch 2.2 Jude Roller 1.1 Service Manual 26.2 Take-up Clutch 2.2 UHF Tuner 36.1	9300 Ree Ree 86 90 Fide 90 Fide 90 Fide 90 Fide 90 Fide 90 Fide 90 Tho 95 Son 90 Tho 95 Son 90 Tho 95 Son 90 Tho 95 Son 90 Tho 95 Son 95 Son 90 Tho 95 Son 90 Tho 95 Son 95 Son 95 Son 96 Son 97 Tho 95 Son 96 Son 96 Son 97 Tho 95 Son 96 Son 96 Son 97 Tho 95 Son 96 Son 9	SHARP SPARES 9700 Motor Idler Idler ON/OFF SWITCHES lity (Rem) ps G11 (Rem) ps G11 (Rem) gs K13 (Rem) G11 (Rem) AT204 (3K3) y KV1612 y KV2022 m (Uni) m TX (Rem) HLIPS KT3/300 Handset Repair Kits Buttons & Foils Text/Non Text £5.55 PHILIPS Universal Remote Control Handset Suitable For All Text K13/00, KT3, KT4/40 £19.95	18.35 .3.30 .1.70 .2.95 .1.35 .1.85 .1.30 .2.45 .1.10 .1.95	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 250MA, 530MA, 800MA, 1A, 1.25A, 1.5A, 2A, 2.5A, 3.15A, 4A, 5A, 6.3A. 200MA, 50, 4A, 5A, 5A, 5A, 5A, 2A, 2A, 2A, 2A, 2A, 2A, 2A, 2A, 2A, 2
AS-20 (Kit) 548 Tuner 556A Tuner 556A Tuner 556A Tuner GEC/HITACHI VIDEO SPARES 000HVT8000 dio Head opstan Motor er F/Raw ay Idler cont Roller ay Idler motor 100H/V4002H 000F/S000 pastan Motor ler F/Rew ay Idler 	14.95 	VCR 6460/00/05 Audio Head Idler Arm Loading Motor Service Manual Take-up Reel Tuner Video Head VCR 6462/00 Capstan Motor Control Motor Erase Head Modulator Video Head VCR 65200/05 Audio Head F/Load Motor Loading Motor Service Manual Take-up Reel Video Head VCR 65200/05 Audio Head F/Load Motor Loading Motor Service Manual VCR 65200/05 Capstan Motor Control Motor Control Motor Control Motor Control Motor Control Motor Motor Motor Motor Control Motor Control Motor Motor Motor Motor Motor Control Motor Motor Motor Motor Control Motor Control Motor Motor Motor Motor Motor Control Motor Control Motor Control Motor Motor Motor Motor Motor Motor Motor Motor Motor Motor Control Motor	ES 25.95 8.25 14.10 12.95 13.95 38.95	C6 Ace Head Assy	.42.20 .17.60 .28.00 .4.20 .9.40 420 .9.40 420 420 420 420 420 420 420 420 420 435 245 230 245 	Inform SFARLS SWOUT672 Capstan Motor 49.9 Drum Motor 49.9 Pinch Roller 72 Take-up Idler (LG) 73 Take-up Idler (SM) 32.9 Video Head (3HSS) 32.9 3V29/30 34.1 Capstan Motor 38.4 Loading Motor 34.3 Take-up Idler (Idler 14.1 Video Head (3HSS) 32.9 3V35/36 32.9 Capstan Motor 28.4 Capstan Motor 28.4 Swi26/36 32.9 Service Manual 36.4 Leaf Switch 1 Service Manual 26.7 Take-up Clutch 2 UHF Tuner 36.3 36.3	33000 Ree Ree Ree Ree Ree Ree Ree Ree Ree	SHARP SPARES 9700 Mator Idler Idler Idler ON/OFF SWITCHES Iny OR/OFF SWITCHES Iny Stitken) ps G11 (Rem) ps G11 (Rem) Stitken) stitken filler stitken stitken filler offiller stitken stitken	18.35 .3.30 .2.95 .1.35 .1.35 .1.45 .2.45 .1.10 	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 250MA, 530MA, 830MA, 300MA, 1A, 125A, 315A, 4A, 5A, 6, 3A. 20mm 0/B, 4A, 5A, 6, 3A. 20MA, 500MA, 530MA, 830MA, 800MA, 1A, 16A, 2A, 25A, 3, 15A. 20MB, 1A, 16A, 2A, 25A, 17A, 17A, 17A, 17A, 17A, 17A, 17A, 17
ABO20 (Kit) 548 Tuner 556A T	14.95 	PHILIPS VICR 6460/00/05 Audio Head Idler Arm F. Load Motor Loading Motor Service Menual Take-up Reel Tuner Video Head VCR 6462/00 Capstan Motor Control Motor Frase Head Winding Motor Video Head VCR 6462/00 Capstan Motor Video Head Video Head FLoad Motor Ider Unit Loading Motor Video Head VCR 6520/00/05 Capstan Motor Service Manual Take-up Reel Video Head <	ES 25.95 8.25 14.10 5.30 5.30 13.95 63.95 38.95 38.95 38.95 38.95 43.35 43.35 25.50 14.10 8.25 5.59 5.	C6 Ace Head Assy		3V00/16/22 Capstan Motor 49.9 Drum Motor 49.9 Drum Motor 49.9 Pinch Roller 72 Take-up Idler (LG) 73 Take-up Idler (SM) 32.5 Video Head (3HSS) 32.6 3V29/30 Capstan Motor 38.4 Loading Motor 49.9 Take-up Idler (SM) 32.5 Video Head (3HSS) 32.5 3V29/30 Capstan Motor 38.4 Loading Motor 31.1 Take-up Idler 14 Video Head (3HSS) 32.1 32.1 3V3/30 Capstan Motor 28.4 Cass Hoad (3HSS) 32.1 32.1 3V3/30 Capstan Motor 28.5 Gass Hoad (3HSS) 32.1 32.1 3V3/30 Capstan Motor 28.5 Guide Roller 14.2 34.4 Cass. Motor 26.5 32.5 Take-up Clutch 2.2 2 UHF Tuner 36.5 36.5	3300 Res	SHARP SPARES 9700 Motor Idler ON/OFF SWITCHES Iny ps G11 ps G11 ps G11 ps G11 mps G11 (Rem) ps G13 ps G11 (Rem) mps K13 (Rem) G11 (Rem) AT20A (3K3) yKV1612 yKV2022 m (Uni) m TX (Rem) PHILIPS KT3/30 Handset Repair Kits Buttons & Foils Text/Non Text E5:95 PHILIPS Universal Remote Control Handset Suitable For All Text KT3/30, KT35, KT4/40 £19.95 For full details of	18.35 .3.30 .1.70 .2.255 .1.35 .1.10 .1.35 .1.10 .1.35 .1.10 .1.10 .1.10 .1.35 .1.10 .1.1.	FUSES 20mm A/S: (Pkts of 10) 80MA, 100MA, 200MA 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 250MA, 315MA, 400MA, 250MA, 315A, 40, 50, 6, 3A 20mm 0/B: (Pkts of 10) 200MA, 500MA, 630MA, 800MA, 11, 16A, 2A, 25A, 3, 15A





AN1270 C2.20 AN7146M C2.20 NA1195 C1.80 LA1110 C2.80 M5124P C2.85 STR5730 AN210 C1.20 AN7154 C2.30 M11315 C2.80 LA120 C1.80 M5124P C2.85 STR5308 AN210 C2.30 AN7158N C2.30 HA1359 C2.81 K13124 C2.85 STR440 AN2110 C2.30 AN7158N C2.35 HA1359 C2.35 HS1514L E1.85 STR440 AN2340 C2.90 AN7168 C2.35 HA1357 C2.35 HA1357 C2.36 M51514L E2.80 STR440 AN2340 C2.50 AN7173 C2.20 HA1368 C1.40 LA1360 C2.36 M51514L E2.80 TA7051P AN2340 C1.50 AN7273 C2.35 HA1377 C2.30 LA1360 C2.36 M51514L E2.80 TA7051P AN240P C1.50 AN7731 C2.30 HA13747 C2.30 LA1360 <	B.5.6 TATERPY E2.5 EANIT B.5.6 B.5.7 TATERPY E2.5 EANIT B.5.6 B.5.8 TATERPY E2.5 EANIT B.5.6 B.5.8 TATERPY E2.5 EANIT EANIT B.5.8 TATERPY E2.5 EANIT EANIT B.5.8 TATERPY E2.5 EANIT EANIT B.5.8 TATERPY E2.5 EANIT EANIT EANIT B.5.8 TATERPY EANIT EANIT EANIT EANIT EANIT B.5.8 TATERPY EANIT EANIT EANIT EANIT EANIT B.5.8 TATERPY EANIT EANIT <th< th=""></th<>
UPDATING COURSES HIGH PERCENTAGE OF PRACTICAL WORK INTENDED FOR QUALIFIED SERVICE ENGINEERS. VCR SERVICING (3 WEEKS FULL TIME) NEXT COURSES START ON OCTOBER 12th & NOVEMBER 30th 1987 – TUITION FEE £575	MAKE YOUR INTERESTS PAY! Train at home for one of these Career Opportunities More than 8 million students throughout the world have found it worth their while! An ICS home-study course can help you get a better job, make more money and have more fun out of life! ICS has over 90 years experience in home-study courses and is the largest correspondence school in the world. You learn at your own pace, when and where you want under the guidance of expert 'personal' tutors. Find out how we can help YOU. Post or phone today for your FREE INFORMATION PACK on the course of your choice. (Tick one box only!)
FULL TIME 1 YEAR	Electronics Radio, Audio & TV Servicing I
DIEG RATIONAL GENTIFICATE 1. T.V. & VIDEO (Electronic Equipment Servicing)	Basic Electronic Engineering (City & Guilds)
2. COMPUTING TECHNOLOGY (Micro Processors, Communications and Interfacing)	Electrical Car Engineering Car Mechanics
3. INFORMATION TECHNOLOGY (Satellite TV, CD, Networks)	Elec. Contracting/ Computer Installation Programming
4. SUF I WAKE ENGINEEKING (Assembler, BASIC, PASCAL, CADCAM)	GCE over 40 'O' & 'A' level subjects
Unemployed may be eligible for new JTS grant support. Further details from:	Name:
(VC Dept.), 20 Penywern Road, Earls Court, London SW5 9SU. Tel: 01-373 8721	Dept. EGS87, 312/314 High St., Sutton, Surrey SM1 1PR. Tel: 01-643 9568 or 041-221 2926 (both 24 hours).



INTERNATIONAL LTD.

QUALITY EX. RENTAL EQUIPMENT TO UK & EUROPE

It seems customary for many wholesalers to advertise the largest range in the UK, at the lowest prices. However when you arrive at some of these places the equipment looks as though it has come out of a war zone and has been delivered by tipper.

At TVS, we purchase our sets from one of the countries principal rental companies, who deal with virtually every major manufacturer thus giving us a range of products that we genuinely feel are unbeatable. Don't take our word for this though. If you care to give us a ring we will send you free of charge, by return a comprehensive price list of all our products. You will also find the prices we advertise are the prices you pay, (a refreshing change we feel these days).

As well as a large range of TVs we have many VCRs on special offer this month including:

FERGUSON 3V29 FERGUSON 3V30 FERGUSON 8940 stereo

£100.00 £105.00 £115.00

These are not just workers but fully refurbished, wrapped and include instruction books.

These must be the best prices in the country for the most popular electronic VCR ever made.

We also have a limited number of other refurbished machines from only £60.00.

To reserve your order phone while stocks last.

EXPORT INQUIRIES WELCOME

Phone Head Office, Bromsgrove FOR FURTHER DETAILS AND A COMPREHENSIVE PRICE LIST CONTACT:

COLIN BROOMFIELD TVS INTERNATIONAL LTD.

Head Office, Unit 7, Station St., Bromsgrove, Worcs. B60 2BS.

(0527) 71186 or 37037

or call our latest franchise dealers:

Pitchford & Evans, Unit 2, Station Hill, Oakengates, Telford TF2 9AA. 0952 616771 Videoscope Europe Ltd., 190 Graig Rd., Godrergraig, Swansea SA9 2NY 0639 843839

Prices quoted for cash payment and subject to VAT Comprehensive spares back up available Delivery service available to UK & Europe

TELEVISION AUGUST 1987

VISA





20222	
** #*<	9p BD370 9p BD371 9p BD371 9p BD433 21p BD433 21p BD433 21p BD433 22p BD433 22p BD433 22p BD433 22p BD433 22p BD533 22p BD533 23p BD534 21p BD533 35p BD537 35p BD537 35p BD675 330p BD680 30p BD680 30p BD681 30p
215p 225p 200p 200p 200p 200p 200p 200p 20	30p 30p 28p 31p 38p 38p 38p 40p 40p 50p 55p 550p 80p 80p 80p 80p 80p 80p 80p 80p 80p 8
NUTIONIC NUTIONIC MUTISODI MUTISODI <t< td=""><td>BR100 BR101 BR103 BR103 BR103 BR103 BR103 BR103 BR104</td></t<>	BR100 BR101 BR103 BR103 BR103 BR103 BR103 BR103 BR104
30500 pp 3000	149 149 149 159 159 159 159 159 159 159 15
2m.1613 2m.1711 2m.1802 2m.1711 2m.1802 2m.2218 2m.2218 2m.2218 2m.2218 2m.2221 2m.2221 2m.2222 2m.2228 2m.2228 2m.2228 2m.2228 2m.2228 2m.2228 2m.2228 2m.2228 2m.2228 2m.2228 2m.2228 2m.228	TIP54 TIP106 TIP107 TIP
2440 505 00 20 20 20 20 20 20 20 20 20 20 20 20	146555 6579 6555 6579 6555 6579 6579 6579
ZENERS 400MV 600MV 600MV 600MV 872N51 600MV 872N51 82X51 82X51 82X51 82X51 8400MV 82X51 8400MV 82X51 845 7815 35 7816 7815 7816 7817 7817 7818 7817 7818 7818 781915 40 7916 400 7817 7818 7818 78119 78112 78112 78112 78112 78112 78112 78112 78112 78112 78112 78112 78112 78112	3N.128 55p 3N.143 55p 3N.143 55p 3N.143 55p SN.128 51p SN.128 51p SN.128 51p SY176 55p SY176 55p SY176 55p SY176 55p SY176 55p SY176 55p SY206 10p SY207 11p SY208 15p SY227 724p SY238 26p SY238 26p SY25600 30p SY355600 30p SY355600 30p SY355600 30p SY355600 30p SY355600 30p </td
Ann.8 Ann.8 P Ann.7 P Ann.7 P Ann.7 P Ann.7 P Ann.7 P Ann.7	PCF200 PCF801 PCF802 PCF802 PCF803 PC4200 PC
12250 12550 15	135p 110p 60p 115p 60p 60p 60p 60p 60p 60p 60p 60p 60p 60
1.4.11245 HA-11226 HA-11226 HA-11226 HA-11226 HA-11226 HA-11703 HA-11703 HA-11703 HA-11703 HA-11703 HA-11703 HA-11705 HA-11706 ICL-7661 ICL-7	BA-6135 : BA-6208 : BA-6208 : BA-6304 : CA-3011 : CA-3012 : CA-3014 : CA-3024 : CA-3024 : CA-3024 : CA-3035 : CA-3036 : CA-3036 : CA-3045 : CA-3045 : CA-3045 : CA-3045 : CA-3045 : CA-3045 : CA-3045 : CA-3045 : CA-305 : CA-305 : CA-305 : CA-305 : CA-306 : CA-306 : CA-306 : CA-306 : CA-308 :
1717 1717	250p 250p 250p 250p 250p 250p 250p 250p
Im-1488 334 IM-1888 3400p IM-1888 3400p IM-1888 3400p IM-1888 3400p IM-1880 3400p IM-1881 255p IM-3151 1551 IM-18152 255p IM-3151 1500p M-4152 250p M-515131 160p M-515132 210p M-515314 160p M-515314 200p M-515314 200p M-51532 210p M-51733 240p M-51733 240p M-53732 300p MB-3773 240p MC-1488 <td< td=""><td>LA-4505 260p LA-4507 30op LA-4507 30op LA-4508 260p LA-4508 260p LA-4508 260p LA-4508 260p LA-4500 100p LA-5700 300p LA-7800 120p LA-7800 120p LA-7800 120p LA-7800 260p LA-7800 260p LA-7800 260p LA-7800 260p LA-7801 150p LA-7802 250p LA-7803 260p LA-7804 260p LA-7802 260p LA-7803 280p LC-7131 260p LC-7132 280p LC-7131 260p LC-7132 280p LC-7133 280p LC-7133 280p LC-7355 60p L-355 60p L-355 60p <</td></td<>	LA-4505 260p LA-4507 30op LA-4507 30op LA-4508 260p LA-4508 260p LA-4508 260p LA-4508 260p LA-4500 100p LA-5700 300p LA-7800 120p LA-7800 120p LA-7800 120p LA-7800 260p LA-7800 260p LA-7800 260p LA-7800 260p LA-7801 150p LA-7802 250p LA-7803 260p LA-7804 260p LA-7802 260p LA-7803 280p LC-7131 260p LC-7132 280p LC-7131 260p LC-7132 280p LC-7133 280p LC-7133 280p LC-7355 60p L-355 60p L-355 60p <
TA-7185 TA-7186 TA-7187 TA-7183 TA-7200 TA-7201 TA-7201 TA-7201 TA-7201 TA-7201 TA-7201 TA-7201 TA-7201 TA-7201 TA-7201 TA-7201 TA-72115 TA-72115 TA-72117 TA-7221 TA-7221 TA-7221 TA-7222 TA-7222 TA-7222 TA-7222 TA-7223 TA-7223 TA-7223 TA-7223 TA-7223 TA-7223 TA-7223 TA-7223 TA-7223 TA-7223 TA-7223 TA-7231 TA-7232 TA-7231 TA-7231 TA-7232 TA-7231 TA-7231 TA-7231 TA-7231 TA-7231 TA-7231 TA-7231 TA-7331 TA-	STK-435 STK-436 STK-436 STK-436 STK-443 STK-443 STK-4457 STK-4457 STK-4457 STK-4457 STK-4651 STK-6651 STK-6651 STK-6029 STK-0029
420% 200% 200% 200% 200% 200% 200% 200%	510p 490p 5500p 5500p 5500p 5500p 5500p 5500p 5800p 55
UPC1197 140p 355.401 735.201 825.9 360p UPC1222 130p 255.401 730.2 825.9 360p UPC1222 130p 255.600 120p 825.9 360p UPC1223 120p 255.131 100p 822.3 300p UPC1238 120p 255.131 120p 825.9 120p 825.131 120p 12	TDA-2004 TOP 2SC-461 30p TIC44 22p TDA-2005 TOP 2SC-485 60p TIC47 22p TDA-2005 TOP 2SC-485 60p TIC47 22p TDA-2005 TOP 2SC-485 30p TIC47 32p TDA-2011 TOP 2SC-485 40p 2SC-485



NEW ITEMS

me of the many des you will receive with your

RE-WIRING? Here's a bargain for you – M.E.M. 3 circuit splitter 45A switch with 3x15A rewirable luses normal cost over £10, but yours for only £5. Our ref 5P100

AUTO TRANSFORMER BARGAIN 200W 230/15V encapsulated into a very neat unit, size 4×4×11/2 app 23, plus 52 post, our ref 3P22. or Only

HOW ARE YOU GOING TO KEEP YOUR CHILDREN OUT OF MISCHIEF THIS SUMMER?

THIS SUMMERT : Why not buy them a computer, they can have tun and be learning at the same time. We have a real bargain the "Acom Elector" if comes complete with mains adapter. TV lead, starter cassette and two handbooks. The only extra you need is a cassette recorder. It's ideal for all the family and Dad, while the kds are not playing their games on it you can even do some of your office work with it. This computer as its 300 page handbook shows can do most things that the BBC computer can do but will only cost you a fraction of the price only 159.50 plus 52 post.

SOFTWARE To go with the Acom. Et each of 5 for £4.00. Desk Diary Business Games Starship Command Arcadians

9" VDU

9" VDU likel to work with computers or video cameras uses Philips black and white tube ref M24/306W. Which tube is implosion and X-ray radiation protected. VDU is brand new and has time bases and EHT circuitry, requires only a 16V d.c. supply to set it going. It's made up in a lacquered metal frame work but has open sides so should be cased (if you are handy with a dill and file you could make a case out of two of our 6½ speaker cabinets). The VDU comes compilete with circuit diagram and has been line tested and has our six months puarantee. Othered at 10 less than some firms are asking for the tube alone may E16 plus 33 post. We also have some that failed the line test again brand new but offered without guarantee at £2 plus £3 post.

IONISER KIT

Refresh your home, office, shop, work room, etc. with a negative ION generator. Makes you feel befter and work harder – a complete mains operated kill withch we guarantee is ten times more powerful than other popular kits. Price includes case and instructions; \$9.50 plus t2:.00 post.

VENNER TIME

SWITCH Mains operated with 20 amp switch. One on and one of the '24 hrs. repeats daily automatically correcting for the lengthening or shortening day. An expensive time switch but you can have it for only £2,95 without case, metal case – £2.86, adaptor kit lo convert this into a normal 24hr, time switch but with the added advantage of up to 12 ontoffs per 24hrs. This makes an ideal controller for the immersion heater. Price of adaptor kit is £2.30. SWITCH

Chess Snapper

Ex-Electricity Board. Guaranteed 12 months.

SOUND TO LIGHT UNIT



kit of parts of a three channel sound to light unit controlling Complete kit of parts of a three channel sound to light unit contraining over 2000 watts of lighting. Use this at home if you wast but it is plen rugged enough for disco work. The unit is housed in an attractive two tone metal case and has controls for each channel, and a master orivo The audio input and output are by '4' sockets and three panel mount fuse holders provide thyristor protection. A four pin plug and socket facilitate ease of connecting lamps. Special price is £14.96 in ldt form.

12 volt MOTOR BY SMITHS

powerful and easily reversible. Size 31/2" long by 3" dia. They have a good length of 1/4" 1/10 hp £3.45 1/8 hp £5.75. 1/6 hp £7.50

25A ELECTRICAL PROGRAMMER

Learn in your sleep. Have radio playing and kettle bolling as you wake – switch on lights to of intruders – have a warm house to come home to. You can do all these and more. By a famous maker with 25 amp on/off switch. A beautiful unit at £2.50

COMPACT FLOOPLY DISC DRIVE For Only £27.50 - VAT & Post Paid As used in the Amstrad 664/6128, the Einstein and other popular computers. Drives the new standard disc, only 3' but with a capacity of 500k per disc, this is equivalent to the 51/4' disc. Other features are: 1. It has the shugart compatible interface (34 way edge compactible, with the 51/4' disc. the recording method, data transfer rate and rotation speed are the same as 51/4'.

transfer rate and rotation speed are the same as 514°. 3. Is fitted with long if the bushless motor and uses steel band driving for reliability and assessing at 3mS. 4. Its touch loading mechanism makes easy handling and disc slot protects against dust. 5. The back of the disc in use can be seen, and up to four drives may be daisy chained. We include the operator's manual and other information showing how to use this with popular computers BBC, Spectrum, Amstrad etc. Brand new and at only 127.50 including post and VAT. Data available separately 52, refundable if you purchase the drive.

J & N BULL ELECTRICAL (T) 250 PORTLAND ROAD, HOVE, **BRIGHTON, SUSSEX BN3 50T**

MAIL ORDER TERMS: Cash, P.O. or cheque with order. Orders under 220 add £1 service charge. Monthly account orders (min £20) accepted from schools and public companies. Access & Bicard orders accepted. Brighten 0273 734648. Bulk orders: write for quote.

OVER 400 GIFTS YOU CAN CHOOSE FROM

There is a total of over 400 packs in our Baker's dozen range and you become entitled to a large free gift with each dozen pounds you spend on these packs. A dassified list of these packs and our latest "News Latter" will be enclosed with your goods, and us will be and a set on the set of the set of the set of the used of the set of the se you will automatically receive our next news letter

22 POUNDERS*

- **22.** POUNDERS*
 22. Wall mounting thermostat, high precision with mercury switch and thermometer
 23. Variable and reversible 8-12V psu for model control
 24. A volt psu with separate channels for stereo made for Mullard ULLEX
 27. Variable and reversible 8-12V psu for model control
 27. A volt psu with separate channels for stereo made for Mullard ULLEX
 27. Controls up to 15 articles. Ideal to program electric heaters
 27. Out 5 and mains transformer with voltage tappings
 27. Out 5 and mains transformer Lew volt winding on separate bobbin and easy to remove to convert to lower works bobbin mains central Lew volt winding on separate bobbin mains operator 1500 pm
 27. Disc or Tage precision motor has balanced rotor and is reversible 28.01 means operator 1500 pm
 27. Disc or Tage precision motor has balanced rotor and is reversible 28.01 means operator 1500 pm
 27. 2 or return the for burget starms, counters, etc.
 27. 2 or return the for burget starms, contents, etc.
 27. 2 or return the for burget starms, contents, etc.
 27. 2 or return the for burget starms, contents, etc.
 27. 2 or return the for burget starms, contents, etc.
 27. 2 or return the for burget starms, contents, etc.
 27. 2 or return the for burget starms, contents, etc.
 27. 2 or return the for burget starms, contents, etc.
 27. 2 or return the for burget starms, contents, etc.
 27. 2 or return the start of burget starms, contents, etc.
 27. 2 or return the for burget starms, contents, etc.
 27. 2 or return the start of burget starms, contents, etc.
 27. 2 or return the start of burget starms, contents, etc.
 27. 2 or return the start of burget starms, contents, etc.
 27. 2 or return the start of burget starms, contents, etc.
 27. 2 or return the start of burget starms, contents, etc.
 27. 2 or return the start of

- Stereo Headphone amplifier, with pre-amp Mains motior, aktra powerful has 1/2* stack and good length of spinGle 1 pair Goodmans 15 ohm speakers for Unitox 1 five bladed fan 6/2* with mains motor 1 kw tangemtial heater 115 ve assily convertible for 230V 1 f2v-0-12v 2 amp mains transformer 1 f3v-0-15v 2 amp mains transformer 1 250v-0-250v 60 mÅ 8.6.3v 5A mains transformer + £1 post 1 f3v-0-15v 2 amp mains transformer 2 chour have, plugs into 13A socket 9v-0-8v 2 amp mains transformer 2 hour time, plugs into 13A socket 9v-0-8v 2 amp mains transformer 30 doem board with press keys for telephone redialler 20v-0-250v 1/2A Mains transformer 13A socket on sain chrome plate very superior G E C. mains transformer 24v-2A upgingt very superior G E C. mains transformer 24v-2A upgingt very superior G E C. mains transformer 24v-2A upgingt very superior G E C. mains transformer 24v-2A upgingt involving 200 min. time switch with knob 90 min. time switch with edgewise engraved controller 13A socket on sain chrome plate very superior G E C. mains transformer 24v-2A upgingt mounting 200 min time switch with edgewise engraved controller 13A socket on sain chrome plate very superior G E C. mains transformer 24v-2A upgingt mounting 201 and the press upgingt the outer 201 and the press of upgingt the outer 201 and the outer to the outer the outer 201 and the outer to the outer the outer 201 and the outer the outer to the outer 201 and the outer to the outer the outer 201 and the outer to the outer to the outer 201 and the outer to the outer to the outer 201 and the outer to the outer to the outer 201 and the outer to the outer to the outer 201 and the outer to the outer to the outer 201 and the outer to the outer to the outer to the outer 201 and the outer to the outer to the outer to the outer 202 and the outer to the outer to the outer to the outer 203 and the outer to the outer
- 2P62 -2P64 -2P66 -2P67 -
- 2P68 2P69 2P70
- 2P82 2P84 2P85 2P88

- 2P88 -2P89 -2P90 -2P95 -2P97 -2P98 -2P99 -2P101 -2P105 -
- 10A c'o switch 2P107 membrane keyboard, telephone type superior plug in type 2P108 mains motor wilh gear box giving 110pm 2P109 5' wide black adhesive pvc tape 33m, add £1 post if not collection

- 2P109 –5' wide black adhesive pvc tape 33m, add £1 post if not collecting 2P111 TTT line output unit 2P112 6 volt 200MA Voltage regulated PSU for 13 amp socket 2P113 9 volt 200MA Voltage regulated PSU for 13 amp socket 2P114 12 volt 200MA Voltage regulated PSU for 13 amp socket 2P116 FM front end with huning capacitor and F.M. circuity 2P118 30pm mains motor with gearbox 2P119 Under carpet switch mat for burglar alarm etc.

LIGHT CHASER KIT Motor driven switch bank with connection diagram, used in connection with 4 sets of X-mas lights makes a very eye catching display for home, shop or disco, only £5 ref 5P56.

£5 POUNDERS*

- ESP POUNDERS*
 SP1 12 voit submersible pump complete with a tap which when brought over the basin switches on the pump and when pushed back switches oft, an ideal caravan unt.
 SP2 Sound to light kit complete in case suitable for up to 750 watts.
 SP3 Silent sentine- ultra sonic transmitter and receive kit, complete protected from direct rainfall, Ex GPO bul in perfect order and guaranteed.
 SP15 Uniselector 5 pole 25 way 50 volt coli
 SP16 TatV atam bell with heavy 6¹ good, suitable for up to 750 watts.
 SP15 Uniselector 5 pole 25 way 50 volt coli
 SP18 motor driven water pump as fitted to many washing machines
 SP20 2 kits, matchbox size, surveillance transmitter and FM receiver 5P23 miniature (appr. 212 wide) tangential blow healer, 1, 2kw
 SP25 special effects lighting switch. Up to 6 channels of tamps can be on or of for varying time periods
 SP27 cartridge player 12v, has high quality stereo amplifier 5P28 gear mains operated push or pull solenoid. Heavy so add £1.50 post
 SP34 24v 5A torokdel mains transformer

- SP32 large mains operated push or pull scretcher, the analysis of the post of the second scretcher second scretcher second scretcher board from telephone auto dialier, complete with keypad and all ICs of the second scretcher second scretch

667

TRANSFORMER IN WATERPROOF METAL CASE 24V 5A output. Ideal for garden lighting or to operate pond pump etc. Case has cable glands for mains in and low voltage output leads. Price 15 plus 11 post, ref 5P88.

BARCLAYCA V/SA

1987 CATALOGUE available - range of components greatly increased - over 136 pages fully illustrated. Price £1.00 per copy (free upon request with orders over £15). Includes 50p Credit Note, Special Offer Sheets, Order Form and Pre-Paid Envelope. Order your copy now.

	TIANAL		TRANSISTORS	DIODES	Type Price (£)	Type Price (£)	Type Price	(E) Type Price (E)
AUGUST DECIAL	FLOURESCENT	TBA520 1.50 TBA530 1.20	Type Price (£) AC127 0.28	Type Price (£) BC118 0.20	BC548 0.08 A B or C 0.10 BC549 0.08	BF181 0.27 BF182 0.32 BF183 0.32	BU133 BU204 BU205	1.60 R2008B 1.40 1.40 R2010B 1.20
BENCH POWER	1 5.99 each	TBA560C 1.50 TBA810S 1.20	AC128 0.30 AC128K 0.38	BC119 0.43 BC125 0.14 BC140 0.48	A or B 0.10 BC550 0.10	BF184 0.47 BF185 0.28 BF1944 0.15	BU208A 1 BU208A 1	1.50 R2540 2.71 1.50 TIP30A 0.35 1.75 TIP31C 0.30
SUPPLY	IU 4.99 each	TCA270SA 4.02 TDA1003A 5.50	AC141 0.36 AC141K 0.36 AC142 0.46	BC141 0.36 BC142 0.26	BC557A 0.10 BC558A 0.10	BF195 0.12 BF224J 0.20	BU407 BUX80	1.40 TIP32 0.36 2.90 TIP33A 0.75
£7.50	CIRCUITS (E) EACH	TDA1006A 2.45 TDA1035S 4.50 TDA1170S 1.99	AC142K 0.38 AC151 0.48	BC143 0.36 BC147B 0.16	BCX32 0.40 BCY70 0.36 BC710 3.21	BF240 0.15 BF241 0.18 BF244A 0.30	BUY69A BUY69B	2.75 TIP34A 0.90 2.90 TIP41C 0.36 1.98 TIP42 0.38
+P&P + VAT	709C 0.35 741 0.16	TDA1352A 1.60 TDA2002 1.80 TDA2020 4.00	AC152 0.44 AC153 0.66	BC148 0.10 BC148B 0.12 BC149 0.12	BCZ11 2.60 BD124P 1.20	BF257 0.22 BF258 0.28	BY100 BY103	0.80 TIP47 0.60 0.50 TIP121 0.63
Stabilized power supply with	AN2140 3.60 AN240P 3.42 BTT6218 1.98	TDA2030 1.80 TDA2140 2.90	AC176 0.25 AC176K 0.33	BC149C 0.14 BC159 0.14 R/C 0.18	BD129 0.90 BD130Y 0.68 BD131 0.46	BF262 0.34 BF263 0.38	BY122 BY126 BY127	0.10 TIP3055 0.85 0.08 TIS88 0.50
Redesigned model. Internal thermal fuse for extra overload	CA301AT 0.80 CA358 0.66	TDA2522 2.75 TDA2530 2.20	AC187 0.44 AC187K 0.44	BC160 0.38 BC161 0.30	BD132 0.50 BD135 0.26	BF270 0.30 BF271 0.28	BY133 BY135	0.10 TIS90 0.27 0.35 Y723 0.92 0.45 Y969 2.80
protection. Polarity reversing switch. Output via lead with 4 way	CA3020 2.10 CA3065 1.60	TDA2580 3.20 TL061 0.40	AC188 0.24 AC188K 0.34 ACV22 1.54	BC168B 0.25 B BC170/A/B/C 0.12 B BC171/A/B 0.10	BD136 0.28 BD137 0.28 BD138 0.30	BF274 0.34 BF294 0.46	BY179 BY182	0.60 IN4001 0.04 0.80 IN4003 0.05
"spider" plug.	CA3080E 0.66 CA3140E 0.38	TL071 0.32 TL072 0.55 TL087 0.28	AD142 0.8 AD143 0.8	8 BC172/B/C 0.12 8 BC177/B/C 0.24	BD139 0.30 BD140 0.29 BD142 1.60	BF336 0.40 BF337 0.38 BF338 0.28	BY184 BY187 BY189	0.38 IN4004 0.05 0.65 IN4006/7 0.07 6.75 IN4148 0.04
Output voltage:	LA4422 3.20 LC7131 4.90	UPC575C2 1.45 UPC1350C 4.05 UPC1156H 2.75	AD149 0.9 AD161/162 1.2 AD162 0.4	5 BC182/A/B/C 0.10 0 BC182L 0.10 0 LA LB LC 0.12	BD145 1.82 BD150B 0.50 BD150 1.58	BF355 0.42 BF371 0.27	BY198 BY199	0.64 IN5400 0.08 0.72 IN5402 0.12
Stability:	LM324N 0.40 LM380N8-P 0.90 LM380N14-P 1.90	UPC1182H 2.75 UPC1208C 1.25 UPC1258C2 1.00	AF114 0.8 AF115 2.1	8 BC183/A/B/C 0.10 0 BC183L 0.10	BD165 0.45 BD183 0.70	BF450 0.30 BF457 0.36 BF851 0.36	BY206 BY207 BY210/400	0.14 IN5405 0.12 0.16 IN5406 0.14 0.21 IN5408 0.18
Dims:	LM1011N 3.20 LM1458N 1.35		AF116 2.1 AF121 0.6 AF124 0.7	6 BC184 0.08 0 A B CL LC LB 0.10	8D202 0.57 BD204 0.54	BFR61 0.32 BFR90 0.86 BFT41 0.58	BY210/600 BY210/800 BY227	0.24 2N2122A 0.34 0.22 2N2222 0.30 0.28 2N2904A 0.48
ABOVE UNIT	M51513L 2.30 M51515L 3.15	74LS & CMOS FULL RANGE OF	AF125 0.5 AF126 0.5	0 BC212/A/B/C 0.10 0 BC212L 0.10	BD225 0.40 BD232 0.52	BFT43 0.38 BFY50 0.32	BY228 BY238	0.50 2N2926G 0.14 0.65 2N3053 0.30
For a limited period only, while stocks last, we offer an ex-equipment Battery Charger for the above units.	MC1307P 1.99 MC1327P 1.50	DEVICES IN STOCK	AF139 0.5 AF178 1.5	6 BC213/A/B/C 0.10 0 BC213L 0.10	BD234 0.30 BD235 0.30 BD236 0.36	BFY52 0.32 BFY90 0.80	BYX36/150 BYX36/600	0.40 2N3054 0.80 0.48 2N3055 0.60 0.48 2N3055 0.60
Although not new these Chargers are fully tested and guaranteed.	ML232B 2.10 ML237B 2.30	CATALOGLIE	AF239 0.6 AF279S 1.4 ASY80 5.2	6 LA LB LC 0.10 0 BC237 0.12 0 BC238 0.12	BD237 0.38 BD410 0.76 BD434 0.58	BR100 0.20 BR101 0.76	BYX55/600 BYX71/600	0.30 2N3773 1.90 1.50 2SB337 1.90
cost over £300. We offer them at £15.00 each including VAT & postage.	NE555 0.20 SAS560S 1.85 SAS570S 1.85	VOLTAGE REGULATORS	ASZ17 2.0 AU110 2.9	0 BC251/A/B 0.14 0 BC262 0.26	BD438 0.64 BD439 0.85 BD441 0.85	BR103 0.60 BR303 2.75 BRY39 0.80	E1222 E5024	0.30 2SC1172Y 1.70 0.30 2SC1172Y 0.88
SOLDER: 60% TIN 40% ALLOY	SAS580 2.85 SAS590 2.85	78L05 0.28 78L08 0.28	B40C200 1.0 BA115 0.1	3 BC301 0.36 2 BC302 0.38	BD507 1.05 BD520 1.20 BD587 0.88	BRY56 0.42 BSX20 0.20 BSY52 0.35	MCR106/5 ME0413 ME6002	1.20 2SC1279 0.50 0.70 2SC1306 1.80 0.26 2SC1413A 2.70
22g. Non-corrosive Multi-core Solder. 500gm Reel £4.99 each 10 Reels £3.75 each	SN762260N 1.30 SN76227N 1.10 SN76533N 1.76	78L15 0.28 7805 0.30	BA121 0.4 BA148 0.1 BA155 0.1	0 BC303 0.36 6 BC307A 0.15 2 BC317B 0.15	BD707 0.80 BDX18 1.00 BDX32 1.75	85Y95A 0.25 8T100A/02 0.90 8T101/300 2.75	MEU21 MJ400 MJ2955	0.62 2AC1449 0.80 1.45 2SC1507 0.60 1.10 2SC1678 1.80
12V RECHARGEABLE UNIT	TA7146P 4.60 TA7203P 2.60	7812 0.36 7815 0.36	BA157 0.2 BB105B 0.3	0 BC323 0.90 2 BC327 0.10	BF115 0.32 BF117 0.50 BF119 0.42	BT101/500 3.25 BT102/300 3.60 BT106 1.15	MJ3000 MJE340 MJE520	1.80 2SC1758 0.68 0.50 2SC1909 1.45 0.60 2SC1923 0.30
10 × 4Ah D size Ni-Cads encapsulated in a Black Plastic Case. Fuse Holder, Gives 12V output	TA7204P 2.50 TA7205AP 1.80 TA7222P 2.33	7818 0.36 7824 0.38 7905 0.38	BB110B 0.4 BC107 0.1	2 BC337 0.08 0 BC338 0.10	BF120 0.36 BF125 0.42 BF127 0.44	BT116 1.20 BT119 3.30 BT138/600 0.98	MJE2955 MJE3055 MPSA05	1,60 2SC1953 0.70 1,40 2SC1957 0.95 0,30 2SC1969 2.80
charged. 245 × 75 × 75mm.	TAA550 0.50 TAA811A12 3.50 TAA621AX1 3.50	7912 0.38 7915 0.38 7918 0.38	A or B 0.1 BC108 0.1	2 BC350A 0.24 0 BC351 0.16 4 BC478 0.24	BF154 0.14 BF157 0.46	BT151/560R 0.90 BTY79/400R 2.80	MPSA12 MPSL01 MPSL05	0.30 2SC2028 0.73 0.34 2SC2029 2.70 1.05 2SC2029 0.70
FULLY GUARANTEED	TAD100 2.90 TBA120S 0.70 S/SB/T/U 0.80	0 7924 0.38 0 LM305H 1.48 0 LM317K 2.40	BC109 0.1 A,B or C 0.1	0 BC516 0.35 14 BC547 0.08	BF160 0.23 BF167 0.32 BF177 0.42	BU105 1.40 BU108 1.90	MPSU06 MR502	1.20 2SC2098 2.90 0.40 2SC2122A 3.20 0.80 2SC2122A 0.80
+ P&P £1.8	TA120B 1.30 SA/SQ 1.30	LM317T 0.96 LM723 0.66	BC115 0.1 BC117 0.2	A or B 0.10 8 BC440 0.36	BF178 0.36 BF180 0.27	BU124AE 0.98 BU126 1.60	OA91	0.14 2SC2335 1.50
VALVES PC92 3.0 Enguiries are wel- PC090 1.41	SHARP NIDL-0005	GE ZZ SI	HARP-0012 3.05	20mm Quick Blow. 100, 12 1.6, 2, 2.5, 3, 4, 5, 6.3A, 45	25, 160, 200, 250, 315, 400. 5p. 20mm Time Delay. 10	500, 630, 800mA. 1, 1.25, 00, 125, 160, 200mA, 250,	Coax Plugs Mete Coax Plugs Plas	al .20 .18/10 tic .10 .085/10
comed for any other PCC89 0.8 valve not listed here. PCC189 0.9 PCF80 1.0	SONY SLC5/7UB	IK	-01 5.85 -02 4.70	315, 400, 500, 630, 800m. Mains. 2, 3, 5, 7, 10, 13A CAR FUSES - British/Euro	A. 90p. 1, 1.25, 1.6, 2, 2.5 1.00. pean cars 5A, 8A, 10A, 20	5, 3.15, 4, 5, 6.3A 90p. 1° 0A, 25A, 30A, 1 - 7p, 10 -	Coax Line Socke Coax Line Conn Coax Cable 750	ta .25 .22/10 ectors .12 .10/10 hm TV Downlead
Type Price (L) PCF82 1.0 AZ31 4.55 PCF84 0.8 AZ41 2.05 PCF86 1.3	VIDEO HEADS	ALL	39.50	60p. British/European/Jap 1.00.	enese cars 7.5A, 10A, 15/	A, 20A, 30A. 1 - 12p, 10 -		18p m – £12.50 100m reel
DAF96 1.06 PCF87 0.6 DF96 0.80 PCF200 2.00	HITACHI	/15000E	30 39.50 37.99 39.44	Used for detecting pipes Battery operated (not pro	or cables in walls prior vided)	to drilling £6.99		ANGE OF LABGEAR RS & TV ACCESSORIES
DM71 3.00 PCF800 1.2 DY86/87 0.70 PCF801 1.1	SANYO SONY	/E and NV ALL SLC 9UB/6/7/9/20/30/40	46.30 48000 49.95	KNIVES - UTILITY compl	ete with 5 blades stored	in body £1.56 REPLACI	EMENT TV MAI	NS DROPPERS
CV850 2.55 PCF805 2.0 CV4015 2.86 PCF806 1.2	SERVICE MANU	ALL	48.66	RETRACTABLE KNIVES C RESISTORS - CARB	ON FILM 5%	des £2.56 GEC 2018 Philips G8 Philips G8	10R + 15R + 2.2R + 68 R - 47R - 15M	19R + 70R + 63R + 188R 1.15 1.00 0.48
E180F 5.55 PCF305 1.0 EABC80 1.06 PCL82 1.0 EAF42 1.55 PCL83 2.5	FIDELITY CTV 145/ SONY HMK3000 SONY KV1810UB I	CTV140/R/CTV 2022	ALL 2.75 2.45 ALL 8.15	1/4W 1RO to 10M (E12 Ra 1/2W 2R2 to 10M (E24 Ra 1W 10R to 2M2 (E12 Ran	nge) 2p each. 15p/1 nge) 2p each. 15p/1 nge) 5p each. 15p/1	0.75p/100 Philips 70 0.75p/100 Philips 300 0.3.00/100 RRI A640	6R + 124R + 118R + 148R 250R + 14R	84R 0.68 (with link) 1.35 + 156R 50W 1.05
EB91 1.35 PCL84 1.0 EBC41 2.06 PCL86 0.9 EBF80 0.80 PCL88 2.5	SONY KV2212/KV2 SONY SLC5UB/SL	705/KV2252 C6UB/SLC7UB/SLC9UE	ALL 5.85 3 ALL 10.50	2W 10R to 2M2 [E6 Rang RESISTOR KITS - eac	e) 8p each. 60p/10 h value individually pa	cked RRI A816 Thorn 1500 Thorn 3000	302R + 70R 350R + 20R /3500 6R + 1R + 1	+ 6.2R 0.78 + 1488 + 1.5K + 317R 1.34 00R Fused 1.05
ECC81 1.06 PCL805 1.1 ECC82 0.96 PD500 2.9 ECC83 1.06 PFL200 1.9	NAT/PANASONIC	S Vi	DB01 2.05	1/4W pack 10 each value I 1/4W pack 5 each value E	E12 - 10R to 1M 610 piec 12 - 10R to 1M 305 piece	es 4.50 s 2.95	Plus Many More	. Please enquire.
ECC84 0.06 PL33 1.5 ECC85 1.00 PL36 1.6 ECC88 1.30 PL82 0.0	HITACHI VT 5000E JVC HR 3360/HR36	60 V	DB03 1.50 DB04 4.15 DB05 3.75	1/2W pack 5 each value E 1W pack 5 each value E1	12 - 2R2 to 2M2 365 piec 2 - 2R2 to 1M 353 pieces	es 4.70 SOLDER 13.76 Soldering Sta	ING SECTION	SERVICE AIDS Goldkiene Degreesing Solvent
ECC189 0.90 PL95 2.0 ECF80 1.26 PL504 1.5 ECF82 0.90 PL608 2.7	JVC HR3300/HR33 SONY SL8000	20/HR3330/HR3600 V V	DBo6 4.65 DB07 6.75 DB08 1.55	RESISTORS - WIRE	WOUND. Generally 1	5% (state which) XS25 W Iron with stand, 1	72.50 htt/complets m tead & plug	Switch Cleaner 1.15 Supa Freeze-it 1.38 Foam Cleanser 1.18
ECF83 1.95 PL519/509 5.3 ECH35 3.80 PL802 5.5 ECH81 1.45 PYB1/800 1.1	SONY SLT-7ME SONY SLT-9ME	V V	DB1098 DB11 .98 DB12 145	2.5W - 0.22 to 270R - Av 4W - 1R0 to 10K - Aveila 7W - 0.47R to 22K - Ava	ailable in preferred values ible in preferred values ilable in preferred values	0.26 attached 0.24 CS17 Iron Kit 0.25 C15 Iron Kit	8.20 7.99 8.30	Video/Tape Head Cleaner 1.10 Plastic-Seal 1.35
ECH84 1.65 PY82 1.8 ECL85 0.80 PY88 0.8 ECL86 1.80 PY500A 2.2	TOSHIBA V5475 TOSHIBA V8600		DB13 1.56 DB14 4.50 DB15 2.05	17W - 1R0 to 22K - Avail 17W -1R0 to 22K - Avail	able in preferred values	0.30 XS25 W Iron 0.38 with steel & CS I8W, as a	plug attached 11.00 bovs 10.90	Aero-Riene 1.10 Anti-Static Spray ellist 1.20 Excel Polish 1.19 Aero Dustar 1.49
EF80 0.90 PY801 0.7 EF86 1.85 UABC80 0.9 EF91 2.05 UAF42 1.3	SANYO 5500 SANYO 9300	S	ANYO-012 2.05 ANYO-013 2.40 HARP.020 3.15	THORN 850 100+300+ 1500 150+150+	100+16/300V 8.1 100/300V 2.4	50 Antax 15W in Antax 25W in Antax 25W in Antax element	on 5.60 on 5.60 nts 3.20	Super 40 1.88 Rapid Fire Extinguisher 3.30 Silicone Grease Tube 1.80
EF183 0.95 UBC41 3.0 EF184 1.05 UBC81 1.5 EF184 1.06 UCC85 0.8	SHARP C6300 SHARP VC7300	S	HARP-021 5.33 HARP-023 6.65	3000 1000/63V 3500 175/400V+ 8000 400/350V	100+100/350V 3.	90 Antex bits 00 Antex stands 66 Soldersucker	1.15 2.20 4.50	Silicona Grease Spray 1.38 Heat Sink Compound 1.18
EL34 3.30 UCF80 1.2 EL36 2.30 UCH42 2.5 EL81 7.00 UCH81 2.0	SHARP VC9700	š	HARP-025 2.65	8000/8500 2500+250 8000 700/250V 1000/70V	21	50 Spare nozzla: 50 Soldarsucker	a for 0.85	Solda-Mop Light guage 0.08mm 0.78 Standald gauge 1.2mm 0.76
EL84 1.06 UCL82 1.8 EL85 5.00 UCL83 3.3 EL86 6.95 UF41 1.3	DATA VOLUME 1 - 1	Frans. data & drawings £9,99	MAINS CABLES	Timer Amp 4700/25V DECCA 10/30 400+400/3 1700 200+200+	1. 350V 3. 400/350V 4.	18 TELEPHONE EO	OUIPM NT + 3m Lead 11.25	Industrial reel 1.2mm 2.96
EL509 7.90 UF89 2.5 EL519 6.00 UE84 1.3 EM80 0.90 UL84 1.3	DATA VOLUME 2 - DATA VOLUME 3 - DATA VOLUME 4 -	as above C-Z £10.75 2N-2N6735 £10.20 2SA & on £13.60	0.2mm (1A) 1.8 metrss 0.96 0.75mm (6A) 3.0	GEC 2047 2048 208 200+200+ 600/250V	3 2084 2104 +150+50/300V 2. 2.	BT App Mister Socket	E2.76 ket £1.85	400 M/W 5 ea value - 55 Z/Diodes £3.50
EM87 2.60 2021 1.6 EY51 0.96 6AT6 1.3 EY86/87 0.70 6AU6 1.0	5 DIODES VOLUME 1 DIODES VOLUME 2 Both Volumes	£10.75 £10.65 £20.60	SCREENED	TTT/KB 200+2004 220/400V PHILIPS G8 600/300V	-75+25/350V 3. 3 tag 2. 2 tag 2.	00 BT 4-Core Cable per m 50 Cable clips for above	etre 15p/m £12.00/100m 10/15p 100/98p	CERAMIC KIT 50 VOLT 5 os value
EY88 0.80 6C4 1.0 EY500A 2.55 6GH8A 1.2 EZ41 2.86 ALIGT 2.8	5 I.C. CMOS 5 I.C. TTL 5 I.C. LIN VOLUME 1	£8.95 £7.90 £8.95	CABLES	G11 470/250V G11 470/250V G9 2200/63V EKCO 691 2004-2004	350V	ZENER DIODES		- 125 Capa £3.50 ORYX PORTASOL GAS IRON
EZB1 0.85 6K7G 2.0 GY501 1.48 6K8G 2.0 GZ32 1.26 6K8G 2.0	6 I.C. LIN VOLUME 2 8 Both volumes 5 THYRISTORS A to Z	£6.98 £13.00 £10.45	Blue 1.75	Series 600/300V RANK 300+300/ AR23 2500+250	300V 3. 10/30V 1.	50 400mW Plastic 3V-75V 75 1.3W Plastic 3V-200V 65 1.5W Flance 4.7-47V	8p each. 10/75p. 15p each. 10/21.40 E1.26 each*	Powered by lighter fuel £14.50
KT77 11.50 6X4 1.5 KT88(G.E.C.) 19.00 30FL2 1.7 PCR8 4.6	TRANSISTORS A to TRANSISTORS 2N-3 Both volumes	Z £5.40 N £5.60 £10.00	metres Black 2.20 4-Core-5.0mm 1.8 metres Black 1.20	220/400V 500/300V FULL RANGE IN CATALO	2. 3. DGUE	20 2.5W Plastic 7.5-75V 20W Stud 7.5-75V *Only available while	64p esch* E1.36 each* stocks last	1.0mm/2.4mm/3.2mm/ 4.8mm £4.50
TODO 1.40 JUPLIS 1.6	outri voidince		ORDERING	: All componer	nts are brand i	new and to ful	I specificat	ion. Please
EAST CORNWA	LL COMF	PONENTS		acid 75p post and then add	lage/packing (i 1 15% VAT to	the total. Mini	ise specifie mum orde	r £5.00. Either sen
119 HIGH STRE	Electron			cheque/cash/	postal order o	r send/telepho	one your A	ccess or Visa
	V4 5TT 1	1 - 0939 32689	4	welcome. (D	o not forget to	send for our	1987 catal	ogue - only £1.00

TELEX: 35565

per copy). Delivery by return on ex stock items. All prices subject to change without notice. RETAIL shop open Mon-Fri 9.00-5.00. Sat 9-12.00.



EDITOR

John A. Reddihough

Please note that the telephone numbers below are for contact with the advertisement departments only. Editorial enquiries should be sent to the editor at the address given on page 657.

ADVERTISEMENT MANAGER

David W.B. Tilleard 01-261 6671

SECRETARY

Janet Reeve 01-261 6671

CLASSIFIED ADVERTISEMENTS

Pat Bunce 01-261 5942

ADVERTISEMENT COPY AND MAKE-UP

Ron Scorey 01-261 6035

SUBSCRIPTION ENQUIRIES

0444 459 188

COVER PHOTO

Our cover photo this month shows a logic probe and pulser being used in the investigation of a problem with a syscon panel in a Fisher VCR. The probe and pulser are the Thandar TP1 and TP2 respectively. They are available from B.K. Electronics of Southendon-Sea – see advertisement elsewhere in this issue.

CORRECTIONS

Our apologies for mislettering Fig. 38(a) on page 613 last month. D0, D1, D3, D4 should have been shown as D0, D1, D2, D3.

It would appear that the source and gate two leadout connections were shown reversed in Fig. 1, page 384 of the April issue. We are investigating this: the BF960 and BF961 appear to have different encapsulations.

TELEVISION

End of an Era

We tend to think of Ferguson as a major TV manufacturer. It has, after all, been the largest supplier of TV sets to the UK market for many years. But today TV manufacture has to be considered in a global context, and looked at in this respect Ferguson no longer appears as a major force. Thorn EMI's decision to sell its Ferguson manufacturing subsidiary to the French Thomson group is probably the right one, though it's nevertheless sad that such an established and respected manufacturer should pass from UK control. Under its new owners Ferguson will be part of a group producing over three million sets a year. This is still well below the annual colour TV receiver output of the two world giants in the industry, Philips and Matsushita, but it does place the group amongst the ranks of major manufacturers such as Sony, Hitachi and Toshiba. Last year Ferguson produced some 680,000 TV receivers. Output is at present running

Last year Ferguson produced some 680,000 TV receivers. Output is at present running at a rate in excess of one million a year. But only a small proportion of this is exported – some ten per cent. Ferguson designs, the famous TX series, are technically excellent and economical to produce. Thorn has invested over £30m during the last two years in modernising the Ferguson plants, but this still hasn't added up to profitability. Ferguson had a bad year in 1984-5 when it made a loss of £25m. The following year saw a return to a small profit but recently, following further price cutting in the UK TV market, it has slid back into losses. Thorn must have wondered when and if it was ever likely to see any profit in consumer electronics manufacturing. It was faced with the need for further investment to increase production capacity but came to the conclusion that it could deploy the resources available to it more profitably elsewhere. One can understand the hard decision that faced Thorn. It nevertheless seems to have been taken fairly hastily, and came as a surprise to the industry. Thorn made an approach to Thomson in the belief that Ferguson should be part of a major European consumer electronics group. It had been forging closer links with Thomson in recent years. The situation was expressed by Thorn director Dr. Jim Maxmin in the following words: "during the last year we came to understand that however efficient we became, if we didn't have overseas markets would couldn't compete".

The merger still leaves the group dependent mainly on the European market, which is a saturated one relying largely on replacement and first-time homemaker sales and rentals. One can't help speculating on whether a merger with JVC, with whom Ferguson also has close ties – the Gosport plant is now producing a JVC designed chassis to meet JVC's European sales requirements – would not have been more appropriate. Maybe Thorn feared the political row that might have ensued, and maybe it felt that Ferguson would retain a greater degree of independence in linking up with Thomson. Whatever the reason, the decision is still a curious one. Thomson may be big, but has not been all that successful in the past in the consumer electronics field. The state-owned company has relied on considerable government support in modernising its operations. It's now on the government's privatisation list. Will it find fund raising all that easy once in the private sector? Seen in this light the link with Ferguson is certainly a favourable development.

The departure of Ferguson from UK control leaves very little of the industry in UK hands, though the UK remains a substantial base for TV manufacture. Matsushita (Panasonic), Sony, Mitsubishi, Hitachi, Toshiba, Sanyo and Tatung all operate plants in the UK. Only Fidelity, whose output has in recent times increased to over 250,000 sets a year, remains in UK ownership, though Fidelity's parent company has made no secret of its hope of hiving off Fidelity as part of a joint venture. The sad thing in all this is how much design and research capacity, if any, will remain in the UK? Just over a year after celebrating the start of TV broadcasting in the UK fifty

The sad thing in all this is how much design and research capacity, if any, will remain in the UK? Just over a year after celebrating the start of TV broadcasting in the UK fifty years ago we suddenly find ourselves with an industry almost entirely in foreign hands. It's a long time since design teams in thirty or so companies were working on TV. But design has for many years been moving from the setmaker to the component manufacturer. Even thirty years ago Mullard was supplying valves along with the circuit designs for their use, and setmakers were adapting these to suit their purposes. Mullard and others extended this to the production of complete receiver designs which formed the basis of what many setmakers went on to manufacture. Ferguson at least maintained a healthy independence throughout, with individualistic designs and a philosophy of looking and planning well ahead. But as more and more circuitry disappeared into a matter of checking on component parameters, compatibility and long-term reliability. This is vital work of course, but it's not like starting on a TV chassis from scratch!

nandrul of chips setmakers' research and development work became more and more a matter of checking on component parameters, compatibility and long-term reliability. This is vital work of course, but it's not like starting on a TV chassis from scratch! In retrospect, one should have seen the end of TV as a major indigenous UK industry long ago. In the immediate post-war era the UK was isolated by its unique 405-line system. No one else was interested in producing 405-line sets and UK manufacturers were reluctant to develop sets for other standards. The collapse started with the use of a common European standard (with minor variants). When the Japanese started to enter the TV field they thought in terms of world-wide markets. This meant designs that with little alteration could be sold anywhere, and guaranteed out of the carton reliability. UK manufacturers subsequently achieved similar standards of performance and reliability, but by that time the Japanese had come to dominate the international market for TV equipment.

Long-distance Television

Roger Bunney

The month of May proved to be a spectacular one for Sporadic E reception. Signals were received from most of Europe and there were several exotics from Africa. Tropospheric reception was encouraging, with several periods of enhanced propagation in Bands I, III and at u.h.f. The SpE log for the month, particularly from the third week onwards, resembles a Band I station list for Europe!

- 6/6/87 TVE (Spain) ch. E3.
- 7/5/87 ARD (West Germany) E2, 3; TVP (Poland) R2; CST
- (Czechoslovakia) R2; TSS (USSR) R2. 8/5/87 TVE E2, 3, 4; +PTT (Switzerland) E2, 3; NRK (Norway) E2, 3, 4; SR (Sweden) E2; NTV Sokoto (Nigeria) E3.
- 9/5/87 TSS R1, 2; MTV (Hungary) R1, 2; TVR (Rumania) R2; TVP R1; ARD E2; JRT (Yugoslavia) E3, 4; TVE E2, 3, 4; RTP (Portugal) E2, 3.
- 10/5/87 NRK E2.

- 16/5/87 TVE E3.
- 17/5/87 TVE E2, 3; RTP E2, 3; RAI (Italy) IA, B; RETE A (Italy) E3; JRT E3, 4; ARD E2; CST R2; MTV R1; +PTT E3.
- 18/5/87 TVE E2, 3, 4; TVE-2 E2; RTP E2, 3; RAI IA; JRT E3; ARD E2; MTV R1; TVP R1, 2; TSS R1, 2, 3; CST R1; RUV (Iceland) E4; Canal Plus (France) L3; RTT (Tunisia) E4; Arabic "wailing" E3, unidentified; DR (Denmark) E3.
- 19/5/87 TVE E2, 3; TVE-2 E2; RTP R3; RAI IA, B; CST R1; JRT E3; TSS R1; ORF (Austria) E3; YLE (Finland) E3, 4; RUV E4.
- 20/5/87 TVR R2; JRT E3, 4; CST R1; TVP R1; RAI IA; TVA Canale A (Italy) E3; TSS R1, 2; NRK E2, 3, 4; SR E2, 3; JTV (Jordan) E3.
- 21/5/87 TSS R2.
- 22/5/87 TVE E2, 3; RTP E3; NRK E2; CST R2; TSS R1, 2.
- 23/5/87 TVE E2, 3; TVE-2 E2; RTP E2, 3; RAI IA, B; MTV R1, 2; NRK E2, 3; TVR R2; ARD E2, 3; JRT E3, 4; TSS R1, 2; RUV E4; RTT E4, RTM (Morocco) E4 seen as floater over RTT at 1600-1700BST!
- 24/5/87 RUV E4.
- 25/5/87 TVE E2, 3, 4; TVE-2 E2; RTP E2, 3; RAI IA, B; +PTT E2; Canal Plus L3.
- 26/5/87 TVE E3; NRK E3; DFF (East Germany) E4.
- 27/5/87 TVE E2, 3, 4; TSS R1; RTP E3.
- 28/5/87 TVE E2, 3, 4; TVE-2 E2; RAI IA, B; ORF E2a, 4; JRT E3, 4; MTV R1, 2; TVE R2; ARD E4; CST R1, 2; DFF E4; Canal + L3; SR E2, 3, 4; NRK E2, 3; RUV E4; YLE E3; NCT (Italy) IA. Arab Band II f.m. stations were also noted. There was blanket SpE throughout Band I with m.u.f.s reaching 150MHz.
- 29/5/87 TVE E2, 3, 4; RTP E3; RAI IA; ORF E2a; JRT E3, 4; TVR R2; TVP R1; CST R1, 2; TSS R1, 2, 3, 4, 5; DFF E4; NRK E2, 3, 4; SR E2, 3, 4; RUV E4; DR E31; RTB-F Belgium from Liege on ch.E3 was noted via very short skip SpE at Torpoint, East Cornwall. Blanket SpE was experienced during part of the day.
- 30/5/87 TVE-2 E2; TVE E3, 4.
- 31/5/87 TVE E2, 3, 4; RAI IA.
- 1/6/87 NRK E2; TSS R2.

An excellent period then, made more interesting by the evidence of ch. E4 outlets in Morocco and Tunisia. NTV Sokoto ch. E3 was logged in Hastings and St. Leonards on May 8th, with programmes from 1945-2030 BST preceded by the test pattern and opening routine. TVE had been in at the same time. Poland TVP-1 was seen using an electronic test pattern not unlike the Channel 4 one, with the identification "TVP-1" across the bottom. Signals were received from several Italian "free" stations during the month, including RETE A on ch. E3 (not IA) and TVA on ch. E3 (though the caption indicated ch. IA!). Spanish TVE-2 signals were received in chs. E3 and 4. This turned out to be material from the TVE-2 centre in Madrid being carried over the TVE-1 network - so take care! NOS (Holland) has on occasion been seen transmitting BRT (Belgium) programmes: at such times the identification "BRT" is present at the top left-hand corner. The Russian 0167 electronic pattern has been seen on ch. R1 with the identification "NTR" - any ideas? Another query comes from Bill Cotterill who noted the caption "T.S. TELSUR" on ch. E4 soon after receiving RUV on this channel. Help needed in identifying this!

There was tropospheric propagation over the period May 7-9th when many W. German, Belgian, Dutch and French Band III/u.h.f. stations, also RTL (Luxembourg), were received over much of central/south England. More productive of signals was the spell during the 22nd-26th, particularly in the east/north of England and Scotland, again with signals from W. Germany, Belgium, Holland and Luxembourg, plus DR (Denmark) and Scandinavia. NRK chs. E3 and 4 were received in Aberdeen on the 22nd but later in the period reception shifted more to the south. Ray Davies had an interesting catch when he received the Dutch pirate "Orion TV Kanal 34", i.e. ch. E34. The signal came from Alkmaar and consisted of captions and a film. Time was 1950-2200 BST. We're checking on power output etc. since this is the most distant report so far of such a pirate station.

My thanks to the following for reports on their reception: Iain Menzies (Aberdeen), Bill Cotterill (Tipton), Roger Fussell (Torpoint), Simon Hamer (Powys), Tim Anderson (St. Leonards), Dave Shirley (Hastings), Cyril Willis (Norfolk), David Martin (Poole) and David Philpott (Polperro).

A letter arrived from Hugh Cocks during the month reporting on his reception in Portugal. He mentions that on most days Ghana ch. E2 is received from 1845-2000 BST. A FUBK type colour pattern is now being used instead of a grey-scale pattern. Programmes start at 1900 weekdays, earlier at the weekends. On April 17th Hugh logged a System M (525 lines) signal on ch. A2, with VITS on the nominal 55.24MHz carrier. There was good picture quality but no sound. Reception was from the south west, suspected as being from south/central America.

News Items

France: A ch. E53 transmitter carries PTT Telecom-1 downlink material during the early mornings - its test pattern has the identification "Paris Poncelet". The direction suggests location in N.E. France in the approximate area of Dunkirk. Apparently the transmitter carries the M6 service later in the day.

East Germany: It has been announced that the Cottbus ch. E4 transmitter, which carries the DFF-1 service, is to be closed down and the v.h.f. mast demolished. DFF-1 will be moved to ch. E53 along with DFF-2 on ch. E23 e.r.p. 1,000kW in each case.

Denmark: The TV-2 transmitter network is to be as

^{14/5/87} TVE E3.

follows: Thisted ch. 28, Aalborg ch. 35, Lolland ch. 52, Fyn ch. 22, Kobenhavn ch. 53, Svendborg ch. 32, Sydsjaelland ch. 50, Aarhus ch. 26, Kalundborg ch. 48, Sonderjylland ch. 27, Vendsyssel ch. 37, Sydvestjylland ch. 33, Vejle ch. 30, Vestjylland ch. 40, Viborg ch. 54. No powers have so far been announced.

Holland: Gosta van der Linden noted two-channel sound from Lopik-2 recently on ch. E27, with Radio-1 left and Radio-5 right. Tests are due soon from Lipik-3 on ch. E30.

Poland: A transmitter has been commissioned to carry the Czechoslovakian CST-1 service in Warsaw on ch. R51 (e.r.p. 20kW).

Satellite TV: A treaty on the W. German DBS services has been signed in Bonn. Of the four channels one will be operated by ARD, another by ZDF and the other two will be run by private companies. The three beams will cover the country as follows: north beam Lower Saxony, Bremen, Hamburg and Schleswig Holstein; west beam Hessen, North Rhine-Westphalia; south beam Baden-Wurttemburg and Bavaria. The north beam will cover West Berlin.

The MTV-Europe pop music service via the 27.5°W Intelsat bird should start this month, using a full east spot transponder. The BT-SRS horse racing service from this satellite is now scrambled using BMAC.

It's likely that a second Astra satellite will be launched some eighteen months after the first, into an adjacent orbital spot, thus providing a total of 32 channels from this direction.

Aerial Update

Details of an East European aerial with helical wound elements were included in this column last month. It had a seemingly very high gain considering the bandwidth and the compact size of the array. Igor Hajek, who is well versed in East European languages, has since looked through the original material. He comments that the initial article on the aerial was actually written in Bulgarian and published in a Bulgarian hobbyist magazine. It was subsequently edited and published in a Russian magazine. It created considerable interest and both magazines followed up with material answering readers' questions. The aerial covers 48.5-230MHz with a gain of 10dB over the entire bandwidth. Its design is based on "spiraldielectric vibrators", the construction using glass/plexi for the elements, boom etc. Suggestions for alternative material include glass textolite/vinidur.

Tests of the Les Wallen short base aerials for SpE reception in Band I continue. Some remarkable results were noted during the recent good SpE periods. A previously mentioned source of interference at 49MHz (the Golden Eagle baby alarm), which is about half a mile from my location, is strongly received by the 27MHz aerial. Output from the 49MHz aerial is 8-10dB down in comparison. With short/medium hop Band I SpE signals the 49MHz aerial produces noticeably greater output than the 27MHz version. This was rather unexpected. The shorter skip (i.e. from a distance of 500-800 miles) signals tend to suffer greater polarisation shift than those from farther afield. With shorter skip signals the vertical aerials provide better results than a standard four-element, fullsize horizontal Band I Yagi array. With more distant SpE signals, such as those from the USSR, the Yagi array gave the best results. Both the vertical aerials had poor performance with such long hop signals.

The response of the 27MHz aerial is substantially level

TELEVISION AUGUST 1987



TOGETHER WITH DETAILS OF PRESENT ITV REGION RECEIVED. For a speedy dispatch, ACCESS and VISA Mail and Telephone orders

may be placed for any of the products listed in our NEW illustrated

Catalogue. We are active TV/FM DXing specialists -- your guarantee

of honest and knowledgable advice:

OUR NEW HIGH QUALITY CATALOGUE COSTS ONLY 75p AERIAL TECHNIQUES (T)

11, Kent Road, Parkstone,

Poole, Dorset, BH12 2EH. Tel: 0202 738232.

AERIAL TECHNIQUES IS UNIQUE -

with respect to ground but the response of the 49MHz aerial increases with signals coming from an upwards direction, i.e. it favours short-skip SpE signals that arrive from a steeper angle. This observation is confirmed by the previously mentioned fact that the 49MHz aerial had poorer response to the local interference signal. A horizontal "dipole" consisting of two 27MHz aerials with signal combining via a low-loss transformer is being constructed and will be mounted at about 40ft, adjacent to the vertical aerials, to assess its performance with more distant signals. The 19in. 49MHz Les Wallen paging aerial certainly gave encouraging results during the recent good SpE conditions. Experiments with these aerials continue.

6m Amateur Band

From June 1st both Class A and Class B radio amateur licence holders are allowed full-time use of the 50MHz amateur band, using all modes of transmission. There is a suggestion that higher output powers may subsequently be allowed. 50-51MHz is for primary users and 51-52MHz for secondary users, i.e. sole and shared use respectively. The 70-70.5MHz band has also been allocated to amateur use, for secondary users. The e.r.p. output at 50MHz must not exceed 14dBW carrier and 20dBW sideband, taking into account aerial gain and feeder losses. Most important is that interference is not caused to other countries' services. Mobile operation is not permitted and the aerial height must not exceed 20m a.g.l. The aerials must be horizontal.

Several European countries now allow a restricted form of 50MHz amateur radio operation on an experimental basis, namely Gibraltar, Greenland, Eire, Portugal, Norway, Iceland and Spain. Countries considering 50MHz

BARCLAYCARD

VISA



Fig. 1: (a) Traditional Band I notch filter. L consists of 11 turns of 24-28g enamelled wire on a ¼in. former, wound over ¾in. and tapped at 5, 6 and 7 turns, with dust core. The potentiometer is a subminiature preset and the trimmer a miniature type. (b) Varicap tuned version.



Fig. 2: Simpler notch filter using a ferrite toroid (Cirkit type T50-12). L consists of 11 turns of 24-28g enamelled wire tapped at turn 5.5. C is 3-30pF.

amateur operation include Cyprus, W. Germany, Malta and Yugoslavia. The 50MHz band is extensively used for amateur radio operation in other parts of the world – the allocation in the USA is 50-54MHz.

There is naturally great interest in amateur radio circles, since given appropriate SpE/F2 conditions and the much narrower bandwidths than those used for TV very distant weak signals can be resolved – long before a TV-DXer could resolve even a vague image from the same area on an adjacent channel. So it's likely that the UK 50MHz band will become very active during the SpE season. With the considerable radio amateur population in the UK and the congestion in the 144MHz band it's quite likely that many Class B operators will move to 50MHz.

Up to the end of May 50MHz amateur operation has not given TV-DXers too many problems, but from now on we must expect interference in chs. E2, R1 and IA. Since amateur radio operation is restricted to horizontal polarisation a useful reduction in such interference should be achieved by using a vertical aerial system. This will also improve short/medium distance SpE reception due to the polarisation shifts that occur. Use of a narrow i.f. bandwidth within the TV receiver, a technique long advocated in this column for weak signal reception, should also help to minimise interference.

We don't at present have a design for a suitable bandstop filter, and it's unlikely that one could be designed with a notch at 50MHz while still allowing reception of the ch. R1 carrier at 49.75MHz. Sharp attenuation over the 50-52MHz band with a steeply sided characteristic and nominal loss outside the band would be a remarkable filter indeed! Since the 50-50-1MHz part of the band is for beacon use only, with s.s.b. activity starting at 50.1MHz upwards, I feel that a short-term solution would be to use a notch filter tuned to approximately 50.4MHz. This should give reasonable attenuation over the 50.1-50.7MHz segment. An alternative would be a varicap tuned notch filter with switched positions for various parts of the band so that notches can be selected to minimise the problem when interference occurs. An alternative would be a fine-tune carbon potentiometer to sweep across the 2MHz segment.

The notch filter circuits in Figs. 1 and 2 have been shown before but are included this time in view of the problems that are now likely to confront us. They are simple but effective designs. Both cover Band I and with the values given provide a notch depth of 24dB. The design shown in Fig. 1(a) is a bit more complicated: the windings should be held in place with glue or varnish. The filter is tuned with the core, the preset potentiometer peaks the notch and enables an extremely sharp characteristic to be achieved in conjunction with the tuning capacitor. Varicap diodes can be used in place of the latter, as shown in Fig. 1(b). Fig. 2 shows a simpler filter using a toroid that's available from Cirkit.

An alternative filter might consist of a stub tuned to say 51MHz. This would remove much of the band, providing attenuation of around 25dB. Either an open-circuit quarter-wave or short-circuit half-wave stub can be used. Experiments along these lines are being conducted and I'll report back in due course. Meanwhile if any other TV-DXers would care to comment on the problem or provide suggestions for filters we'd like to hear from them.

Two-channel Sound

Stereo sound transmissions are now an established part of the W. German TV network and NOS (Holland) is carrying out experimental transmissions. Japan started two-channel sound transmissions, using an f.m./f.m. audio multiplex system, in 1978 - there's a main and a subchannel and a further control signal to denote either stereo or twin mono channels, the latter for bilingual programming for example. The W. German two-channel system started in the summer of 1981, using the standard 5.5MHz carrier (relative to the vision carrier) and a second carrier at 5.742MHz. The system developed by the BBC and accepted for UK terrestrial use has a second digitally-modulated carrier at 6.55MHz. This is in addition to the standard 6MHz f.m. sound carrier of course. The second carrier can provide sufficient information for either stereo or two-channel (e.g. bilingual) sound. The USA uses another system, a single sound carrier with pilot tone insertion of stereo or second channel information. The MAC system to be used for DBS TV broadcasting allows for two (or more) sound channels in yet other ways.

The BBC has been transmitting stereo sound on a test basis for some time. Unfortunately no circuit details that would allow a decoder to be built have been released. If any reader has a circuit or other information that would enable a decoder to be designed and built we'd naturally like to hear from him/her! When they become available commercial designs will doubtless use special-purpose chips.

For diposal

A reader in the Bournemouth area has several items for disposal to good homes. Apart from a Heathkit wobbulator, factory aligned and new for £25, the rest are free. There are two 19in. Ultra 800 series chassis 405/625line TV sets, one modified for DX use; various Thorn 850 chassis spares; a Philips G6 chassis with valved line output stage and another with a tripler; a 22in. Bush set with the A823 chassis, varicap tuner version, with various spares; *Television* magazines from 1967-1986; and a car cartridge player plus two speakers. Items will have to be collected. If interested, write in with s.a.e. and we'll pass this on to the reader.



SPECIAL OFFER THIS YEARS AHEAD THE CREDIT CARD CALCULATOR

	SULA	ttery Powered	Calcula	tor	000010	£8.00
NEW PHILL	PS SBC 1855 Solar & Ba	tiery rowered	55 00 ·	HI EL MICROPHONE N8501 Philin		£8.00
RECEIVER K3 Tex F	ront Panels with LCs (SAA3027P SAB3013/HO	948.528) 9	£15	CR THNER V/CAP on Panel		£3,50
G8 100K Pots on Pane	el & Lead for 6 Push Button Unit		£2.00 £1.00	G8 SPEAKER		75p
K30 Mains Switch ren K35 Mains Switch ren	mote		75p £1.50	9.000 SPEAKER		£1.00
K35 Aerial Socket an KT3-K30 Slider Pots	d Plug in Lead to Tuner 4.7ku 47ku		20p each	THORN 9000 Sound OP Panel		£30p
LARGE Foacs Pots.	Fits Pye. GEC, ITT. Decca		75p	ONE I.C K35 Decoder		£7.00
G8 Power Supply Par	nel		£4.00 £5.00	THICK FILM, Hitachi RB-32 4A		£2.00
EX DECCA 80-100 L EX DECCA 80-100 F	Frame		£5.00 £6.00	K30 IF/K35 IF		\$5.00
THORN 8000-8500-82	800 Decoder		25 for £1.00	THICK FILM, Hitachi Frame		£4.00
GLASS BEADS Diod	ies 200w/1.2A		£8.00	THORN LOPI SOULARD	Pots	£3.00
GII Decoder Panel			£8.00 £20	NEC Light Emitting Diodes	100	20p
VIDEO HEADS JVC NEW and Model PS3	B Betamax Equivalent to Sony BSR 08R and 01	OR-011R and RSV3B	£20.00	RV223 Replacement		30p
G11 611 Condenser 4	470/250V 1TT		£3.50	THORN CHASSIS 1600-1700 Series	Mono	£10,00
G8 Line Panel			£9.00	THORN 1600 Rec- & Anode Cap		50p
G8 Transductor	and the second		£1.25	KT3-K30 Slider Pots 4.7k		£1.00 for 10
KT4-KT3-K30 Hand	set Replacement		£15.90	ET-614 UHF V/CAP Tuner		6p each
9000 SERIES Decord	er ()] 929 ()]4 ()80 Thorn		£5.00	HITACHL& GEC 20k Pots		20 for £1.00
LATEST VIDEO		ship and purk button and a	ous and	KT3 K30 Speaker		300
For Latest Philips, G	EC, Pye and Hitachi, Front panel with memory	emp and push oution and p	£6.00 NEW	K35 Sound O/P Panel Plug in		£3.00 £1.50
20AX GEC LOPT F	Panel with Split Dlode		£4.00	K35 12 way Push Button Unit		\$6,00
LOPT Split Diode 2	2432871 Pot		75p	RANK T20 Front Panel		£6.00
RANK 718 Fouce Po	01		£8.00	G8 6 Button Unit. New Type		00.03
16" LOPT Split Dio	de 2433481		£6.00 £5	6 off LED DISPLAYS, Mixed		£1.00
Ex Panel Split Diod Split Diode 2433752	es 24328/1/2432981		£6 £3.00	HAND SET TESTER, Infra Red	eadphone with Volume Controls	£17.00
T703A LOPT Trans	former Rank with Focus Pots and Diode		50p	AERIAL SPLITTER with filter		£1.00
HITACHI Mains Sw	witch		30p	DYNAMIC STEREO HEADPHON	E EM 6146	£10.00
HITACHI AE SOCK	mil 1 ands 450 A/C 1200 D/C		15p	PHILIPS UNI DIRECTIONAL DVI	namle Microphone	100
MAINS TRANSFOR	RMER 24(ly in/20//8y		£1.00	20 TURN POTS with Band Switch	Screw Holes Fixing	4 for £1
GREEN FLAT, NE	C, LED's	Зр.	each 100 for £2	PYE 713 Line Trans		£4.50
15V015V Amp Pr	rint Type		£1 75p	PYE 731 Line Trans		65 and 20 for \$1.00
12+12V 2.8VA Prin 8+8V 1 Amp Print	nt l"×l"		75p	800v DIODES at 3 amps. Glass Be	ads	£12.00
HITACHI 6 x 4 - 8	In Speaker		50p £2.50	KT3 Line Output Transformer	IS (Diawei Onk) Replacent	£5,00
ET5% UHF V/CAI FIDELITY Panels v	P Tuner, small with 1.C.		£1.00 €3.00	9000 THORN Front Panel with PO	Ts & Push Buttons	£4.00
FIDELITY LOPT S	Split Diode AT2076/80		£5.00	THORN 8500 Time Base	7 (047)	50p
ITT CVC20 to 45 P	ANELS Send for list		£5.00 each	- 7 SEG DISPLAYS 4 Bank Display	/5 2-00421	£5.00
PHILIPS KT3-KT3	EX DECODER Type VM6103		£7.00	PHILIPS KT3 4R7 W.W. Resistor		15 for £1.00
LINE TRANSFORM	MER Philips TX 12" and 14" Portable		£12.00 #2.00	BU508D		(@ £1.00 each
WANDER PHONES	S Key Pad and Hand Set. No Case.	1			AT2036/00	
2432211	COLIT DIODE	33651		LO.P.T.	AT2048/11 AT2055	
2432301	SPLIT-DIODE	36072 36362			AT2076/35	C10
2432461 2432491	£6 EACH	36383			AT2076/38 AT2076/51	£ IU
2432871		36482		PHILIPS	AT2076/55	EACH
2432981		36831		And the second second	AT2076/71T AT2080/15	
2433581	INPT	36832		£5 EACH	RCO ST CT3325	
2433751 2433452 TX 100 TH	L.U.I . I .	30803			OT2041	
2433432 14100 11	CNI	7		0014		
	DEINI	JL		COM		
63	BISHOPSTEI	GNTON,	SHC	AY SERVICE	55, E55E7	553 OAF.
All	items subject to availa	bility. No Ac	counts:	No Credit Cards.	Postal Order/Ch	eque with order.
	Add 15	vai, then	Callers	: To shop at		20000
	212 LONDO Open 9-1/2.3	N ROAL	o, SC	orders accepted	on official heading	32992 ngs.
		Add	d 10%	nandling charge.		

The 8mm Video System

Part 5

Because, unlike the f.m. audio, the PCM audio occupies a totally different area of the tape from the vision signal it's possible to dub the PCM track without upsetting the picture. The existing PCM track is erased by feeding a suitably timed burst of energy to the flying erase head. The new PCM track is then laid down on the next video head pass. During this time the ATF servo is in the playback mode in order to maintain correct tracking and ensure that the dubbed PCM section is correctly aligned with the appropriate video track.

While the flying erase head is energised during the dubbing process the very strong magnetic field in the rotary transformer leaks into the signal sections, causing interference to the playback picture – the PCM period for one head coincides with a picture-read period of the other head. To conceal this, a masking signal is generated and used to mute the vision playback channel during the relevant period. This is the job of IC111 (see Fig. 36). The effect seen on the monitor during an audio dub is a complete masking of the bottom section of the picture plus, in the SP mode, a flickering bar about half way up the screen. The material recorded on the tape is not affected however and the picture is reproduced fully during subsequent, normal playbacks.

Multi-PCM

As we've seen, the whole of a stereo sound programme can be compressed into just 30° of each video head's rotation. If the tape is to be used entirely for hi-fi sound six such segments will occupy the length of each helical track. This is referred to as the multi-PCM mode, which permits six passes of the tape through the machine with a different segment (and hence stereo programme) being recorded or played back each time. Thus the total potential playing time for one P-60 cassette in the SP mode is 6 \times 90 minutes = nine hours, or 6 \times 180 minutes = 18 hours in the LP mode. Provision is included in the ATF servo system previously described for reverse PCM reading, so that the recording and playback can be continuous in either mode with the machine auto-reversing at each tape end.

For multi-PCM each helical track is divided into six equal segments of 36° each, including a guard band of about 6° between segments – the track layout is shown in Fig. 40. It should be borne in mind that the segments are unlikely to be aligned in a "straight queue" as shown here: each segment is recorded at a different time by a pair of heads whose path has no particular relationship to existing segments, and which may be writing SP or LP tracks. In other respects the data-on-tape format is identical to that used for PCM sound plus video. Each of the 36° segments has a data section of about 30° , with $26 \cdot 3^{\circ}$ of sound data prefixed and suffixed by $2 \cdot 06^{\circ}$ clock run-in and run-out periods.

An additional pilot signal at about 230kHz is continuously generated and added to the PCM sound signal during a multi-PCM recording. In the playback mode this signal is picked up by the ch. 2 and ch. 1' heads which are both in contact with the tape at the same time. It's used to indicate which of the segments have been used to make a

Eugene Trundle

recording. With each recorded segment one of the heads provides a small output and the other a large output. These are combined to provide pulses while each "full" segment is being scanned. After processing the pulses are used to light up the section of the fluorescent "segmentexist" indicator on the front panel.

PCM Adaptors

As a very high quality alternative to analogue audio recording on reel-to-reel or cassette tape PCM got here before the Video-8 format. Several years ago Sony produced the PCM-F1 digital audio encoder for use with the SLF1 VCR – or others, including VHS machines. The PCM-F1 produces a PCM signal for application to the machine's video input terminal: so far as the VCR is concerned the input data looks like a baseband video signal, complete with line and field sync pulses, so that the entire tape area becomes occupied with PCM signal to the exclusion of any video signal. The system became very popular with professional sound recordists and was used to excellent effect for audio mastering, its only limitation being the two-channel capability. For mastering CD recordings a digital original is essential.

A PCM adaptor, Model PCM-EV10, is available for use with suitably equipped Video-8 deck machines with f.m. audio facilities only, e.g. the Sony EVA300. This adaptor carries out all the processing required to a line or microphone signal and provides picture with PCM sound operation similar to that with the top-line deck machines such as the EVS600 and ECS700. It hooks up via a multipin socket at the rear of the EVA300.

Servicing Aspects

The main feature of the Video-8 format is miniaturisation, and full advantage is taken of the small cassette, head and deck to produce very compact equipment. The electrical components are also very small and are in positions and of shapes largely dictated by the machines and, where applicable, the optics. All the latest miniaturisation techniques are used: chip (surface mounted) components, double-sided PCBs, flexible PCBs, 64- and 80-pin chips and so on. To deal with them



Fig. 40: Arrangement of recorded segments in the multi-PCM mode. Not all segments will necessarily be used, and those that are may be in the SP or LP mode. Each segment represents a different pass of the tape through the deck.



Fig. 41: Linear presentation of the Video-8 tape path. Guide functions and alignment are described in the text.

you need a small, hot soldering iron, a good set of test equipment with small probes, and an ability (so far as is possible!) to diagnose faulty components in situ – in most cases substitution tests are not really practical.

Here's a tip, passed on to me by a fellow reader, for removing multi-legged chip components intact. First remove as much solder as possible with desoldering braid and a hot, small iron. Next pass a length of 5A fuse wire under all the legs and anchor it by soldering at the far end. Pull the free end of the wire under the feet as each is released in turn with the soldering iron, starting at the near end. When fitting a chip component, anchor it with a pinhead-sized blob of Blu-Tack before soldering it in.

Various jigs are available from the manufacturers. Relevant to all makes and models are the following Sony alignment tapes: tracking WR5-1C; r.f. sweep WR5-2C; LP colour bars WR5-3CL; colour bars with PCM audio WR5-3CSP. These are not cheap, and one cannot help but wonder why their features could not have been incorporated in a single cassette. Also available is the J608-082-4A forward/reverse torque cassette and a head lapping tape for bedding in newly fitted heads. For individual models a wide range of jigs, gauges, extension leads and switch boxes is available.

Fig. 41 shows a linear presentation of the Video-8 tape path. Guide 1 can be adjusted vertically: its upper edge contacts the tape. It is set to poise the tape slightly above the "shelf" machined on the lower drum, in preparation for the action of guide 2 which is adjustable in respect of height and tilt. Neither of this guide's flanges contacts the tape. Its tilt biases the tape downwards on to the guide machined into the lower drum casting – in similar fashion to the slant poles in VHS machines. Guide 3 has little effect on tape running or tracking: its main function is to absorb tape tension fluctuations as the tape runs on to the drum.

The first guide encountered at the exit side of the drum is no. 4 which, like guide 3, smooths the running of the tape. The main governor of the wrap exit angle is guide 5 which is adjustable for height and tilt. Its upper flange contacts the tape and adjustment is made for a flat waveform at the end of the head sweep of the alignment tape. The alignment of guide 6, beyond the capstan, is for tape running in the reverse mode. The following guides, 7 and 8, are not adjustable: they are tape-steering rollers on the threading ring. Guides 9 and 11 are deck-mounted pillars which define the tape's routing on its way on to the take-up spool. They work in conjunction with guide 10 which is one of the pull-out poles used for tape threading: its action was described in an earlier instalment in this series.

The actual positions of the guides with the tape threaded and running are shown in Fig. 42. The action of the ATF servo system will mask a great deal of misalignment of the crucial entry and exit guides – the situation is akin to trying to tune in a TV set with the



Fig. 42: Plan view of the main deck components and the tape route around them. Guides 1, 6 and 10 are responsible. for tape threading, followed by guides 7 and 8 on the loading ring.



Fig. 43: The familiar-looking tape path in the compact Video-8 camcorder Model CCD-M8E.

a.f.c. on. A track shift and monitor jig is available from the manufacturers to overcome this problem: it gives you back an "adjustable" tracking control potentiometer.

How do you set up the guides on the record-only Handycam Model CCD-M8E? The above-mentioned track shift and monitor jig provides a playback f.m. signal envelope from this camcorder as well as "spiking" the ATF circuit. The tape path in this compact machine is quite different from that shown in Figs. 41 and 42 – in fact it's almost identical to that of a VHS machine. Fig. 43 shows the arrangement. The guides have similar functions to their counterparts on a VHS deck, nos. 3 and 6 having the greatest effect on the tracking.

Many physically small fuses are used in Video-8 hardware. The rating is stamped on them in coded form, i.e. N10, F25 etc. Multiply the number by 40 to get the rating in mA – this also applies to the same small fuses fitted in JVC/Ferguson equipment.

It's too early yet for any fault patterns to have become established or to be able to suggest diagnostic procedures. Very little has emerged so far by way of servicing experience – apart from the fact that the heads have to be cleaned at too frequent intervals! In fact the products are proving to be reliable. The need for frequent head cleaning seems to arise from a ready migration of the tape coating on to the heads. It's worse with some batches of MP tape than with others. I've encountered the problem to some extent with all makes of tape so far tried – maybe they all come from the same factory anyway!

Regarding other faults and bearing in mind the need, more than ever before, to separate the diagnostic and repair procedures, it pays to study and analyse the symptoms carefully. Thus corrupt or intermittently muted PCM sound should lead first to a check on the alignment of the entry guide; mistracking to an investigation of the SEL1 and SEL2 lines and the effects of the TSA and TSB outputs; unstable capstan operation to an initial check on the SP/LP auto playback switching as an indication of TSB functioning; incorrect chroma levels to a test for the presence and effect of the burst-emphasis gating pulse; and so on.

In Conclusion

There is tremendous rivalry on an international scale between the protagonists in the battle between the Video-8 and VHS/VHS-C systems, led on one side by Sony and on the other by JVC. Philips, originally a leading contributor to the Video-8 blueprint, is currently selling VHS-C clones, which seems a shame from where I'm sitting. Apart from Sony, who have been backing the new format very strongly, and Pioneer who currently market

Budget Variable Power Supply

William Harrison

Eugene Trundle's test report on a commercial bench power supply, in the May issue of *Television*, stressed its many uses in the workshop. Impecunious engineers, or those who need a unit for less exacting requirements than E.T., may care to try this DIY model. The circuit is shown in Fig. 1 and it can be built at very little cost. It was originally made to power radio receivers, but its 2A output is suitable for use with monochrome portables. The output could probably be increased by using a Darlington as the series regulator transistor, in conjunction with a larger mains transformer of course.

The design is based on the venerable 723 variable voltage regulator chip. There's protection via the 0.33Ω current sensing resistor and feedback to the i.c. at pin 3.

"badged" Sony camcorders, those so far committed to the Video-8 system are companies in the photographic fraternity: Video-8 products are currently available from Aiwa, Canon, Minolta and Pentax – the Canon and Pentax models are independent designs.

The performance of Video-8 tape and equipment seems to me to be excellent. There are particular advantages in the high quality sound systems, the long running time and the tiny cassettes. Market surveys suggest that Video-8 is taking a large and well-deserved section of the camcorder market, and that home-base Video-8 decks are selling well for both audio and video use. By the time this appears in print the Sony "Professional" Video-8 CCD-V100 outfit should have had time to become established. I for one hope that Video-8 does well: it deserves to!

The Video-8 format does not at present cater for Secam colour – only PAL and NTSC versions of the basic format are available. For use with Secam TV signals an additional chip and peripheral components are required in the machine, in the form of a transcoder that works during record and playback as a PAL interface.

My grateful thanks are due to the Technical and Training Departments of Sony (UK) Ltd. Sony have gone to a great deal of trouble to make available in-depth technical information on the system and their products. I'm in particular indebted to their Mr. Garry Godfrey, an erudite and much-travelled soul who has answered my questions with the patience of Job.

The reference voltage appearing at pin 6 feeds the set voltage control which enables the output to be varied between 1.8V and 15V.

Most of the parts required are on offer by advertisers in the magazine. 15-0-15V mains transformers are available from J. and N. Bull Electrical and from Sendz Components – they are designed for use with monochrome portable TV sets. Sendz offer 4,700 μ F or 2,500 + 2,500 μ F electrolytics, 3A diodes and the 2N3055. The LM723 is available from Grandata. The prices they quote won't break the bank!

A multi-turn potentiometer for the set voltage control is money well spent, also extra flexible wire with crocodile clips and covers for the output leads. Get decent analogue meters, an i.c. holder and a good heatsink for Tr1 – suitable types are the Maplin FL54J and HQ70M, or you could bolt the transistor to a substantial metal case area.

The formula for calculating the value of the ammeter shunt resistors is Rs = Rm/(M - 1), where Rs is the shunt resistance value, Rm the meter resistance and M the multiplication factor.



Fig. 1: Circuit of the budget variable power supply. Ammeter M2 is shunted for 100mA and 2A f.s.d. – the formula for calculating the values of shunt resistors R1 and R2 is given in the text. In the prototype S2 is a 10A rocker switch.

Servicing with a Probe and Pulser

Perhaps the biggest problem that service engineers face today is in coping with the complex digital circuitry encountered when repairing VCRs. Hours can be spent in trying to locate the cause of problems in the system control circuitry – possibly with only one function refusing to work. After a lot of testing expensive logic or microcomputer chips may be ordered from the manufacturers, but when they finally arrive and are fitted the problem may still be present. The VCR may then be put aside while the engineer desperately tries to catch up with a pile of TV sets and other VCRs, and the odd microcomputer that awaits his attention – and here again he encounters plenty of digital circuitry.

The use of a logic pulser and probe greatly facilitates fault-finding in digital circuitry. In a previous article (see Television, November 1985) we described the use of a probe, something many TV engineers now possess. The probe is extremely handy since by simply touching its tip on the point under test an instant indication of the circuit condition is obtained - it does this by indicating the presence of a binary one (high), a binary zero (low) or a fast-changing logic level. The probe is thus essentially a signal tracing device that enables you to follow the progress of digital signals through the circuitry. It can be compared with the old-time signal tracer (used back in radio servicing days) with which you could follow the signal from the aerial to the loudspeaker. But instead of registering the presence of an analogue signal the probe registers the presence of digital information. What the complementary logic pulser does is to generate digital signals that can be detected by the probe, thus enabling you to check the operation of logic circuits in detail.

Until recently several different pulsers were required to cope with the various logic families. The cost of purchasing them could be well over £100. It's now possible however to obtain at modest cost a logic pulser that operates effectively with all types of logic circuitry.

The circuit of a simple logic pulser you can build is shown in Fig. 1. It generates a series of digital pulses at a frequency of about 5Hz. If you like to experiment, this is a handy circuit. It's not really suitable for practical servicing however.

Pulser Features

When you buy a logic pulser, check that it has the following features. (1) The ability to operate with d.c. supplies between say 4.7-15V with reasonable current consumption, and that it's protected against overloads and



Fig. 1: A simple logic pulse generator circuit that will act as a very basic pulser. The component values can be varied to give different output frequency ranges.

wrong polarity connection. (2) The provision of an additional (removable) chassis earth lead is handy so that the pulser can draw power from the circuit under test or from a separate power supply. (3) Full compatibility with CMOS, MOS, TTL and other types of logic circuitry. This microprocessor/ should include memories and microcomputer i.c.s etc. (4) The ability to generate a continuous digital pulse train and single pulses, with switch selection. (5) Indication of output and overload conditions - coloured LEDs are generally employed for this purpose. (6) The pulser should be light and easy to handle and at the same time robust enough to stand up to workshop conditions.

Fig. 2 shows the circuit of a logic pulser (Tandy) suitable for professional TV, VCR and microcomputer servicing. It employs a number of discrete transistors and four nand gates which are contained in an MC14093BCP chip. When switch SW1 is pressed pin 13, connected to one of the inputs of nand gate one, changes from the binary one (high) state to binary zero (low). With SW2 in the pulse selection position the circuit acts as a one-shot multivibrator, producing a single 5µsec pulse which is fed to nand gate four. With switch SW2 in the continuous position the circuit acts as a clock oscillator, producing a continuous 5Hz signal. Nand gate four simply buffers and inverts the signal which is amplified by transistors Q12-Q17 and fed to the probe tip. The signal at the junction of R18/R19 is fed to the base of Q3 which drives the green led LD1. This gives an indication as to whether a pulse or continuous output is present at the probe tip. D1 provides protection in the event of an incorrect polarity supply being connected to the pulser. Conventional supply voltage regulation is incorporated. Should an overload at the probe tip cause excessive current to flow the red warning led LD2 will light. Fig. 3 shows the pulser's output waveforms.

Logic Gates

By now you'll no doubt be familiar with the symbols used for the standard types of logic gates and their truth tables. For convenience they are shown in Fig. 4 and Table 1 respectively.

A Caution

Before discussing servicing procedures, a note of caution. If the pulser is powered from a d.c. supply that's



The Micronta digital logic probe (top) and pulser (bottom). Available from Tandy under catalogue numbers 22-303 and 22-304 respectively.

and and

David Botto



Fig. 2: Circuit of the Tandy logic pulser.



Fig. 3: Outputs produced by the Tandy pulser. (a) A single 5μ sec pulse. (b) A continuous 5Hz pulse train.



Fig. 4: Standard logic gate symbols. (a) And gate. (b) Nand gate. (c) Or gate. (d) Nor gate. (e) Exclusive-or gate. (f) Exclusive-nor gate. (g) Inverter – sometimes referred to as a not gate.

separate from the equipment under test, make sure that this d.c. voltage never exceeds the supply voltage of the digital circuitry you are testing. Otherwise damage to the circuit could result. In practice however the power supply of the circuitry under test is almost always used.

Servicing Procedures

In most digital circuitry the logic inputs and outputs change at a fast rate. By using the low-frequency pulses or single pulse from the logic pulser the changing logic levels can be slowed down and more easily checked with the logic probe. Without the pulser you have to rely on the pulse indication given by the logic probe alone. It's also

TELEVISION AUGUST 1987

useful to be able to check logic i.c.s out of circuit. Logic i.c. testers can be bought but are very expensive. The TV/ VCR engineer will find that an inexpensive solderless breadboard is handy for these tests – it will also help you to appreciate digital logic circuit operation! The chips in some of the equipment you service may be connected into circuit via plug-in sockets and thus be easy to remove: or you may wish to check a logic chip before fitting it.

Testing Gates

Fig. 5 shows the test method for an and gate (remember that an and gate can have two or more inputs). All inputs except one are connected to the supply line. The pulser's

Table 1: Logic gate input/output conditions.

	And gat	te		Nand g	gate
A L H H	B H L H	C L L H	A L H H	B L H L H	C H H L
	Or ga	te		Nor ga	ite
Α	В	С	А	В	С
L L H H	L H L H	L H H H	L L H H	L H L H	H L L
Ęx	clusive-o	r gate	Excl	usive-no	or gate
A L H H	B L L H	C L H H L	A L H H	B H L H	C H L H

679

output is connected to the remaining input. The output indication obtained using the probe should follow the input. Check each input in turn with the pulser while the other inputs are connected via the switch to the supply line. This test can reveal a logic gate fault where a static d.c. test may not. Use the same procedure with a nand gate, only in this case of course the output will be the opposite to the input.

In practice the and and nand gates encountered in servicing are usually simply two input only gates and in domestic equipment are soldered into circuit. If you suspect a particular gate in a piece of equipment first check the supply voltage to the chip, using a digital voltmeter, then simply desolder the gate's inputs. Connect one input to the supply rail and connect the pulser's output to the other – see Fig. 6(a).

With an or gate all inputs but one should be earthed – see Fig. 6(b). Again the output should follow the input. With a nor gate the output is inverted.

Testing Flip-Flops

You'll remember that a flip-flop is a two-state logic circuit which stores one bit of binary information. Its two outputs are referred to as Q and inverted-Q. When the Q output stores a binary one (high) the inverted-Q output is at logic zero and the flip-flop is said to be set. With the Q output low and the inverted-Q output high the flip-flop is said to be reset.

Fig. 7 shows a D flip-flop. To test this in circuit check the T and D (data) inputs with the probe. Provided the T input is high (or being driven at high speed by pulses from a clock oscillator) the Q output should follow the D input. Before replacing a suspect D flip-flop desolder the D input pin and if the T input is not high, or is not being driven by clock pulses, unsolder the T input and connect it to the supply line via a 470 Ω resistor. Feed the pulser's output to the D input and monitor the Q and inverted-Q outputs with the probe. If all is well you'll see the outputs change as the D input changes. When the T input is connected to chassis the flip-flop should ignore the output from the pulser and stop.

You'll often encounter the JK flip-flop in VCR and computer circuitry. A block diagram of the internal circuitry of a typical JK flip-flop is shown in Fig. 8. Notice that it has two main sections, a master and a slave flipflop. Two such flip-flops are contained in the commonly used SN7476 i.c. First use the probe to check that the preset and clear lines are high – these lines are internally connected in some JK flip-flops. The JK flip-flop can continue to respond to the clock signal only when both the J and K inputs receive logic ones or are connected so as to be permanently high. When a clock pulse is present at the T input the logic probe should indicate that the JK flipflop is rapidly setting and resetting.

If you suspect that a JK flip-flop has failed and you're not sure whether the flip-flop i.c. or associated circuitry is faulty, desolder the pin for the T or clock input and connect the pulser to it. With a continuous 5Hz input the Q and inverted-Q outputs should set and reset at a rate of 2.5Hz. This is because the master flip-flop must set and reset first before setting and resetting the slave flip-flop. For this reason the JK flip-flop is sometimes used as a frequency divider. Fig. 9 shows the duty-cycle waveforms. It's easy to remove and check a JK flip-flop on your breadboard: unfortunately in TV and VCR work they always seem to be well soldered in!



Fig. 5: Solderless breadboard check for an and gate. The method is the same for a nand gate. For an or or nor gate the common connection of the gate input switch is taken to chassis instead of to the positive side of the supply. Dual inline pack switches (S2) are available from suppliers such as Maplin (catalogue number XX27E).



Fig. 9: JK flip-flop duty cycle waveforms with the J and K inputs high or disconnected. Top, clock input (T). Bottom, Q output.



Fig. 10: Block diagram of a one-shot multivibrator.

Another logic chip often encountered in VCRs and microcomputers is the one-shot multivibrator, which is sometimes called a retriggerable multivibrator. When the one-shot multivibrator detects a trigger input pulse it generates a single output pulse. Fig. 10 shows the circuit symbolically. An SN74123 i.c. contains two complete one-shots. To test the operation, first check that the CLR (clear) input is low, using the probe. Then disconnect pin 1 (in this case) and apply to it a pulse from the logic pulser. If capacitor C1 is of low value the output pulse at pin 13 may be detectable only via your logic probe. If C1 is of large value the pulse may last for more than a second. C1 could be anything from 15pF to $1,000\mu$ F depending on circuit requirement.

Practical Servicing

When tackling a piece of equipment it's a good idea to start by studying the service manual to try to see how the system is supposed to work. Don't forget first to ensure that the correct supply voltages are present. With VCRs especially it's well worth making sure that the fault is in the logic circuitry and is not due to some external cause. For example, a slack loading belt in the Panasonic NV333 VCR will cause the capstan motor on signal from the system control microcomputer to stay low when it should be high. Also check that the various switches, such as the cassette down switch etc., are clean and in good order.

The usual faults in digital/microcomputer circuitry are short-circuits, open-circuits and incorrect logic levels, plus problems caused by halted clock oscillators – and sometimes an off-frequency oscillator. Thus problems in digital circuitry can in the main be tackled by the TV/VCR engineer with a digital voltmeter, a logic pulser and a logic probe.

The pulser is particularly useful when fault tracing in circuitry that consists of a combination of various logic devices, perhaps contained in a single i.c. package. IC6002 in the Panasonic NV7000 VCR is such a package. At first sight when you encounter it in the circuit diagram testing might appear to be a formidable task. As Fig. 11 shows however the i.c. simply consists of eight D-type flip-flops and is thus quite easy to check.

The first in-circuit tests are made with the logic probe. Pins 1 and 2 are supplied with clock pulses from the controlling microcomputer chip. The probe should show L + P + very dim H at these pins. Remember that without the presence of these clock pulses the flip-flops cannot change state.

As the various VCR functions are selected the logic levels at pins 3-6 will change. So too should the Q outputs

of each pair of flip-flops whose D inputs are joined internally. For example, if the fast-forward button is depressed (with a cassette loaded of course) the logic probe should indicate H + P at pin 3. Connect the probe to pins 11 and 15 in turn and check that the logic levels change.

If the chip doesn't seem to be functioning and you're not sure if the problem is in the device itself or somewhere else, first make sure that the clock pulses are present at pins 1 and 2 then desolder pins 3-6. Set the pulser to provide a continuous output and apply it first to pin 3. Connect the logic probe to pin 11 then to pin 15. The logic levels should change as the relevant flip-flops set and reset.

If you next apply the pulser to pins 4, 5 and 6 you should be able to monitor the changing logic levels of the Q outputs at pins 10, 14, 9, 13, 8 and 12 in turn.

When checking microcomputer and microprocessor chips it's best to use the probe – you've probably noticed that *Television* servicing articles often include helpful lists of the logic levels found at the pins of these i.c.s. The logic pulser comes in when input signals to such chips are missing. The pulser-probe combination enables you to check the various devices that feed signals to the microcomputer or microprocessor i.c.

Suppose that some or all of a VCR's functions fail to occur when the relevant key-matrix function buttons are operated. With many types of VCRs you'll often find that a signal from the pulser applied to or near the function control connections will initiate the relevant VCR operation without the button(s) being depressed. In this case you'll know that the fault is in the small area of circuitry near the function keys, making location of the fault an easy matter.

Particularly in VCRs, various sensors often drive logic circuitry. If the circuit doesn't operate as it should and the supply rail d.c. voltage is correct, has the sensor unit failed or is the problem in the logic circuitry? The fast way to find out is to feed a signal from the pulser into the



Fig. 11: IC6002, type MN1201A, in the Panasonic NV7000 VCR contains eight D flip-flops.

circuitry. If the circuit then operates the sensor is faulty.

Another handy test using the two probes is in speedy location of print breaks. If, in the absence of a logic signal, you suspect the printed circuit board tracks, trace along the print with the logic probe. Should the logic signal suddenly appear you know you've found the break. If an input to a logic device is missing and you suspect the print, activate the device with the pulser and check its output with the probe. Move the pulser's probe slowly away from the input connection to the device. If the device suddenly ceases to work or changes state then again you know you've located the print break.

Print shorts or an overload caused by some other faulty component in the circuit often stop a suspect digital device from working. If you think that this may be the case, desolder the output pin(s) and check it again with the probe and pulser.

It's not too difficult to check the digital channel indicators used in TV sets and VCRs using a pulser and probe. In fact when the pulser's signal is supplied to the serial data input connection of the logic decoder that drives the display the segment display should go round and round, showing all the numbers in turn!

The logic pulser and probe are also useful when checking the digital circuitry used in remote control and digital tuning devices.

When servicing a TV set, VCR or microcomputer, don't forget to make notes in the manual of the various logic levels you encounter. Include in your notes the effect of injecting logic pulses into various sections of the equipment. Quite soon another of the same type of set or whatever may confront you and you'll be glad you made those notes!

Boolean Algebra

A basic understanding of Boolean algebra can be



THORN SELLS FERGUSON

In a move designed to create one of the world's largest consumer electronics organisations Thorn EMI plc and the French government owned consumer electronics company Thomson Grand Public have reached agreement on the acquisition by Thomson of the Thorn TV manufacturing subsidiary Thorn EMI Ferguson Ltd. Thomson will pay approximately £90m to Thorn EMI on completion of the sale, which is expected to be in early July, representing a premium over the current book value of Thorn EMI Ferguson. Ferguson has long held a predominant position in the UK market and had a turnover in the year to the end of March 1987 of £300m. Last year the company produced 680,000 colour and monochrome sets and production is at present running at the rate of over a million sets a year. Thorn and Thomson nevertheless concluded, after a joint study of the world consumer electronics market, that both companies would benefit from operating as a single, large European manufacturer, with the improved economies of scale and market shares that this would give. Thomson is at present producing sets at the rate of 2.8 million annually. It has never had anything other than minor representation in the UK consumer electronics market, which is Europe's largest,

helpful when dealing with complex blocks of circuitry. This subject is outside the scope of the present article but a few basic points may be useful. Note first that the rules of Boolean algebra differ completely from ordinary algebra. Fortunately it's much easier to learn! Boolean algebra serves as the special language of digital logic circuits – it's the next step forward from truth tables.

For example, taking the and gate shown in Fig. 4(a) with inputs A and B and output C, the Boolean expression for the action of this device is $C = A \cdot B$, which is read as C equals A and B. For the or gate – Fig. 4(c) – the Boolean expression is C = A + B, the + sign indicating the or function. For an inverter – Fig. 4(g) – the Boolean equation is B = A.

In Conclusion

Once you begin to use a logic pulser you'll discover how much faster and easier fault location in digital circuitry becomes. You'll then find that the pulser and probe rapidly become indispensible.

Logic pulsers and probes are now available from sources such as B.K. Electronics, Maplin, RS Components, Verospeed and many other companies. The logic pulser I use is a Tandy 22-304A which costs just £16.95. It comes with an excellent instruction booklet. Most of the above firms also supply solderless breadboards, miniature 8-way SPST DIP switches and suitable connecting wire. These, as indicated in Fig. 5, are useful for checking digital i.c.s out of circuit.

Note that some of the comments in this article relate specifically to the Tandy pulser just mentioned. Pulsers from different sources differ somewhat in their characteristics. With many of them checks can be carried out with no need for any desoldering or PCB track cutting. The moral of course is to read carefully the instructions relating to the pulser you intend to use.

while Ferguson has had negligible sales overseas. World output of TV receivers by the largest producers in 1986 is estimated by BIS Mackintosh to have been as follows, in millions of units: Philips 6.2, Matsushita 4.7, Sony 3.8, Toshiba 3.2, Hitachi 3.1, Thomson plus Thorn-Ferguson 3, GE/RCA 2.8, Samsung 2.5, Sanyo 1.8, Sharp 1.7. The merged company will be the second largest in the industry in Europe, after Philips. Thomson already has substantial representation in the W. German market, with ownership of the NordMende, Saba and Telefunken brands.

Thorn and Thomson have for several years worked together in the area of colour TV tubes and have been associated, with JVC, in the J2T joint VCR manufacturing venture. J2T is at present producing around 900,000 VCRs a year at plants in the UK, France and W. Berlin. Thorn is to support the new group by entering into a formal, long-term agreement for it to supply sets to the Thorn rental businesses (Radio Rentals, DER, Multibroadcast and Focus TV). See leader comment on page 669.

HUGHES TO BUILD UK'S TV SATELLITES

The contract to supply the satellites to be used by British Satellite Broadcasting (BSB), which has the UK DBS franchise, has gone to the Hughes Aircraft Company of Los Angeles. The American company is now part of the General Motors group. Hughes will be supplying two HS376 satellites, equipped with 110W transponders, in a deal that's worth some £200 million. The satellites are due

to be launched in late 1989 and 1990. There has been keen competition with British Aerospace and Comsat over the deal to supply the satellites for BSB's services. It's understood that the Hughes success is in part due to the fact that it agreed to take on the financial risks of the launch. The satellites are to be turned over to BSB only after they have been tested in orbit.

UK TV BROADCASTING IN THE 90s

The government is planning to introduce a bill in late 1988 covering changes in UK TV broadcasting arrangements. The main aim seems to be to increase competition amongst the ITV companies, whose present franchises end in 1991. One possible approach under consideration for the next franchising round would be to apply quality tests to applicants followed by tendering. The latter could consist of an initial down payment, an annually adjusted rent, and bids based on a percentage of advertising revenue rather than the present levy on profits. The arrangements covering the financing of Channel 4 could also be changed. The government is thought to be considering the possibilities of adding further terrestrial channels. A study by US consultants CSP International, commissioned by the Home Office, is understood to have suggested a fifth national network in the v.h.f. bands and local stations using low-power u.h.f. transmitters.

VIDEO PRODUCTION

The two millionth 8mm video unit was shipped by Sony in the first quarter of the year, only 26 months after the first 8mm products rolled off Sony's production lines in January 1985. Sony points to increasing world demand for its 8mm video equipment and expects to deliver the three millionth unit within a year. Sony is doubling the output of 8mm camcorders at its W. German plant to an annual rate of 120,000 units and has switched production from the CCD-V100 to the new Handycam Auto CCD-V30.

Monthly output of VCRs at Sharp's Wrexham plant in N. Wales is being increased from 22,000 units to 35,000. Output of microwave ovens and electronic typewriters is also being increased and the plant is being extended to produce photocopiers.

Hitachi is doubling VCR production at its S. Wales plant. Following an investment of some $\pounds 4.2m$ the plant will be able to produce 240,000 VCRs annually.

THE COMPACT VIDEO DISC

Philips and Sony, co-licensers of the compact audio disc (CD), announced last February the development of the CD with video format as an extension of the CD standard. The two firms have since been holding discussions with the industry on the official name and logo for the new range of discs. Agreement has been reached as follows: (1) The five inch (12cm) compact disc with video will be called CDV. These discs will contain a maximum of five minutes of analogue video information accompanied by digital audio plus a maximum of twenty minutes of CD digital audio. To differentiate them from the silver audio only compact discs the CDV discs will be golden coloured. (2) In addition, the words "CD Video" will be used as the basic system name, the CD Video System including the hardware (CDV Clip player, CDV Combi player, etc.)



and the five inch CDV discs and the eight and ten inch laser-read video discs (LD).

The following identification marks will be used: CDV for the five inch discs, LD for the 8/12in. discs, CD CDV for players that play CD and CDV discs, and CD CDV LD for players that handle the whole range of discs.

SPARE PARTS ANNOUNCEMENTS

The supply of spare parts for Ingersoll, York and Thomson consumer electronics products that have been sold in the UK has been taken over by Service All Electronics, 21/22 The Craft Centre, West Wilts Trading Estate, Westbury, Wilts. Telephone 0373 826 739 or, after hours, 0373 865 214.

Spare parts for the Grundig VCR4000 and SVR4004 ranges of VCRs are now available only from Willow Vale Electronics Ltd., 11 Arkwright Road, Reading, Berks RG2 0LU. Telephone 0734 876 444.

NEW FROM MULLARD

Mullard has released a new multi-standard teletext chip, type SAA5250. This is described as a CMOS interface for data acquisition and control (CIDAC) and performs the dual functions of data capture and storage in a separate memory for subsequent retrieval and processing. CIDAC was originally developed for the French Antiope system but will also operate in accordance with the UK and N. American teletext transmission standards. It's designed for use with the SAA5231 video input processor (VIP2) chip. The CIDAC chip controls the separate memory directly, without extra logic, and can be interrogated by a microcontroller chip.

Mullard has also announced a four-chip set to implement pulse-code modulated (PCM) digital audio in VCRs using the 8mm tape format. The four CMOS chips use just 60mW power in total, making them ideal for use in both battery and mains powered equipment. The chip set comprises the SAA1133 analogue/digital interface, the SAA1131 error corrector-1, SAA1132 error corrector-2 and SAA1136 optional ident word interface. The chip set requires only the addition of some RAM to form the complete PCM audio section of a VCR. The Video-8 PCM audio system was described in some detail last month (see pages 609-614).

SHOWS, CONVENTIONS, ETC.

Next year's brown goods trade shows will be held over the period May 15-18th 1988. In the following years it's intended to move the dates back to March, the provisional dates for 1989 being March 5-8th.

The next International Broadcasting Convention is to be held in Brighton on September 23rd-27th 1988. As in 1986 the Convention will be at the Metropole Conference and Exhibition Centre, the Grand Hotel and the Brighton Centre, with the esplanade fronting and linking these locations being used for outside exhibits.

The Institution of Electronic and Radio Engineers has announced that the seventh international conference on Video, Audio and Data Recording will be held at the University of York on March 21st-24th 1988. For further details contact the IERE at 99 Gower Street, London WC1E 6AZ.

The next SIM-HI.FI-IVES consumer electronics and musical instruments exhibition will be held in Milan on September 3rd-7th 1987. The Italian Broadcasting and Telecommunications Show, covering professional audio, video and post-production equipment, will be held in Milan on September 24-28th 1987.

"Broadcast '87", the Frankfurt trade fair for film, radio, TV and video equipment, will be held on October 14-17th 1987.

THORN SELLS EX-RENTAL SETS

As an experiment, limited to the London area initially, Thorn is to sell second-hand, ex-rental sets directly to the public. The sets will be sold through servicing centres as a separate operation under the name Multicare. If the experiment is considered a success the idea might be adopted in other areas.

UNIVERSAL REMOTE CONTROLLER

The Onkyo universal infra-red remote control unit is being introduced by Natural Sound Systems of Watford (092 326 499). It's claimed that the unit can be programmed to control almost any manufacturer's consumer electronics products. It will sell for around £120.

VIDEO ROUND-UP

Mitsubishi has launched an S-VHS VCR, Model HVF23, in Japan. Production will be at 5,000 units a month initially and the selling price will be the yen equivalent of about £935. Loewe Opta has announced its intention to show an S-VHS machine at this year's Berlin International Audio and Video Fair.

Sanyo's latest VHS VCR, Model VHR3100E, features super-slim styling, being just 89mm in height. There's a SCART socket as well as the usual standard u.h.f. output. The suggested retail price is around £350.

Steepletone Products Ltd. (Park End Works, Northants NN13 5RD, 0869 810 081) has introduced a video tape winding and cleaning unit which is expected to sell at about £30. It will rewind or wind forward an E180 tape in two and a half minutes. Use of the winder reduces VCR wear and enables a tape to be prepared for use whilst the VCR is in operation. The winder has a resettable three-digit counter, an auto brake arrangement and a button to bring the cleaning system – a spirit impregnated pad – into operation. The unit comes complete with six replacement pads.

The latest issue of the Society of Electronic and Radio Technicians' journal *Electronic Technology* contains a useful guide to fault location in VHS machines. Well worth study if you know a member who will lend you his copy.

IN BRIEF

Matsushita is to supply its new video recording system, the half-inch M2 format, to Thames Television in a deal likely to be worth £8-10m over four-five years. The equipment is already in use in Japan and USA for both studio and outside broadcast applications . . . China has announced a major order from Canada for 700,000 14 and 22in. colour TV sets. The country already exports to Hungary and the UK. There is also to be a joint Chinese-Canadian VCR production venture . . . A US toy manufacturer, Fisher-Price, intends to market a cheap camcorder that will record eleven minutes of monochrome TV on a C90 audio cassette (five and a half minutes per side). The Pixelvision camcorder will be sold for about £95. It has a stationary video head, a fixed-focus video camera and a deck that will run for five hours on six AA alkaline batteries.

The Computer as an Aid to Servicing

Part 3

We've already looked at ways in which a computer can be used to simplify the stocking and handling of spares, to provide an indexing and locating service for manuals and so on. We'll now examine the possibilities of keeping useful service records for sets on rental or on maintenance contracts. It's clearly of great importance to know just how much is being spent on the upkeep of such sets apart from the advantage of being able to refer back to see whether a particular part has been changed in the past, and if so when.

In determining the best way to set up files we must consider the provisions of the Data Protection Act, 1984, which came into force last year. Briefly, the Act sets out to control the storage and use of personal information in computers and other equipment. It gives an individual the right of access to any files which he believes might hold such information, and requires people who operate personal data storage systems to register with the appropriate government department. Exemptions are set out at some length (part iv, 31-35) and come chiefly under four headings - club membership records, domestic records, payrolls and accounts. Only living individuals are covered by the Act, so there's no restriction on the names of companies, organisations and so on. Furthermore it's permissible to file names and addresses only when these are to be used for "preparing the text of documents". This appears to mean that if you have entries such as "J. Smith, 99 Peabody Buildings, Upper Spranfield" for the purpose of making up say a monthly account or an occasional bill registration is unnecessary. If you should wish to add any additional information however, such as "age 29", "bad payer" or "husband works funny hours", you will have to register. Note that keeping written comments of this type is not restricted. If you set up your computer files suitably there should be no problem.

The sort of information that's likely to be most useful when stored is the customer's name and address, the make and serial number of the equipment, the date of purchase or commencement of rental, the dates when servicing has been carried out and the cost of this work. With this basic information in mind we can set up a suitable database file on the following lines - refer back to the previous articles in this series (February and April 1987, and see also the letter in the June issue) for full details of the procedure.

On receiving the prompt and entering the command "create" we receive the usual request for a file name, which might in this case be "Setrecords" or "B:Setrecords" depending on which disc drive is used. The various fields could be arranged as follows:

- 001 Name, C, 20
- 002 Address, C, 100
- 003 Set, C, 15
- 004 Serial, C, 15
- Purdate, C, 15 (date of purchase) 005
- 006
- Rendate, C, 15 (date of rental) Serdate, C, 100 (date[s] of servicing) Parts, C, 100 007
- 008
- Costs, C, 100 009

The 100 character field width allows a fair number of

entries but can be modified to suit your own particular needs. A specimen record might look like this:

- 001 Smith, J.
- 002 99, Peabody Buildings, Spranfield.
- 003 SuperTV 20"
- 004 12345
- 005 12th Aug 1980 006
- 007 13th Aug 1980, 20th Jan 1983, 4th Nov 1986.
- 008 Complete new chassis, 3.15A fuse, new c.r.t.
- 009 u/g, £5.50, £72.90

As usual, indexes can be made up to cover the appropriate fields. In this instance the customer's name, address and type of set will probably be sufficient, for which we use the commands:

- Index on Name to Namind
- Index on Address to Addind
- Index on Set to Setind

Records can be examined as required at a later date by using one of the indexes:

- . Use Setrecords index Namind
- . Find Smith
- . Display

Due to the large field widths you may well find that the information is scattered about the screen - the dates especially may be confused. To overcome this (and to make alterations and additions) make a note of the record number and enter the command:

. Edit 00001

whereupon the record as originally composed will appear on the screen.

You might wish to add a new repair. Use the CR to take the cursor down to field 007 and insert the appropriate date. CR will then take you on to field 008 for the parts used and then to field 009 for the cost of the job. A final CR will bring up the next record for editing. Should you not wish to do this you can escape by using CTRL-W.

A handy way of making it easy to consult the records is to write the set's file number somewhere on the back. Details can then be called up on the computer as soon as the set comes into the workshop and the information can be up-dated as required.

Numerous other items of information can of course be stored. For example a field could be devoted to the monthly (etc.) date when rental or other payments are due or when they are scheduled to finish. If rental sets are disposed of after a certain time in service the projected date for each set could be recorded and the records checked periodically to weed sets out. Other possibilities will no doubt suggest themselves to you. The scope is pretty wide, as any record will accept a maximum of 32 fields, with a maximum of 1,000 characters overall.

Forms for registration under the Data Protection Act are obtainable from main Post Offices or direct from The Data Protection Registrar, Department 1, Springfield House, Water Lane, Wilmslow, Cheshire SK9 5AX.

VCR Clinic

Ferguson 3V31/JVC HR7650

The complaint with this machine was of intermittent variation in the sound level. The actual problem was not intermittent: there was variation of sound level in the record mode on certain tapes. In fact the problem was confined to a brand new Panasonic tape provided by the customer and an old test tape of ours found lying around in the workshop. Six other tapes we tried worked perfectly, while the two tapes that showed the fault worked correctly in other machines. No displacement of the tape could be seen during record, and small adjustments of the audio/control head didn't improve the situation. A cure was finally provided by a rather unscientific 90° anticlockwise turn of the right-hand tape pillar. C.H.

JVC GRC1 Camcorder

Summer is here and it's time to get out the camcorder last used at Christmas! Two of them came into our workshop recently. The first needed no more than video head cleaning but the second appeared to have a more difficult fault. The complaint was that the microphone didn't work, but in fact there was no audio record or playback while the microphone gave good sound through a monitor during recordings.

I always approach these units with a great deal of caution – their intricacy and compact layout demand considerable respect. Luckily this one turned out to have no more than an open-circuit lead to the audio head. Time to repair it: five minutes. Time to uncase and case it: almost two hours – and that's following the instructions in the manual! C.H.

JVC HRD140/Ferguson 3V44

This machine would work perfectly for long periods of time but occasionally the capstan would start to speed up, the effect being as if the machine was in the rapid forward search mode but with the sound unmuted. If the tape was stopped and ejected while the machine was in the fault condition the capstan motor would continue to spin. The problem was due to the presence of 10V d.c. at the base of Q603. This wasn't leaking through diodes D606, D607 or D608 but apparently came from the collector of Q603 itself. Even though the transistor read perfectly when checked with an ohmmeter a replacement 2SD637R provided a cure.

Mitsubishi HS306

HS306s don't like smoky houses! The typical fault is that the machine stops playing after ten seconds and the counter doesn't move. This is due to the take-up rotation optosensor and reflective strips being dirty. Cleaning with foam cleaner is all that's required. **P.B.**

Philips VR6462/Finlux VR1010

For low recorded sound with these machines, before suspecting an audio fault try listening very closely to see if the sound is wowing. If it is the sound is being muted, most likely due to a capstan servo fault. If it isn't wowing try cleaning and resoldering the pins to the audio/control If you find poor take-up torque that doesn't respond to replacement of the reel idler or omega spring, remove the two reel carriers and check whether any metal debris are sticking to the magnets on the underside. So far I've had circlips, springs and hairgrips here. If they jam on, the Hall sensor's reel rotation will stop. **P.B.**

Fisher FVHP615

This machine appeared to have a capstan servo fault: after playing for a few minutes the voices would sound like Mickey Mouse and tracking lines would appear on the screen. A look at the servo board revealed that all the i.c.s had been replaced. Someone had been beaten by this one! Luckily I noticed that the reel belt was straining when the fault occurred, so I checked the take-up torque which was much too high. What was happening was that the rewind idler was contacting the take-up spool which was in effect in the rewind and play modes at the same time. A new idler gear and leaf spring were required. **P.B.**

Ferguson 3V35/JVC HRD120

This machine would load, run for five seconds then unload. Watching the head drum it was obvious to us that the motor was running fast. As we had only five seconds to measure voltages and scope waveforms before the machine unloaded we decided to swap the motor with one from a stock machine in order to rule it out. It proved to be innocent, so the scope would have to be connected to each test point in turn then play selected in the hope that something would show. Fortunately the first test point chosen revealed that there were no drum pick-up pulses. The pick-up head was open-circuit. **A.D.**

Grundig VS180 and VS220

The problem with these two machines was intermittent or no play, with F1 flashing in the VS220's display and the pause light flashing in the VS180. The usual cause of this is dirty contacts on the brake solenoid switch S4. Cleaning the switch will restore normal operation – Grundig recommend removal of the plastic dust cover. A.D.

Mitsubishi HS318

This machine refused to load a tape and produced a loud clicking noise from the mechanism. Cam gears A and B were jumping back as the machine tried to load. The fault was in the first nylon gear driven by the loading motor – every other tooth on the gear was either missing or badly worn. Similar mechanisms are used in the HS306/7 and HS337/8. A.D.

Ferguson 3V29/JVC HRD110

The customer's complaint was that the picture was poor in the forward search mode – there was a large noise bar at the top of the screen. The reel servo voltages didn't tally with those shown in the circuit but proved to be correct when compared with those in another machine. Swapping the servo panels failed to cure the fault so the drum motor assemblies were interchanged. This cleared the fault. When the customer was told the cost of a new drum motor he decided that it was a fault he could live with.

A.D.

Panasonic NV7200

There was intermittent no play with this machine, the fault usually occurring during loading, i.e. the tape would load then unload. When the machine did load everything worked perfectly. Checks on the drum flip-flop and takeup sensor signals were inconclusive because of the nature of the fault. We next decided to run the machine without a tape and check for faults visually. While watching the mechanism during loading we noticed that the cassette lamp flickered due to vibration from the solenoid. No, it wasn't an intermittent lamp but tarnished contacts on the cassette detect leaf switch. A.D.

Ferguson 3V29/JVC HRD110

This machine would select the wrong modes, i.e. if the play and record buttons were pressed the play, pause and audio dub LEDs would light up while other buttons including stop had no effect. There were voltage changes at the input to the comparator on the mechacon board but no changes at the output pin. A check on the output from the D-A converter revealed only one staircase instead of a repeated waveform. At the microcomputer chip's key scan port each output produced only one set of pulses. A replacement microcomputer chip cured the fault. A.D.

JVC HRD755

This machine would accept a cassette but wouldn't respond to any commands either from the front controls or the remote control unit. If the machine was switched off then on again the cassette would be ejected. If the cassette was then reinserted the machine might work. The fault was eventually traced to a faulty cassette end load switch in the cassette housing. A.D.

Akai VS2

Anyone familiar with these machine would consider this fault old hat and wouldn't even reach for the service manual. The machine would load a tape, play for five seconds, then stop and unload. The reels were turning and the clover leaf pattern indicated that the drum was running at the correct speed. At this point we decided that the problem was either in the syscon or that pulses were not arriving at the syscon panel, so a service manual was ordered. When it arrived a read through the circuit description made everything clear. The reel pulses are derived from a LED and phototransistor, the LED being supplied via the cassette lamp. Replacing the lamp cured the fault. At least the initial diagnosis of missing pulses to the syscon panel was correct! A.D.

Ferguson 3V36/JVC HRD225

A very intermittent deck shutdown fault was present on this machine. It made two fruitless journeys to the workshop for soak testing before the fault put in an appearance for us. The output pulses from the take-up reel sensor were intermittently absent, triggering the syscon into the alarm mode. We discovered that these

TELEVISION AUGUST 1987

sensors can be checked by turning each spool carrier by hand while the machine is in the standby mode with no cassette present. This should result in jumps from zero to 5V at pins 3 and 4 of CN23 on the A/S/M panel – most easily seen on a d.c. oscilloscope. This method gives you the opportunity to check the sensor optocouplers while they're being heated, cooled, prodded and generally harassed . . . E.T.

Sanyo VTC5150

Now that these machines have given a few years' service we've had several cases of tape chewing – not for the usual Sanyo reasons but because of a worn pinch roller assembly. The problem is easy to recognise: the tape becomes creased and crinkled across its full width at random intervals. E.T.

JVC HRD370

This brand new machine, straight out of the box, failed a predelivery test – the clock functions couldn't be set. In general the mode keys worked while the numerical ones didn't. The cause turned out to be a "silly": the ribbon cable from program board 23 was only half pushed home into CN5 on timer board 15. Its half-cock angle was such that the end half dozen or so of its contacts were making, hence the registration of only some of the commands. Had we not seen this a giveaway would have been that the timer could be fully set up using the remote control handset.

Panasonic NV100

This portable VCR had long been used with a JVC GXN5E camera without problems but was eventually brought in for service with the complaint that use of the camera's run/stop trigger would sometimes put the VCR into stop. On test we found that the stop mode could be invoked very intermittently by going from record to record-pause or vice versa. By a lucky chance we got another GXN5E camera in for service at the same time: the NV100 played the same tricks with this. A somewhat inconclusive scope check around the syscon microcomputer convinced us that the port expansion chip I6003 (type VCR 0060) was the culprit: replacing this cured the problem – well, we've not heard any more about it since the machine went back . . . E.T.

Ferguson 3V28 Tuner/Timer

The tuner/timer half of the 3V24/3V28 ensemble gives less hassle than its partnering VCR. This particular one got into trouble only because the yobbos at the local Youth Training Centre had knobbled it by setting the mains voltage selector to 110V. Not surprisingly the 1A mains fuse blew when it was next powered from the 240V mains supply. Several replacement fuses were fed in by the supervisor before he eventually brought it in for attention. The fuseholder is right beside the voltage selector switch, which clearly said 110V!

Under the circumstances they got off lightly. The massive mains transformer was unaffected, as were all the l.t. fuses, the regulator transistors and main rectifiers. Damage was confined to D3 (type 10E2) going short-circuit and a burnt out safety resistor (R18, 2Ω) on the regulator panel. The resulting loss of the 40V line had mercifully cut off the main 12V regulators, while the reservoir capacitors had held out. E.T.

Tiny Tim's Triple Trouble

Tim sat behind his bench and looked out at the world, or some of it. Pretty girls looked at the door to get a reflection of themselves – this was apparently their favourite occupation. How could they tell their boy friends they loved them? There just wasn't room. Not till they got older and told their children they were selfish.

It's a funny place this world, thought Tim. Then he realised he was the same himself. It was just that he didn't show it so blatantly. He sort of covered it up and pretended he cared for others. Like Tinker Bell really did – not for Tiny Tim of course, but she seemed to care for others.

His eyes strayed under the bench. How did those books of naked girls get mixed up with his service manuals? Oh yes. He was saving them for his brother who liked things like that since he couldn't do anything other than sit in a chair all day and read and watch videos and things. Tim didn't like these rude books. It was just that he had to make sure that his brother wasn't going to see something that would upset him. Besides, he would have to keep them until Saturday so that Phil could read them too.

Mr Golightly's K40

Just then Mr. Golightly opened the door and carried in a Philips K40. "It goes off just when it's getting interesting, and my wife's getting fed up with it and with me" he explained.

Intermittent operation. Tim's heart sank. He wasn't keen on K40s as he hadn't had much to do with them as yet – not like the KT3, which he was always pleased to see, with its unreliable tripler and probably a faulty chip or two, or the usual problem of the 4.7Ω resistor without chip faults.

He removed the rear cover warily, switched on and connected an aerial. A lovely picture appeared and remained. Tim got out the hairdryer but nothing responded to it. He then drew out the lower, centre power panel to see whether heat on this would do anything. Now to get this panel out you have to lower the main panel. Having pushed the power panel back in Tim raised the main panel and the set went off. He lowered it and the set came back on.

"There you are" said Mr. Golightly, "on off, on off".

Tim sighed and peered at the main board closely. A tiny spark caught his eye. Yes, on one of the line output transformer pins. Quick as a flash it was resoldered. "All done Mr. Golightly. See you next year perhaps."

"What? When? Wait a minute!"

Tim moved the main board about and tapped it with the screwdriver handle. "All done. Next gent please."

He wrapped it up and put it back in the car while Mr. Golightly muttered about what his wife would say if it happened again. We haven't seen him since – except when he popped in with half a bottle of Bells for Tim. In fact the poor joint hadn't been cleared that quickly. The pin had been scraped clean before resoldering.

Tim's Second Trial

When two fellows staggered in carrying a big TV set with doors Tim wondered what it was. It turned out to be a fairly old 26in. GEC set of the C2110 variety. Tim felt at home with this type of set and had no qualms about undertaking the repair. The two chaps departed, having given their details, and said they would return later that afternoon.

Tim removed the back cover and went straight to the fuse on the upper left side. It had failed but wasn't blackened. Tim fitted a new one and switched on. The sound came on and the e.h.t. rustled up and Tim felt pleased that he had taken this short cut. The fuse then curled up an failed, and Tim stamped his foot in anger.

He checked the lower centre power unit which said it was in order - the thyristor, the electrolytics, everything. He then checked the line output stage carefully. Again no fault. He remembered Beardy's 3500 and disconnected the tripler, then fitted a new fuse and tried again. The sound burst out but the new fuse died as the previous one had. Tim reconnected the tripler and disconnected the line output transistor. Another new fuse was fitted and this time it held. Tim didn't suspect the line output transistor but changed it just the same. He disconnected all the l.t. lines from the line output transformer just in case then tried again. The fuse failed after thirty seconds. Feeling a bit fed up, Tim tested all the items associated with the line output transistor's base. Everything was in order, but then they would be if the failure occurred only when the set was working. So it would have to be panel replacement.

Tim thought hard, which was something he was not used to doing. What if a replacement panel was fitted? Would they be prepared to pay? Tim put the set to one side.

When the owners (carriers) returned, Tim asked them how much they were prepared to pay for the job. "Somewhere between five and ten pounds" was the answer.

"Clear off" said Tim angrily. So they carried it off and Tim sulked. All that time and worry wasted. He would have to change his ways. But why should he? He'd been doing this job for forty years or so and he wouldn't change now. Oh for a couple of nice G11s.

Mrs Fidler and the G11

Just then the phone rang. It was nice Mrs. Fidler who lives on the outskirts of town. Tim had sold her a Pye G11 some years ago and this was the first time she'd been in trouble. Nice Mrs. Fidler, a young sixty year old, who had her mother living with her.

"Hallo Mr. Tim. Can you come and fix my telly? The tube's gone."

"How do you know the tube's gone Mrs. Fidler?"

"Because there's a white line across the screen. Our neighbour had the same thing and Snappy Repairs took the set away and fitted a new tube. It only cost them eighty pounds."

"I'll come and see to it Mrs. Fidler, and promise it won't cost you eighty pounds." Tim packed his bags and made sure he had some 800mA fuses, a TDA2600 chip and a chip holder. He sped up the road avoiding the dogs who were chasing a bitch on heat. When he arrived he whipped the back off the set and switched it on. There was a supply to the field output stage so the fuse was intact. He unsoldered the TDA2600's heatsink and removed it, having checked that the base of the holder had not been overheating and had no dry-joints. The new TDA2600 was fitted and the heatsink replaced. Upon switching on a nice picture appeared.

"Oh Mr. Tim. It wasn't the tube after all."

"No dear. You're not the only fiddler in town I fear." By the time Tim got back to the shop the phone was ringing. "The white line is back Mr. Tim."

Tim cursed himself. He hadn't checked the 470μ F h.t. reservoir capacitor. He sped back, carrying a replacement capacitor and another TDA2600. Tim looked sheepish when he got there. He removed the 470μ F capacitor from the power board. It was a red one and the tags were blackened. After fitting the new welded one and the TDA2600 Tim was rewarded with a nice clear picture. "You're lucky Mrs. Fidler. This could have cracked the tube."

Letters

THE TX9 THYRISTOR PSU

Gordon Haigh's article on servicing Ferguson TX9 thyristor power supplies, in the July issue, was timely and interesting. Anyone who has to face these sets in the field will welcome the wealth of advice and information given in the article. Although the TX9 chassis was basically very reliable, the PC1001 and PC1040 versions were prone to fuse blowing caused by repetitive spikes on the mains supply at or near the a.c. waveform's zero-crossing point. Ferguson introduced several modifications, mentioned in the article, in an attempt to overcome the problem. These were successful to some extent but the problem of fuse blowing persisted until the arrival of the PC1044 version with its switch-mode power supply.

If the fuse blows while the receiver is working, a replacement fuse restores normal operation and all seems to be as it should be in the receiver it's likely that the cause of the fuse failure is a spiky mains supply – domestic appliances in the same house could be producing the mains interference.

A few years ago an "unofficial" modification appeared. This altered the operation of the power supply in a way that avoided the spiky mains problem. It consisted of adding a second thyristor to the circuit. An outline sketch of the arrangement is shown in Fig. 1. Both thyristors are triggered via transformer T1 and both are fed with mains a.c. at their anodes. Ferguson made the modification



Fig. 1: Thyristor power supply modification for the Ferguson TX9 chassis. Note that in the PC1040 version W66 is omitted and R165/W67 are interchanged.

TELEVISION AUGUST 1987

"That's what I told you, Mr. Tim."

"I... er. Oh, never mind. Just joking. Goodbye Mrs. Fidler. Have a nice day."

Tim slunk back to his little shop and told Tinker Bell all about it.

"I've heard you tell a million people about that capacitor and what it can do. And when it comes to it you don't bother to check it yourself" she said.

"I know, I know. Silly me."

Wickman Fuses

Oh, incidentally, Wickman fuses (see last month). Ferguson don't call them that. They refer to them as "circuit protectors". They seem to be the same however, like a small black transistor with two legs. But order them as circuit protectors from Ferguson, Wickman fuses from Philips.

available for the PC1040 board and developed a small modification kit which was issued to some of the more desperately plagued dealers. It can also be applied, with care, to the PC1001 version. The extra 470Ω resistors are $\frac{1}{8}$ W types and the thyristor labelled SCR4 should be of the same type as SCR1. Where W66 is fitted it can be removed: the network C142/R173/W74 across SCR1 can also be removed.

This modification made life a lot easier for many service engineers.

Harold Raven, Nottingham.

THE FLAT SATELLITE TV AERIAL

Publicity has been given recently to a small, flat, wallmounted domestic aerial for satellite TV reception. It's certainly an extremely appealing idea and has been generally welcomed. For the present and for the forseeable future however it's likely to remain just a concept. There's no question of a new generation of flat "dishes" suddenly replacing the conventional parabolic dish. In the fullness of time the flat satellite TV aerial will undoubtedly come into its own, but at the moment its development is inhibited by manufacturing costs and the challenge of perfecting viable electronic steering from satellite to satellite.

It's claimed that the cost of a flat dish aerial is thirty per cent higher than that of a parabolic dish giving the same performance, and that a smaller surface area is required for the same performance. This cost figure could be a gross underestimation in view of the fact that the main receiving elements on the flat aerial must be etched to provide $\frac{1}{4}$ or $\frac{1}{8}$ wave sections with a manufacturing tolerance of less than a thousandth of an inch. The distances between the large number of these sections have to be maintained at an even closer tolerance. In addition, the surface must be kept perfectly flat. If these criteria are not meticulously adhered to the signal picked up by some of the sections may be out of phase with the signal picked up by other sections, the result being phase cancellation.

At its current stage of development the flat aerial, whether mounted on a roof or wall, would need a conventional azimuth/elevation mount and would require the same degree of care in alignment as a conventional parabolic dish. An electronically steerable flat aerial could indeed be mounted in an arbitrary position, but electronic steering is a long way off and is unlikely to be available in the consumer satellite TV market. Electronic steering is expensive because it needs a powerful microprocessor to provide control. The flat aerial would have to have a larger surface area than a parabolic dish that's mechanically steered to point directly at the satellite – deviation in either azimuth or elevation reduces the effective area of a flat aerial. The flat dish is really suitable for use only with the high-powered DBS satellites that are not due to start transmitting to the UK until 1989/90.

I hope that these observations will have put the flat dish development into a more realistic context and timescale. Yes, the flat aerial is coming. But not yet. The conventional TVRO parabolic dish will be with us for a good long time to come.

Michael J. Stone, Chairman and Technical Director, Satellite Technology Systems Ltd., Bristol.

RECENT PHILIPS TV CHASSIS

I found Harold Peters' article (June issue) on recent Philips CTV chassis most interesting. My own set is an upmarket stereo "glass plate" model fitted with the System 4 chassis. The overall performance is excellent, though I've experienced many of the problems outlined in the article plus a few others.

My receiver has the TRD4 tuning system and has suffered from the usual drifting symptoms on BBC-2 (channel 64) only. Philips advised tuning the set upwards, in the manner described by Mr. Peters, some five-ten minutes after switching on from cold. D6107 also failed, causing height shrinkage with top foldover.

The most obscure problem to date however was a tendency for the power supply to shut down (usually preceded by field collapse) and then immediately start up again. This would occur at intervals after about an hour from switching on, and seemed to be aggravated by thumping the back cover in the region of the line output transformer. I searched for dry-joints to no avail. For some reason, probably rage, I gave a sharp tap to the side of the large (small) signals panel and the fault revealed itself. The power supply started to switch on and off continuously and E1 appeared in the display. I could hear a faint clicking from the line output transformer and noticed a tiny flashover. Choke L5163 in the h.t. feed to the line output transformer was mounted very close to the transformer's body and was arcing across. Moving it sideways cured the problem.

I also have a Model 934 fitted with the KT3 chassis. This is six years old and is 100 per cent reliable. I would like to modify it to take a 1V p-p composite video input and would be interested in hearing from anyone who has done this.

John Wood,

John Wood Photography, Newcastle-upon-Tyne.

Editorial comment: Since the KT3 has a live chassis a mains isolating transformer would be required for a start. We would be happy to pass on or publish any comments from readers on the feasibility of this modification.

MAINS SUPPLY PROBLEMS

I am grateful to L. Hutchinson and Peter Chadwick for raising the important points in their letters in the June issue.

The advice concerning the repositioning of the antiglitch capacitor to avoid supervisory tones blowing 50mA mains fuses was supplied in the first instance by the importer of the merchandise affected, and I cannot claim originality for it! Tones of quite large amplitude were used at the time. They could be heard in some appliances, like electric radiant heaters with a slack element that vibrated. The advice was given to the trade and presupposed a degree of common sense in the choice of fuse for the mains plug. Doubtless the practice is now falling into disuse as digital techniques take over.

In attempting to keep strictly to the point in my article in the April issue I unfortunately had to miss out reference to RCCB- and PME-type installations. In my experience the installation of an independent earth completely free from any connection to the water supply or the earth provided in the domestic electrical installation is fraught with problems. Whatever one does is relatively short lived. Burried copper plates corrode away in the soil and require frequent watering to remain efficient: even galvanised copper rots away eventually. My QL computer refuses to work for long on "raw" mains and has to be run either from batteries or a constant-voltage transformer.

The moral of course is that you must be careful with raw mains – I still keep one hand behind my back! Whenever there is any doubt about an installation the area Electricity Board should be consulted. They are usually very helpful. Sometimes an isolation transformer is required to make a completely safe installation. Often such a transformer is in itself sufficient to remove any unwanted garbage, though the cost is naturally greater than that of a filter.

J. LeJeune,

Nottingham

COMPUTER AS A SERVICING AID

I have been using a computer in my business for about five years now and have therefore been interested in the articles published recently in *Television* on the use of computers for storing service data.

In some cases the search for relevant information on the set that's being repaired can take as long as the repair itself, and is thus both time consuming and costly. The articles have referred mainly to the dBase II program, which runs on the IBM and its clones. This is complex – some of the command instructions must be frightening and seem almost gibberish to the beginner – and expensive unless you already own or use one of these machines and are familiar with its operation. All is not lost however. There are easier and cheaper database programs that will do almost as well on a more readily available home computer.

I use the well known and now very cheap Sinclair Spectrum computer, with an Opus Discovery disc drive. Any Spectrum will do (except the early "beige key version", issue one, which cannot be upgraded to 48K memory now as the bridge panel is no longer available). Spectrums may be found lying around unused or can be bought for around £40. The Opus disc drives cost around £80 if you can find one secondhand. Even new Spectrum Plus computers sell for only £70.

The database I use is Masterfile, by Campbell Systems. It will hold about 29,000 bytes of information. I use it as an index file with all the relevant data from your contents page plus the model(s) and number(s) of any sets referred to in the articles. I find that an index for a full volume (twelve issues) occupies around 24K, so there's room for extra "special references" to be added.

My method is to use the computer to search for the
pages that refer to the set I'm working on in the volumes of *Television* and then select these copies from my collection of the magazines. I use three search routines: Title of article; Details of the first part (128 characters) of the contents' description; and Extra details, which covers the rest of the description. I use D for the most frequently used references to sets I service and E for the less frequently used items in TV Fault Finding, VCR Clinic, Service Bureau and similar articles, and from these three searches I can find all the articles in a particular volume in a very short time.

I can load any other volume index I've compiled from the Opus discs in about twelve seconds. It would take about three minutes from tape. So finding the articles takes quite a short time. There's not enough room in the Masterfile database for much technical data, but it's very easy to delete references that may not be used regularly and thus make extra room for such details as may be required. I've compiled full indexes for volumes 35 and 36 and would be prepared to supply copies of such data files on tape at £1.80 each, including VAT, post and packing, to anyone who already has the Masterfile program. If there's a demand for them I'll compile indexes for earlier volumes, and of course for volume 37 when this is complete. I would be prepared to give a fuller description of the way to modify the data and how I use the files. For example, since I service mainly Philips and Pye sets I went through the existing Master data files and eliminated the references I didn't need. I saved these as Philips 1, 2 and 3, then using a combined program I have for Masterfile datafiles I combined all these three into one. This would be possible for any make of set, and the Masters can be retained unharmed. It makes searching very much faster for the brands a dealer may handle. Anyone who has a Masterfile for the Spectrum could load the indexes from my tapes and use them straight away or modify them as required.

John H. Cowing, High Humbleton, Wooler, Northumberland NE71 6SU.

A WORD OF WARNING

A few weeks ago someone planted a colour TV set full of old PCBs and rubbish, including a spring-terminated 6V battery, on my doorstep at around two o'clock in the morning. My dog barked but the clowns had gone. I've also had TV sets etc. left on my doorstep with a note attached saying please repair and I'll call in two days' time – sometimes a phone number is included. One of these sets was a joker. On taking the back off there was a microswitch stuck to the cabinet, with its button held in by the back cover. This was wired to a battery and a Veroboard with a 555 timer circuit and a buzzer. It was a bit of a surprise when this went off but thank goodness I'm here to tell you!

When I thought about this it reminded me of the hoax bomb made up of a water-filled balloon with batteries tied to it. This was found at the Christmas party in our local gay club disco. We got rid of it during a break in the festivities, but what if it had been a real bomb?

It seems that the targets of this sort of thing are mostly dance and disco and gay clubs. If you find one, get the battery out and treat the item as suspect. I try to help out repairing appliances, TV sets and so on belonging to fellow unemployed people. In conclusion, I'd urge readers to take care.

Ian Ruddock, G8NCZ, Stanstead Abbotts, Herts.

TELEVISION AUGUST 1987

next month in

TELEVISION

INTERFACING THE VM6101

In the September 1985 issue Keith Cummins described the use of the Tifax XM11 decoder as a teletext adaptor for the Sony KV1820UB, showing how a set not originally designed for such use could be modified to give satisfactory teletext operation. Unfortunately, changes to the broadcast teletext signal since then have caused problems with the XM11 decoder, which was designed before the final teletext transmission standard was agreed. So Keith decided to redesign the adaptor project for use with the Philips/Mullard VM6101 8748 decoder, using а programmed microcontroller chip to interface a modified XM11 type keypad with the VM6101. The exercise ended up giving very good results.

MAINS SUPPLY CHECKER

The possibility of electrical shock from equipment connected to the mains supply is ever present, especially when a customer's supply has been incorrectly wired. Gordon Haigh describes a very simple plug-in checker, using just three neons, that enables you to see at a glance how the socket outlet has been wired. Something that field service engineers should find well worth carrying with them.

COAXIAL CABLE TV

In the second part of his account of cable TV techniques J. LeJeune describes the planning of a coaxial distribution system and the vital passive hardware used for signal splitting, teeing off and tapping.

• A LOOK AT SALORA SATELLITE RECEIVERS Time we thought to take a look at the signal processing in a representative satellite TV receiver unit. The Salora units provide a good example, with straightforward and easy to follow circuitry. PLUS ALL THE REGULAR FEATURES

Order your copy on the form below:

TO.....(Name of Newsagent)

Please reserve/deliver the September issue of TELEVISION (£1.30), on sale August 19th, and continue every month until further notice.

NAME

ADDRESS

691

TV Fault Finding

Zanussi ZA374 Chassis

We fitted this set with a teletext adaptor kit. After doing so we found that no pages above 199 could be selected. Several days were spent testing, phoning and headscratching before the cause of the problem was found – the ITV text transmissions from certain transmitters were out of tolerance. The following procedure provided a cure:

(1) Switch the set on and select ITV text.

(2) Select mix.

(3) Ground pin 22 of CI1 (SAA5230). This will give the effect of weak sync.

(4) Adjust the crystal trimmer C28 until the text information begins to run from left to right across the screen – the text information should take approximately three seconds to run across the screen.

(5) Remove the ground link from pin 22 of CI1.

This adjustment cures the fault which is caused by a variation in the timing of the transmitted text signal and the inability of the crystal, because of its precise frequency, to cope with this variation. The crystal used in the latest teletext conversion kits has a wider bandwidth, so this fault should not occur. It's possible that a similar fault could be experienced with some Philips chassis that use a similar combination of CPU chip and crystal. A.R.

Mitsubishi CT2627

This new set suffered from height variations and occasional field collapse. The fault was very intermittent and the use of a hairdryer and freezer didn't help. We found that the problem lay with the field output transistors Q402 and Q403. Mitsubishi say that the output coupling capacitors C412 and C413 (both 330μ F) should also be checked – their value is critical. M.Du.

NordMende FV Chassis

Set dead was the complaint. H.T. was present up to the anode of the flyback thyristor DU16 but there was no other life. A scope check showed that there was line drive output at pin 15 of line oscillator panel Z. There was also a waveform at the gate of DU16, but no other life. While we were working in this area the set suddenly came to life. The problem was traced to a dry-joint at one end of one of the line output stage tuning/coupling capacitors, CU16 (82nF). When we had resoldered this the set worked correctly, but after a few hours on test it failed. We had to replace DU16. M.Du.

Sharp C1415

This set had been dropped and the complaint was that the search tuning intermittently wouldn't work. We traced this to a crack in the print around the rear edge of the board, at the back of the tuner. M.Du.

Sanyo CTP5101

This elderly colour transportable came in with the complaint that the sound was o.k. but there was no picture. We checked the tube voltages and found that the grids were at 200V negative. This was because R617 $(330k\Omega)$ which provides bias from the first anode supply had gone open-circuit. When this resistor was replaced the set produced an excellent picture with the tube still in good condition. We also had to clean the push-button assembly and the line hold control. M.Du.

Etron EC142

This imported colour portable came in with the complaint that the tuning would intermittently drift off. The fault appeared on soak test and we found that a gentle tap on the front panel near the push-button unit would restore normal working. When we removed the front control panel the cause of the problem was obvious. Q700 in the 33V supply to the tuning presets had been soldered into the board and then twisted, with the result that its legs were intermittently shorting. Untwisting it cured the problem. M.Du.

Decca 80 Chassis

The complaint with this set was that it was dead. We switched on and found that the output from the power supply was correct. Our next suspect was the 5·1k Ω (or 6·8k Ω) line oscillator start-up supply resistor. This proved to be o.k. however. When we started to make voltage measurements around the TBA920 line oscillator chip we found that the set sprang to life when the meter was touched to either pin 3 or pin 4. Once it was working however the start-up resistor still got hot, with the 12V supply voltage low at 8V. The problem turned out to be that D302 (1N4148) was open-circuit. This diode provides isolation between the 12V rail and the line oscillator's start-up supply. M.Du.

ITT 80 Chassis

This fault had everyone baffled. The set produced a blank raster with a bright squiggle down the centre, like partial line collapse. The electronic tuning wouldn't tune either. The fault turned out to be due to the mains rectifier's reservoir capacitor C606 (220μ F) which was open-circuit. As a result there was ripple on the h.t. line. **D.A.B.**

Fidelity ZX2000 Chassis

The TDA2581 chopper control chip and the chopper transistor were both faulty. These were replaced but no reason for their failure could be found – all the usual things were tested. We noticed that an enormous amount of lacquer had been applied to the set and when we switched on we found out why! Arcs flew everywhere from the top of the line output transformer. After replacing this there was no field scan as the TDA1170S chip had failed, then no colour because of another faulty chip (TDA1365).

Sony BT871 Tuner

The BT871 u.h.f. tuner is used in several older Sony CTV models including the KV1400 and KV1810 – it's the long narrow one with quasi-phono sockets for the signal input



Fig. 1: Trouble spot in the Sony BT871 tuner.

and output. We've had several examples that have suffered from intermittent tuning drift which can usually (but not always!) be instigated by tapping or squeezing the tuner. The cause has in all cases been a bad joint between the earth print land and the screening wall on the r.f. side of the mixer/oscillator compartment. Fig. 1 shows the trouble spot. E.T.

Rank T22 Chassis

This set came in with a leaky BU208A line output transistor. After checking for other faults the BU208A was replaced and the set was put on soak test for a couple of hours. A few days later it was back with the same fault. This time we discovered that someone had fitted a 1.5Ω instead of a 1Ω resistor (5R8) in series with the BU208A's base. Assuming that this was the cause of the trouble we replaced 5R8 and the BU208A. This time the BU208A lasted for only a few seconds. Careful examination of the BU208A's base circuit revealed a dry-joint at pin 3 of the line driver transformer. Resoldering this and fitting yet another BU208A produced a good picture and no further trouble. M.D.

Sharp DV1600

This set would intermittently go into the standby mode. Due to the intermittent nature of the fault it took us a long time to discover the cause. Once it had gone into standby, which could take anything from three hours to three weeks, the set couldn't be switched back on unless it was allowed to cool for about an hour. The last time it went into standby repeated switching on and off gave the fault away - there was a vertical line from top to bottom (line collapse). Now the line scan coils are connected to the collector of the 2SD869 line output transistor via a bolt which is soldered to the print: the other bolt that secures the transistor is connected to the line output transformer. A circular ring (dry-joint) was noticed round the former bolt. This was the cause of the fault and after resoldering with a 140W gun to provide a good solid joint there was no further trouble. M.D.

Thorn 9600 Chassis

This set had no sound or picture, though e.h.t. was present. When we made a quick check on the power supplies we found that the 34V supply was missing, with F511 (500mA) open-circuit. An ohmmeter check from the fuseholder to chassis showed a dead short which was traced to C171 ($6\cdot 8\mu F$) on the decoder panel. After replacing this item and the fuse the set was found to be tripping. This time the 34V rail was a good 10V low at

TELEVISION AUGUST 1987

24V. The cause was traced to the 24V regulator transistor VT812 which was short-circuit collector-to-emitter. When this had been replaced normal working was restored.

M.D.

Rank T20 Chassis

I still get these sets with a BU208 fitted instead of a BU208A. This one was starting up and there was plenty of audio noise. Occasionally a channel could be tuned in. The h.t. voltage was varying wildly around 110V instead of being steady at 200V and there was no e.h.t. of course. The BU208 had developed leaks between all three connections. The owner swore that the set had had only a replacement on-off control. Oh yes, and they'd been having trouble with the line collapsing. Another fine burn up you've got me into Stanley! **R.B.**

Murphy V1400

No field scan on this Hitachi-looking set was due to C408 $(1\mu F)$ being open-circuit. R.B.

Rediffusion Mk. 3 Chassis

The problem with one of these sets was low, distorted sound which at first was intermittent. Replacing the audio driver transistor's load resistor 0R71 (820Ω) provided a cure – use a 1W resistor in this position. Another of these sets had washed-out video, with the contrast and brightness controls inoperative. The cause was the chroma demodulator chip 2IC1 (MR1327P). R.B.

Pye 731 Series Chassis

The fault with this set was no green. The usual voltage checks were made and the resistances in the circuit appeared to be within normal tolerances. I noted however that the TBA530 matrixing chip's green output load resistor R458 was about $43k\Omega$ instead of $39k\Omega$, and to my amazement found that the relevant part of the chip shuts down when the load resistor value exceeds about $42k\Omega$, thereby switching off the output transistor. **H.MacM.**

Grundig GCS 100/200 Chassis

The fusible resistor R607 would open now and then. I eventually found that the cause was that old favourite with the G8 and G11 chassis – the insulating pad under thyristor Ty501 sometimes read about 500Ω to chassis.

H.MacM.

GEC C1407H

The fault with this set was no colour and weak contrast, with all three controls (colour, volume and brightness) doing very little. We went about this in rather the wrong way, by checking the voltages around the single chip decoder. No significant errors were found and the sandcastle pulse was present. A helpful GEC technical representative suggested a careful check on the shape and amplitude of this pulse as the decoder chip does odd things if this is even mildly incorrect. The pulse was correct however and after further investigation we found that the 12V supply to the controls was missing due to a hairline crack. Isn't it strange how you can convince yourself that a fault is going to be a pig even before you start, then you lead yourself up the garden path! S.L.

Servicing Mechanical VCRs

Part 5

In the last instalment (June issue) we looked at the rather horrendous but clever part of the mechanism whose sole function is to make the drive arm move one way when play, record or audio dub is selected and return it when stop is selected. The bulk of the mechanics below the deck are concerned with this operation and don't cause too many problems.

The drive arm is the prime mover for the loading arms and for the first part of the pinch roller's travel, before the solenoid takes over. Subordinate functions are: moving the loading arm lock levers which operate the "stoppers" that hold the guide rollers and slant poles firmly in position; releasing the reel brakes; allowing the backtension device to engage; and moving the take-up clutch into position.

All the electrical functions are carried out by the row of microswitches above the keys, the UL and AL switches on the deck, and the two slide switches on the audio/servo or audio only (3V16) board. The first two of the above groups mainly switch supply rails: the slide switches are concerned with audio and erase switching. Control of much of the servo and signal circuitry is achieved by switching supply rails.

Loading Arm Mechanism

We'll start this month with the loading arm mechanism. Movement is initiated by a pin on the slide plate: it engages with a slot in the drive arm – see Fig. 1. The adjustable link at the other end of the slide plate moves the rotary lever and its two attached links which move the loading arms into position. At the completion of loading a wire link from the rotary lever partially rotates the tension cam: a projection on this passes up through a slot in the deck. This projection releases the back-tension arm from its parked position, allowing the pole to contact the tape. The back-tension device is in fact a mechanical servo: the brake is pulled off if the tape tension increases.

The drive arm also operates the loading arm lock levers. Primarily (see Fig. 2) these move the two lock arms into position during the final part of the loading cycle. These lock arms carry the alloy impedance rollers (plastic on the Mk. III deck), also the stoppers that lock the slant pole/guide roller assemblies (see Fig. 3) in position. The lock arm on the supply side also carries the full erase head. A projection on the loading arm lock lever on the take-up side moves the pinch roller slide plate (see Fig. 2) which brings the pinch roller into the pause position, releases the reel brakes, and engages the take-up clutch.

It's useful to study the detailed operation of the slant pole/guide roller assemblies as they tend to cause problems in ageing machines. Each assembly consists of a cast base into which a slant pole is pressed and a guide roller is screwed, the latter being locked with a setscrew – see Fig. 3(a). The guide roller has a plastic centre section which should rotate freely on the metal pin. The guide rollers are vertical, but the slant poles incline in opposite directions. The only other item in the slant pole base is a steel pin that engages in a notch in the locating block (part of

Mike Phelan

the drum base). This determines the height of the assembly when loaded. The slant poles also locate in a pair of V notches in each block, giving registration in the horizontal plane.

An angle bracket to carry the slant pole base is screwed on to the end of the loading arm. The base is not rigidly attached to this - it's allowed considerable freedom of movement. This is achieved by means of a screw with an integral spacer and an enlarged hole for the bracket. The purpose of this arrangement is to allow the base to be located purely by the pin and slant pole without the loading arm having any influence on its position. Furthermore, although the angle brackets are firmly screwed to the loading arms the holes are large enough to allow adjustment.

During the loading cycle, once the loading arms are in position the lock arms move forwards and the stoppers engage the guide rollers, holding each assembly rigidly. It's important that the stoppers don't play any part in moving the loading arms into position. If, through misadjustment, this happens the guide rollers and slant poles cannot be rigid.

Problems

The problems that occur are many, and are often increased by previous unskilled repairs. The loading arms and associated parts are critical as they determine the path of the tape.

Probably the most common problem is caused by the method of driving the loading arms. They are both propelled forwards by adjustable links attached to the rotary lever. That on the take-up side has a peg which projects down through a curved slot to take the link. This peg occasionally becomes loose, requiring rerivetting or replacement of the loading arm. The supply loading arm is moved by a short arm which is attached to its pivot by a single screw. The pivot has two flats to locate the short arm. If the screw works loose the flats wear and the hole in the short arm gets chewed up. The cure is to replace both components. See Fig. 4 for details of this trouble spot. To check for this problem, press play with the machine switched off, then turn the flywheel until the machine is half loaded. Grasp the right-hand (supply) loading arm and check for excessive movement in the direction of travel.

It's important that the loading arm pivots are free and lubricated – they sometimes seize up due to corrosion of the plating. Unfortunately they have to be dismantled to lubricate them – this requires removal of the lower drum assembly. A useful tip here is to unplug the pre-rec board instead of unsoldering the rotary transformer leads, then remove the board and lower drum as a unit.

Tape path errors caused by the loading mechanism require careful observation while the flywheel is being turned by hand. The pole/roller bases must not foul the deck or drum base, and they must be free to locate in the notches without being forced one way or the other. If the latter occurs the angle bracket is probably bent or misplaced. Slacken the screws, load, then tighten. Both bases



Fig. 1: Loading arm drive system.



Fig. 2: Simplified diagram showing the loading arms in the almost fully loaded position.



Fig. 3: (a) Details of the right-hand slant pole/guide assembly and the left-hand side opposite angle. (b) Cross section when in the loaded position.

must reach the loaded positions simultaneously. If one gets home first either the flats on the supply arm are worn or the adjustable links have been altered.

It's sometimes easier to check the movement of the loading arms after removing the slide plate, but note the positions of the polythene washers.

The back-tension cam doesn't give any trouble, but if anything is sticking here the back-tension pole can remain outside the tape loop, causing incomplete tape wrap. The result is that in the record mode approximately a third of a previously recorded picture remains – this produces a very wide noise bar on playback.

The pinch roller slide plate can get stuck to the deck

TELEVISION AUGUST 1987



Fig. 4: Details of the loading arm links.

plate with spillage, causing sluggish action.

The loading arm stoppers should contact the guide rollers squarely: watch out for misplaced erase head wiring that prevents this.

A fairly common fault with several causes is the intermittent appearance of a noise bar at the top or bottom. It can be cleared by adjusting the guide roller(s) but reappears in time. The most common cause is that the setscrew on the guide roller is loose. If it's not slackened before adjustment the thread will be damaged. Slacken only sufficiently to allow the roller to be moved - if it's too loose the tape motion can disturb the adjustment before you tighten up. The same symptom can be caused by anything that prevents positive location of the pole/roller base assembly. One reason for this can be a burr on the notch that takes the pin. Another is foreign matter compressed into the same notch. Don't forget about the drive arm lock roller (see previous instalment). If this jumps out at the completion of loading the loading arms can move back imperceptibly.

Don't alter the positions of the two locating blocks. This is no consolation if someone else has! All you can do in this case is to hope that the locking paint gives a clue to the original positions.

It goes without saying that parts such as the slant poles, guide rollers and impedance rollers should be smooth and undamaged. The same applies to the full erase head, whose surface is rather brittle and easily damaged.

Reel Assemblies

There are not too many problems when it comes to the reel assemblies. The height of the reel discs, which is adjusted with shims, is not too critical, but the discs are prone to seizing on their pins, especially with the Mk. III deck. Note that the Mk. III uses plastic rings in place of circlips to retain some parts, including the reel discs.

All rubber tyres require replacement periodically. The first one to wear out is that on the take-up reel. It becomes glazed and slips instead of the clutch slipping. The result is a squeak on record and playback.

The take-up clutch is the real villain of the piece here. The felt friction washers become polished and the clutch then slips, driving the tape erratically but sufficiently to chew it up before the Hall sensor operates and stops the tape transport. The Mk. III version is better in this respect. Replacement is the only cure.

The unloading and reel idlers, and indeed the clutch, are prone to seizing up due to fluff winding itself around the spindles, but the first two give little trouble otherwise.

A loud screech on fast forward or rewind should direct attention to the counter pulley which loses its lubricant after a while. If it seizes up the machine trips out. This can be very intermittent and baffling – the clue is to watch the counter closely. A drop of oil suffices.

The brake mechanism gives little trouble if kept clean

697

and lubricated. Check that the unloading operation does indeed wind the tape back into the cassette -a fault here can be missed.

Back-tension Band

The back-tension band needs replacement periodically, and the back tension must then be readjusted. If a gauge is not available, a rough and ready way is to set it so that in playback the right-hand impedance roller is just moving and the back-tension lever is at about half travel. If the back-tension arm moves about considerably during playback, suspect a faulty pinch roller or take-up clutch or tyre – but try another tape first.

To Follow

up?

was 6.5V.

In the final article in this series we'll talk about the key assembly and any other odds and ends that have not so far been discussed.

circuit. The interference limiter in the sound channel was

unusual, employing both sections of another D77 in a

negative feedback arrangement that muted the first a.f.

amplifier stage (DH77) in the presence of short-duration interference pulses. Younger readers, reared on 625-line

TV, might well wonder what all the fuss was about. With

the modulation system used for 405-line transmissions the

receivers were very vulnerable to impulsive interference, especially from motor vehicles. This could result in large

white splashes on the screen, accompanied by a machine-

gun effect from the loudspeaker. In the days before the

compulsary fitting of interference suppressors the BBC

used to put out a short film designed to press home the

need for them. An irate viewer, unable to stand the

annoyance caused by a nearby car any longer, hurled a

brick at his TV screen whereupon the set, and the car,

both went up in two glorious bangs! The car, by the way,

was an old Austin Seven, which would now be worth thousands of pounds. I wonder if they really did blow it

The sound output was from a KT61, a large octal-based

"kinkless tetrode" capable of providing 4.3W as a class A

amplifier. Another of these valves was used in the field

output stage, but was in this case triode connected. It worked as a multivibrator in conjunction with an L63

triode, and had transformer coupling to the low-resistance

scan coils. Both the height and linearity (referred to as "form") controls were in its cathode circuit, consisting of

The line timebase circuitry was unusual enough to

deserve illustration (see Fig. 2). An L63 was used as a line

sync pulse inverter whose output pulses were coupled to another L63 via the secondary winding on the line output

transformer and C56. The line output valve was a Mullard

EL38 output pentode, which must have been a bitter pill for the designers who would no doubt have much pre-

ferred to stick with GEC valves, but an equivalent type

was not available. The L63 and EL38 acted together as a multivibrator, the drive waveform being generated across

C57. At the end of the scan there was feedback via the line sync pulse path. Wonder of wonders, flyback e.h.t.

was used, provided by an overwinding on the transformer

and a U37 soldered-in rectifier. The nominal e.h.t. voltage

 $1k\Omega$ and $10k\Omega$ potentiometers respectively.

Vintage TV: Early GEC Receivers

GEC and Sobell were part and parcel of the same group for so many years that it's difficult to recall the early days when the companies were separate and GEC produced some highly individual designs of its own. GEC is in fact one of the oldest names in the industry, its radio sets dating back to the earliest days of broadcasting. Sobell came along rather later, at the end of the second World War, and quickly gained a reputation for reliability – as evidenced by the unprecedented length of its guarantees. When the merger took place, in the early sixties, it was the latter company's designs that survived. The name GEC became yet another badge engineering job.

GEC had been in on television from an early stage, and at this point I must shamefacedly admit that many years ago I let one of their pre-war models slip through my hands. This was on the celebrated occasion (recorded in this column some time ago) when I had the job of clearing out a radio and TV shop's stockroom above a cinema in Newcastle-under-Lyme. There were two old TV sets amongst the spoils, one being a 5in. Marconiphone and the other a monumental GEC which in a moment of incautious generosity I gave to one of my erstwhile assistants. So, Gerald Horrox, if you read these words . . .

The BT1091B

I must start therefore with the first post-war GEC set I encountered, a 9in. table model known as the BT1091B. Its moulded cabinet held a large, single-deck chassis that carried 21 valves and the c.r.t. A two-screw quick-release system was fitted to make service access easy. Considering the general design of TV sets at around this time (the BT1091B was released in August 1949) the GEC set was refreshingly sensible and straightforward.

The receiver section was of the superhet type, using mostly Z77 miniature r.f. pentodes, but oddly enough an octal-based L63 triode was used as the local oscillator. The sound i.f. was extracted in the Z77 mixer pentode's anode circuit via a trap, there being no common vision/ sound i.f. amplifier stage. There were two vision i.f. amplifier valves followed by a diode demodulator (half a D77) whose output was passed to yet another Z77 which was used as the video amplifier. This stage was interesting (see Fig. 1) since it was an early example of what was to become quite common practice, the use of h.t.-derived standing cathode bias to improve the stability and overall frequency response of the stage.

The c.r.t. was driven at its cathode, the other half of the previously mentioned D77 acting as an interference limiter. Four preset clipping levels were available by altering shorting links across the resistors in the D77's anode Focusing was provided by means of an electromagnet which was fed from a negative supply derived from the centre tap on the mains transformer's secondary winding. This supply was bypassed by a variable resistor. The current through the coil was of the order of 150mA, the voltage being between 28-37V. Normal h.t. was supplied by a pair of MU14 rectifiers, each rated at 120mA and

Chas E. Miller



Fig. 1: The video circuitry used in Model BT1091B. Much work had gone into the design of the video output stage. Note the bias stabilising by means of R34 and the use of both series (L20) and shunt (L21/22) h.f. peaking coils. As a result of partial decoupling (C29) there is l.f. negative feedback at V7's screen grid while at very low frequencies R36 is added to V7's anode load due to partial decoupling by C30.

delivering 348V after smoothing. The mains transformer was of the fully isolated type, and an obscure feature was the provision of a separate l.t. winding for the D77 sound interference limiter valve. Although this valve had a heater voltage rating of 6.3V the winding supplied only 5.8V and was centre-tapped, the centre tap being connected to the focus coil's supply. Possibly a portion of this supply was used as bias for the valve.

The BT2147

In July 1950 the BT2147 made its appearance. This was a compact 9in. table model in a plastic cabinet. It was an excellent set with an advanced design for the period, but it tends to have been forgotten compared to the similar but more famous Bush TV12. GEC marketed models for London and Birmingham, the only difference being the detachable r.f. unit which made it easy to convert a set for use in a different area.

For some inexplicable reason the earlier superhet design was abandoned in favour of a t.r.f. receiver, but the rest of the circuitry took on a more modern appearance. There were on fewer than four vision r.f. amplifiers, again the redoubtable Z77s, three of them being common to the sound channel. A crystal diode was used as the vision demodulator, with the contrast control as its cathode load (see Fig. 3). The wiper of this control was d.c. coupled to the video amplifier valve's control grid (a Z77 again). This time the video amplifier had a single low-value resistor (5k Ω) as its anode load and its screen grid was connected directly to the h.t. line, with no decoupling. Half the inevitable D77 was used as an interference limiter, the other half being used as an interlace filter for the field sync pulses.

A B36 double triode did duty as the blocking oscillator in both timebases. The line output stage now used a boost



Fig. 2: The line timebase circuit used in Model BT1091B, an early example of the use of the output stage as part of a multivibrator circuit.



Fig. 3: The video circuitry used in Model BT2147. This time an RC I.f. attenuating network was incorporated in the feed to the c.r.t. cathode. C61 was 1.5kp in Midlands sets.

diode, but the voltage gain thus obtained was by no means as great as that in later designs. Once again a U37 provided the e.h.t., now 7kV. Marconi-Osram (the valve company jointly owned by GEC and EMI) had by now produced its own line output valve, the KT36, which was used here.

A permanent magent was used to focus the c.r.t. Normal h.t. came from a metal rectifier in a conventional a,c./d.c. circuit, and all the heaters were series operated. Voltage tappings were provided for mains inputs of 200-250V, with part of the rectifier being shorted out on the lower d.c. ranges.

A single separate sound r.f. amplifier had its output demodulated by the diodes in a DH77 which was followed by a much simpler crystal diode interference limiter circuit. N37 miniature output pentodes were used in both the audio and field output stages.

Later versions of this set had a superhet receiver unit which was tunable to all the Band I channels. I remember buying one of these from a customer, at a nominal price, more or less to do him a good turn. I casually asked what was wrong with it, and received the reply that "Mr. Blank (a well known local dealer) said the tube had gone and it wasn't worth repairing". The set had been sent in for field collapse! It was far from being the first time that I'd come across this sort of thing in connection with Mr. Blank, but as always it was hardly worth persuing the matter. The fault was in fact due to an open-circuit blocking oscillator transformer, and when this was repaired the set gave an excellent picture.

A Portable Conversion

This was in the days before portable TV sets were generally available, the sole example at the time being the Ekco TMB272. The little GEC set seemed a suitable candidate for a conversion job. I fitted a 13-channel tuner and wired all the valve heaters for series-parallel 12V operation, replacing such valve types as necessary with 6.3V equivalents. The line output valve was changed from a KT36 to an EL81 for example, and the U31 boost diode was changed to an EY81. H.T. was provided by an external vibrator power pack obtained from an ex-government surplus store and intended for use with the No. 19 tank set. The results were excellent, the sensitivity being more than adequate for most areas even with a short rod aerial. But I didn't enjoy them for long. The set was seen by a long-distance lorry driver who was so impressed that he made me an immediate, non-refusable offer. I often wonder what became of that set, for I never saw it again. The battery drain was fairly high - around 6-7A as I recall - but this would have been of little account with a heavyduty lorry battery.

Later GEC Models

GEC stayed with the removable r.f. chassis idea for

many years. In fact the basic design of GEC chassis varied ' little during the following years, apart from the fact that the timebase chassis was changed to vertical mounting. For a time the mains dropper resistor was replaced with a barretter, which was fine for dealing with mains variations but became difficult to obtain when it failed.

An ingenious converter was produced for use when ITV came along. It consisted of a plinth about four inches deep to house the tuner unit. This assembly was screwed to the bottom of the original cabinet. The selector switch was in a convenient place, central beneath the tube, and there was no need for elaborate drilling and fixing. These converters were difficult to obtain at one time, causing customers who had seen "Snow White and the Seven Dwarfs" to comment "some time my plinth will come", which proves that what this column may lack in class it makes up for in sheer nerve. Seriously though, the tuner was of the incremental type, having one Band I and two Band III positions. Since each channel had its own separate adjustments, it was possible to peak them up if need be to obtain extra gain at the expense of bandwidth. GEC used this type of tuner for a number of years, the performance being perfectly adequate as regards the choice of channels.

When 110° c.r.t.s appeared towards the end of the fifties GEC brought out its famous bow-fronted range, which had two vertical chassis and a twelve-position turret tuner. The line output stage was mounted horizontally beneath the tube, between the two receiver and timebase sections. Various versions of this basic layout took the company into the sixties and thence to the time of the merger with Sobell.

A Look at Capacitors

Probably the least understood, though important and often referred to, expression in electronics is that "capacitor current leads the voltage by 90°", i.e. the current flowing is at maximum when the voltage is starting to rise from zero and vice versa (see Fig. 1). This gives rise to the question "how does the current know what the voltage is going to be?" Capacitive current is given by the expression V/Xc, where Xc is the capacitive reactance or the capacitor's opposition to a.c., but this doesn't get us very far. In textbooks Xc is given as $1/2\pi fC$ where f is the frequency and C the capacitance in Farads (so 1,000,000 must be placed above the line for μ F calculations). Thus the reactance of an 0.01µF mains filter capacitor to the 50Hz supply is roughly $8k\Omega$, and 0.03A will seemingly be taken by the capacitor though it won't affect the supply meter. At the other end of the scale an 0.01μ F capacitor will have a reactance of some 16Ω at 1MHz, and by simple proportion the reactance of other capacitor values at other frequencies can be determined.

It's easy to appreciate that the current in an inductor lags 90° behind the applied voltage, since the application of d.c. to a coil induces an equal but opposing e.m.f. at switch on when the current is zero, rising at a rate dictated by the *LR* values until finally, when the counter e.m.f. is minimal, the current is at maximum and is dictated by the voltage applied across the coil's resistance. To a.c. voltages of course I = V/Xl, where *Xl* is the inductive reactance or $2\pi fL$.

Thus only a switch-on pulse is needed for the line

George Wilding

output transistor to initiate the rise of current though the highly inductive combination of the line output transformer's primary winding and the line scan coils, this current rise being limited, for scanning purposes, to the initial and most linear portion of the current curve. As the field frequency is only about a third of one per cent of the line frequency the loading presented by the scan coils is predominantly resistive, with only a small reactive component. Thus to obtain a sawtooth current rise we must apply a sawtooth input to the output transistor(s). Therein lies the reason for the totally different approaches re-



Fig. 1: Capacitor current-voltage characteristic – current leads the voltage by 90°. Because the voltage rate-ofchange is at maximum when it crosses the zero line, though the instantaneous voltage is zero the resulting charge/ discharge current flow is then also at maximum.

TELEVISION AUGUST 1987

700

quired to field and line output stage design.

Back now to the capacitive VI relationship. Consider first a battery shunted by a crowbar. The terminal voltage across such an almost perfect short will be minimal, but the current will be at maximum, with virtually all the battery's e.m.f. being developed across its internal resistance. The power output, being the product of V and I, will also be zero – since V is zero. Similarly, at the instant when a capacitor is connected across a d.c. supply source the voltage will be reduced to zero, subsequently rising in the usual manner to the initial supply voltage. Again we have the situation where zero voltage occurs at the same time as maximum current flow.

Turning now to the application of a capacitor in an a.c. circuit, consider the situation when the applied voltage waveform is falling in amplitude and is approaching zero – refer to Fig. 1 again. This rapidly changing voltage coincides with a high current flow that reaches a momentary peak when the voltage rate-of-change is at maximum. This is the point where the instantaneous voltage is zero, and the current is reversing from the peak charging rate in one direction to the peak discharge rate in the other direction. Later, when the voltage reaches its peak value, the current is simultaneously at zero – there is no longer any charge or discharge current.

Power Factor

We can now see why capacitive current is termed wattless: the charge a capacitor accepts when the voltage is rising is returned to the supply when the voltage is falling. To a series connected ammeter however this current ebb and flow, constantly reversing in polarity, produces the same reading as the true current flow through a resistor of equal value to the capacitor's Xc. Clearly then when measuring a.c. power we must include another factor in addition to V and I, to allow for the phase relationship between these two. This is called the power factor, and ranges from zero in a purely capacitive or inductive circuit, when the phase relationship is 90° (as shown in Fig. 1), to unity in a purely resistive circuit when V and I are in phase. Power factor is expressed as $\cos \phi$, R/Z or true watts/apparent watts.

The aim of the power supply engineer is naturally to keep the power factor as close as possible to unity, for the "wattless" current of a pure capacitor or inductor will still cause a power loss when passing through the resistance of the power supply cables etc. The "goodness" of highvalue, high-voltage capacitors is sometimes expressed in terms of power factor, thus covering both shunt leakage and series resistance losses.

Capacitor Uses

In the component lists contained in manuals capacitors will, if their purpose in the circuit is given, be described variously as reservoir, smoother, filter, coupler, decoupler, pulse shaping, tuning, ramp generation and so on. Whatever their use, the end result depends on the ability of a capacitor to hold a charge, offer an apparent current flow path to a.c. or fulfill both functions at once.

Thus while the reservoir capacitor in a mains rectifier circuit must take up sufficient charge during the rectifier diode's conductive periods to maintain a reasonably level voltage during the rectifier's non-conductive periods, the associated smoothing capacitor must provide a low reactance path to the 50 or 100Hz ripple and act as the power supply source for the following circuitry. Obviously the effectiveness of this reactance is improved by increasing the value of the series resistor in such a circuit, so that this component develops across it most of the ripple.

With switch-mode power supply circuits that operate at a much higher frequency the values of the reservoir and smoothing capacitors used can of course be drastically reduced while still maintaining the same level of smoothing. This arises because for the reservoir capacitor the time between the charging pulses is very much shorter, while the high ripple frequency means that the smoothing capacitor's reactance is reduced in direct proportion.

The capacitive reactance required in any application is largely determined by the circuit resistance or impedance. Thus to filter out the residual i.f. from a video signal applied to an emitter-follower stage with an input impedance of about $100k\Omega$ the reactance of the shunt filter capacitor must be a fraction of this value - but not so low that it would offer a relatively low reactance path to the higher video frequencies. With the i.f. at 39.5MHz and the top video frequency at 5.5MHz, giving a ratio of just over 7:1, the optimum value is fairly critical. In practice therefore a series choke would be used with a shunt capacitor to form a low-pass filter. Whatever value capacitor is decided upon will have negligible effect if it's connected across the emitter load resistor. This arises because the value of the load resistor is only a fraction of the input resistance. For this reason emitter-follower stages are widely used following the detector in discrete component circuitry.

Similarly, a stray capacitance of say 100pF across the $12k\Omega$ or $15k\Omega$ load resistor in an RGB output stage will produce more h.f. attenuation than 100pF across the stage's $1k\Omega$ or $2k\Omega$ input impedance.

Decoupling

Everything depends on capacitive reactance values in relation to circuit impedance or resistance. To be at all effective the reactance of the capacitor shunting an emitter resistor must be a fraction of the resistor's value – ten per cent is the accepted figure.

Thus for i.f. and chroma amplifier stages only small capacitors are needed while for complete emitter decoupling of an audio or field output transistor an electrolytic type is called for.

With RGB output transistors and the video output transistors used in monochrome portables only partial emitter decoupling is employed. This is done to linearise the frequency response. Due to the increasing effect of the load shunt capacitance towards the top end of the spectrum the gain tends to fall off. By using a small-value emitter decoupling capacitor the stage gain is maintained at the higher frequencies but, due to increasing negative feedback, decreases as the frequency response. By careful choice of RC values, with often more than one RC combination, the stage gain can be tailored to yield optimum performance.

Without any emitter decoupling the base-to-chassis voltage applied as the input to a transistor is reduced by the oppositely phased waveform developed across the emitter resistor – these two waveforms are effectively in series opposition. For full decoupling, the capacitor should charge as the emitter current rises, the charge being returned as the emitter current falls. In this way the voltage change across the parallel emitter RC pair is minimised and the base-to-chassis input is almost wholly developed across the transistor's base-emitter junction.

Cable Television Techniques

Part 1

"Cable television" is a general term used to describe the distribution of primarily TV signals over a closed-circuit network - as opposed to radiating the signals so that anyone can pick them up via a suitable aerial. The term is applied to a variety of systems from a small communityaerial installation serving a block of flats to the mammoth multi-channel networks that cover whole towns and cities both here in the UK and abroad. Within the cable TV fraternity the preferred term for a small communal system is MATV, or "master aerial television", while large networks fall into the category of CATV, which has been variously defined as "community aerial television" or "coaxial television" - the latter term excludes of course the large number of multi-pair networks that don't use coaxial cable, so the all-embracing term "cable television" is most appropriate here.

Having established the basic terminology we should next consider the reasons for installing a cable television system. Today cable distribution may be adopted for any of the following four reasons - or a combination of the four. (1) To provide signals where reception is difficult or impossible due to site geography. (2) To allow a single array to be shared by a number of receivers in an attempt to prevent a mass afforestation of aerials. (3) To provide additional channels to those available off-air, as a commercial undertaking, using the closed nature of the network to prevent piracy of the signals. A charge is made for receiving such a service. (4) To provide an integrated communications network, with two-way traffic to allow viewer participation, and normal telephone and data transmission within the area covered by the network. Aims (3) and (4) can include the provision of a local TV channel for local news etc.

Radio Relay

These latter arrangements are a long way from a simple MATV system, and this is in turn a long road from the humble beginnings of cable TV. In fact cable distribution of signals began in the early days of wireless, when there was but one programme and radio sets were expensive and beyond the means of many people. In those days it was usual to have a d.c. mains supply and it was a relatively simple matter to superimpose on the supply an audio signal that could be picked off at the terminal unit by means of a capacitor, with chokes to isolate the audio from the appliances used in the house. This "radio relay" system brought the pleasures of wireless to many who could not afford a radio set, for the installation was cheap - just a loudspeaker with a transformer, a switch and a volume control. Commutator ripple from the generators at the local power station was a problem, and when more than one radio programme became available this method soon fell into disuse, helped by the widespread conversion to a.c. supplies.

Subsequently audio networks sprang up in towns where the population density was sufficient to warrant the cost of installing distribution cables. Various names were used for them – radio relay, wireless relay and wired wireless were amongst the most popular, though use of the word wireless was a terrible misnomer. Open pairs were used, carried on porcelain "dollies" in a similar fashion to the telephone wires of the same era. A pair of wires was required for each programme carried. The audio signals were distributed at high level from the receiving station: a power of 1kW into 600Ω was common, giving an r.m.s. voltage of approximately 800V!

For obvious reasons such a high level was not practicable for direct subscriber connection. The power of the trunk lines was stepped down for local distribution purposes, using bridging transformers that preserved the balance and impedance matching of the trunk lines. The directional properties of the bridging transformer prevented disturbances occurring on a branch of the distribution network affecting the whole system. Resistive attenuation was used for the subscribers' connections, giving a power of 100mW per programme - a level that was perfectly adequate and was unlikely to cause annoyance to neighbours. Programme selection was carried out by means of a multi-way, two-pole rotary switch. The volume could be regulated by a 25Ω potentiometer in the speaker transformer's secondary winding connections. The system was not designed for maximum quality but for efficiency and simplicity.

Adding TV

When World War II came to an end and the television service was restarted relay operators, as they were called, began to devise methods of carrying television signals on their networks. The attenuation introduced by the audio cables was too high to permit their use for v.h.f. signals, and this in turn made it impossible to use standard off-air receivers. The relay operators distributed the TV signal at lower frequencies, in the band from 3-10MHz, where the attenuation introduced by the cables was tolerable and the losses could be compensated by electronic means. The two major operators at the time, Rediffusion and British Relay, adopted this scheme, though their networks were not identical. Rediffusion allocated one pair of wires per TV channel, with the sound distributed at audio frequency. British Relay managed to add TV to an audio channel, the TV sound being on a 100kHz subcarrier. This latter arrangement gave cable economy, requiring fewer pairs.

The high TV signal attenuation caused by the cables required the use of repeater amplifiers to restore transmission levels whenever these fell to an unusable level. These repeater amplifiers had to be of a high linearity standard to prevent picture distortion and of a high reliability standard to ensure continuity of service. The subscriber terminal unit, as the receiver was called, consisted of an ordinary TV set minus the tuner and vision/sound i.f. section. In place of these latter items a signal-frequency strip amplified the signal selected from the distribution network to a level suitable for detection – the British Relay unit also required a 100kHz sound section.

Multi-channel networks depended on the maintenance of accurate balance in each pair to prevent crosstalk between them. Special cables were developed to aid this aspect of the operation, and latter-day networks are capable of good performance with simple equipment. As a result of the general availability of good off-air signals and the continuing decline in the real cost of TV receivers however many of these h.f. multi-pair networks closed down, the companies concerned generally diverting into television rental. The nature of h.f. multi-pair operation made it feasible only for large networks – the economics mean that large numbers of subscribers are required to make a network viable.

VHF Distribution

With the spread of the television service to more remote parts of the UK in the fifties, and with advances in valve, ferrite and coaxial cable technology, others entered the cable TV field, developing v.h.f. TV signal distribution via cables similar to those used for aerial downleads. V.H.F. operation permitted standard receivers designed for off-air reception to be connected to the system. This had the advantage that the user was freed from the limited choice of receivers on offer from the h.f., multi-pair operators. Subscribers could shop around for their sets, and if they moved house to an uncabled area they could take the set with them. Moreover one coaxial cable could carry several channels, with obvious advantages in terms of cable costs and aesthetics.

Increasing System Capacity

In more recent times satellite distribution of material for cable TV networks has meant that networks require greater channel capacity. Coaxial systems have for some years had greater channel carrying capacity than the programmes available – only in places such as Belgium, with four other countries on its borders, could sufficient channels be found to fill the network capacity. Holiday makers in Ostend will know that BBC and ITV programmes can be seen via the town's cable network.

To increase the channel capacity coaxial operators have gone to the u.h.f. bands, using trunk lines operating at v.h.f. (where cable attenuation is less than at u.h.f.) to distribute the signals for long distances with less need for frequent amplification. This gives better quality pictures at network extremities. Block up-conversion is carried out at the point where subscriber feeds occur, allowing standard u.h.f. receivers to be used. On the Continent, distribution at both v.h.f. and u.h.f. is used to achieve maximum coverage of the TV bands, standard receivers there being capable of v.h.f. and u.h.f. operation. Large networks such as these frequently use twin trunk lines, both operating at v.h.f., with alternate channels on the twin trunks (see Fig. 1). One trunk line is used with up-conversion to feed the subscriber distribution lines, the other feeding v.h.f. directly to them.

To allow more economical use of its existing networks Rediffusion followed British Relay practice, adding TV channels to pairs previously occupied by radio programme audio signals, with the TV sound on a 2MHz subcarrier. This made all the pairs in the system available for radio and TV simultaneously.

The h.f., multi-pair companies made one further development in an attempt to modernise their systems and increase the channel carrying capacity without having to add extra cables over the entire network. This was the Rediffusion "dial-a-programme" system (see Fig. 2). Prime-quality signals are sent by trunk line to the areas to be served, where they feed distribution lines or spurs which carry the signals through the neighbourhood. Subscribers are connected to the system via exchanges. A









Fig. 2: Basic Rediffusion "dial-a-programme" arrangement, a method of increasing system capacity.



Fig. 3: Simplified "dial-a-programme" installation.

single pair couples the exchange to the subscriber's terminal unit and also carries pulses from a dial that functions as the channel selector. The dial is depicted in Fig. 3 as an older, rotary telephone type, but others of more modern design can be employed.

The dial-a-programme concept is ingenious: it has obvious economies in terms of cable, is expandable, and the subscriber connections constitute less of an eyesore. The overall vulnerability of the network to pirating by people with a suitable terminal unit is minimal, and only the siting of each local exchange has to be considered carefully. Nevertheless, in the UK at any rate, the demand for cable TV services of this kind decreases annually. There's a danger of these mighty h.f. networks falling into disuse, as indeed so many already have.

In this first part we've looked at the history of cable TV and the reasons for it. For most readers interest in this will be only academic and it's pointless to go into h.f. system hardware. In part two we'll be looking at the development of v.h.f. and u.h.f. coaxial networks and in this case the kind of hardware in use will be described in some detail. Knowledge of how a coaxial network is planned, designed and commissioned is of benefit to readers who may either use such a system or service receivers connected to one. A good relationship between TV receiver suppliers and cable system operators is essential, and knowledge of each others' problems is a help in achieving this.

Service Bureau

Requests for advice in dealing with servicing problems must be accompanied by a £1-50 cheque or postal order (made out to IPC Magazines Ltd.), the query coupon and a stamped addressed envelope. We can deal with only one query at a time. We regret that we cannot supply service sheets nor answer queries over the telephone.

PHILIPS KT3 TELETEXT

There's a problem with teletext on this set – on all channels. The TV picture is o.k. with no ghosting but there's an intermittent teletext fault that varies between no text on the screen, or a jumble of letters, or a correct teletext display. Applying freezer to the teletext decoder chips and to various parts of the RGB circuitry hasn't pinpointed the cause of the fault.

Your problem is not likely to be due to chip failure in the teletext decoder though the SAA5030 VIP chip could be intermittent. We suggest that you check the tuning very carefully, retuning each station for best performance in the mixed mode. Note if this condition deteriorates when the drawer is pushed back. If so this would indicate that the a.f.c. is off tune. Mistuning can seriously affect teletext reception without showing the slightest impairment of the TV picture.

HITACHI VT9300

The following fault on this machine is intermittent. When play or record is pressed the tape threads and moves but there's no picture or sound on the monitor. After about five seconds the tape returns to the off position. The pause and search controls have no effect when the fault is present, but if the pause control is pressed on and off repeatedly the tape will continue to play - still with no picture or sound. If pause is pressed then released when the machine is working correctly it switches off, leaving the tape loose in the machine.

It's likely that these problems will disappear if you replace the loading belt (across the rear of the deck) and fit a new reel idler assembly of the modified (blue coloured) type.

DECCA 120 CHASSIS

The soft touch channel selector cannot be moved from channel one – even when the button contact is unsoldered. Since this channel cannot be tuned into anything but a very distant transmitter I suspect a supply voltage fault. Changing the SN76705AN chip on the channel selector panel has had no effect.

First check that the 12V supply is present and correct at pins 9 and 10 of the i.c. Then check RM17 (560k Ω). If this is o.k. and you are sure that the replacement chip is in good order change the four resistors, one diode and one capacitor associated with pins 2 and 8 of the chip.

GEC C2110 SERIES

The picture collapsed to a 2in. vertical band then the set went dead. On checking we found that the fusible h.t. resistor was open-circuit and that R617 and C605 in the raster correction circuit had burnt out. Is there anything else that should be checked?

In addition to replacing C605 and R617, replace the raster correction transductor T602 and check the condition and jointing of the associated components R615 and L603. If there's still partial field collapse when this has been done it's likely that the field output transistors will have been damaged.

SONY SLC5

Prerecorded tapes play back perfectly, but when one of the machine's own recordings is played back there's colour noise on the screen – short, fine dark horizontal lines moving into light areas. The sound is unaffected.

The symptoms you mention are typical of worn video heads, which is a common enough thing with these machines now that they are ageing. Prerecorded tapes will play back o.k. until the wear becomes greater because they have only one pass of the faulty heads – self-recorded tapes have two passes. It's unlikely that cleaning the head surfaces will provide any improvement though it's worth trying.

TV SETS AS COMPUTER MONITORS

My Acorn Electron computer works perfectly with a new 20in. Ferguson TV set and with monochrome portables but when used with 14in. Philips or Ferguson colour sets the display tends to wobble and flicker.

Since the computer works happily with some sets the problem is almost certainly due to overloading of the affected sets. It should be overcome by fitting a 6dB (12dB if necessary) in-line coaxial attenuator in the lead between the computer and the set's aerial socket.

PHILIPS G11 CHASSIS WITH REMOTE CONTROL

This set would go to standby when switched on but would go to a station when the remote control handset was operated. Now it goes to standby and operating the remote control unit makes no difference.

The most likely cause of the problem is the set's on/off switch which has a third set of contacts that make momentarily to give power-on reset whenever the set is switched on. If this isn't the cause of the problem, try replacing the two standby transistors T85 (BC148) and T86 (BC158) on the power panel.

FIDELITY ZX2000 CHASSIS

There's an ident problem with this set, i.e. green faces. Changing channels will restore correct colour, suggesting that the ident flip-flop is faulty. I suspect the decoder chip.

This type of ident fault is extremely rare in sets that use a single-chip decoder. We have to agree that the chip is probably faulty since there appear to be no external components that could cause this fault.

FISHER FVH P725 VCR

The fault with this four-head, long-play machine is as follows. SP record and playback are perfect. LP record and playback are o.k. with a new tape, but when LP mode recordings made on top of previously recorded tape (SP recordings) are played back the head switching relay operates at random every few seconds, alternating between LP and SP, though it never stays in the SP mode for more than a split second – it's as if some SP information had not been erased. Basically, playback speed switching is carried out by IC702 (syscon board) on the basis of information received from the control track head. The probable causes of the fault are: (1) a dirty or misaligned control track head; (2) a vertically misaligned full erase head not seeing the bottom edge of the tape; (3) insufficient drive to the control head during LP mode recording.



Each month we provide an interesting case of TV/video servicing to exercise your ingenuity. These are not trick questions but are based on actual practical faults.

Field scan problems are not exactly unknown in Philips colour receivers – the G11 chassis in particular had its share of "bright white line" troubles, and we've one or two examples of these sets on our patch with a dark horizontal line etched across the middle of the screen as a result of the set being run with no field deflection.

The Philips set in the spotlight this month was not a G11 however: it was a later one fitted with the KT3 chassis. This has a discrete transistor field timebase with a BD223/BD234 output pair in a complementary-symmetry class B circuit – a reliable and straightforward arrangement. It was on the bench for treatment of a no-go complaint – the cause of the problem was quickly traced to a faulty e.h.t. tripler.

After replacing the tripler the technician examined the newly-restored picture. "Blimey, that tube's been burnt at some time" he said, observing a stationary line across the centre of the screen. In fact it wasn't a burn mark since the narrow line was brighter than the rest of the picture. It seemed unlikely that one of the tube's electrodes was being modulated by a narrow pulse at field rate: the pulse would have had to have been timed at about the middle of the field scan, when there are no such pulses around, are there? Just to be sure, a scope check was carried out at the cathodes, grids and first anode. No spurious pulses were seen.

Plainly something strange was happening in the field timebase. As a first check the field hold preset R8390 was twiddled to see what effect this had. With the picture moving slowly downwards it was seen to be passing through the white line. So an oscillator problem was unlikely. The field output waveform at the "top" of the field scan coils was next examined, using the scope. The sawtooth present looked normal, as did the linearity of the picture itself. The field output stage supply (LT2) at C1588 was reasonably correct at 31.5V; the output stage mid-point voltage (junction R1531/2) was also within tolerance at 17.1V; and the voltage at the collector of the field driver transistor was likewise within a few per cent of being correct. It's true to say that with more care and attention the voltages around the field output stage would have given some solid clues to the cause of the problem. It's also probably true that by magnifying the centre portion of the scope's trace when it was hooked to the output stage mid-point another strong indication of the cause of the fault would have been obtained.

In fact the solution came not from the test equipment but from a Clever Dick who happened to be passing through the workshop at the time. Once he'd satisfied himself that the set used a complementary-symmetry class B output stage he assured those present that he knew what was causing the problem and was reasonably sure as to which individual component was at fault. He was working purely from theory, but as it turned out he was dead right! You'll have his answer next month . . .

ANSWER TO TEST CASE 295 – page 634 last month –

Last month's test case described a classic no colour fault in a modern VCR – a Ferguson 3V42. Despite the frequency of the 4.43MHz voltage-controlled crystal oscillator being correct and proven signal continuity through the playback chroma path there was not a vestige of colour to be seen on the monitor when a colour-bar tape was played back. The fault was also present in the record mode, since a tape recorded by the machine produced no coherent colour when played back via another machine.

The oscilloscope and service manual had provided a fairly full picture of what was happening inside the ailing machine, in that the chroma signal was present right up to the playback colour killer – and occasionally beyond it. It was disordered however, in such a way that the auto-killer circuits in the VCR and the TV set wouldn't recognise it. On further thought the likelihood was that the subcarrier and burst were of incorrect phase. And so indeed it proved to be.

The phase of the chroma signal is shifted during both record and playback by the phase-rotation stage in the colour-under circuitry. This is buried deep inside IC401. To do its job this stage requires two pulse feeds, a 25Hz flip-flop signal and a line-rate pulse. It was these items that our technician had not thought to check. We discovered that the line pulse (referred to as "sync" in the circuit diagram) at pin 8 of IC401 was missing due to a bad contact at a crimp terminating the J1 cross-board lead adjacent to Q27.



Published on approximately the 22nd of each month by IPC Magazines Limited, King's Reach Tower, Stamford Street, London SE1 9LS. Filmsetting by Trutape Setting Systems, 220-228 Northdown Road, Margate, Kent. Printed in England by the The Riverside Press Ltd., Thanet Way Whitstable, Kent. Sole Agents for Australia and New Zealand – Gordon and Gotch (A/sia) Ltd.; South Africa – Central News Agency Ltd. Subscriptions: Inland £16, overseas (surface mail) £19 per annum, payable to Quadrant Subscription Services Ltd., Oakfield House, Perrymount Road, Haywards Heath, Sussex RH16 3DH. "Television" is sold subject to the following conditions, namely that it shall not, without the written consent of the Publishers first having been given, be lent, resold, hired out or otherwise disposed by way of Trade at more than the recommended selling price shown on the cover, excluding Eire where the selling price is subject to cover by way of Trade or affixed to or as part of any publication or advertising, literary or pictorial matter whatsoever. ISSN 0032-647X.



Drake brings satellite TV down to earth. An exciting variety of television entertainment exists and the Drake line of satellite equipment will bring it into your home — EASILY and AFFORDABLY. Get on the road to expanding your entertainment horizon by seeing the Drake line TODAY!

Become a DRAKE SATELLITE DEALER and take advantage of our special dealer prices. We are the main importers and distributors for R.L. Drake, one of the largest USA manufacturers. Don't be misled by inferior products when you can sell the best. From only £495 + VAT (inc 10mts cable). Contact TELEVISION AND VIDEOS AT REALISTIC PRICES FROM THE SPECIALISTS. LATE MODELS ALWAYS AVAILABLE WITH 100% CABINETS AND TUBES. ALL SETS READY FOR INSTANT INSTALLATION AND VIDEOS FULLY SERVICED.

QUALITY AND RELIABILITY IS OUR AIM AT ALL TIMES.

КТ3												from only £60
K30												from only £75
СТХ								•			•	from only £125
K35												from only £135

LATER MODELS ALSO AVAILABLE.

ELECTRONIC VIDEOS FROM ONLY £135 + VAT. MOST MAKES IN STOCK. FREE DELIVERY FOR SENSIBLE SIZED ORDERS

ALSTON-BARRY INTERNATIONAL

Due to expansion our new premises and luxury showrooms are at Unit 4 and 5, Winborn Building, Convent Drive, Waterbeach, Cambridge. Tel. 0223 860958. Fax. 0223 860965.





HITACHI VHS COLOUR CAMERAS	SPECIAL OFFER TDA 4600-2 52.70 TDA 8180 53.60
Working – £125	All Type A
 Working – 2120 VHS VIDEOS FERGUSON 3v00, 3V22, 3V23, 3V16, 3V29, 3V30, 3V31, 3V32, 3V35 HITACHI 5000, 8000 MATIONAL PANASONIC NV8600, 8610, 2000, 7000, 370, 333, 2010 SHARP 620, 630, 640, 2300 H T/P Untested from £70 BETAMAX VIDEOS SANYO VTC 9300, 5000, 5300 SONY C5, C6, C7, C9 Untested from £30 HITACHI VHS TUNER/TIMER £10, HITACHI VHS BATTERY CHARGER £10, ROBERTS VHF RADIOS £5 VHS/Beta tapes used – from 40p each DYS 18" 20" 22" 26" Hybrid/ Solid State from £8. Also available CTVs Remote Control & Teletext All prices subject to 15% VAT Discount for Quantities Complete loads delivered from pick up point 	TRANSISTORS INTERATED CIRCUITS A1726 D134 PS26 D143 PS26 D134 PS26 D134 PS26 D134 PS26 D134 PS26 D134 PS26 D134 PS26 D230 CT28 D234 CT
GALLOWS INN,	Briss D115 2N3703 D010 TT CVC 30 D6.75 Deres induces of mounting SMidle Briss D0.17 2N3704 D0.18 TT CVC 30 D7.75 Wains from mounting D1.75 Briss D0.17 2N3704 D0.18 TT CVC 35 D7.88 3008 D0.75 Briss D0.36 2N3904 D0.10 Decca 80 D7.06 Tuners and other trays available of Briss Troot regues of tuners and other trays available of the tuners and other trays available of the trays available of the tuners and other trays available of tuners availa
ILKESTON Phone: 0602 303124	without notice. Official orders from Schools and Colleges accepted. Tel: 0924-375895 Between 3–6 pm Mon to Fri WEST YORKSHIRE WF2 8XA







VHS VIDEOS

FERGUSON 3V22

WORKING NON-WORKING £65 £30 (FAULTS)

ALL MACHINES ARE COMPLETE NO MISSING TRIM GOOD CABINETS

ELECTRONIC VIDEOS

MANY MODELS – SOME REMOTES WORKERS £100 NON-WORKERS £70

V.C.R. ELECTRONICS (THE VIDEO PEOPLE!) UNIT 5, PRESTWOOD COURT, LEACROFT ROAD, BIRCHWOOD, WARRINGTON, CHESHIRE TELEPHONE: 0925 819081 Company Limited

FROM OUR NORTH WEST LONDON OFFICES AND WAREHOUSE WE SUPPLY MAJOR COMPONENT DISTRIBUTORS WITH VIDEO SPARES OF BOTH GENUINE AND REPLACEMENT TYPES

These items include:

- VIDEO HEADS
- PINCH WHEELS
- **IDLER ASSEMBLIES**
- BELT KITS
- **MOTORS**
- **REMOTE CONTROLS** (TV and VIDEO)

Specific spares are also stocked for:

- FERGUSON/JVC
- NATIONAL PANASONIC
 - SHARP
- **HITACHI**
- SANYO/FISHER

• SONY

OUR PRODUCT RANGE IS CONTINUALLY INCREASING TO INCLUDE OTHER ITEMS AS THEY BECOME POPULAR

CONTACT US TODAY ON 01-968 9684 FOR DETAILS OF YOUR LOCAL DISTRIBUTOR

(EXPORT ORDERS WELCOME)

pany Limited



YOUR NUMBER 1 VIDEO COMPONENTS IMPORTER

	DEN C	DADE	CE	AQT	
PASI I	JEU J	PARE	DF	ADI	
VIDEO HEADS ALL STO	WE CARRY HI		PARES	BELT KITS (GEN Panasonic NV2000, 2010	E6.50
NV2000, 2010, 7000, 7200, 8600, 8610, 333, 370 genuine £44.00 NV366, 688, 777, 788 genuine £64.50 Panasonic 4HSS Equivalent heads (Not NV366). 227, 95	INC. PLAY ID	LERS, CLUTCHES, MC	NDS,	NV7000, 7200 NV333, 366 NV688, 788	£6.50 £6.50 £4.70 £5.50
NV730 (genuine)	BELTS A	UDIO/CONTROL HEAD T TOOLS AND TAPES	DS, ETC.	NV8600, 8610 Sharp VC6300	£6.50 £6.50
3V38 genuine 227.95 Ferguson3HSS Equivalent heads 227.95 Sharp vroato seco szon 381 386 387 388 482 581 penuline 257.20	**SPECIA **FOR	AL ORDER FACILITIES NON-STOCK ITEMS**	**	VC8300. VC9300, 381 etc Sanyo	£6.50 £6.50
VC3300, 3500, 201, 201, 201, 201, 201, 201, 201, 2	ALL SPARES LISTED ARE G CHEAPER REPLACEMENT PA	ENUINE PARTS. WE ALSO STOCK THE F RTS E.G. BELT KITS, PINCH ROLLERS, HEA IDLERS (GENUINE)	ULL RANGE OF DS, ETC. P.O.A.	VTC5300. VTC5000 VTC5300, 5400	£6.50 £1.99 £6.50
C 5, C 6, C 7 genuine	CREDIT CARD	Panasonic NV2000, 7000, 7200 NV333, 366, 688, 788	£3.45 £3.45	SUC5, C7	£6.50 £7.50 £6.50
Sony C5, C6, C7 Equivalent	TELEPHONE RECEIVED BY	NV777, 370, 430 NV730 Sharp	£4.50 £6.50	Hitachi VT5000 VT8000, 8500	£6.50 £2.90
VTC3300, 5000, 5150, 5300, 5400 genuine	4 PM. ARE DESPATCHED	VC9300, 9500, 9700 381, 386, 387, 388 482, 483, 486, 581 etc	£3.90 £3.90 £3.90	VT9300, 9300 VT11E, 14E, 17E Ferguson/JVC	£3.30 £6.50
Toshiba V9600, V31, V33 genulne	SAME DAY	Amstrad 7000 Sony	£3.90	3V00, 3V10, 3V22 3V23 3V29, 3V30 3V35, 36, 38, 39	£4.50 £6.50 £3.90
V 15000, 8000, 8300, 9300, 9300, 9700, V 11, V 142 [39,90 Amstrad 7000 Equivalent		C5/C7 Idler kit	£4.95 £4.95 £1.65	Toshiba V9600 V8600	£6.50 £6.50
PINCH ROLLERS SENSOR LAMPS Panasonic All Panasonic All Pan	£1.80 £1.80	VTC5000, 5150, 6500	Σ6.50 £6.50	MOTORS Reel Motors Sharp 9300 etc	£15.30
NV333, 366, 688, 370. £7.95 Sharp VC3900 etc NV430, 730. £7.95 Sharp VC7300 etc Sharp C7300 etc	22.90 £2.90 £1.80 £1.80	VT8000, 8300, 8500 VT9300, 9500, 9700 VT11E, 14E, 17E, 19E	£4.72 £4.75 £6.50	Amstrad 7000 Sanyo 5000 etc Panasonic NV333	£9.98 £16.80
VC5300, 7700, 8300, 28.70 SENSOR LE.D's VC7300, 381, 386 etc. 25.40 All Panasonic All Panasonic All Panasonic	12.90 12.90	Ferguson Clutch assy large	£5.95 £6.95	Ferg/JVC, 3V22 etc Sharp 9300 etc Hitachi VT5000	£29.90 £29.30 £24.75
VT5000, 8000, 9000	F SPARES FOR	Clutch assy small Idler assy 3V29, 30 3V35, 3V36, 3V38, 3V39	£6.95 £3.45 £4.50	Sharp VC7300, VC8300 Capstan Motors Sharp 9300, 9500	£26.40 £29.30
C5.C6.C7	GUSON, ETC.	Fisher FVHP615 etc. MOST OTHERS AVAILABLE	£6.90	VC8300 VC7300, 7700, 7750 Ferg/JVC. 3V22 etc	£29.30 £29.90 £29.60
30(0) SV16 3V22 E5.95 AVAI 32(2) 32(2) 32(2) 32(2) 5(2) 5(2) 5(2) 5(2) 5(2) 5(2) 5(2)			c	3V35, 36, 38, 39 Hitachi VT5000 VT8000, 8300, 8500	£25.77 £24.75 £37.70
Sanyo VTC9300, 5000 .5300	EVIDEU	SERVIGE	5	VT11E, 14E, 17E Sony C5, C7	£27.30 £34.50
145 STATION RD, BEESTO	N, NOTTIN	IGHAM NG9 2	ZAZ, I	EL: UDUZ-	
Send 2 × 18p stamps for full catalogu OVERSEAS ORDERS WELCOME ON	CREDIT CARDS, PO	STAGE AT COST OFFIC	IAL ORDERS	WELCOME FROM	COLLEGES ETC.
Propried and a series of the s		Limited number are now availa available single returns and the cabinets, but the suitable for re- substantial save 221 Bridge Street JUNCTION 1 Unit 11, Pr Birchwood, M	r of Cold ble Mixe y or in may be he tube furbishming on p For Furt DLOU t West, H Tel: 02	bur and Mono d Models size tens. They ar faulty or ha is warranted g ent or rental rice. her Details: IRTRAD ockley, Birming 1 359 7020 RADE DISPO Court, Leacro on. Phone: 09	Televisions es and types e catalogue ave marked good. All are and show a E ham B19 2YU. SALS LTD ft Road, 25 826387
In the there is a real difference at Cricklewood File That's why you should never be without the FREE CRICKLEW COMPONENTS CATALOGUE, for sheer variety, competitive from the U.K.'s number one 100% component shop. No gimm computers, just components, millions of them, all easily avail calling or credit eard telephone orders. Just pick up the phone is FREE copy now (no SAE required). You have nothing CRICKLEWOOD ELECTRODICS AD Cricklewood Broad way, London NW Tel: 01-450 0995/01-452 0161 Telex: 91 4977	etronics. DOD ELECTRONICS prices and service nicks. no gadgets or lable by mail order. for a pen't to get your g to lose. ELIMITED 2 3ET	FULL RA AN 8800 N/R 8800 R 9000 N/R 9000 R	NGE ID VH £20 £25 £30 Text	OF THOF S VIDEO 9900/920 9900/920 9600 TX9/10 £70	RN TV'S S 0 N/R £40 0 R £45 £65
	TV	All prices sut	Ject to V		August 100



A NEW SUPPLIER OF EX-RENTAL T.V. AND VIDEO AT TRADE PRICES

WORKING OR NON-WORKING THE CHOICE IS YOURS

THE PRICES ARE RIGHT!

RACECOURSE IND. ESTATE, UNIT 2, COUNTY BUILDING, ORMSKIRK ROAD, LIVERPOOL L9 5AL TELEPHONE 051-530 1285

BOLTEN LTD. 63, JEDDO ROAD, LONDON W12 9EE. Tel: 01-749 0915 (2 lines)

Telex: 262421 BOLTEN G

VIDEO HEADS	
Sony Universal Eq. DSR 36	£29.95
Sony Universal Eq. DSR 43	£29.95
Sony C-9	£47.95
Ferguson/JVC Universal	£28.50
National Panasonic Universal	£28.50
National Panasonic (370/380/430/460)	£32.95
National Panasonic (777/330)	£46.95
Hitachi 5000 (Not Genuine)	£29.95
Hitachi VT11/HIVI/VT33 (Genuine)	£29.95
Toshiba 9600	£39.00
Sanvo (Genuine)	£44.95
Fisher Universal Eq. FVH D720	£37.00
Akai Universal	£28.50
Sharp	£39.95
Amstrad 7000/9000/4600	£32.95
Saisho 605/705/805/905/100	£32.95
Triumph 9500/9501/9525	£32.95
Sanvo Pulley VTC 5150	£6.95
Sanvo Motor VTC 5150	£7.25
Belt Kits (Most Models)	£3.99
Remote Controls TV Grundia/Philips	£16.95
Remote Controls Philips TT (4300)	£17.95
Pinch Wheels (various Models)	£5.95
Sony Idler Kits C-5/C-7	£4.50
Sony Idler Kits C-6	£2.95
Other Accessories - Mod kits, Integrated Circuits, Idle	r Assy, Gear
Idler Assy, Reel & Loading Belts, Capstan & Reel motor	s, Reel Drive
Pully units also available in most models. Please call	for full list.
Please add 15% VAT plus £1.00 p&p per order.	
Delivery within 7-14 days subject to availability.	
PLEASE NOTE OUR NEW ADDRESS	2.085
AND TELEPHONE NUMBER	

CREWE WHOLESALE	TV		
77 Coleridge Way, Crewe			
161: 0270 382924 15 mins from Junction 17, M6			
WORKING TVs FULLY ENGINE AND TESTED. TRY THEM BEI YOU BUY. NO BUMPED TUB	ERED FORE ES.		
Decca 80s & 100s	£25		
Bush T20	£30		
ITT CVC 20 & 30 & 32	£25		
G11s	£35		
GEC Starline	£25		
GEC 2110, 2111	£20		
Rediffusion Mk 3	£25		
Thorn 8,800 to T/X from	£20		
Text Available	POA		
CABLE DORICS WITH OR WITHOUT TRANSLATORS PLUS A FULL RANGE OF OFF THE PILE SETS JUST ARRIVED 1000s OF			



28.4673 01.13 25.4673 01.20 25.6695 02.00 HA1156 1.30 TA-7239 FL30 GC-3078 00.055 28.4683 00.20 250-4869 02.00 HA1367 CL300 TA-7240 FL30 GC-308A D0.055 28.4768 C10.00 250-1135 DL85 HA1406 D0.75 TA-7310 C1.25 GC-308A D0.85 28.4776 C1.50 AH-210 DL90 HA11227 C1.00 TA-7313 DL30 GC-3079 D0.85 28.4779 C1.50 AH-214 C1.00 HA-1217 C1.00 TA-7314 C1.35 GC-3079 D0.85 28.4786 CD.60 AH301 C2.36 HA-11217 TA-7323 C1.20 GC-3376 D0.85 28.4985 DD.30 AH303 C2.20 LA3165 C1.20 TA-7324 C1.10 BC-3377 D0.85 28.4986 DD.75 AH315 C1.30 HA-316 C1.57 HA-5162 LA4160 D1.85	BDX-588 D0.42 TDA-2009 E2.80 LIGSV E2.80 SMM70 D1.84 STVL PP-ACEMENT PW-321 D1.25 BDX-586 D0.42 TDA-2000 FL.50 D1.86 STVL PW-321 D1.25 BF-257 D0.30 TDA-2000 MF 24 MC-1489P D1.46 SMM70 FL.40 FM-472 D1.36 BF-259 D0.30 TDA-2000 HE 24 MC-1489P D1.46 MC-1489P D1.46 MC-1489P D1.46 MC-1489P D1.46 MC-1489P D1.46 MC-1489P D1.46 MC-4500 CE 27.70 PV-3280 DL 31 D1.45 MC-7500 DL 31 MC-
- NEW VIDEO HEADS - From Equador Sector Data V.A.T. Base Contact us for details of Our	OSCILLOSCOPES TELEQUIPMENT D35. Dual Trace 50MHz Delay Sweep. Large Tube. COSSOR OSCILLOSCOPE CDUISO. Dual Trace Sweep. Cossor OSCILLOSCOPES Cossor OSCILLOSCOPE CDUISO. Dual Trace Sweep. Cossor Oscilloscope Cossor Os
Full Range of Video Spares including Motors, Pulleys, Belts, Idlers, Etc. Our Full List will be sent on request. ELECTROVISIA LIMITED	FD . AUDOCUMINS AC 300/IN-300V FSD . Storm MARCON VALVE VOLTMETER TF2500 10Hz-10MHz . Storm 1mVS.CHANG DMM 7030. 312 digit. Hand held 28 mages including 10 Amp AC/DC 0.1%. Complete with batteries & leads. P&P24 1mVS.OLURBAR GENERATOR type 5501. PHILIPS COLOURBAR GENERATOR type 5501. Videout Many functions. Cut Many Stand Matteris and Colorial of





717



SERVICE PAGES

All prices plus 15% VAT. All cheques, postal orders etc., to be made payable to Television, and crossed "Lloyds Bank PLC". Treasury notes should always be sent registered post. Advertisements, together with remittance, should be sent to the Classified Advertisement Dept., Television Room 204B (H.H.), IPC Magazines Limited, Kings Reach Tower, Stamford Street, London SE1 9LS. (Telephone 01-261 5942).



All leading makes available. Large quantities of some lines. New and second hand equipment bought and sold.

J. H. Roche & Co. Ltd., 36 Station Road, Wylde Green, Sutton Coldfield, West Midlands B73 5JY. Tel: 021 354 2393 (24 hrs).



NORTH NEW ST	BESCO LTD T/A WEST ELECTR OCKS ARRIVING	ONICS DAILY
H.P.F	DISCOUNT FOR QUANTITY WORKING TVS AND VIDEOS ON SHOW	NTALS
Refurbished TV's Refurbished TV's BUSH T20/T26 £45 G11 £50 PYE KT3 £65 PYE KT3 FYE KT3	Annual Clearance Rock Bottom PricesPYE G11 EXCPYE KT3£50CAB.£40GEC 2213£20BUSH T20/26 CH £35THORN 3000£7HITACHI 191£15GRUNDIG G415/FERGUSON TX£554206£25Best Stock in Country over 2000 in stock60% of our TV'sSPYE 222£15Switch on)PHILIPS 550£10Special PriceBUSH 718£15QuotedBUSH 2 CHIP£8For Bulk PurchasesGRUNDIG 5010£10From Source.DISCOUNT FOR QUANTITY	VideoVideoWORKINGSHARPS 7300, 8300, 9300HITACHI, VTI1, 9300HITACHI, VTI1, 500Dre to our excess video stock and limited time we have electronic VHS videos with sight faultExcess video SPECIAL PRICE FOR LARGE ORDERSANYO, SONY, BETA
LAU BRADFO	REL STREET, LEEDS I ORD, W. YORKSHIRE 5 MINS FROM MOTORWAY	ROAD, BD3 9TP.
100's PX HOOVER JUNI VACS All models in st Tel (0274 66099	DR NORTH WEST ELECTRONICS LCUINES ST LCUINES ST LCUINE	X. WASHERS OOKERS TC ASHONLY PEN6DAYS SAT 9-5.30

TVs GREAT BUYS G11s from £20

REMOTES I/R AND SONIC from £35 TEXT MANY MAKES from £55

200+ FULLY WORKING SETS AVAILABLE. ALL SEEN IN OUR COMFORTABLE TRADE ONLY SHOWROOM. EXCELLENT CABINETS, READY FOR SALE OR RENT, BASIC TO TEXT. NO JUNK.

VHS VIDEOS ALL ELECTRONIC, GOOD CLEAN MACHINES NOT KICKED ABOUT, BASIC TO FULL I/R WITH DOLBY. MAKES BY PANASONIC, HITACHI, JVC, MITSUBISHI, FISHER ETC. AND OTHERS AS THEY ARRIVE.

2000 SYSTEM VIDEOS FROM ONLY **£20** LOAD ON STOCK, GOOD CLEAN MACHINES AT BARGAIN PRICES, ALL HAND PICKED. 2020-2021-2022. PHILIPS, GRUNDIG 4×4 and 2×4 SUPER AS AVAILABLE.

TVS ALL OF THE FOLLOWING MAKES AND TYPES IN STOCK ON PREPARATION OF THIS ADVERT: *DECCA* 80-88 100. *FERGUSON* TX 9 + 10, 9000. *GEC* 2642-2242, 2642 TEXT. *GRUNDIG* 7200-7400-6012-6610-6245-2200. *SONY* 1810-2040-2022. *ITT* CVC 8-9-20-23-25-30-32. *TELEFUNKEN* 8256. *MITSUBISHI* CT200-2606. *TANDBERG. KORTING. PANASONIC.* GOOD CLEAN CABINETS ON MOST SETS. WE LOOK AFTER THEM FOR YOU.



CASH ONLY

OPEN 10am to 5pm MON-FRI PRICES BASED ON QUANTITY ALL PLUS VAT.



TELEVISION AUGUST 1987

TV's HITACHI, MITSUBISHI, Panasonic, Sony, Toshiba, JVC, Sharp, fully refurbished. PEARSON TELEVISION. 0484 863489. Delivery arranged.

OCHRE MILL TECHNICAL – GRUNDIG Spares 1972-1982 comprehensive module service, sensible prices. Telequipment, Philips testgear e.g. reconditioned Oscilloscopes £100, colour bars £45. Oscilloscope Manuals. 0785 814643.



'BOBS'	'BOBS' TELEVISION WAREHOUSE
TELEVISION WAREHOUSE A NEW CONCEPT IN EX-RENTAL T.V. & VIDEO	NEW
WORKING TV & VIDEO	PHILIPS
SHOWROOM	NEW
GUARANTEED COMPLETE AND UNCANNIBALISED GOOD CABINE	ETS AT LOW PHILIPS
ELECTRONIC, REMOTE, FRONT LOADER VIDEOS	NEW
NAT PAN, JVC, HITACHI, TOSHIBA, SANYO, SONY, E	TC, ETC. PHILIPS
ITT, GEC, BUSH, JAPS., DECCA, ETC.	NEW PHILIPS EX
PHONE BOB BEAN ON: 0268 728966	CATALOGUE RETURNS
AND DISCUSS YOUR REQUIREMENTS	LARGE STOCK NOW
BOBS T.V. WAREHOUSE, 6, The Glade, Basildon, A132 A128	CURRENT MODELS
1172	ALL WORKING AND
A127	BOBS GUABANTEED
A13	PHONE
DARTFORD TIMNEL	BOB BEAN 0268 728966
	TO RESERVE TOOR SOFFET NOW
VIDEO SPARES	ENGINEERS
Stock items despatched by return Access & Visa welcome	Undate your skills and improve your job
VIDEO HEADS BELT KITS Universal VHS heads most models	prospects on our 16 week
Hitachi, Ferguson, Panasonic etc. (most Sanyo VTC5000 £1.00 models) (genuine) £45.00 Sanyo VTC3300 £3.75	
Sharp VC9300, VC9500 etc. Ferguson 3V31, 3V35, 3V36 £1.95 (equivalent) £31.50 Fisher VBS 7000 £4.50	MICROPROCESSOR SYSTEMS
Sony SLC5, C6, C7 (genuine) £42.00 Sony SLC5, C6, C7 (equivalent) £31.00 Most Models £4.95	SERVICING COURSE
Sony SLF1, C20, etc. (equivalent)	You will spend your time on realistic
Reprocessed Heads Sharp (most models) <u>22.95</u> (Send old head with order. The drum should be Hitachi VT11, VT14, VT17, VT19, VT33	practical work
Interview of scratches and marks) Ed. E3.50 Most VHS models E29.00 Hitachi VT9300, VT9500, VT8000 E6.50 Sharp (most models) E37.50 model	PLACES AVAILABLE NOW
Most VHS 4 head types £47.50 Sanyo VTC5150, VTC5000, VTC6500 complete reel drive pulley unit £8.90 VIDEO MOTORS Sony SLC5, SLC7 rewind kit £5.95	Interested? Then send full C.V. to:
Drum Motors Ferguson 3/29/30 Take up idler £2.20 Ferguson 3/29/30 Take up clutch £3.50 Ferguson 2/29/30 Take up clutch £3.50	
Sharp VC9300, VC9500, VC9100 etc. £26.60 Ferguson 3V35 Reel idler £3.95 Ferguson 3V35 Reel idler £3.95 Ferguson 3V35 Reel idler £3.95	SWINDON SKILLCENTRE
Reel Motors Sanyo VTC5000, 5150, 5300, 5400, tdler Tyres (Please state size in mm and make	SWINDON, WILTS
Sharp VTC9300 etc. (most models) £18.30 Capstan Motors MISCELLANEOUS Of Constant Motors	or phone Jon Colley on
Ferguson/JVC (mechanical models)	(0793) 641671
Hitachi VT11, VT33, VT14, VT17 £25.00 BU208A £1.00 Hitachi VT8000, VT8300, VT8500, Exchange Modulator, Aerial Booster £14.95 VT8300 [Liniversit/Geo.Com/utileo.com/utileo	for more information
Sony SLC5 SLC7 (BHF 1100d) £29.95 Universal Video Copying kit (scart) £5.85 Sharp VC3300, VC3500 etc. £27.60 Universal Video Cassette Lamp £0.50	
Please add 75p per order for p&p and then add 15% VAT	NU IUIIIUN FEES
	A training anowance will be baild
A.Z. ELECTRICS	(AN M.S.C. FUNDED COURSE)





MISCELLANEOUS

BMR 90

Versatile and reliable.



expectancy, etc. can pay for itself in 4 weeks, if you are not using BMR 90 you are making less profit than you could. Sole Agents BLENDOWN LIMITED, 34 Glan-y-Mor Road, Penrhyn Bay, Llandudno, Gwynedd, Wales. Tel. (0492) 49246



TELEVISION AUGUST 1987

57 High Street, Sandhurst, Camberley, Surrey GU17 8HB.

U-VIEW, 29 Warmsworth Road,

Doncaster, Yorkshire DN4 0RP. Tel. 0302-855017. Callers ring first

SERVICE SHEETS



Classified Advertisement Dept., King's Reach Tower, Stamford Street, London SE1 9LS. Telephone 01-261 5942. Rate: (5p per word, minimum 12 words. Box No. 7p extra + 15% VAT.

Company registered in England. Registered No. 53626. Registered Office: King's Reach Tower, Stamford Street, London SE1 9LS.

TELEVISION AUGUST 1987

ADDRESS

8/87


INDEX TO ADVERTISERS	SPARKWORLI THE SOUTH W	D LTD.	CARTON HOLESALE LITD.			
ADMIN TELEVISION 724 AERIAL TECHNIQUES 671 ALSTON - BARPYINTERNATIONAL 706 APOLLO 725 ASJAA INTERNATIONAL LTD. 715 AVON METERS 721 A-Z ELECTRICS 722 BESCOLTD. 720 BES COLTD. 720	No. 1THEIn Ex-Rental TV's, Video'sLargeand Graded White Goods30, 45& Inlin& Inlin			by the second se		
B.K. ELECTRONICS 662 BLK. ELECTRONICS 662 BLENDOWN LTD. 724 BOB'S TELEVISION WAREHOUSE. 722 BOLTEN LTD. 713 BULL, J & M ELECTRICAL 667 CAMPION WHOLESALE LTD. 727 CARTER, JOHN (ELECTRICAL) LTD. 708 Cell TEL 683	New Stock Arr All The Tim	riving T2 10 10 10 222 G1	T22, T24, T26; Decca 30, 80, 90, 100; Doric 1, 11, 111, 1V; Pye 223, 911, KT3, KT30; Philips G8, G11, KT3, KT30; Thorn 8K, 8.8K,			
CENTRAL TV & VIDEO WHOLESALERS LTD. 716 CENTREVISION. 717 CHROMAVAC LTD. 665 COLSE HARDING & CO. 718 COLOURTRADE 712 CREWE WHOLESALE TV 713 CREVE WHOLESALE TV 713 CRICKLEWOOD ELECTRONICS LTD. 712 CONFUNCE LECTRONICS. 710 CUTMORE, T.B. 725	FOR THE BEST PRICES AND THE BEST SERVICE CALL US NOW!			MOST JAPANESE MODELS INCLUDING PORTABLES VHS & BETA VIDEOS		
DATA-GO 724 DHOUPER VISION 724 DISPLAY ELECTRONICS LTD 726 DONBERG ELECTRONICS 725 EAST CORNWALL COMPONENTS 668 EAST CROYDON DISCOUNT ELECTRONICS 710	on 0626 552	94	FRESH STOCKS DAILY WE ALSO OFFER NATIONWIDE DELIVERY			
ECONOMIC DEVICES 692, 693 ELECTRIC CITY 711 ELECTROVISIA LTD 715 EURO A. M. LTD. 710 EURO-SAT. 724 FORD, FRANK. 714 GENERAL FACTORS 721 G.G.L. COMPONENTS 660 GRANDATA LTD. 666	Unit 3, Brunel Bu Brunel Roa Newton Abbot, I	ildings, d, Devon.	UNIT 80, BARRACKS ROAD, SANDY LANE INDUSTRIAL ESTATE, STOURPORT-ON-SEVERN,			
HALTON TV TRADE DISPOSALS. 721 HENRY'S AUDIO ELECTRONICS. 665 HILLIER, ANTHONY 718 HUSSAIN CENTRAL TV LTD. 709 ICS. 663 ISLAM, GEORGE & DUIGDALE 725	Regular deliveries to many areas London weekly			79642 & 79643		
I.T.V.C. 719 JUNCTION 11 T.V. TRADE DISPOSALS LTD. 712 KENT LEDGERWOOD WHOLESALE LTD. 725 KESH ELECTRICS LTD. 725 LONDON ELECTRONICS COLLEGE 663 LRC (SPARES) 707 MANOR SUPPLIES Commit	IRE TV T LARGE QUANTITY OF BRA	LAND'S RADE SALES	SO at E	WN D.I. NNEL UHF/VHF WORKING		
MAURITRON (TV) 725 METER CO. (POOLE) LTD. THE 707 MONTANA MAIL ORDER 708 N.ETTO. 713 N.F.P.C. 718 N.G.T. ELECTRONICS LTD. 726 NORTHAMPTON TRADE TV's 778	VIDEO RECORDERS: Ferguson 3V39, 3V29, 9803E, Nordmende V102K, Sharp VC482. Front and top loaders UHF/VHF. All fully serviced.					
PAPWORTH TRANSFORMERS 727 PHILEX COMPANY LTD. 711 POWELL, T 683 PRO-VISION 661 P.V. TUBES	HI-FI STACK SYSTEMS: As new. Sanyo, Sharp and Ferguson 15-20 Watts per channel. TVs from £50. VIDEOs from £140 "KEEN TO SELL AT KEEN PRICES".					
SABACO 723 SANDHURST TV SERVICES 724 SEMPLE SERVICE 724 SENDZ COMPONENTS 674, 728, Cover III, Cover IV S.M. ELECTRONICS 719 SOUTPLEIDE TV 707	E.D.I. House, Ballyfermo Tel. 263517-264	t, Dublin 10 Clo 139	ver Place Te	A. College St., Killarney a. 064 33655 Bardavcard and		
SPARKWORLD LTD. 727 STEWART OF READING 715 SUPERTEL 673 SWINDON SKILLCENTRE 722	PRICES INCLUDE CARRIAG	E. VAT NOT APPLIC	ABLE.	Access welcome Access welcome REWIND SERVICE		
TECHNICAL INFORMATION SERVICES 725 TELEFIX 719 TELETRADERS 714 TELEVICES 712 TELEVICES 712 TELEVICES 712 TIDMAN MAIL ORDER LTD. 707 TRENT TUBES 718 TVINTERNATIONAL 707	CS1730 1733 colour 9.00 CS1830 1835 colour 9.00 '30' series Bradford colour 9.00 80 series colour 8.00 100 series colour 8.00 KB LTT Colour	G8 & G9 series colour PYE 368,169,569,769 mor 725-741 CT 200 REDIFFUSION Doric Mk. PAPWORT	8.00 no 8.00 8.00 3 9.00	WINDINGS RANK BUSH MURPHY T20a T22, T26 Pri & Sec 6.00 Z718 primary state 18" or 22" 6.00 Z718 EHT overwind 8.00		
IVS. INI ERNATIONAL LTD. 664 T.V. TRADE SALES 727 UNDERWOOD ELECTRONICS 723 UNIVERSALS. SEMICONDUCTOR DEVICES LTD. 714 U-VIEW TUBES 721, 724	VC200 VC205 VC207 mono 8.00 CVC5 CVC7 CVC8 CVC9 col. 9.00 CVC20 series colour 8.00 CVC30 CVC32 series colour 8.00	TRANSFORM 80 Merton High S London SW19	IERS Street, 1BE	SOVEREIGN FARA £15.00 14" colour overwind		
V.C.R. ELECTRONICS. 711 VISION PROMOTIONS 723 WELLVIEW. 717	CVC45 8.00 FT100 FT110 state p/no. 9.00 All lopts and	15% DISCOUN FOR TRADE ORD	T ERS	1690–1691 EHT overwind 7.00 Waltham 190 EHT overwind 6.00 1590 EHT overwind 6.00		
WILTSGROVE LTD. 723 WILTSGROVE LTD. 717 WING ELECTRONICS 717 WING ELECTRONICS 718 WIZARD DISTRIBUTORS 721	windings are new and guaranteed	Complete Transform Delivery by return o	ers Only of post.	CALLERS WELCOME Open MonFri. 9 to 5.30 pm		

TELEVISION AUGUST 1987

					D	Philip's Headnbones
Philips small stereo headphones £4	CV 8617 10p Y 716 10p	ZTX 451 10p ZTX 550 10p	24V 4Amp (100VA) Trans £4.00	Nickel Cadmium Charger AA-C-D-PF	Battery 9 £6	Compact Disc Stereo Type £13
Rank UHF 4 push button tuner £4	Y 730 10p	MJ 2253 600 -	Mains 240V (100VA) to	12 Volt Aprial Ch	anger	8 Seg Display FND500 20p
GRC power supply	Y 827: 6A/1KV 20p Y 860 30p	MJE 2209 10p SP 8385 50p	240V out fully shrouded	over Relays 144	Mc/s	Model 3000
Rank front panel	Y 933 5p Y 969 50p	SAB 3205 £1.00 SAB 4209 £1.00	\$5.00	45 watts 5	50p	Volts range AC. DC 200M/V to
Z950 £5	Y 997 30p Min 12 volt Relays 75p	300M + 700 320V £1.80	ITT CVC45 8 way resistor	6 Push Button Unit f	or GEC	Export PYE731
Power panel 8.500 Thorn £5	R 1038 40p R 1039 40p	150 + 200 + 250M 300V 50p	unit for v/cap £3	2100 Series		6 Push Button unit with (UHF- VHF) band switch £4
6 TAG print mains	R 2009 80p R 2010b £1	Computer Transformer	CVC40.8 button unit with	Replacement for Button Unit	Touch £8	ITT Micro Phone M5 50p with
switch PREH 1983 ITT 75p	R 2029 50p R 2210 60p	20v/2.25A; 20v/1.5A; 17/5A: 19/5A: 28/05A \$3	mains lead & slider pots			11/2 Volt Sub Min Relays 25p
Rank T603A tuner on	R 2257 60p R 2265 50p	Mains ViewData 240V/240/6V/4	with sockets 210.00	8 SEG LED Dis	splay	Philips Solar Scientific
panel 20	R 2305 50p R 2306 30p	amp/6v 500m/a in / out	8000/30v 50p	LM1017 50p		15v-0-15v 1 Amp
GEC IE tuner panel	R 2322/2323 pair 80p R 2323 15p	Mains trans 240/12v-0-12v 2 amp	$\frac{4}{0400} \times 10^{-10}$	C1/C2 0	_	Transformers £1
PC786B £12.50	R 2396 50p R 2461 80p	£3.50	100/350v 70p 400/350v 70p	Push Button U	Jnit	RGP30K 10p RGP30G 8p
Rank IF 742 £3 Rank decoder Board	R 2030 50p P 2443-BD124 30p	Voltage Regulators	.47/500v 25p 1/600v 25p	£10	-	RGP15G 6p T6024WGI 10p
MTS 200/1 Tuner & IF £12.	R 2540 £2 R 2737 400	-5V/LM79MO5CP 25p	.022/1kv 10p	Electronic Buz	zer	SEND FOR DATA
Z733 Rank mains in nut-panel £1	R 2738=TIP41 30p R 2775=TIP41c 40p	-8V/79M08c -90p - +6V/78M06c - 30p	NI CD Charger MW 398	60p		HD1000 £20
Rediffusion Mark 3-4 6	R 3129=TIP47 40p	+10v/78LA10 20p I M 337 30p	6A.A £8	15V 015V, 1A	£1	HD5000 £24
& 7 Push Button	S 2008b 80p	LM 342/18 30p	Charger £8	Print Type Trans		HD8000 £35
Tuner IF Cans ITT	2SC1942 £1	+12V/LM 340T12 50p			-	
CMR200 £10	STR441 £2.50	+15V/78M15 +18V/MC78M18 20p	Multi Core 60-40 Soldar 500G 20 SWG			£4.50 £5.00
UK £12	S 2000AF line o.p. £1	MC 7724cp 40p	15 Watt Stereo Amp Sanyo	Module with Data		50p £6.00
4 types of front panels	BU 105/04 80p	MC 7824 40p	25 Watt Solder Iron	£ 1001 Set		£4.00
types £5	BU 124 50p	TIS 90 10p	TRU MIA - 1 2000 250	Various Tools and A	ccessories	£1.50
CVC20, CVC32 IR, CVC40 Cans	BU 180a 65p	TIS 93 20p	L.C.D. clock display with al	arm		75p
20AX Line lin coil 50m	BU 205 £1 BU 206 £1	U 19885 40p	D/P push mains switch Mains lead & two pin socket	for radio cassette		20p each 35p
GEC switch mode	BU 207 £1 BU 208 90	U 3832 15p U 3845 15p	T/V loop aerial Radio Telescopic Aerial			75p £1.00
trans 20AX ITT mains CVC9 to	BU 208A £1.10	MR 508 10p MR 501 10p	Philips Neon Lamps for TV	sets		5p £1.20
CVC33 print type 60p ITT 2.800 mains	BU 222 £1	MR 502 10p BCW 71P 30p	Foam Cleaner Philips			£1.20
remote switch 50p	BU 407 60p	BYF 1202 10p	Contact Cleaner Philips Cans of Anti Static, Degrea	se Cleaner and Anti C	Corona	All at £1.40
2110 GEC Sound O/P	BU 500 £1.10	BYF 3126 40p	Lorlin Full Remote Relay S Mains timer, 13 amp - up	witch fit most T/V set to 2 hours: easy to us	s, mains 4 se, plugs i	into socket £3.00
2110 GEC L.O.P.T.	BU 508A £1.20 BU 526 75p	BYF 3214 400 BYX 10 10p	Screen locking agent, large	can orde Can		£1.50 £1.00
Panel 20	- BU 705 £1 BU 807 £1	BYX 36/600 35p BYX 38/300 25p	Weller solder iron 15 watt/2	5 watt	DA4 1 5V	£5.00 7 60n
Panel £5	BU 824 50p BUT 11 50p	BYX49/600R 75p BYX 55/350 10p	100 Coax Plugs	OIS OCCSS/ IEC S	1.54	£12.00
GEC 20AX £10.00	BUW 11 75p BUW 84 60p	BYX 55/600 (Bead) 10p BYX 71/350 20p	De-solder pump + 2 nozzel Flat Red LED and Green	s Philips		5p
Button Unit & Mains	BYW 20-08-9 £1 BYW 95 10p	BYX 71/600 50p BYX 72/300 20p	500gm 60/40 solder reel Solder t Vilo reel			£5.50
	- TIC 106a 30p TIC 116m 40p	BYX 36/600 50p	Dual v/u meter -20 - +10d	0		£1 75p
Rank Panels	TIC 116n/Y 1003 35p TIC 126N 40p	BVY 95C 12p	De-solder Pump			£2.50 £16.00
Z736 Tuner 1.F. £10 A805 Conv. 7/8 £2	TIC 206m 30p TIC 225S 40p	BYZ 106 10p	Portasol Fiameless Gas Solo	lering from		
Z780 Line O/P £10 Z968 £10	TIC 226E 40p TIC 226m 30p	BPW 41 15p BYW 56 2A/1000v G11 8p	GPO 3 Meter Lead New	Panel Meters	VM/A	50p
Z582 I.F. Panel £5	TIC 236m 30p TAG 226/600 50p	BZU 15/24 54p BZY 93c75 50p	Gray front and .0-300V AC	/DC 23/4 × 21/4		£2.00 each
KT3 Teletext Power Supply £10	TICV 106D (T092 case 2A/400V) 10p	BZV 15/18 30p BZV 15/30 30p		F	Plastic Boy	xes $4^{3}/_{4} \times 4 \times 1 \times {}^{3}/_{4}$ 50p
		10n	SONY 1400KV Chroma Pa	nel £6	ITI HICOC	¥ / 181
DA 201 51	TIP 30 35p	BZX 79.3v 10p	CONV 1400KV Touch butt	an unit tta sul i -	00 W/W	Res. £1.50
BA 301 £1 TA 4127 £1 HD 3994 2A23 £3	TIP 29 20F TIP 30 35p TIP 30A 35p TIP 30B 40p	BZX 79.3v 10p	SONY 1400KV Touch butto	on unit £3.50	00 W/W 3F 199 0 × 20 T	Res. £1.50 20 for £1 "urn 100k pots. Rank £2
BA 301 £1 TA 4127 £1 HD 3884 2A23 £3 TA 4184 £1 TA 2125 £1		BZX 79.3v 10p BZX 79.3v 10p Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chartie theo Enconformer	GEC Decoder Panel PC772 PC444	2A3 5A5 £6 2	100 W/W 3F 199 $10 \times 20 \text{ T}$ 3F 470 20 Slider 1	Res. £1.50 20 for £1 20 for £1 îurn 100k pots. Rank £2 20 for £2 Knobs ,
BA 301 £1 TA 4127 £1 HD 3884 2A23 £3 TA 4184 £1 TA 2125 £1 TA 4190 £1 TA 4198 £1	- TIP 29 20 TIP 30 35 TIP 30A 35 TIP 30B 40 TIP 30C 45 TIP 31 30 TIP 32 25 TIP 33B 50 TIP 33C 70	BZX 79.3v 10p BZX 79.3v 10p Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chasis type Transformer 240v/12 Volts 500m/a 75p	SONY 1400KV Touch butte GEC Decoder Panel PC772 PC440	2A3 5A5 56 2	00 W/W 3F 199 0 × 20 T 3F 470 20 Slider 1 5 Mixed L	Res. £1.50 furn 100k pots. 20 for £1 furn 100k pots. Rank 20 for £2 20 for £2 Knobs 70p JHF Aerial Isolating Sockets. Sockets.
BA 301 £1 TA 4127 £1 HD 3884 2A23 £3 TA 4184 £1 TA 2125 £1 TA 4184 £1 TA 4190 £1 TA 4138 £1 TA 4138 £1 TA 4136 £1 TA 4174 €1	- TIP 20 25 TIP 30 355 TIP 30A 355 TIP 30B 400 TIP 30C 455 TIP 31 300 TIP 32 255 TIP 33B 500 TIP 33C 700 TIP 34A 500 TIP 34B 500	BZX 79.3v 10p BZX 79.3v 10p Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma75p Chassis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20	SONY 1400KV Touch butto GEC Decoder Panel PC77 PC440 Tube Base 20AX GEC PC	2A3 25A5 26 2 852B3 £1 5F	100 W/W 3F 199 $10 \times 20 \text{ T}$ 3F 470 20 Slider 1 5 Mixed U come with Philips, Py	Res. 21.50 Furn 100k pots. 20 for £1 Furn 100k pots. Rank 20 for £2 70p JHF Acrial Isolating Sockets. 10ng leads. Fit ITT, GEC. re £1.00
BA 301 £1 TA 4127 £1 HD 3884 2A23 £3 TA 4184 £1 TA 2125 £1 TA 4190 £1 TA 4138 £1 TA 4190 £1 TA 4138 £1 TA 4139 £1 TA 4190 £1 TA 4190 £1 TA 4198 £1 TA 4199 £1 TA 4198 £1 TA 4198 £1	- TIP 20 20 TIP 30 35; TIP 30A 35; TIP 30B 40p TIP 30B 40p TIP 31 30p TIP 32 25; TIP 33B 50p TIP 33C 70p TIP 34A 50p TIP 34B 60p TIP 34B 50p TIP 34B 50p	BZX 79.3v 1000 Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma75p Chassis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20 6v-9v-13v tape motor 75p	SONY 1400KV Touch butto GEC Decoder Panel PC77 PC44k Tube Base 20AX GEC PC Thorn Aerial Socket TX10	2A3 2530 E 2A3 266 2 852B3 £1 5 £1	000 W/W 3F 199 $10 \times 20 T$ 3F 470 20 Slider 1 5 Mixed U come with Philips, Py	Res. 20 for £1 Furn 100k pots. Rank £2 20 for £2 10 for £3 10
BA 301 £1 TA 4127 £1 HD 3884 2A23 £3 TA 4184 £1 TA 2125 £1 TA 4190 £1 TA 4138 £1 TA 4138 £1 TA 4190 £1 TA 4196 £1 TA 4196 £1 TA 4196 £1 TA 4198 £1 TA 4199 £1	- TIP 20 20 TIP 30 35; TIP 30A 35; TIP 30B 40p TIP 30B 40p TIP 31 30p TIP 32 22; TIP 33B 50p TIP 33A 50p TIP 34B 60p TIP 34B 60p TIP 34B 50p TIP 35D 80p	BZX 79.3v 10p BZX 79.3v 10p Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20 6v-9v-13v tape motor 75p Infra red led LD57CA 15p	SONY 1400KV Touch butto GEC Decoder Panel PC772 PC440 Tube Base 20AX GEC PC Thorn Aerial Socket TX10	2A3 E1 E1 CA E1 OF CA	100 W/W 3F 199 10×20 T 3F 470 20 Slider 1 5 Mixed U come with Philips, Py TO66 12 1 Replacement	Res. 215.0 20 for £1 1 furn 100k pots. Rank Knobs . 20 for £2 20 for £3 20 f
BA 301 £1 TA 4127 £1 HD 3884 2A23 £3 TA 4184 £1 TA 2125 £1 TA 4184 £1 TA 4184 £1 TA 4190 £1 TA 4138 £1 TA 4139 £1 TA 4174 £1 TA 4196 £1 TA 4198 £1 TA 4198 £1 TA 4198 £1 TA 4198 £1 TA 4199 £1 BA 546 £1 BA 328 £1	- TIP 20 20 TIP 30 335 TIP 30A 355 TIP 30B 40p TIP 30B 40p TIP 31 30p TIP 32 255 TIP 33B 50p TIP 33B 50p TIP 34B 60p TIP 34B 60p TIP 35B 50p TIP 35B 50p TIP 35B 50p TIP 35C 70p TIP 36C 70p	BZX 70502 100 BZX 79.3v 100 Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20 6v-9v-13v tape motor 75p Infra red led LD57CA 15p AT 4041/41 transductor £1 15K.20 turn pots 200	SONY 1400KV Touch butto GEC Decoder Panel PC77 PC440 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M	2A3 £1 5A5 £6 2 852B3 £1 \$ £1 (A £1.00 1	100 W/W 3F 199 10×20 T 3F 470 20 Slider 1 5 Mixed L come with Philips, Py TO66 12 1 Replacement Kits 50 Mixed	Res. 21.50 Furn 100k pots. Rank Knobs . 20 for £1 20 for £2 20
BA 301 £1 TA 4127 £1 HD 3884 2A23 £1 TA 4184 £1 TA 2125 £1 TA 4184 £1 TA 2125 £1 TA 4184 £1 TA 4190 £1 TA 4138 £1 TA 4139 £1 TA 4139 £1 TA 4139 £1 TA 4139 £1 TA 4167 £1 TA 4167 £1 TA 4174 £1 TA 4196 £1 TA 4196 £1 TA 4198 £1 TA 4199 £1 TA 4167 £1 TA 4176 £1 TA 4176 £1 TA 4176 £1 TA 4145 £1	- 11P 29 24 TTP 30 335 TTP 30A 355 TTP 30B 440 TTP 30B 440 TTP 31 300 TTP 32 255 TTP 33B 550 TTP 33A 500 TTP 34A 500 TTP 34B 600 TTP 35B 550 TTP 35B 550 TTP 35C 700 TTP 35C 700 TTP 36C 700 TTP 36C 700 TTP 41B 400	BZX 70502 100 BZX 79.3v 100 Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20 6 v-9v-13v tape motor 75p Infra red led LD57CA 15p AT 4041/41 transductor £1 In5K-20 turn pots 20p Thorn panel 6×100 pot + chanceover switch (frish) 50n	SONY 1400KV Touch butto GEC Decoder Panel PC772 PC44c Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M	2A3 E1 E1 A E1.00	00 W/W 3F 199 10 × 20 T 3F 470 20 Slider 1 5 Mixed L 20 Slider 1 5 Mixed 1 5 Mi	Res. 21.50 20 for £1 20 for £1 20 for £2 20 for £2
BA 301 £1 TA 4127 £1 HD 3884 2A23 £1 TA 4184 £1 TA 2185 £1 TA 4184 £1 TA 2125 £1 TA 4130 £1 TA 4130 £1 TA 4130 £1 TA 4196 £1 TA 4196 £1 TA 4198 £1 TA 4198 £1 TA 4199 £1 BA 528 £1 TA 4167 £1 TA 4176 £1 TA 4176 £1 TA 4176 £1 TA 4176 £1 TA 4195 £1 TA 4145 £1 TA 4191 £1 HA 11710 £1	- 11P 29 24 TTP 30 335 TTP 30A 335 TTP 30B 440 TTP 30B 440 TTP 31 300 TTP 32 25 TTP 33B 500 TTP 33A 500 TTP 34A 500 TTP 34A 500 TTP 34A 500 TTP 35D 700 TTP 35D 800 TTP 35C 700 TTP 36C 700 TTP 41B 40 TTP 48 40	BZX 70502 100 BZX 79.3v 100 BZX 79.3v 100 Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20 6 v-9v-13v tape motor 75p Infra red led LD57CA 15p AT 4041/41 transductor £1 15K-20 turn pots 20p Thorn panel 6×100 pot + changeover switch (Irish) 50p Thorn 3500 2A cut out 50p	SONY 1400KV Touch butte GEC Decoder Panel PC77 PC440 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY204/4	2A3 E1 SA5 £6 2 SA5 £6 2 852B3 £1 F £1 (A £1.00 1 1 1 25 for £1.00	too local sector 100 W/W 3F 199 $10 \times 20 \text{ T}$ 3F 470 20 Slider 1 5 Mixed U 20 Slider 1 5 Mixed L 7066 12 H Replacement $Kits50 Mixed25 Panel h10A25 LED r20/UC Hall$	Res. 21.50 Furn 100k pots. Rank Knobs . 20 for £1 20 for £2 20
BA 301 £1 TA 4127 £1 HD 3884 2A23 £1 TA 4184 £1 TA 2184 £1 TA 4184 £1 TA 4184 £1 TA 4185 £1 TA 4190 £1 TA 4138 £1 TA 4138 £1 TA 4139 £1 TA 4196 £1 TA 4198 £1 TA 4199 £1 TA 4167 £1 TA 4176 £1 TA 4185 £1 TA 4185 £1 TA 4185 £1 TA 4188 £1 TA 4188 £1 TA 4188 £1 TA 4197 £1	- 11P 29 24 TIP 30 335 TIP 30A 355 TIP 30B 4407 TIP 30B 4407 TIP 31 307 TIP 32 255 TIP 33B 507 TIP 33A 507 TIP 34A 507 TIP 34A 507 TIP 34A 507 TIP 34B 607 TIP 35D 807 TIP 35C 707 TIP 35C 707 TIP 35C 707 TIP 35C 707 TIP 35C 707 TIP 36C 707 TIP 36C 707 TIP 40 707 TIP 40 707 TIP 42/08C 6109 300 TIP 42 400 TIP 49 300	BZX 70502 100 BZX 79.3v 100 BZX 79.3v 100 Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20 6v-9v-13v tape motor 75p Infra red led LD57CA 15p AT 4041/41 transductor £1 15K-20 turn pots 20p Thorn panel 6×100 pot + changeover switch (firsh) 50p Thorn 3500 2A cut out 50p	SONY 1400KV Touch butte GEC Decoder Panel PC77 PC446 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY2064 W005 bridge	2A3 E 2A3 E 3A5 £6 2 852B3 £1 E £1 (A £1.00 E 25 for £1.00 E 20 for £2	two rescales of the task of t	Res. 21.50 Part 100k pots. Rank 20 for £1 furn 100k pots. Rank 20 for £1 20 for £2 20 for £2 2
BA 301 £1 TA 4127 £1 HD 3884 2A23 £1 TA 4184 £1 TA 2184 £1 TA 4184 £1 TA 4184 £1 TA 4185 £1 TA 4190 £1 TA 4138 £1 TA 4139 £1 TA 4196 £1 TA 4198 £1 TA 4199 £1 BA 528 £1 TA 4167 £1 TA 4167 £1 TA 4176 £1 TA 4176 £1 TA 4185 £1 TA 4191 £1 TA 4191 £1 TA 4188 £1 TA 4188 £1 TA 4197 £1 TA 4197 £1 TA 4197 £1 TA 4197 £1	- 11P 29 24 TTP 30 335 TTP 30A 355 TTP 30B 4407 TTP 30B 4407 TTP 31 307 TTP 32 255 TTP 33B 507 TTP 33A 507 TTP 34A 507 TTP 34A 507 TTP 34A 507 TTP 35D 807 TTP 35C 707 TTP 35C 707 TTP 35C 707 TTP 35C 707 TTP 35C 707 TTP 36C 707 TTP 36C 707 TTP 36C 707 TTP 40 30 TTP 40 30 TTP 40 30 TTP 40 30 TTP 57 300 TTP 102 30	BZW 7060v2 10p BZX 79.3v 10p BZX 79.3v 10p Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20 6v-9v-13v tape motor 75p Infra red led LD57CA LD57CA 15p AT 4041/41 transductor £1 15K-20 turn pots 20p Thorn panel 6×100 pot + changeover switch (Irish) 50p Stereo GEC amp 20 watt + pre- amp with 4 pots + mains power	SONY 1400KV Touch butte GEC Decoder Panel PC77 PC446 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY204/4 BY206 W005 bridge KT3 touch button black G11 touch button black	en unit £3.50 E 2A3 E 5A5 £6 2 852B3 £1 E £1 (A £1.00 E 25 for £1.00 E 25 for £1.00 E 6 for £1 E	$100 \ \text{W/W}$ $3F \ 199 \ \text{O} \ \times 20 \ \text{T}$ $3F \ 199 \ \text{O} \ \times 20 \ \text{T}$ $3F \ 470 \ \text{O} \ \text{Sider} \ 1$ $5 \ \text{Mixed} \ \text{L}$ $5 \ \text{Mixed} \ 12 \ \text{Replacema}$ $50 \ \text{Mixed} \ 25 \ \text{Arab} \ 12 \ \text{Small} \ 1$ $10A \ 25 \ \text{LeD} \ \text{T}$ $20 \ \text{J/C} \ \text{Hol} \ 20 \ \text{Large} \ 20 \ \text{J/C} \ \text{Hol} \ 20 \ \text{Small} \ 100 \ \text{Toruge} \ 1$	Res. 21.50 Part 100k pots. Rank 20 for £1 20 for £2 20 for £2
BA 301 £1 TA 4127 £1 HD 3884 2A23 £1 TA 4184 £1 TA 2125 £1 TA 4184 £1 TA 4184 £1 TA 4184 £1 TA 4184 £1 TA 4190 £1 TA 4138 £1 TA 4138 £1 TA 4138 £1 TA 4139 £1 TA 4198 £1 TA 4167 £1 TA 4199 £1 HA 11710 £1 TA 4185 £1 TA 4186 £1 TA 4187 £1 TA 4188 £1 TA 4183 £1	- 11P 29 24 TIP 30 335 TIP 30A 355 TIP 30B 440 TIP 30B 440 TIP 30C 45 TIP 31 300 TIP 32 25 TIP 33B 500 TIP 33A 500 TIP 34A 500 TIP 34A 500 TIP 34A 500 TIP 35C 700 TIP 35C 700 TIP 35C 700 TIP 35C 700 TIP 36C 700 TIP 36C 700 TIP 36C 700 TIP 36C 700 TIP 36C 700 TIP 376 400 TIP 376 500 TIP 100 TIP 100 TIP 115 500 TIP 117 500	BZW 7060v2 10p BZX 79.3v 10p Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20 6v-9v-13v tape motor 75p Infra red led 15p LD57CA 15p AT 4041/41 transductor £1 15K-20 turn pots 20p Thorn panel 6×100 pot + thorn 3500 2A cut out Stereo GEC amp 20 watt + pre- amp with 4 pots + mains power unit with circuit £6	SONY 1400KV Touch butte GEC Decoder Panel PC77 PC446 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY2064 BY206 W005 bridge KT3 touch button black G11 touch button black G11 ouch button black	2A3 E1 2A3 E2 5A5 £6 2 5A5 £6 2 5A5 £6 2 5A5 £6 2 6 6 852B3 £1 5 £1 (A £1.00 1 25 for £1.00 20 for £2 6 for £1 5 5 with 3 57 00 1 57	too tax, 00 w/w 3F 199 00 x 20 T 3F 470 20 Slider 1 5 Mixed U 5 Mixed U 5 Mixed 12 1 12 Slider 1 5 Mixed 2 50 Mixed 25 Panel N 10A 25 LED r 20 Large 1 20 Cmultiple 1 20 Small 1 102 Cmultiple 1 20 Cmultiple	Res. 21.50 Part 100k pots. Rank 20 for £1 20 for £1 20 for £2 20 for £2
	- 11P 29 24 TIP 30 335 TIP 30A 355 TIP 30B 440 TIP 30B 440 TIP 30C 45 TIP 31 306 TIP 32 25 TIP 33B 500 TIP 33A 500 TIP 34A 500 TIP 34A 500 TIP 34A 500 TIP 35C 700 TIP 35C 700 TIP 35C 700 TIP 35C 700 TIP 36C 700 TIP 36C 700 TIP 36C 700 TIP 36C 700 TIP 36C 700 TIP 376 400 TIP 376 500 TIP 376 500 TIP 376 500 TIP 42/BRC 6109 300 TIP 42/BRC 6109 300 TIP 42/BRC 6109 300 TIP 48 400 TIP 49 300 TIP 102 300 TIP 102 300 TIP 115 500 TIP 117 500 TIP 126 400	BZX 70.502 100 BZX 79.3v 100 BZX 79.3v 100 Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20 6v-9v-13v tape motor 75p Infra red led LD57CA 15p AT 4041/41 transductor £1 ISK-20 turn pots 20p Thorn panel 6×100 pot + thangeover switch (Irish) 50p Thorn 3500 2A cut out 50p Stereo GEC amp 20 watt + pre- amp with 4 pots + mains power unit with circuit £6	SONY 1400KV Touch butte GEC Decoder Panel PC77 PC446 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY2064 W005 bridge KT3 touch button black G11 touch button black G11 touch button black G11 touch button black K30 full remote Dawer As I.C. VHF. UHF Dawer A	en unit £3.50 F 2A3 F 5A5 £6 2 852B3 £1 5 £1 (A £1.00 1 25 for £1.00 2 26 for £1 60 2 6 for £1 50 5 5 00 £1 60 5 5 00 5 1 50 5 5 00 5 0 5 1 50 5 5 0 5 0 5 1 50 5 5 0 5 0 5 0 5 0 5 5 0 5 0 5 0 5	100 W/W 3F 199 10 × 20 T 3F 470 20 Slider 1 5 Mixed U come with Philips, Py TO66 12 1 Replaceme Kits 50 Mixed 12 25 Panel h 10A 25 LED r 20//C Hoi 20 Jurge 20 Sider 10 Trans 20 Conver 10 Therm 20 Sider	Res. 21.50 Part 100k pots. Rank 22 20 for £1 20 for £2 20 for
	- TIP 20 20 TIP 30 35; TIP 30A 35; TIP 30B 407 TIP 30B 407 TIP 31 309 TIP 32 25; TIP 33B 500 TIP 33A 507 TIP 34B 601; TIP 34B 601; TIP 34B 601; TIP 35B 507 TIP 35B 507 TIP 35C 700 TIP 36C 700 TIP 36C 700 TIP 36C 700 TIP 41B 700 TIP 41B 700 TIP 41D 700 TIP 42/BRC 6109 300 TIP 42/BRC 6109 300 TIP 420 300 TIP 40 300 TIP 15 500 TIP 15 500 TIP 125 350 TIP 126 400 TIP 127 40 300	BZX 70.502 100 BZX 79.3v 100 BZX 79.3v 100 Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20 6v-9v-13v tape motor 75p Infra red led LD57CA 15p AT 4041/41 transductor £1 15K-20 turn pots 20p Thorn panel 6×100 pot + changeover switch (1rish) 50p Thorn 3500 2A cut out 50p Stereo GEC amp 20 watt + pre- amp with 4 pots + mains power unit with circuit £6 SPECIAL OFFER Deca-TIT etc.	SONY 1400KV Touch butte GEC Decoder Panel PC77 PC446 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY2044 BY206 W005 bridge KT3 touch button black G11 touch button black G11 touch button red K30 full remote Dawer As I.C. K30 VHF. UHF Dawer A BY298 3 amp/fast/R BU126	en unit £3.50 F 2A3 F 5A5 £6 2 852B3 £1 S £1 7 (A £1.00 1 25 for £1.00 25 for £1 so 10 55 £6.00 55 £6.00 55 £6.00 55 £6.00 55 £6.00 55 £6.00 50 50 50 50 50 50 50 50 50 50 50 50 5	100 W/W 3F 199 3F 199 3F 199 3F 470 20 Slider 1 5 Mixed 1 5 Mixed 1 5 Mixed 1 5 Mixed 2 5 Panel h 10 25 Panel h 10 25 LED r 201/C Hol 20 Large 20 J/C Hol 20 Large 20 J/C Hol 20 Large 20 Slider 30 Presets 40 glass n	Res. 21.50 Provide the second
BA 301 £1 TA 4127 £1 HD 3884 2A23 £1 TA 4184 £1 TA 4184 £1 TA 4184 £1 TA 4184 £1 TA 4180 £1 TA 4190 £1 TA 4138 £1 TA 4198 £1 TA 4198 £1 TA 4199 £1 TA 4167 £1 TA 4167 £1 TA 4176 £1 TA 4176 £1 TA 4176 £1 TA 4183 £1 TA 4175 £1 TA 4175 £1 TA 4175 £1 TA 4146 £1	TIP 20 24 TIP 30 35; TIP 30A 35; TIP 30B 40r TIP 30B 40r TIP 30C 45; TIP 31 30; TIP 32 25; TIP 33B 50; TIP 34B 60; TIP 35C 70; TIP 35B 50; TIP 35B 50; TIP 35C 70; TIP 36C 70; TIP 36C 70; TIP 41B 40; TIP 40 30; TIP 100 30; TIP 115 50; TIP 100 30; TIP 115 50; TIP 126 40; TIP 130 25; TIP 130 25; TIP 130; 30; TIP 130; 30;	BZW 7060v2 10p BZX 79.3v 10p Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/12 Volts 500m/a 75p Chussis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20 for 9v-13v tape motor 75p Infra red led 15p LD57CA 15p AT 4041/41 transductor £1 15K-20 turn pots 20p Thorn a500 2A cut out 50p Stereo GEC amp 20 watt + pre- amp with 4 pots + mains power £6 SPECLAL OFFER Deca-TTT etc. FEO4/1/250AC/4 Mains filters (grey type) × 4 50p	SONY 1400KV Touch butte GEC Decoder Panel PC77 PC446 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY2044 BY2046 W005 bridge KT3 touch button black G11 touch button black G11 touch button black G11 touch button black G11 touch button red K30 full remote Dawer As I.C. K30 VHF. UHF Dawer A BY208 3 amp/fast/R BU126 BU105	2A3 E1 SA5 £6 2 SA5 £6 6 E1 £1 (A £1.00 1 25 for £1.00 25 for £1.00 25 for £1.00 25 for £1.00 25 for £1.00 20 for £1 so 10 for £1 so £6.00 10 for £8.00 10	100 w/x3 100 w/x3F 199 100 x 20 T 3F 470 20 Slider 1 5 Mixed U 5 Mixed V 50 Mixed 25 Panel N 10A 25 LED r 20 Large 20 Large 20 Large 20 Large 20 Large 10 A 21 LD r 20 Large 10 A 20 Large 10 Convet 10 Term 20 Slider 30 Press t 40 Pots 40 Pots	Res. 21.50 Purn 100k pots. Rank 22 20 for £1 20 for £2 20 for
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	TIP 20 235; TIP 30A 35; TIP 30B 340; TIP 30B 440; TIP 30B 440; TIP 30C 45; TIP 31 30; TIP 32 25; TIP 33B 50; TIP 34B 60; TIP 35B 50; TIP 35C 70; TIP 35C 70; TIP 36C 70; TIP 41B 40; TIP 40;/BRC 6109 30; TIP 40; 30; TIP 40; 30; TIP 100 30; TIP 115 50; TIP 125 35; TIP 130 25; TIP 131 25; TIP 131 25; TIP 140; 50; TIP 140; 50;	BZX 70.502 100 BZX 79.3v 100 BZX 79.3v 100 Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20 Gv-9v-13v tape motor 75p Infra red led LD57CA 15p AT 4041/41 transductor £1 INFR.20 turn pots 20p Thorn panel 6×100 pot + changeover switch (Irish) 50p Thorn 3500 2A cut out 50p Stereo GEC amp 20 watt + pre- amp with 4 pots + mains power unit with circuit £6 SPECIAL OFFER Deca TIT etc. FEO441/250AC/4 Mains filters (grey type) × 4 50p	SONY 1400KV Touch butte GEC Decoder Panel PC77 PC440 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY2044 BY206 W005 bridge KT3 touch button black G11 touch button	en unit £3.50 F 2A.3 F 5A.5 £6 2 5A.5 £6 2 5A.5 £6 6 £1 7 (A £1.00 1 25 for £1.00 25 for £1.00 25 for £1.00 20 for £1.50 10 for £8.00 10 for £1.50 10 for £1.00 20 for £1.60 10 for £1.00 20 for £1.40 10 for £1.00 100 for £1.00 10 for	100 W/W 100 W/W 101 × 20 T 101 × 20 T 102 × 20 T 104 × 20 T 104 × 20 T 105 × 20 T 104 × 20 T 105 × 20 T 104 × 20 T 105 × 20 T	Res. 21.50 Res. 20 for £1 Furn 100k pots. Rank 20 for £2 20 fo
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	TIP 20 24 TIP 30 35; TIP 30A 35; TIP 30B 40; TIP 30C 45; TIP 31 30; TIP 32 25; TIP 33B 50; TIP 33C 70; TIP 33B 50; TIP 34B 60; TIP 35B 50; TIP 35C 70; TIP 35C 70; TIP 35C 70; TIP 36C 70; TIP 41B 40; TIP 40; 70; TIP 40; 30; TIP 100; 30; TIP 115 50; TIP 131 25; TIP 131 25; TIP 131 25; TIP 131 25; TIP 130 30; TIP 130 30; TIP 130	BZX 70.502 100 BZX 79.3v 100 BZX 79.3v 100 Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20 Gv-9v-13v tape motor 75p Infra red led LD57CA 15p AT 4041/41 transductor £1 ISK-20 turn pots 20p Thorn panel 6×100 pot + changeover switch (Irish) 50p Thorn 3500 2A cut out 50p Stereo GEC amp 20 watt + pre- amp with 4 pots + mains power unit with circuit £6 SPECLAL OFFER Decca-TTT etc. FEO-4/1/250ACT4 Mains filters (grey type) × 4 50p BRIDGES KBL 005 30p	SONY 1400KV Touch butte GEC Decoder Panel PC77 PC440 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY2044 BY206 W005 bridge KT3 touch button black G11 touch button black G12 touch button	cm unit £3.50 E 2A3 F 1 5A5 £6 2 \$652B3 £1 5 £1 £1 1 (A £1.00 1 25< for £1.00	100 W/W 100 W/W 151 199 100 Slider 1 100 Large 1 100 Large 1 100 Large 1 100 Large 1 100 Large 1 100 Convert 100 Therm 100 Trans 100 Jones 1 100 Jones 1	Res. 21.50 Res. 20 for £1 Furn 100k pots. Rank Knobs . 20 for £2 20 for £
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	BZW 7050210pBZX 79.3v10pBZX 79.3v10pBush thyristor RCA 76122£1Transformer 240v/20v-500Ma 75pChassis type Transformer240v/12 Volts 500m/a75pCVC 20 tube base£2Tube Base Rank & G11£1.206v-9v-13v tape motor75pInfra red ledLD57CALD57CA15pAT 4041/41 transductor£115 K-20 tum pots20pThorn panel 6×100 pot +changeover switch (Irish)50pThorn 3500 2A cut out50pStereo GEC amp 20 watt + pre-amp with 4 pots + mains powerunit with circuit£6SPECLAL OFFERPoteca-TTT etc.FEO4/1/250AC/4 Mains filters(grey type) × 4 50pBRIDGESKBL 00530pKBF 0430p	SONY 1400KV Touch butte GEC Decoder Panel PC77 PC440 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY2044 BY206 W005 bridge KT3 touch button black G11 touch button black G10 VHF. UHF Dawer As BU205 BU105 BF458 BF224 OA90 S0 Ceramic Condensers Mixed Mounting Kit for P Transistors	cm unit £3.50 E 2A3 F 1 5A5 £6 2 \$652B3 £1 F £1 £1 1 (A £1.00 F 25 for £1.00 25 for £1 5 for £1.00 5 6 for £1 5 with 3 5 £6.00 10 for £8.00 10 for £8.00 10 for £8.00 10 for £8.00 10 for £1.00 20 for £1.50 with 3 £1.50 with 3 5 50 for £1.50 10 for £8.00 10 for £8.00 10 for £8.00 10 for £1.00 20 for £1.50 20 for £1.40 40 for £1.00	100 W/W 100 W/W 151 199 100 X 20 T 154 740 20 Slider 1 156 Mixed U 156 Mixed U 157 066 12 1 Replaceme Kits 107 Mixed 25 Panel N 108 20 Korbs 20 Small 1 107 20 Tu 100 Trans 20 Conve 10 Therm 20 Slider 30 Presets 40 glass m 10 press t 40 pos 5 Tube B 1,000 Dio Bandolier 20 Knobs 20 Knobs 20 Knobs 20 Knobs 20 Knobs	Res. 21.50 Res. 20 for £1 Furn 100k pots. Rank 20 for £1 20 for £2 20 for £1 20 fo
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	BZX 70.50210pBZX 79.3v10pBZX 79.3v10pBush thyristor RCA 76122£1Transformer 240v/20v-500Ma 75pChassis type Transformer240v/12 Volts 500m/a75pCVC 20 tube base£2Tube Base Rank & G11£1.206v-9v-13v tape motor75pInfra red ledLD57CALD57CA15pAT 4041/41 transductor£115K-20 turn pots20pThorn panel 6×100 pot +changeover switch (Irish)50pThorn 3500 2A cut out50pStereo GEC amp 20 watt + pre-amp with 4 pots + mains powerunit with circuit£6EBL05Stepe (Lat OFFER (grey type) × 4 50pBRIDGES30pKBL 00530pKBL 0230pKBP 0430pW0215pW0415b	SONY 1400KV Touch butte GEC Decoder Panel PC77 PC440 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY2044 BY206 W005 bridge K13 touch button black G11 touch button to black G11 touch button toblack G11 touch button touc	cm unit £3.50 E 2A3 5 £6 1 5A5 £6 2 2 \$S52B3 £1 £ 6 £1 1 1 1 (A £1.00 1 1 25 for £1.00 2 2 6 for £1 5 2 6 for £1 5 2 5 £6.00 10 5 10 for £8.00 10 10 10 for £1.00 2 5 20 for £1.50 10 5 5 £6.00 10 10 20 for £1.00 2 1.00 20 for £1.00 2 1.00 2 20 for £1.00 1.00 2 1.00 2 20 for £1.00 £1.50 5 5 5	100 W/W 100 W/W 15 199 10 × 20 T 16 × 20 T 17 470 10 Slider 1 10 Mixed 10 A 10 A 10 A 10 X 20 Tu 10 X 20 Tu 10 X 20 Tu 10 X 20 Tu 10 Z 0 Sinder 10 Dresst 40 glass ri 10 presst 40 glass ri 10 presst 20 Sinder 10 presst 40 glass ri 10 presst 20 Slider 10 presst 40 glass ri 10 presst 20 Slider 20 Slider 20 Slider 20 Slider 20 Slider 20 Slider 20 Slider 10 presst 40 glass ri 10 presst 40 glass ri 10 presst 40 glass ri 10 presst 40 glass ri 40 glass ri	Res. 21.50 Res. 20 for £1 Furn 100k pots. Rank 20 for £1 20 for £1 20 for £2 20 fo
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	BZX 70.502 100 BZX 79.3v 100 BZX 79.3v 100 Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/12 Volts 500m/a 75p CVC 20 tube base £2 Tube Base Rank & G11 £1.20 6 v-9v-13v tape motor 75p Infra red led LD57CA 15p AT 4041/41 transductor £1 ISK-20 turn pots 20p Thorn panel 6×100 pot + changeover switch (Irish) 50p Thorn 3500 2A cut out 50p Stereo GEC amp 20 watt + pre- amp with 4 pots + mains power unit with circuit £6 SPECIAL OFFER Deca TTT etc. FEO4/1/250AC/4 Mains filters (grey type) × 4 50p KBL 005 30p KBP 04 30p W004 15p W005 20p	SONY 1400KV Touch butth GEC Decoder Panel PC77 PC440 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY2044 BY206 W005 bridge KT3 touch button black G11 touch button red K30 full remote Dawer As I to Button black G10 button black G11 touch button red K30 full remote Dawer As I to Button black G10 Condensers 300 Cenamic Condensers 300 Cenamic Condensers 300 Cenamic Condensers 300 Cenamic Condensers 300 Resistors 300 Dawer As I to Button black G11 button black G11 button black G11 touch button red K30 full remote Dawer As I to Button black G11 button black G11 button black G11 touch button red K30 full remote Dawer As I button black G11 button black G11 touch button red K30 full remote Dawer As I button black G11 button	cm umit £3.50 E 2A3 F 1 5A5 £6 2 5A5 £6 2 \$\$52B3 £1 F £1 1 1 \$\$(A £1.00 1 \$\$25 for £1.00 2 2 \$\$25 for £1.00 2 2 \$\$25 for £1.00 2 2 \$\$6 for £1 6 6 \$\$2 for £1.50 2 5 \$\$2 for £1.60 1 6 \$\$2 for £1.50 1.50 1 \$\$2 for £1.50 1.50 1 \$\$2 for £1.50 1.40 1 \$\$2 for £1.40 40 for £1.40 1 \$\$2 for £1.50 5 5 \$\$2 for £1.50 5 5 \$\$2 for £1.50 5 5	100 W/W 100 W/W 15 199 10 × 20 T 10 Slider 1 10 A 25 Panel N 10 A 25 Panel N 10 A 25 Panel N 10 A 20 Small 1 10 A 20 Small 1 10 A 20 Small 1 10 A 20 Slider 1 10 Presets 40 glass n 10 press t 40 glass n 10 press t 40 glass n 10 press t 40 glass n 10 press t 40 Slider 20 Slider 2 20 Slider 20 Slider 2 10 Slider 20 Slider 2 10 press t 40 Slider 20 Slider 2 10 Sl	Res. 21.50 Res. 20 for £1 Furn 100k pots. Rank 20 for £1 20 for £2 20 for £1 20 fo
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	TIP 30 335 TIP 30A 365 TIP 30B 440 TIP 30B 440 TIP 30C 457 TIP 33B 500 TIP 33C 700 TIP 35C 700 TIP 35C 700 TIP 36C 700 TIP 40 700 TIP 40 30 TIP 100 30 TIP 130 30	BZX 70.502 10p BZX 79.3v 10p BZX 79.3v 10p Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/12 Volts 500m/a 75p Chusis type Transformer 240v/20v-500Ma 75p Chusis type Transformer 240v/20v-500Ma 75p Chusis type Transformer 240v/12 Volts 500m/a Tube Base Rank & G11 £1.20 D57CA 15p AT 4041/41 transductor £1 15K-20 turn pots 20p Thorn panel 6×100 pot + changeover switch (Irish) Thorn 3500 2A cut out 50p Stereo GEC amp 20 watt + pre- amp with 4 pots + mains power unit with circuit £6 SPECIAL OFFER Decca-TTT etc. FEO-4/1/250AC/4 Mains filters 30p KBL 005 30p KBL 002 30p W004 15p W005 20p	SONY 1400KV Touch butte GEC Decoder Panel PC77 PC440 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY204/4 BY206 W005 bridge KT3 touch button black G11 touch black G11 touch black G11 tou	on unit £3.50 E 2A3 F F 5A5 £6 2 5A5 £6 2 \$\$52B3 £1 F £1 1 1 \$\$(A\$ £1.00 1 1 \$\$25 for £1.00 2 2 \$\$26 for £1 5 5 \$\$26,000 10 10 \$\$26,000 10 10 \$\$26,000 10 10 \$\$21,50 1.00 2 \$\$25,50 £1.50 £1.50 \$\$2,00 40p 5 \$\$2,00 40p 5	100 W/W 100 W/W 15 199 10 × 20 T 15 470 10 Slider 1 10 A 25 Panel N 10 A 25 Panel N 10 A 20 LED r 20 JWC Hol 20 Large 2 20 JWC Hol 20 Large 2 20 Convet 10 Trans 20 Convet 10 Convet 10 Trans 20 Convet 10 Trans 20 Convet 10 Convet 10 Trans 20 Convet 10 Convet	Res. £1.50 Purn 100k pots. Rank 20 for £1 Yurn 100k pots. Rank £2 20 for £2 20 for £1 21 HF Acrial Isolating Sockets. 100g leads. Fit ITT, GEC. 10 mixed Packs Power Trans RCA 16182 NPN Power Trans RCA 16182 NPN £1.00 AC series Transistor £4.50 Mount Bulbs & Neons £1.50 iders £1.20 LED Red £1.00 LED Red £1.00 istor £2.50 regence Pots \$00 ises £1.00 ises, Condensers, Resistors on des, St.100 £1.00 ises, St.100 £2.00 ises, Condensers, Resistors on des, St.100 £2.00 ises, St.100 £2.00 ises, Condensers, Resistors on des, St.100 £2.00 ises, St.100 £2.00 ises, Condensers, Resistors on des, St.100 £2.00 ises, St.100 £2.00 ises, St.100 £2.00 ises, Mail 20 for £1
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	BZW 70502 10p BZX 79.3v 10p BZX 79.3v 10p Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 75p Chassis type Transformer 240v/12v-500Ma 75p Chassis type Transformer 75p Tube Base Rank & G11 £1.20 Thom panel 6×100 pot + thangeover switch (Irish) Thom panel 6×100 pot + thans power Thom 3500 2A cut out 50p Stereo GEC amp 20 watt + pre- pre- amp with 4 pots + mains power unit with circuit £6 SPECIAL OFFER Decca-TTT etc. FEO4/1/250AC/4 Mains filters (grey type) × 4 50p \$0p KBE 005 \$0p KBE 005 \$0p W004 15p W005 20p Thorn Chassis U916D Complete Complete £10	SONY 1400KV Touch butto GEC Decoder Panel PC77 PC446 Tube Base 20AX GEC PC Thom Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY2044 BY206 W005 bridge KT3 touch button black G11 touch button black G11 touch button black G11 touch button red K30 full remote Dawer As I.C. K30 VHF. UHF Dawer As BY208 3 amp/fast/R BU126 BU205 BF458 BF224 OA90 S0 Ceramic Condensers Mixed Mounting Kit for P Transistors 300 Resistors 15 Bulbs Philips Antistatic Discloth	con unit £3.50 E 2A3 F F 5A5 £6 2 \$52B3 £1 F £1 7 F (A £1.00 2 25< for £1.00	100 W/W 100 W/W 151 199 100 X201 T 154 7470 100 Slider 1 101 Slider 1 102 Slider 1 103 Slider 1 104 Slider 1 104 Slider 1 104 Slider 1 104 Slider 1 104 Slider 1 104 Slider 1 105 Slider 1 100 Slid	Res. \$1.50 Particle State 20 for £1 Furn 100k pots. Rank \$2 20 for £2 20 for £2 20 for £2 20 for £1 10 glass F1 ITT, GEC. ye £1.00 Mixed Packs Power Trans RCA 16182 NPN ent for BD124 and Mounting Power Trans RCA 16182 NPN ent for BD124 and Mounting £1.00 AC series Transistor £4.50 Mount Bulbs & Neons £1.50 tedsycllow/green £1.50 tedsrs £1.00 iders £1.00 istor £1.00 istor £1.00 istor £1.00 istor \$0 omake switch £1.00 omake switch £1.00 fount 20 for £1 100 mixed £2.50 dotes, Small 20 for £1 d Diodes £1 (Cap Pots 1TT-GEC-Hitachi-
	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	BZW 70502 10p BZX 79.3v 10p BZX 79.3v 10p Bush thyristor RCA 76122 £1 Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/20v-500Ma 75p Chassis type Transformer 240v/20v-500Ma 75p Tube Base Rank & G11 £1.20 Tube Base Rank & G11 £1.20 D57CA 15p AT 4041/41 transductor £1 15K-20 turn pots 20p Thom panel 6×100 pot + changeover switch (Irish) 50p Thorn 3500 2A cut out 50p Stereo GEC amp 20 watt + pre- amp with 4 pots + mains power unit with circuit £6 Stereo GEC amp 20 watt + stere grey type) × 4 50p BRIDGES 30p KBL 005 30p W004 15p W004 15p W005 20p Thorn TX9 Remote Panels with 1C.s £10	SONY 1400KV Touch butte GEC Decoder Panel PC77 PC446 Tube Base 20AX GEC PC Thom Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY2044 BY206 W005 bridge KT3 touch button black G11 touch button b	on unit £3.50 E 2A3 5 £6 2 3A5 £6 2 2 \$852B3 £1 £ 7 (A £1.00 2 5 25 for £1.00 2 5 25 for £1.00 2 6 25 for £1.00 2 5 20 for £2 6 for £1 5 with 3 £7.00 2 5 66.00 10 for £1.50 10 for £6.00 10 for £1.00 20 for £1.00 2 5 20 for £1.00 2 5 21.50 £1.50 £1.50 £1.50 21.50 £1.50 £1.50 £1.50 21.50 £1.50 £1.50 £1.50 5 for £1 5 5 5 5 for £1 5 5 5 5 <td< td=""><td>100 W/W 100 W/W 15 199 10 × 20 T 15 Mixed U come with Philips, Py 10 Silder 1 16 Mixed U 17 Office 12 I Replaceme Kits 10 Mixed 12 Spanel h 10 A 20 Silder 1 10 × 20 Tu 10 Trans 20 Convet 10 Trans 5 Tube B 1,000 Dio Bandolier 20 Knobs 200 Mixee 10 0 1.225 Mixed V/V Philips et TT Mair</td><td>Res. 21.50 Yurn 100k pots. Rank 20 for £1 Yurn 100k pots. Rank 22 20 for £2 20 for £2 yorn factor 70p JHF Acrial Isolating Sockets. 100g leads. Fit ITT, GEC. ye £1.00 Mixed Packs 100 Power Trans RCA 16182 NPN £1.00 ent for BD124 and Mounting £1.00 AC series Transistor £4.50 Mount Bulbs & Neons £1.50 iders £1.20 LED Red £1.00 IED Red £1.00 rgence Pots \$00p istor £2.50 rgence Pots \$0p sed switch £1.90 isces £1.00 for fall 20 for £1 00 mixed £2.50 fount 20 for £1 100 mixed £2.50 xdes, small 20 for £1 d Diodes £1 I/A Fuse £1 Cap Pots 1TT-GEC-Hitachi- £1 for £1 20 is tors £1.00 is tors £1.00 is tors £1.00 is tors £1.00 fount 20 for £1 <</td></td<>	100 W/W 100 W/W 15 199 10 × 20 T 15 Mixed U come with Philips, Py 10 Silder 1 16 Mixed U 17 Office 12 I Replaceme Kits 10 Mixed 12 Spanel h 10 A 20 Silder 1 10 × 20 Tu 10 Trans 20 Convet 10 Trans 5 Tube B 1,000 Dio Bandolier 20 Knobs 200 Mixee 10 0 1.225 Mixed V/V Philips et TT Mair	Res. 21.50 Yurn 100k pots. Rank 20 for £1 Yurn 100k pots. Rank 22 20 for £2 20 for £2 yorn factor 70p JHF Acrial Isolating Sockets. 100g leads. Fit ITT, GEC. ye £1.00 Mixed Packs 100 Power Trans RCA 16182 NPN £1.00 ent for BD124 and Mounting £1.00 AC series Transistor £4.50 Mount Bulbs & Neons £1.50 iders £1.20 LED Red £1.00 IED Red £1.00 rgence Pots \$00p istor £2.50 rgence Pots \$0p sed switch £1.90 isces £1.00 for fall 20 for £1 00 mixed £2.50 fount 20 for £1 100 mixed £2.50 xdes, small 20 for £1 d Diodes £1 I/A Fuse £1 Cap Pots 1TT-GEC-Hitachi- £1 for £1 20 is tors £1.00 is tors £1.00 is tors £1.00 is tors £1.00 fount 20 for £1 <
BA 301 £1 TA 4127 £1 HD 3884 2A23 £1 TA 4124 £1 TA 2125 £1 TA 4184 £1 TA 4184 £1 TA 4184 £1 TA 4184 £1 TA 4190 £1 TA 4138 £1 TA 4138 £1 TA 4138 £1 TA 4196 £1 TA 4197 £1 TA 4199 £1 BA 328 £1 TA 4167 £1 TA 4167 £1 TA 4176 £1 TA 4167 £1 TA 4176 £1 TA 4183 £1 TA 4183 £1 TA 4183 £1 TA 4183 £1 TA 4177 £1 TA 4175 £1 TA 4175 £1 TA 4197 £1 TA 4197 £1 TA 4197 £1	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	BZX 70.50210pBZX 79.3v10pBZX 79.3v10pBush thyristor RCA 76122£1Transformer 240v/20v-500Ma 75pChassis type Transformer 240v/12 Volts 500m/a75pCVC 20 tube base£2Tube Base Rank & G11£1.20Gv-9v-13v tape motor75pInfra red led15pLD57CA15pAT 4041/41 transductor£115K-20 turn pots20pThorn panel 6×100 pot +changeover switch (1rish)50pThorn 3500 2A cut out50pStereo GEC amp 20 watt + pre-amp with 4 pots + mains powerunit with circuit£6SPECLAL OFFERDeca.TTT etc.FEO-4/1/2S0AC/4 Mains filters(grey type) × 4 50pW00415pW00520pThorn Chassis U916DComplete£10Thorn TX9 Remote Panels withI.C.s£2.50Thorn 9000 4 Slider Front Panel	SONY 1400KV Touch butth GEC Decoder Panel PC77 PC440 Tube Base 20AX GEC PC Thorn Aerial Socket TX10 12 Volt Mains Trans 500M Quantity Reduct BY2044 BY206 W005 bridge KT3 touch button black G11 touch button	con unit £3.50 F chas £6 2 chas £6 2 chas £6 2 shas £6 2 shas £6 2 shas £6 2 shas £1 1 shas £1.00 1 chas £1.00 2 chas £1.00 2 chas £7.00 2 chas £1.00 20 chas £1.00 20 chas £1.50 £1.50 chas £1.50 £2.00 stillistic £1.50 £2.00 stillistic £1.50 £2.00 stillistic	100 W/W 100 W/W 151 199 105 X20 X20 X20 105 X20 X20 X20 105 X20 X20 X20 105 X20 X20 X20 105 X20 X20 X20 107 X20 X20 X20 100 Trans 20 Slider 20 Slider 10 Tresst 40 Pots 5 Tube B 1,000 Dio Bandolier 20 Knobs 20 Chrube 20 Mixed 20	Res. 21.50 20 for £1 20 for £1 20 for £2 20 for £1 20 fo

TELEVISION AUGUST 1987

	SENDZ TO ORDER S	COMPONENTS EE BACK PAGE	G11 Chroma Panel Rank T20 Z136 Panel NEW 1617 THORN Chassis with ICs & AUU NEW GEC 20AX Power Supply Switch Mox Complete new GEC portable chassis M1201	13 Je H/M1501H with P.B.U./	£5.00 £6.00 £5.00 £12.00	Tube Thermpath 167 £1.00 Rank Secam Decoder Panel UHF & VHF T115A £13.00 10 off .91 CAP G11 £2 £13.00 Philips K4 CAP ISUM/385V 50n 50n
	Matsushita PY34220 Tuner £ Toshiba VHF/UHF EG411 £ Toshiba VHF/UHF EG522F £ Mitsumi MEC1-F51 £ Thorn Spares New 9000 Decoder £8.5	7 K13 Decoder £8.00 6 K35 Sound OP £4.00 6 K35 Spith Diode 3122-138-35930 £10.00 7 Thick Film Daughter KT3 3122-127-43891 £10 7 LC. H. K30 Tex Rec Front Panel with U.C. £5	v.cap/LOPT1 Field + Jungle panel for GEC 3133/3135 GEC 2110 line panel with transformer GEC 2110 tune runit + 1F Panel Pye/Chelsea Linc op panel Pye 205 T/unit Pye 205 T/unit Pye 205 Line op panel	25%	£10.00 £1.50 £7.00 £12.00 £12.00 £3.90 £7.50	Multi-Caps 220 MFD Sprague 385V 50p 350V 300M + 300M £1.00 400V 400M 60p 350V 300M 60p Thorn 3500 60p
	9000 Frame panel £ £ 9000 Cyclops panel £ 1.5 8000 Cyclops panel £ 6 8000 Convergence panel £ 8000 convergence panel £ 8000 convergence panel £ 9000 convergence panel £	K35 IF £5.00 Fidelity Tube Base with transitor & focus pol	Pyc 713 IF panel and tuner Pyc 713 Chroma Pyc/CheSea Timebase panel with LOPTI Pyc 731 Frame Panel Pyc 731 Convergence Panel Pyc 731 Convergence Panel Pyc 731 Chroma	OFF ALL	£7.00 £10.00 £10.00 £5.00 £5.00 £10.00	175/100/100/350v £1.00 KT3/200/25/25/385v £1.00 200+200+75+25M 325V £1.00 300+300+150+100+50MFD 350V 2501 £1.00 2502 £1.00 2504 £20 2502 £2 2504 £20 2504 £20 2504 £20 2504 £20 2504 £20 2504 £20 2504 £20 2504 £20 2504 £20 2505 £20 2506 £20 2507 £20 2508 £208 2509 £208 2500 £208 2500 £208 2500 £208 2500 £208 2508 £208 2508 £208 2509 £208 2509 £208
	16(0) Mains lead, switch 35(0) 6 push button + cable form£1.5 76(05 1)/NPN T066 8(0//6A 10 90(0) Sound output panel £ 35(0) Focus unit £1.5 35(0) Mains Trans £	Bush Tube Base on panel \$1.00	Pye 731 IF panel + tuner Pye CDA/205 panel GEC portable chassis + LOPTI 2114 New Thorm 1613/1713 chassis G9 Power Panel Mono RANK Chassis 127A NEW	PANELS	£10.00 £6.00 £4.00 9.75 £6.00 £10.00	47/220/35(v 60p 154/154/104/101/32(v £2,00 2500/25(W/33v 50p 154/201/201/30(v 70p 304/104/104/16/25v £1,50 100/201/325v 40p
	3500 cut outs 10 for £ 3500 Frame panel £ 3500 Frame panel £ 3500 Line panel £ 3500 Line panel £ 3500 Line panel £ 3500 Frame panel £ 100 Constraints 10 for £ 100 Constraints 20 100 Export 3500 IF panel £ 100 Constraints 10 for £ 100 Constraints 10 for £	Line Transformers Line O.P. Trans. Mono T.X. 12"-14" Philips 27482 £10 4822 £10 10273 £10	NEW G9 Frame Panel NEW G11 IF Panel G8 Tuner Unit + Panel 500 G8 Power Supply 500 G8 6 Sloping PBU £12.00-		£4.00 £10.00 20p 20p 5p	150/150/100/375v £1.50 200/200/75/25M 325V £1 200/200/75/25M 325V £1 Thorn TX9 Caps 500+500M 175V £1.75 300/300/100/32/32/300v 2.00 150/150/2000/30v S0p 150/150/2000/30v S0p 150/150/2000/30v S0p
	4000 Tube base \$3500 A1 pots Beam limiter panel \$1.5 \$500 Power panel with Y969 \$3 Way regulated adaptor 240V 6V/ 7.5/9V/X00mA \$23,56	Thorn 1640 LOPT £6.50 2 J/Pots 3,500 L off each type £3.00 GN Trans. Philips £7.00 G11 Split Diode £12.00 CVCR30 Split Diode ITT £10.00 Thorn B/W ADS308F + Stik + £1.60	G81F&Chroma £10.00 G8 Chroma £3.00 Philips Batteries U2 25p U11 20p	IMFD-250AC 1/100 × 10 22/100 4.70/100 4700/100 4700/100	25p 30p 10p 5p 20p 75p	100/350 + 300/2000/100/16/275v £2.00 225+25/380 GEC 70p 200/100/100/350v £1.50 500/500/25v 50p 150/150/100/300v 75p 200/150/150/300v 1.00
L	Rank/Toshiba prch unit 0354 £9.5. 4 Push button unit prch £1.00 6 Push button VIIF/UHF for v/cap. GEC-Decca type £7.00 7 Push button for CVCS ITT 68 Push Button Unit £10.00 10 Push button for CVCS 100 10 Push button Unit £10.00 10 Push button for CVCS 100 10 Push butt	1640 Thorn EHT over-wind with diode 1640 Thorn EHT over-wind with diode 1640 E3.00 GEC 2440 £3.00 GEC 2110 £7.00 Mullard AT 2036 £1.50 Pye 169 Line Trans £3.00	PP3 40p Duracell A.A.A. 10p AEC V/Cap Resistor Unit UHF with IC	47100 300/300/ 800/160 1/250 Pulse 2.2 250v 3n3/250 A.C. .33/250V	80p 50p 5p 10p 10p 200	ITT 8 and 6 Push Button £1.00 Pyc 731 LOPTs £6.00 Pyc 731 LOPTs £6.00 Thorn 8500-8800 LOPTs £5.00 CMC 301 front panel £8.00 CMC 301 front panel £8.00
1000	KT3 (Export) 12 P.B.u £ 6 Push button Unit Thorn £1.0 6 Push button GRC £6.0 6 Push button PYE 731 £6.0 Hearing aid unit FCH £	Pye mono L5.00 Rank mono T704A £3.50 Split Diode Trans £7.00 GEC 20 AX Rank Z522 £3.00 Rank L.O.P.T. Z970 £3.00 CVC20 ITT £7.00 AT2048W15 £5.00	SAS660 SAS670 £3.00 Z714 RANK IF Panels 6MHz 1 I.C. SL437F £3.00 Z909B RANK IF Panels Export 5.5MHz 2 I.C.'s TBA1205B TCA2705O £2.50	39/250V 4n7/250 tested 5KV 22/250 47/250 100/250 G11 470/250V G11 470/250V	15p 25p 15p 10p 20p £1,75	CMD 800 Chassis. No tuner £20.00 CMD 800 Decoder £8.00 CMD 800 IF/Tuner £20.00 UPC 574 30p BSS 38 30p
	7 Button Unit GEC with Lamps £ 697 Push Button Unit £6.00 2916B panel £5.00 T513AP panel £5.00 Mains Droppers G8 2R2+68R £1.22	CVC30 IIIT £5.00 CVC32 Line Tran £7.00 CVC40 Line Trans £6.00 CVC40 Slip/Diode £12.00 CVC41 Slip/Diode £12.00 CVC 41 Slip/Diode £12.00 GEC Portable GIOT21M1 £3.00 GEC Portable GIOT21M6 £3.00	K35 IF £6.00 Z743 RANK IF Panel Export 5.5MHz 3 I.C.'s TBA 750+SC9504P + SC9503P £1.50 Pye G11 Front panel with transducer,	GEC000/250 700/250 300+300 MFD 350v 800/250 32/300 4/350 8/350	60p £1 £1,00 40p 20p 5p	G11 £1.50 11.C. Receiver Panel 31.C. Power Supply G11 Full Remote Receiver Panel £3 FET Power VN88AF 50p
-	GR 47R 15 wait £L0 Pyc 731 3+56+27R 50j Thorn 50/17/1K5 £L0 120/20/20/48/117 £L0 270/1106 for Thorn 4000 50j 18/320/70/39 £1.0 Thorn 50/17/185 £1.0	EHT Split Diode Leads ITT EL00 3500 L.O.P.T. & HT Trans each 22.00 LOPT Rank Z763 £5.00 K35 Split Diode 3122/13835930 £10.00	pots, tuner pots, 6 pb switch+lead £5.00 Pye 6 button switch portable £1.00 GEC V/cap VHF/UHF tuner and IF+ sound O/P PC 706B3 (Export) £12.00 GEC Line O/P PC 659B3 £6.00 2110 GEC Power Panel £8.00	4.770/350v 33/350 220/350 300/350 400/350 10/375	10p 20p 30p 40p 50p 10p	PHILIPS SBC 469 Stereo Microphone £23,00 Meters Hills 520 £17,00 Meters Hills 420 Hills HD5000 Digital Meter 1000V DC 750AC 10 Amp 20 MRG Rangers £28
	Ac Socket & Lead GEC, ITT. Philips. Pyc 25 7×3 ³ 4 Thorn (50)-17(1) £1.50 Rank Toshiba Tube Bases 30 Sneakers	Black Triplers S.T.C. Universal Tripler £5.00 II TJT £2.50 II TGA £2.00 ITT CVC 5-8-9 £3.50 Rank T25LE Tripler £2.00	CVC 20 Front panel with stiders + mains input panel \$4 CVC 40 PUSH BUTTON ASSY with sliders: complete with lamp assy + pots 8 and 12 button units \$9,00 CVCV slider pots panel \$0p	22/375 220/385 (1TT) 330/385 CVC 820HT 3.1/400 KT3 E/W .39/400 .56K/400v	15p 75p 60p 15p 15p 20p	HT100 Multimeter £6,75 HT300 Multimeter £7,75 HT300 Multimeter £9,00 HD1000 Digital £20,00 HD3000 Digital £25,00 HD5000 Digital £25,00
	6×4 G11 25 ohm £1.00 \$ ¹ / ₂ ×2 ¹ / ₂ 3 ohm £1.00 \$×3 80 ohm 700 \$×3 50 ohm 500 \$×3 350 ohm 500 \$×4 15 ohm £1.00 \$×4 bonk £1.00	Rank 111CP AR23 £3,50 TU 25 30K Rank £3,00 11 TEZ Rank £3,00 G9 Philips £4,00 GEC 2110 £4,00 3600 Thorn £3,00	Universal Focus. Fits Pye, Thorn and Decca Units. T147 Rank tube base on panel £1.00 Z718 Focus Unit £1.50 T20 Focus Unit £1.00	22/400 8/400 33/400 400/400 94K/400V 220/450	10p 15p 20p 40p 20p	HD6000 Digital £32.00 HD8000 Digital £37.00 Hanset Tester Works at 24 feet - Sound repeater. Works off 9 volt battery £8.00
1	7×3 70 ohm 61.00 8×5 8 ohm 15 wait £1.00 8×5 8 ohm 15 wait £1.00 7×3 16 ohm £1.00 £1.00 7×3 16 ohm £1.00 £1.00 5° dia 16 ohm £1.00 £1.00	9000 Thorn 66,00 9500 Thorn \$4,50 9600 Thorn \$4,50 9600 Thorn \$4,50 2040 GEC \$2,50 GEC Tripler \$2,00 Universal Tripler \$5,00 G8 Tripler \$5,00	Deces Small 75p Deces Small 75p KT3 Focus Unit 75p K30 Focus Pot 75p K30 Toube 95p 100 TX10 Focus Units \$7,000 CYC 32 Focus Unit 75p	47/500).1/600).1/200V wire end).1/450 A/C wire end 22/1000 047/600 047/000	25p 15p 20p 20p 20p 15p	Fits in top pocket. Repaired Handsets Philips K4-K35, RC330-RC5300, RC5370, RC5375, repaired same day £10.00 RC4001 Full Remote KT3 K30 Teletext
	5 Juni 8 ohm 21.56 6 J2" dia 4 ohm 21.56 6 J2" dia 3 ohm 21.56 J3" dia 8 ohm 75p 3 dia 8 ohm 75p 4 J2" sq. 15 ohm 75p K J3 speaker K 30 75p	Green Tripler with foacs pot £6.00 CVC 825 TT CVC 20/25/30/32 £3.50 Decca 80 100 £4.50 Grundig TVK 52 £2.50 HTBQ Pye 731 £3.00 HTHY £4.00 D22 for Pye 15" colour portable £4.00	Ecdility Focus Unit 14R-14S 30p 1 3500 Thom Focus Unit £1.00 1 ITT Small for use with Split 2718 Bush Focus £2.00 Diode 50p 1 TV11 50p 1	.047/1000).1/1000 47/1000× 47/250V A.C. 001K/1250 0047/1500	10p 10p 65p 10p 10p	Handsets exchanged £9.00 GEC Full Remote Infra-red, 1983 models £15.00 Timers, 60 mins, small £1.00 TOSHIBA
	.7 dia 15 ohm 60p 1690 5×3 12 ohm £1 K45 Philip 15 ohm 75p K30 15 watt £1 KT3-K30 ()F-425 ()F-50) F W 100	LP 119363 E4.00 BG 100/41 £3.25 ERO Tripler print type with foacs PO7 BG2087 £5 Trtext ultrasonic rec'r panel £14.00 L2-14V. 20 for £5.00 200 for £25.00	Remo TV12SP 50p 1600 Thorn EHT Rec and Lead 50p TV13 50p TV14 50p TV18 60p TV20 £10.00	005/1500 0105/1500 In8/1500 In0/1500 In2/1500 01/1600 10N 2,000V 01/1600 10N 2,000V	10p 10p 15p 15p 15p	24 Button CT938 Fullremote £5,00 32 Button CT938 Videotext £6,00 Large type ITT TV and V.C.R. Handset Handset £15,00 GEC Ultrasonic &CH Full Remote £15,00
-	OF-\$13 correction 10p OF-\$57 50p 50p BY 126 DIODES 10p BY 127 10p 10p BY 133 10p 10p	GEC 8 touch unit assy complete with all I.C.'s + pots \$4,00 G11 E.W. Transformer \$90 G11 E.W. ools \$1,00 G11 Transient Suppressors 245V 20p G11 IOW. tuner pots \$2,600	TV45 S0p Thorn 14/1500 rec stick Sp G11 drawer ASS 3 pots Mains switch and lead 22	311.82002KV h992KV h092KV h0015/2KV h02KV h0/2KV h0/2KV h22KV	15p 20p 15p 10p 15p 15p	G11 Full Remote Ultrasonic £32 G11 Touch Unit Full Remote £13 G11 Ultrasonic Teletext Handset £24.00 8 C.H. Ultrasonic GEC Full Remote C2014H/C2219H £15.00 New Replacement for G11 Ultrasonic
	b i (.54) Upp B Y (164) S0p B Y (176) 25p B Y (174) 40p B Y (184) 25p B Y (187) 10p B Y (190) 40p	K13 IF panel £6.(0) KT3 line OSC transformer £1 KT3/K20 infra-red receiver £1 K30 drawer unit with 1C's £1 K30 drawer unit with 1C's £10	K30 Drawer Ass with pots cable forme 4 Line O/P panel GEC 2217/2218/2213/ 6 2214/2226/2227/2228 £100	70pf 4KV 500pf72KV 600PF73000V m772KV m272KV m1/1500V	10p 10p 10p 15p 10p 10p	Full Remote £12.00 Thorn 4000 insert with 7 buttons £5.00 Decca RC 12 £14.00 Decca RC 12 £14.00 Oll infra-red full teletext £24.00 Dynatron-Full remote CTV 62, 63, 64
~	BY 19% 300 BY 198 100 BY 20%4 80 BY 20%40 80 BY 20%400 . № 80 BY 2104400 50 BY 2104400 100	(export) £10 KT3 AE Sockets 50p KT3 receiver panel £8 KT3 line driver transformer 50p Pye. K.W. GEC, etc. Pre-mains stand-by switch £1 Decca 80/100 F panel £5	PHILIPS BATTERIES 9 (Small Types) HAND SETS 0 SR41 40p 1 SR43 40p 40p	ht21500V in2/2KV 0082/2500 50/3500 800/4KV .7nt/5KV	10p 15p 15p 10p 5p	Hitachi infra red handset £19,00 Philips full remote KT3, 16(2928/20C934; 7228/7324; K12 26C 797/IST 66K 1826 £12,00 G11, Full remote repairs service (architecture)
÷	BY 223 600 BY 224/4001: 4.8A/6006 bridge 500 BY 226 150 BY 227 150 BY 227 1500 200 Flat BY229 black 150 BY 209 Red 200	NPN PNP 80V 6'Amp TO66 O.P. Trans. 5 button touch tuner BBC1/2 1TV1/2 video with ic SAS 560T/570T £7.00 Control panel 5 siders + mains lead£1.50 G118 touch button unit replaces old 6 P.B.11	SR54 40p 1 LR43 40p 2 LR44 40p 2 LR54 40p 1 CR2032 40p 1	70/8K∨ 80/8K∨ 10/8K∨ 000/10K∨ 47/100∨	10p 10p 10p 10p 80p	unit) all termote new ultrasonic £18.00 G11, Full remote new ultrasonic £32.00 GEC infra red full remote & channel (1.C.SAA1250) £14.00 Philips infra red full remote 9 channel for 60 CP2605
*	BY 229/400 30 BY 239/40p Tag 30p BY 237 5p BY 254 10p BY 255 30p BY 255 30p BY 299 10p	G116 touch unit replacement with dat Tube base + base unit for 820 Euro chassis GEC Line O/P Trans. & Rec Stick for Portable CVC 2025/W15/40 decoder page 10	CVC 24-25-30 Mann Switches Infra Red and Ultrasonic G11 Teletext Decoc RANK & ITT Mains Remote On-Off Switch (RANK & ITT Mains Remote Switch 2800 ohm G11 Mains Switch 4 amo Mains Switch	ler Panel 720R) n	60p £30 £1.50 £1.50 £1.50 £1.50 50p 250	Philips infra red full remote 12 channel for 60 CP2605 £12.00 K25 KT3/K30 KT3/K30 T/Text £15.00 KT3/K30 KT3/K30 Full remote £15.00 KT3/K30
	BY 40b 8p BY 527 20p BY 407a 10p BY 527 10p BY 627 10p BY 602 10p F 247 10p GP20G 10p	CVC 20/25/30/35/40 decoder panel 25 functstell 65 CVC 40/45 IF panel 25 40K Transducer 50p PHILIPS NE511N £1.20 LM337M Reg. 30p 01 GEC Black Same Come 30p	GEC Mains Switch 4 amp KT3 Mainswitch THORN Rotary Mains Switch GI1 Preh Red LED P/Button for C.H. Chang RANK TOSHIBA Transductors TPC-2011 Mains Switch ITT Long Type Print	ze	30p £1.00 50p 20p 50p 75p	GEC 8 button full remote £14,00 GEC 8 button full remote £14,00 GEC push pad handset button blobs 10p each Pye & Philips handset KT3-K30 chassis, No RC5150-RC5176-RC5171-RC5177, Sneich Duis
	XK 3102 30 BYV 28/200 200 BYV 28/200 200 Milv/2.75 amps 100 International Rectifier EHT Diodes GA/600V Stud Diodes 200 6A/1000V Stud Diodes 200	BTW AUSI Selection \$21,00 Assy. Back Sop \$25,807 BTW AUSI Sop Sop \$307 PTW-134 6K V 3 for 8p BTW 92/800R £3 S25A473 PNP C/P 10p \$309 \$309	Mains Switch Frillip Long Type TAG Mains Switch GEC Long Type TAG Thorn 12 or 24 volt battery convertor for port 2000 Chassis Fidelity Mains Switch (4 TAG) 250V/4A White Lordin Mains Switch (6 T Teletext Adaptor Kit TY-500 Panasonic	able colour T/V AG)	/5p 75p £6.00 60p £1 £12	RC4001 KT3 and Teletex £14.00 IT CVC 32 handset repaired £15.00 PHILTS UNIVERSAL HAND SET £16.00 KT3 - K45 We have all parts for Philios Handsete

iii

