

INDEX TO TELEVISION VOLUME 53

November 2002 to October 2003

Pages	Issues
1-64	November 2002
65-128	December 2002
129-192	January 2003
193-256	February 2003
257-320	March 2003
321-384	April 2003
385-448	May 2003
449-512	June 2003
513-576	July 2003
577-640	August 2003
641-704	September 2003
705-768	October 2003

AUDIO FAULT FINDING

Aiwa CSD-MD5K	743
Aiwa CSD-SR540K	679
Aiwa CX-Z1800K	679
Aiwa CX-ZM2600UK	565
Aiwa CX81MK	180
Aiwa DX990	437
Aiwa NSX5909	679
Aiwa RX-N5K	309
Aiwa XRM25	44
Aiwa ZR770	614
Amstrad MC2900	565
Arcam Alpha 8R	679
B&O Beolit 700	244
Denon DC30	244, 288
Freeplay S360	181
Goodmans S4475	501
Goodmans System 2850	565
Goodmans System M500	742
JVC AX50	678
JVC CA-D5T	565
JVC CA-MXJ75R	743
JVC CAS30 Midi hi-fi	44
JVC UXT100N	101
JVC VS-DT2000R	743
JVC XLE3	244
Kenwood 1080	373
Kenwood RXD-3L	436
Kenwood RXD-F4L	565
Kenwood RXD-M33MD	180
Kenwood RXD551	614
Kenwood XA3L	44
LG ADR620	614
Macgregor BG100	373
Marantz CP230	309
Marconi 345	679
Marshall Valuestate Model 8008	180
Musical Fidelity B1 integrated amp	309
NAD 613 cassette deck	565
NAD Model 304	564
Nakamichi CR3	679
Numark radio-mic system	373
Nytech C252 amplifier	373
Panasonic SA-AK28	615
Panasonic SA-PM30MD	565
Panasonic SAFX1	101
Panasonic SAPM01	372
Philips AZ1005	565
Philips AZ1101	373
Philips C104	679
Philips FW12	44
Philips FW670P	245
Pioneer MIS21 amplifier	373
Pioneer NS-11TQ	564
Pioneer PD8700	501
Pioneer PM603	373
Pioneer TX9100	679
Pioneer VSAE07, VSX908RDS	101
Pioneer XC-L11 CD	614
Pioneer XR-P470C + S-P470V speakers	308
Revox A700	679
Sanyo DC-F280U	500
Sanyo JCX-X5 tuner	44
Sanyo MD-MX30H	372
Sanyo MD-MX30H	309
Schneider 2290 Midi	244
Sharp CD-BA1200H	501
Sharp CD-BA1700H	54
Sharp CD-CH1000	615
Sharp MD-SR60E(GL)	679
Sherwood RX1010	679

Sony CDP-CX235	436
Sony CDP-CX235	180
Sony CDP-H3750	743
Sony CDP-M35	564
Sony D240 personal CD player	181
Sony DEJ835	614
Sony HCD-A190	309
Sony HCD-BX3	437
Sony HCD-CP100	501
Sony HCD-CP33	373, 436
Sony HCD-ED1	245, 501, 564
Sony HCD-EP30	101
Sony HCD-EP50	101
Sony HCD-EP707	678
Sony HCD-EX1	437, 565
Sony HCD-G1	436
Sony HCD-H1200	372
Sony HCD-H4900	436
Sony HCD-H51	614
Sony HCD-H51M	372
Sony HCD-H650M midi system	501
Sony HCD-H901AV	564, 615
Sony HCD-M70	309
Sony HCD-MD373	436
Sony HCD-N355	615
Sony HCD-RG30	742
Sony HCD-RX70	373
Sony HCD-RX99	244
Sony HCD-RXD3	309
Sony HCD-RXD5	743
Sony HCD-XB200	437
Sony HCD-XB500	180
Sony HCDCP33	101
Sony HST-V302	615
Sony HTC-NX1	101, 678
Sony ICF-SW100E	373
Sony LBT-D359	742
Sony MDS-JE520	501
Sony MHC-EX7 system	500
Sony MZ-N1	564
Sony MZ-N707	308, 678
Sony MZ-R35	436
Sony MZ-R55 MiniDisc unit	501
Sony MZ-R900	743
Sony MZ-R91	501
Sony MZR-700PC	615
Sony MZR50 MiniDisc recorder	564
Sony MZR700	372
Sony MZR90	373
Sony RX77S	309
Sony SA-WM525	564
Sony SA-WMS7	309
Sony STR-DB1080	564
Sony STR-DB830	437
Sony STR-DE135	373
Sony STR-DE475	308, 437
Sony STR-H100	500
Sony STR-NX1	590
Sony TA-FE230	743
Sony TA-S7AV	500
Sony TA-VE100	501
Sony TA-VE150 integrated AV amp	244, 614
Sony TA-VE215	678
Sony TA818M	309
Sony TC-TX313CEK	436
Sony TC158SD	309
Sony ZS-D50	743
Tascam MD801R	373
Technics CH7 system	101
Technics RS-TR373	742
Technics SA-CH550	437
Technics STX990L tuner	180
Toshiba SJ3429	309
Trio KR-4070-L	743
Welltech car radio	615
Yamaha CRX-M5	501
Yamaha CT7000	679

CAMCORDERS

PC-camcorder connection problems	
Steve Beeching IEng MIEE	266, 413

DVD FAULTS

Bush DVD1000	58
Bush DVD2013	550
Dansai DVD1010	486
Dual-layer disc incompatibility	341
Grundig GDP51UO	378
H + B DVD4155S	424
Hitachi HTDK150E	122
JVC XV-S302SL	378
JVC XV-THA5R	550
Kenwood DVR7000	314
Kenwood RXD-DV50	122
Kenwood RXD-DV9	58
Oritron DVD600	736
Panasonic DVD-LA65	736
Panasonic NV-VHD1B-S	378
Panasonic SA-HT70	597
Panasonic SA-HT80	378
Panasonic SAHT80	122
Panasonic SCHT70	58
Philips DVD711	186, 661
Philips LX3000D	250
Pioneer DV454S	314
Pioneer DV515	736
Proline DVD1000	58
Samsung DVD-S224	736
Sanyo JCX-TS750 Home theatre	486, 597
Sharp DV600H	58
Sharp DV740	314
Sharp DV740H	314
Sony DAV-S300	122
Sony DAV-S400 or HCD-S400	314
Sony DVD-NS300	597
Sony DVD-SL20	661
Sony DVP-NC600	661
Sony DVP-NS300	186, 661, 736
Sony DVP-NS305	736
Sony DVP-S300	250
Sony DVP-S336	250
Sony HCD-S300 home cinema	186, 250, 486, 736
Sony HCD-S400	424
Sony HCD-S500	186, 550
Sony HCD-S550	550
Sony HCD-S800	314, 486, 661, 736
Sony HCD-S880	424, 486
Technics SLDV250	122
Toshiba SD110 and SD210	58
Toshiba SD110EB	58
Toshiba SD210EB	424
Toshiba SD22VB DVD player	661

DVD problem <i>Steve Roberts</i>	341
Dangerous stuff <i>Martin Pickering</i>	119
Do we need terrestrial TV? <i>Bill Wright</i>	551
EEPROM reprogramming jig <i>Sharp Technical team</i>	200, 341
Faulty PC electrolytics <i>Jack Armstrong</i>	209
Faulty scan coils <i>Michael Dranfield</i>	54, 183
Grundig digiboxes <i>Jack Armstrong</i>	182
Heater-cathode shorts <i>Martin McCluskey et al</i>	54, 118, 288
Hints and tips <i>Martin Pickering</i>	732
How long? <i>Peter Graves</i>	118
JVC HRJ610EK <i>John C Priest</i>	209
LOP transistors, DTT reception <i>Philip Lane</i>	54
Large-screen TVs in workshop <i>Laurie Watkinson</i>	692
Live-test ESR checker <i>Ian Field</i>	153, 208
Magic past <i>Phil Avis</i>	119
Magnetism problem <i>Geoff Darby</i>	244, 288
Mains voltage problem <i>Ian Johnson</i>	118, 183
Microwave ovens <i>Michael Dranfield</i>	113, 182, 288
Model numbers <i>Graham Bond</i>	209
Monitor LOPTs <i>Steve Hague</i>	182
Monitor information and spares <i>A Jacques</i>	183, 288
Monitors etc <i>Mark Garton</i>	412
Multimeter fuses <i>Nicholas Arnold BDS</i>	341
Nokia monitors <i>Mark Garton</i>	540, 600, 733
PC-camcorder connections <i>Steve Beeching</i>	266, 413
Passing thoughts <i>Brian Gilbert</i>	119
Philips AA5 AA chassis <i>Martin Cole</i>	628
Poor TV set design <i>Ray Withey</i>	551
RSL TV stations <i>Jane Scarfe</i>	412
Samsung SCT11D chassis <i>Chris Avis</i>	209
Scratched discs <i>Geoff Darby</i>	692
Sharp DA100 chassis <i>Philip Salkeld</i>	406, 551, 628
Sharp DS chassis, Freemans' mod <i>Philip Salkeld</i>	119
Silicon planar process <i>Keith Scott</i>	628
Skills shortage <i>Steve Pendlebury</i>	208
SkyStar 2 boards <i>Paul Sansom</i>	628, 650
Spares and faulty scan coils <i>Matthew Biddlecombe</i>	54, 183
Starting up <i>Mike Adye</i>	210
Test card please <i>David Payne</i>	628
Thomson ICC7 chassis <i>Pete Howarth</i>	551, 628
Those were the days <i>Philip Bearman</i>	732
TiVo <i>Michael Maurice</i>	487, 628
Timer <i>Steve Hague</i>	732
Toshiba C5SS chassis <i>Cyril Snapshaw</i>	346, 412
Transistor problem <i>Derek Minns</i>	692
Useful projects <i>Symon McCabe</i>	412
VCR SCART puzzle <i>Keith Cummins</i>	692
Video resolution <i>Richard Russell</i>	518, 628
WEEE Directive <i>Alan Jones</i>	183
Where there's a will <i>Peter Nutkins</i>	488

DX-TV & SATELLITE RECEPTION

An enthusiast's satellite receiver <i>Roger Bunney</i>	676
High-dielectric aerial <i>Roger Bunney</i>	356
Long Distance Television <i>Roger Bunney</i>	34, 98, 162, 226, 290, 354, 420, 482, 546, 610, 674, 738
Satellite dish maintenance <i>Roger Bunney</i>	290
WW2 TV from the Eiffel Tower <i>Roger Bunney</i>	100

LEADERS & COMMENTS

Freeview's good start	131
ITV's mergers	67
In-store TV	259
New Year reflections	195
Sony's business planning	323
The Weinstock era	1
TV display options	387
An adventurous life	451, 628
The extended warranty business	515
Have we lost the way?	579
Nostalgia or what?	643
TV politics	707

LETTERS

A warning <i>Michael Dranfield</i>	487
An odd condition <i>Matthew Biddlecombe</i>	487
As we were <i>Philip Bearman</i>	412
Asbestos danger	119
Audio fault <i>Peter Graves</i>	413
BSkyN and ex-directory numbers <i>Steve Roberts</i>	552
Battery polarity protection <i>Jim Littler</i>	732
Bin it? <i>Frank Mills-Clifton</i>	551, 692
Car radios <i>Nicholas Arnold</i>	488
Check your work! <i>Geoff Darby</i>	54
Coherer revisited <i>Ian Harland</i>	278, 341
DIY solutions <i>Philip H Bearman</i>	551

MICROWAVE COOKERS

Bench notes <i>Adrian Gardiner</i>	113, 177, 196
------------------------------------	---------------

MISCELLANEOUS

Memoirs of a cable technician <i>Mike Rutherford</i>	604
Obituary: Ian Charles Beckett	488
Scots Family Robertson, The <i>Tom MacDougall</i>	139
WEEE looms closer <i>William Dell</i>	116

MONITOR FAULTS

ADI L5032TD	429
ADT 2018 PSU	553
AOC 5VLR	489
AOC MM415, Atari-converted	490
AOC Spectrum 5VLR	682
Acer JD144F	173
Advance OS2000R oscilloscope	237
Apple M4681	428
Apple M6300 Performa computer	617
Apple M6496	682
Apple Macintosh Power PC 7100	682
Apricot XJ55639 (VT17)	489
Apricot XJ57560	553
Apricot XJ58210	428
AST LR14	173
AST TE1564G	682
AST TE1764G	300
ASTVision 4L (CMC-1423B1)	41
Atari SM124	300
CTX 1415GM	490
CTX 1465D	109
CTX 1565D	40, 173, 236
CTX 1565GM	236
CTX PL7+	301
Cheer VGA Autoscan VC1024	40
Chuntex (CTX) 1769E	365
Compaq 140	365

Compaq 171FS (Model 490)	301
Compaq 440	41
Compaq 445	429
Compaq 450	172
Compaq S510	428
Compaq V55 (Model 612T)	618, 746
Compaq V90	301
Daytec DT1730 (Daewoo)	364
Dell 1028LR (Philips CM6800 chassis)	554
Dell 1600HS	237
Dell D1025HE 1000HS (Nokia 447S061)	733
Dell P1428E	682
Dell P790	173
Digital PCXCV-VA	618
Digital VRT17-W3 (Sony chassis)	301
Elonex MN022 (Philips chassis)	108
Elonex MN069	40
Elonex TE1464G	490
Elonex XV17	172
Elonex/AST TE1464G	108
Enact JD144H	745
Essex PV772IM	236
Fujitsu Siemens 151E (5Elr)	489
Fujitsu/ICL ErgoPro 141V	364
Gateway 2000 EV900 (Model X19001)	745
Gateway 2000 Model 500CS	490
Gateway EV500	683
Hansol 501P (Model B15BL)	617
Hansol 710P (Model E17CL)	41
Hansol Mazellan 900P (Model B19AL)	617, 681
Hewlett-Packard D2800A (Panasonic H)	428
Hewlett-Packard D2825	173
Hewlett-Packard DeskJet 640C	429
Hewlett-Packard Pavilion MX70 (C7E)	41
Hitachi CM1587M	681
IBM 6332-002	745
IBM 6540	301
IBM 6540-02N	41
ICL ErgoPro141V (Hyundai chassis)	617
IDEK Iiyama MF5317	681
Iiyama S102GT	618
Iiyama Visionmaster 501 (S101GT)	301
Iiyama S700J1	365
JD144L	490
KDS KD1510	428
LVI Magnilink X14	746
LVI/Magnalink A4GAR picture unit	554
Line output transformer problems	182
Logix LGX173F	617
Medion MD1772ie (Acer 7277)	301
Mitac MB03, type L1555GD-1	489
Mitsubishi TFW9105SKTKW	364
Mitsubishi XJ64880	489
Nech CA6515DL (Model no. CA6525DL)	429
Nech Checksum CB6525	428
Packard Bell 1412SL	300
Packard Bell A726 (Tatung chassis)	364
Packard Bell C920	554
Panasonic TC15M1M	429
Philips 17A8808Q	745
Project LM1564	172
Project LM1764	429
Project PD697	300
Proview 564DM	489
Proview PK770M	364, 428, 489, 554
RM C7BBR	554
Relisys Teco KM511, chassis C411	489
Royal 14in mono VGA Atari monitor	108
Royal X1448	746
SM785F	490
Samsung CQA4147L	173
Samsung SyncMaster 15GLi	40
Samsung SyncMaster 17GLi (CMG7377L)	617
Samsung SyncMaster 3 (CVM4967T)	365
Sony CPD200EST	745
Tandon TC0511	365
Taxan EV2280	489
Taxan EV865	429
Taxan ErgoVision 730	300
Taxan ErgoVision 747 Model G786PYW	681
Tests after dead mains fuse	429
Time/LG 520Si	618
Viewsonic E70	618
Viewsonic P810	745
Viglen Envy 17DS (V7PAV1)	681

MONITOR SERVICING

Nokia monitors servicing <i>Donald M Henry</i>	540, 600, 733
--	---------------

PC SERVICING

Bench Notes (Adrian Gardiner)	310, 374, 561, 625, 689, 753
-------------------------------	------------------------------

PROJECTS

EEPROM reprogramming jig <i>Sharp Technical Team</i>	200, 341
ESR checker, Live-test <i>Ian Field</i>	153, 208
Motorised garage door control <i>Keith Cummins</i>	14

REVIEWS: TEST REPORTS

Coship CDVB3188C satellite receiver <i>Roger Bunney</i>	676
ERSA PCB rework station <i>Michael Dranfield</i>	710
Email box, A low-cost <i>Martin Pickering</i>	332
Grundig GDT1500 DTT adapter <i>Peter Marlow</i>	198
HS Publications D500 DX-TVconverter <i>Roger Bunney</i>	741
Icom IC-PCR1000 <i>Cyril Willis</i>	588
Pure Evoke-1 DAB radio <i>Peter Marlow</i>	262
SkyStar 2 PC satellite receiver <i>High Cocks</i>	628, 650
Sony RM-VL700T Universal RC Unit <i>Jeff Scoins</i>	476
Spectralook satellite monitor <i>Roger Bunney</i>	8

REVIEWS: SHOWS, SEMINARS & VISITS

CES 2003 Las Vegas <i>George Cole</i>	326
JVC's progressive world <i>George Cole</i>	716
RETRA Service Conference 2003 <i>Eugene Trundle</i>	662
Smart Show 2003 <i>Goerge Cole</i>	524

SATELLITE TV FAULTS

A new fireplace & electrician <i>Eddie</i>	566
Amstrad DRX100	38, 167, 232, 295, 360, 502, 632
Amstrad DRX200	103, 232, 502
Amstrad DRX300	295, 568, 632
Asiavision news exchange	696
BBC FTV changeover on Astra 2D	695
BBC's number games	759
BBC's regional variations	759
C-band reception	39, 102, 166, 230, 294, 358, 440, 503, 567
Cable troubles	102, 166
Digibox fault summary	104
Digibox missing EPG channels	230
Digiboxes 'Dead'	294
Digital channel updates	39, 102, 166, 230, 294, 358, 439, 503, 567, 631, 695, 759
Downloads	568
Grundig GDS200 Digibox	38, 104, 232, 295, 438, 502, 568, 631, 632, 696
Grundig GDS200 series	438
Grundig GDS310	295, 568, 696
Humax CR5510	360
Humax IRCi5400	503
Intelsat 605 update	230
Ku-band reception at 43 degrees W	760
LNB cross-polarisation	692
LNB problems	758
Middle East newsfeeds	504
Mobile phone interference	631
Multi-satellite radio reception	358
Pace 2200 Digibox	103
Pace 2300 Digibox	103, 232, 295, 696
Pace 2400 Digibox	760
Pace 2500S	630
Pace 2500S3 Digibox	632
Panasonic TU-DSB20 Digibox	567, 696
Panasonic TU-DSB30 Digibox	568
Panasonic TU-DSB31 Digibox	38, 167, 360, 438
Panasonic digiboxes	760
Radio volume levels	182
Sony VTXS750U digibox	294
Sony VTXS760 digibox	502
Test cards, Unusual	696
Twin-LNB problem	631, 696, 760
	38

SATELLITE TV SERVICING

Digibox, Connecting a VCR <i>Keith Cummins</i>	692
Satellite dish maintenance <i>Roger Bunney</i>	290

SERVICING, GENERAL

Accessories Guide <i>Eugene Trundle</i>	218, 282
Adhesives, Know your <i>Pete Roberts</i>	74
ChipQuick SMD removal kit <i>Steve Beeching</i>	454
Dehumidifier repairs <i>David Benyon</i>	598
Jack's Workshop <i>Jack Armstrong</i>	52, 209, 544, 613
PAT testing, Practical <i>Ian Rees</i>	394
Practical field servicing <i>Ian Rees</i>	582
Tom Baker's tales <i>Tom Baker</i>	78
Under the bench <i>Chris Avis</i>	224

TELETOPICS

3D Technology	68
3D-video consortium	389
Advanced set-top box IC	325
Amstrad wins BskyB orders	452
Analogue TV switch-off	452
BBC's satellite move	388
BF AV LCD TV sets	5
Blu-ray recoder, First	388
Business news	5, 581
Camera-phones	325
Car radio problem	708
Chip developments	5
Chomerics thermal gap fillers	68
Combined screen	453
Corrections & satellite update	196
DAB radio	261
DAB update	644
DTT aerials	645
DTT receiver, Philips	645
DTT, Japanese	645
DVD developments	516
DVD news	197, 261
DVD players, Progressive-scan	645
DVD update	453
Digital Home Working Group	709
Digital multimeter, New	324
Digital sound projector	68
Dish planning regulations	453
Engineer shortage	68
Euro HDTV	580
Exhibition dates	68
Finlux returns	197
First MHP Licence	132
Flying wing transmits TV	4
Freeview & those ITV digiboxes	261
Freeview is here	68
German's first switch-off	708
Global display solutions	197
Government pushes digital TV	325
Grundig withdraws from UK	325
Grundig's insolvency	452
Hard disk developments	196
Henkel Loctite Adhesives	68
Institutions plan merger	581
JVC news	261
LCD TV with DVD player	261
LCD TV with DVD player	644
LCOS rear-projection TV	132
Latest TV indexes	132
Linux for CE	645
MPEG-4 developments	260
Memory Sticks, New-generation	261
Microsoft's Media Center	709
Mirror TV	581
Multi contact	133
Multistandard mains-battery TV	133
New TV	389
OLED display technology	580
OS for domestic electronics	197
Obituary	261
On-line broadcasting	389
Optical HD video transmission	68
Optical disc technology	68, 324
PVR news	389
Pace launches personal video	4
Panasonic DVD recorder, New	325
Panasonic's servicing move	708
Philips add DTV to analogue TV	516
Philips news	325
Philips wireless TV link	68
Photo printing new standards	197
Plant closures	516
Plasma displays	325
Polymer display technology	5
Powerhouse receivership	708
Progressive scanning with DVDs	4
Projection TV development	5
Projection system from Sony	324
Radio repair service	260
Samsung LCD Panel	68
Samsung aims at LCD leadership	581
Satellite news	132
Service 2003 Exhibition	196
Set-top boxes	517
Sharp Projector	260
Sharp and Loewe join forces	453
Sky cards and RC unit, New	644
Sky services	133

Sky's results	708
Sony Camcorder developments	260
Sony technology	453
Sony's networking system	68
Sony's new camcorders	709
Step forward with MHP	5
TTI news	196
TV with 5.1 sound	5
TVs, New models	133
Tele-Lift	325
Tele-Lift	581
Thurlby Thandar instruments	709
Time-limited DVDs	580
UK TV setmaking declines	324
Vehicle productivity boosting	452
Video format, New	644
Video news	68
Video news	580
Vintage Radio	68

TEST CASES

Aerial distribution (480)	79
Aerial problem (479)	36
Digibox (481)	165
Hitachi C2114T (489)	685
Hitachi VTF860 (485)	423
JVC HRD910 (483)	280
Mini-DV camcorder (488)	621
Samsung CI14FIT5X (S15A) (482)	225
Satellite Reception (484)	344
Sharp VCMH54M (487)	557
Sony Music Centre (486)	493
Tatung TUV8A02 (490)	749

THEORY & DESIGN

Coaxial cables, Modern <i>J LeJeune</i>	154
Coherer revisited, The <i>Ian Rees</i>	278
DVD, from tape via a PC <i>Colin McCormick</i>	518
Distributing analogue & digital <i>J LeJeune</i>	330
Lightning strikes, When <i>Mike Rutherford</i>	352
Low-drop linear regulators <i>Ray Porter</i>	478
Optical amplifiers <i>J LeJeune</i>	646
Pace Twin Digital TV recorder <i>Peter Brough</i>	534
Philips' latest technology <i>George Cole</i>	390
Sky+ update <i>Goerge Cole</i>	5
Sony's Cyber-shot U digital cameras <i>Ralf Buckstone</i>	134
Sony's latest technology <i>George Cole</i>	756
Television software <i>Brian Storm</i>	414
The future: very small & very fast <i>Ralf Buckstone</i>	74

TV FAULT REPORTS

Alba CTV3409 (11AK08 chassis)	559
Alba CTV3458	112
Alba CTV5984	496
Alba CTV841	367
Akai CT2159UT	367
Akai CT2870 (Nokia Comp D2 FST)	469, 590
Akai TV2835	469
Akura ATPTVO28WSS (PT92 chassis)	687
Amstrad CTV1410 (Onwa 8214)	303
Amstrad CTV3028	432
Amstrad CTV3121N	496
Amstrad CTV3128	239
Amstrad CTV3128N	110, 303
Amstrad CTV312N	686
BPL KLR9402-01	624
Beko 12220 (10.2 chassis)	495
Beko 15225NX	590
Beko 19321T	558
Beko 20212T (12.1 V1 chassis)	687
Beko 28128 (11.1 chassis)	25
Beko 30128T	623
Beko NR2541ND	302
Beko NR28411ND	430
Beko NR28416NDS	176
Beko NR30128T	112
Bush 1433 (11AK08 chassis)	752
Bush 1433 (11AK20 chassis)	688
Bush 1473T (11AK08 chassis)	302
Bush 1497ITV	368
Bush 2020	304
Bush 2054T	686
Bush 2059	432
Bush 2152T (Onwa chassis)	240, 750
Bush 2550NTX	687
Bush 2721 (11AK03 chassis)	688
Bush 2850NTX (TV4 chassis)	176
Bush 2866NTX	111, 303, 405

Bush 2867NTX (11AK19 chassis)	302, 686, 751	JVC AVN280EKT (BY11 chassis)	623
Bush 2868NTX (11AK19 chassis)	176, 622	JVC C1480EK (BX11 chassis)	751
Bush 2868NTX (11AK19-5 chassis)	431	JVC C14ET1EK (Onwa chassis)	431
Bush 2871NTX (11AK19 chassis) (Goodmans GTV288)		Hitachi C2114T (G7PS chassis)	47, 110
	111, 405, 496	Hitachi C2117T	687
Bush 2872NTX (11AK19-E3 chassis)	112, 303	Hitachi C2117TE	623
Bush 2876NTX	405	Hitachi C2118R	174
Bush 2877NTX	46	Hitachi C2125T (11A19K chassis)	175
Bush 3114T	688	Hitachi C2146TN	496
Bush 3472NTX (Pro 4400 chassis)	239, 495, 560, 686	Hitachi C2156TN (A7 chassis)	559
Bush 6690D (11AK19 chassis with DTT)	688	Hitachi C2164TN	368
Bush BTV17	496	Hitachi C24W1TN-311	688
Bush BTV17A (Orion chassis)	559	Hitachi C24W410	239
Bush WS6667	752	Hitachi C24W410SN	176
Bush WS6671 (11AK19 chassis)	46, 303	Hitachi C2509T (G7PSL chassis)	158
Bush WS6672	430	Hitachi C2546TN	47, 239
Bush WS6673 (11AK37 chassis)	303, 533	Hitachi C2556TN2	111
Bush WS6673SIL	430	Hitachi C2576TN (A5 chassis)	687
Bush WS6674	176, 366	Hitachi C28300TN	560
Bush WS7673SIL	405	Hitachi C2842N (11AK19PP chassis)	304
Crown CRP2196T (SM1 mono chassis)	752	Hitachi C2874TNY	240
Crown CRV37 (11AK08 chassis)	688	Hitachi C28W40TN	751
Crown CTF25NT	623	Hitachi C28W410SN (A7 chassis)	560
Daewoo DWP28W2GB	25	Hitachi C28WD2TN	432
Daewoo GB14H1N	494	Hitachi C2976TN (A5 chassis)	111
Daewoo GB20C4T	623	Hitachi C32W510SN (A7 chassis)	47
Daewoo GB2898ST (CP775 chassis)	688	Hitachi C32WD2TN2 (A7 chassis)	431
Decca D10R609	46	Hitachi C32WF810	239
Decca D28NT92S	111	Hitachi CPT2174 (G6P chassis)	688
Decca/Tatung F series chassis	751	Hitachi CPT2178 (G6P chassis)	304
Ferguson 14D1 (TX85 chassis)	111	Hitachi CPT2888 (Salora K chassis)	623
Ferguson 37140 (TX90 chassis)	624	Hitachi G7PS Mk II chassis	48
Ferguson 59J7 (TX100 chassis)	590	Hitachi IDTVs	238
Ferguson 59P7 (ICC5 chassis)	367	JMB JMBN028WSS	240
Ferguson B59F (ICC7 chassis)	558, 756	JMB NO28WSS (PT92 chassis)	432
Ferguson B68N (ICC8 chassis)	496	JMB TV430SLR	752
Ferguson B78NT (ICC5 chassis)	368	JVC 7860GB	431
Ferguson D14R (TX805 chassis)	176, 494	JVC AV21F1EK (JX chassis)	367
Ferguson D59F (ICC9 chassis)	687	JVC AV25GS1EK (MX chassis)	751
Ferguson M3615UT (TX807 chassis)	240, 303	LG 21A50E	687
Ferguson M7022U (625R)	624	LG C114B50F (11.1 chassis)	47
Ferguson M7073GH (TX92 chassis)	48	LG C120E20	368
Ferguson T14T (TX805 chassis)	174	LG Flatron RZ-15LA31	751
Ferguson T51N (TX91 chassis)	112	LG KE14U73	47
Ferguson T59N (TX92 chassis)	303	Matsui 1408R	752
Ferguson T59NB (TX92F chassis)	176	Matsui 1436XA	240
Ferguson T68N (TX92 chassis)	304, 487	Matsui 1476	174
Ferguson T68NB (TX92 chassis)	495	Matsui 201R	624
Fidelity 3132NF	624	Matsui 20T1 (Grundig G1000 chassis)	688
Fidelity CTV3128	623	Matsui 20TN (Tatung chassis)	238
Fidelity CTV3221NF	368	Matsui 2107T	430
Fidelity CTV3228NF	175	Matsui 2109NS	368
Fidelity WSTV7028N (11AK19-8A chass	494	Matsui 21V1N (Grundig CUC7350)	688
Finlux 3024F (3000 chassis)	112	Matsui 28DW01A	158
Finlux 5025S (5000 chassis)	559	Matsui 28WN20	688
GoldStar CI21A80FA (PC31A chassis)	48	Matsui 28WV2N (Grundig CUC2059)	623
GoldStar K114U71	112	Matsui TVR161	112
GoldStar WE32Q101P	46	Matsui TVR180R	496
Goodmans 1450T (Onwa chassis)	368	Mitsubishi CT14MV1 (Philips chassis)	304
Goodmans 206NS Daewoo CP380A chass.	559	Mitsubishi CT21M5BT (EE4 chassis)	111, 752
Goodmans 215N Daewoo CP365 chassis	112	Mitsubishi CT2525TX Euro 10 chassis	624, 752
Goodmans 256NS	686	Mitsubishi CT25A5STX (Euro 14SF cha	496
Goodmans 2575 (F11 chassis)	112, 159	Mitsubishi CT25AV1BS (EE3 chassis)	158
Goodmans 2580 (TX92 chassis)	111	Mitsubishi CT32BW1B	469
Goodmans 285DPL	277	Naiko N2897	111
Goodmans 285NS (CP775 chassis)	752	Nikkai 3743 (11AK08 chassis)	240
Goodmans 286NS	48, 238	Nokia 3724UKFX (Mono Plus chassis)	304
Goodmans 286NS	496	Nokia 5524 (Mono Plus chassis)	624
Goodmans 286TVS	559	Nokia C114F80	25
Goodmans Compact 110	112	Okishi N2818W (PT92 chassis)	495
Goodmans GD2880D (Thomson TX92F cha	496	Panasonic TC14S3R (Z7 chassis)	176
Goodmans GTV288 (11AK19 chassis)	175	Panasonic TC15M1RP (Z4 chassis)	367
Goodmans GTV66W1 (11AK19 chassis)	238	Panasonic TX1 (Alpha 1 chassis)	688
Goodmans TVC201T	559	Panasonic TX14JT1	240, 558
Goodmans W280NS (F19 chassis)	751	Panasonic TX2172 (Alpha1 chassis)	752
Goodmans W288NS	368	Panasonic TX21MD1 (Euro 2 chassis)	48
Goodmans W322NS (F19 chassis)	239, 496	Panasonic TX21MD3 (Euro-2 chassis)	687
Grundig CUC2040 chassis	623	Panasonic TX25AD1DP (Euro 2 chassis)	159
Grundig CUC7301	495	Panasonic TX25MD1 (Euro 2L)	366, 432, 431
Grundig GT2103 (G1000 chassis)	112	Panasonic TX25MD3 (Euro-2M chassis)	432
Grundig ST63-550 (CUC5360 chassis)	687	Panasonic TX25X1 (Alpha 4 chassis)	277
Grundig ST70-460 (CUC4635 chassis)	687	Panasonic TX28W3 (Euro-1 chassis)	239
Grundig ST70-755	688	Panasonic TX28X1DP (Alpha 4 chassis)	756
Grundig T63-539 (CUC5310 chassis)	48	Panasonic TX29AD1DP Euro 2 chassis	239
Grundig XS63	217	Panasonic TX32PG30 (Euro-7 chassis)	47
Bush 7764 (11AK37 chassis)	533	Panasonic TX33AK10 (Euro-5 chassis)	175
Ferguson ICC7 chassis	551, 628	Panasonic TX42PT10	686
JVC AV28WFT1EKS	239	Philips 14PV170	688
JVC AV28X10EKS	624	Philips 14PV184	47
JVC AV29SK1EK (JA chassis)	246	Philips 14PV330	303
JVC AV29SX1 (JA chassis)	240	Philips 14TVCR240	48, 495
JVC AV29SX1EK (JA chassis)	25	Philips 15CE1518 (CP90 chassis)	25
JVC AV29SX1EK (JA chassis)	366, 432, 496	Philips 20PV184	687
JVC AV32WFP1EK	239	Philips 20PV184	756

Philips 20PV220	687	Sharp 66GS62H	752
Philips 21GR2550 (G90AE chassis)	367	Sharp 76FW53H (DA100 chassis)	431, 622
Philips 21PT1164	750	Sharp C3720H (14A chassis)	496
Philips 21PT1532 (L6.1 chassis)	559	Sharp CV2133H (8PSR chassis)	240
Philips 21PT1663 (L7.2E chassis)	431	Sharp DV5107H (Deco 4 chassis)	303
Philips 21PT1664-05S (SL9.2E AA)	622	Sharp DV51083H (D3000 chassis)	175
Philips 21PT166B (AA5 chassis)	174	Sharp DV5932H (BCTV-A chassis)	368
Philips 21PT166B	176	Sharp DV6632H (4BSC chassis)	559
Philips 21PT4457	752, 495	Sharp LC20E1E	750
Philips 21PT5322	560, 590	Sharp XG-P10XE	48
Philips 21PV288	239	Sony FE1 chassis	54, 118, 288
Philips 21PV330	239	Sony KD32DX100U (AE6D chassis)	751
Philips 24PW6324	110	Sony KV1400UB	175
Philips 25MN1550 (GR2.2 mono)	48, 240, 751	Sony KV14FV1U (BC5 chassis)	176
Philips 25PT4103 (L6.2 chassis)	559	Sony KV14T1U (BE4 chassis)	622
Philips 25PT4103	176	Sony KV21LS30U	112
Philips 25PT4475 (L9.1E chassis)	432	Sony KV21LT1U (FE2 chassis)	559
Philips 25PT4493 (L6.3AA chassis)	751	Sony KV21M3U (BE4 chassis)	111
Philips 25PT4495	303	Sony KV21X1U	368
Philips 25PT4521	623	Sony KV27XRTU (SX chassis)	687
Philips 25PT4523 (MD1.2E chassis)	750, 751	Sony KV28DS20U (BE3E chassis)	559
Philips 25PT532A (GR2.2AA chassis)	559	Sony KV28DX20U (BE3E chassis)	751
Philips 25ST1724 (GR2.1 chassis)	217	Sony KV28FD1E (GE1 chassis)	47, 217
Philips 28/32PW6005 (A10E chassis)	174	Sony KV28FS20U (BE3E chassis)	431
Philips 28CL6770	111, 432	Sony KV28LS66U	559
Philips 28PT4494 (L6.3AA chassis)	558	Sony KV28WS2U (BE2A chassis)	158, 495
Philips 28PT4523	240	Sony KV32DS60U (GE1A chassis)	302
Philips 28PW6006	687	Sony KV32LS60U (AE6B chassis)	751
Philips 28PW6315	47	Sony KV32WF1U (BE3D chassis)	559
Philips 28PW6324	112	Sony KVA2942U (AE2A)	111, 217
Philips 28PW6332 (MD1.2 chassis)	47	Sony KVD2512U (AE1A)	590
Philips 28PW6515	110	Sony KVDX271TU (AE1 chassis)	469
Philips 28PW6816	112	Sony KVM2140 (BE2A chassis)	432
Philips 28PW9512	47	Sony KVM2140U (BE2A chassis)	368
Philips 28ST2781 (GR2.2 chassis)	175	Sony KVM2511U (AE1 chassis)	110
Philips 29PT632A (GR2.4 chassis)	217	Sony KVV2142U (AE1C chassis)	48, 367
Philips 29PT727B (GR2.4 chassis)	175	Sony KVV2152U (AE1C chassis)	752
Philips 32PW6305	47, 176, 239	Sony KVV2552U (AE1C chassis)	430
Philips 32PW6515 (A10E chassis)	623, 752	Sony KVV2572 (AE2A)	159
Philips 32PW6526-05 (SA10E chassis)	622	Sony KVV2575U (AE2 series chassis)	277
Philips 32PW6615	176, 697	Tatung C series chassis	558
Philips 32PW9523	432, 559	Tatung F series chassis	302
Philips 32PW962B	175	Tatung T28NE51 (E1W and E1N chassis)	366, 750
Philips 32PW9763	48	Tatung T28W441 (4400 chassis)	750
Philips AA5 AA chassis	628	Tatung V21NDF0 (D4N series)	686
Philips CP90 chassis	48	Tatung V25NEFO (E series chassis)	110
Philips GR2.2AA chassis	238	Tatung VU2CEO (C chassis)	238
Philips GR2.4 chassis	469	Thomson 14MGI5U (TX807C chassis)	431
Philips STU3600	277	Thomson 20CB25UT	176
Philips TV	687	Thomson 21DK24U (ICC17 chassis)	48
Proline 1415R	367	Thomson 24WK25UG	238
Proline 28N1	158, 559	Thomson 28/32VK24/25 etc (ICC17 chassis)	46
Protech 5131NT (Vestel chassis)	302	Thomson 28DG35UD (ICC19 chassis)	175
REOC 21TN (Beko chassis)	246	Thomson 28DT73H (TX92 chassis)	303
Roadstar CTV552 (See also Goodmans Compact 110)	112	Thomson 28WF25U (ICC17 chassis)	174, 240, 432
Sony KVE2932U (AE2 chassis)	112, 590	Thomson 32WR22 (ICC17 chassis)	623
Sony KVM2101U (BE2A chassis)	432, 590	Thomson 32WT45U	302
SEG CT7951 G3 (11AK19P chassis)	174	Thomson 443/Combi Model 21CB26VN	494
Salora 24K70	590	Thomson ICC9, TX92 chassis etc	623
Samsung CI20S20BT (S15A chassis)	240	Toshiba 1400TB	686
Samsung CI3352XT (P68SC chassis)	304	Toshiba 145E7B	624
Samsung CI501FT5X	46	Toshiba 2101TB	112
Samsung CI5052 (P68 chassis)	302	Toshiba 2140RB	368
Samsung CI5079T (SCT11D chassis)	494	Toshiba 2151TB (C4ER chassis)	496
Samsung CI5337AN (US60A chassis)	238	Toshiba 215T8B	48
Samsung CI5373 (SCT11B chassis)	469	Toshiba 21S04B	209
Samsung CI593CN (S51A chassis)	368	Toshiba 2500T	217
Samsung CI593CN3X (S51A chassis)	304	Toshiba 2500TB	174
Samsung CI5944	47	Toshiba 2505DB	238
Samsung CI6844N	686	Toshiba 2505DBT	558
Samsung SCT11D chassis	209	Toshiba 2573DB (C7SR chassis)	533
Sanyo 25BN2	111	Toshiba 2805DB	112
Sanyo 28DN5 (EB6 chassis)	367	Toshiba 2812DB	174
Sanyo 28WP3 (WB2A chassis)	367	Toshiba 2877DB (C7SS chassis)	559
Sanyo 28XP1 (EB4A chassis)	751	Toshiba 28W23B (11AK37 chassis)	366, 495, 622
Sanyo 32WN5B (EB6A chassis)	304	Toshiba 28W8DB (C7SS chassis)	366, 751
Sanyo CE28WN5	431	Toshiba 28W93B (C7SS chassis)	495
Sanyo CE32WN4 (EB6-A chassis)	432	Toshiba 2927DB	239
Sanyo CE32WP3	48	Toshiba 32Z13P	304
Sanyo CE32WP4 (EB6 chassis)	623	Toshiba 32ZD09G (C005 chassis)	246
Schneider STV2802T	752	Toshiba 32ZP18Q	750
Schneider STV5501 (11AK19 chassis)	240	Toshiba 40PW8DB	756
Sharp 37GQ-20H	367	Toshiba 43PJ93B	176
Sharp 51AT15 (5BSA chassis)	430	Toshiba 50PJ98B (C9SS chassis)	303
Sharp 51AT15H (5BSA chassis)	558, 752	Toshiba VTV14025B	495
Sharp 51CS03H (CS chassis)	111	Wharfedale 550	46
Sharp 51DS03H	111	Wharfedale 550S	239
Sharp 51DT25H (CA1 chassis)	304, 495	York X5 Junior (PT92 chassis)	533
Sharp 56FW53H (DA100 chassis)	111, 558, 756		
Sharp 66DS03H (CA10 chassis)	119, 303, 368		
Sharp 66ES03H (CA10 chassis)	368, 559, 687, 750		
Sharp 66FW53H (DA100 chassis)	366, 430, 495, 559, 686		
Sharp 66FW54H (DA100 chassis)	751		
Sharp 66GF63H (DA50W chassis)	687		

TV SERVICING

Toshiba C5SS chassis servicing <i>John Coombes</i>	346, 412
EEPROM reprogramming jig <i>Sharp Technical Team</i>	200, 341
Line output stage operation <i>Keith Cummins</i>	342
Panasonic Euro-4H chassis <i>Brian Storm</i>	460
Panasonic Euro-7 Servicing <i>Brian Storm</i>	26
Panasonic Z8 chassis Guide <i>Brian Storm</i>	136
Samsung SCT11D chassis servicing <i>John Coombes</i>	72
Sharp DA100 chassis service notes <i>Philip Laws</i>	406, 551
Sharp DA100 chassis servicing <i>Alex Towers</i>	406, 725
Sony TV chassis update <i>Giles Pilbrow</i>	10
Thomson's TX92 chassis <i>Mark Paul</i>	29, 90

VCR SERVICING

Betamax video 1975-2002, RIP <i>Ralph Buckstone</i>	12
---	----

VCR CLINIC

Aiwa HV-FX2800K	684
Aiwa HV-FX7700	556
Aiwa HV-FX7700K	620, 684
Aiwa HVFX5100K	43
Aiwa HVGX350K	107
Akai VSA650EK	363
Akai VSF33	363
Akai VSG240EK	684
Akai VSG280	426
Akai VSG796EK	620
Alba VCR8900	556
Amstrad DD8900 Twin deck	684
Bush 190TA	42
Bush BTV14	170
Bush VCR880NVP	620
Daewoo DVP832P	684
Daewoo DVT14F4P	556
Daewoo V435	620
Daewoo V60	362
Ferguson 3V36	557
Ferguson FV10	235
Ferguson FV205	106
Ferguson FV305HV	684
Ferguson FV305V	493
Ferguson FV44L	426
Ferguson FV62LV, Toshiba V312B	362
Ferguson FV67HV	42
Ferguson FV71 (R3000 chassis)	43
Ferguson FV77HV	42, 107
Ferguson FV91LV	171
GoldStar 5121	748
GoldStar GHV1240I	234
GoldStar GHV1296I	107
GoldStar GSE1290IQ	556
GoldStar GSEQ2011	748
GoldStar RC703I	363
GoldStar RC705I	363
Goodmans TVC1400	556
Goodmans TVC202TS	685
Goodmans TX3650	235
Goodmans TX4000 (Daewoo FM)	170
Goodmans VN6000	42
Goodmans VN9500S	748
Goodmans VN9600B (Daewoo K deck)	43, 170, 426
Goodmans VP2500	299
Granada VHSHS5	158
Grundig 2 x 4 Super	685, 749
Grundig VS540	685
Grundig VS720	426
JMB D1020	363
Hitachi VT520E	684
Hitachi VTF150	492
Hitachi VTF150E	170, 756
Hitachi VTF350	427
Hitachi VTF350E	42
Hitachi VTF360	298
Hitachi VTF540E	426
Hitachi VTF550K	171
Hitachi VTF650E	427
Hitachi VTFX765E	427
Hitachi VTFX860	556
Hitachi VTFX940	362
Hitachi VTFX980	299
Hitachi VTM722E	557
JVC HRD180EK	684
JVC HRD540	684
JVC HRD540, 560 etc	405
JVC HRD540, HRD560, HRD910, HRJ200	405
JVC HRD610	171
JVC HRD790EK	426
JVC HRD880EK	748
JVC HRD910	556

JVC HRD960	492
JVC HRJ205	298
JVC HRJ410EK	684
JVC HRJ411EK	684
JVC HRJ420	42
JVC HRJ610EK	209
JVC HRJ625	43
JVC HRJ635 (1996 deck)	363
JVC HRJ665	234
JVC HRJ670	170
JVC HRJ755EK (1998 deck)	170
JVC HRS7000	493
JVC HRS7000EK	42
JVC HRS7500EK (1998 deck)	170
LG 221	748
LG BC969NI	557
LG KE14U43	106
LG N311	621
Matsui TVR141	685
Matsui TVR161	685
Matsui VP9405	299, 621
Matsui VP9601N	299
Matsui VP9605	107
Mitsubishi HS561V	748
Mitsubishi HS651	492
Mitsubishi HSM37	107
Mitsubishi HSMB32	748
Philips VR6490	298
Philips VR6547 (JVC deck)	106, 234
Philips VR675 (Turbo deck)	492
NEC N895	298
Nokia VCR3716	748
Nokia VCR3785UK	299
Orion D2000	621
Panasonic AG5260 (K mechanism)	426
Panasonic AG5700B	556
Panasonic G Deck	298
Panasonic NV45	427
Panasonic NV530B	362
Panasonic NV870	170
Panasonic NVF55B (G deck)	170
Panasonic NVFJ610	170
Panasonic NVFJ610B-K	235
Panasonic NVFJ620B (Z mechanism)	106
Panasonic NVG25	426
Panasonic NVG40	556
Panasonic NVHD600	43
Panasonic NVHD620 (K deck)	620
Panasonic NVHD620B (K deck)	170
Panasonic NVHD660B (K deck)	362
Panasonic NVL28	748
Panasonic NVSD200 (K deck)	362
Panasonic NVSD220 (K deck)	492
Panasonic NVSD230 (Z deck)	299
Panasonic NVSD40B	234
Philips 14PV163	106
Philips 14PV164	106
Philips 14PV165	621
Philips Turbodeck VCRs	469, 629
Philips VC522 (Turbo deck)	426
Philips VP28	299
Philips VR165	620
Philips VR231	493
Philips VR2547 (JVC deck)	363
Philips VR260 (Turbo deck)	469, 629
Philips VR453	748
Philips VR572 (and many others)	493
Philips VR600 (Turbo deck)	492
Philips VR630-07	685
Philips VR700	42, 492
Philips VR765	620
Sanyo VHR777E	107, 426
Sanyo VHR790	234
Sanyo VHRH290E	749
Sanyo VTC5000	621
Saisho VR3400	426
Samsung SV213B	42
Samsung SV221B	42
Samsung SV241K	362
Samsung SV245B and others	298
Samsung SV301	362
Samsung SV401K	363
Samsung SV630B	234
Sanyo TLS942P (P90 mechanism)	171
Sanyo VHR274E	556
Sanyo VHR279	427
Sanyo VHR279E	106
Sanyo VHR289	171
Sanyo VHR335E	749
Sharp VCA50HM	362
Sharp VCA63HM	298
Sharp VCA72HM	299
Sharp VCM29HM	556
Sharp VCM321	748

Sharp VCM321HM	749
Sharp VCMH60	684
Sharp VCMH711HM	590
Sony EVS550E	492
Sony KV21V5U	106
Sony SLF30UB	427
Sony SLV625UB	590
Sony SLV715UB	277, 556
Sony SLV757UB	749
Sony SLV815UB	106
Sony SLVE230UY	620
Sony SLVE40UX	171
Sony SLVE700	43
Sony SLVE700UX	171, 362
Sony SLVE710UX	298
Sony SLVE730UX	42
Sony SLVE80	362
Sony SLVE80UX	298
Sony SLVSE30UX	427
Sony SLVSE70	427
Sony SLVSE70UX	684
Sony SLVSE710	298
Sony SLVSE99UX	748
Thomson VTH6021U	298
Thomson VTH7090U	748
Toshiba V219B	556
Toshiba V230K	620
Toshiba V631UK	492
Toshiba V701UK	492
Toshiba V709B	171, 426
Toshiba V710	298
Toshiba V711UK	621
Toshiba V725K	234
Toshiba V726	106
Toshiba V726B	362
Toshiba V813C	171

WHAT A LIFE! FAULT REPORTS

Aiwa HVFX1500 VCR	634
Aiwa VXT147 TV	698
Bush 2872NTX (11AK19E3 chassis)	248
Bush WS6672	184
Bush WS6674	313
Ferguson FV77HV	377
Goodmans W282NS	698
Hitachi C2556TN	120
Minato ST1411	120
Panasonic Digidox	377
Panasonic NVFS90	634
Panasonic NVHD90	313
Panasonic TX21V2	699
Philips 21GR2550	120
Samsung CI5079 (SCT11D chassis)	313
Samsung CI5944 (SCT12B chassis)	376
Samsung SV241K	698
Sanyo 25BN2	184
Schneider STV2802T	56
Sharp 56FW53H	312
Sharp CV2133H (8PSR chassis)	698
Sharp DXR555 CD player	377
Sony HCDS800 DVD player	762
Sony KV25X5U (FE1 chassis)	634
Toshiba SD110 DVD player	377

A sixteen year compilation Index (volumes 38-53) is now available on CD-ROM for use with a PC from SoftCopy Limited, 1 Vineries Close, Cheltenham, Glos GL53 0NU, UK.

Article reprints are also available from the above address. Send an SAE with enquiries.

Visit our web site at <http://www.televisionmag.co.uk>